



**TRANS EUROKARS PTE LTD**  
**NO:5 UBI CLOSE, SINGAPORE 408605**  
**FINALISED COST OF REPAIRS**



<b>MSIG INSURANCE SINGAPORE P/L</b> 4 SHENTON WAY #21-01 SGX CENTRE 2 SINGAPORE 068807 <b>ATTN. :</b> MOTOR CLAIMS <b>FAX :</b>	<b>NAME :</b> TRANS EUROKARS PTE LTD <b>ADDRESS :</b> 12 SUNGEI KADUT AVE SINGAPORE 729648 <b>TEL :</b> 63633003	<b>WIP :</b> 57502 <b>EXCESS :</b> \$ 1,000.00 <b>DATE :</b> 31-Jan-18
--	---	--

<b>VEH NO :</b>	<b>SLQ765U</b>	<b>DATE IN :</b>		<b>CONTACT PERSON :</b>	
<b>CHASSIS NO :</b>	JM6DJ2HAA01100856	<b>MILEAGE :</b>		<b>TYPE OF CLAIM :</b>	PROPERTY CLAIM
<b>MODEL :</b>	MAZDA2 HB DELUXE	<b>DATE REG.:</b>	28-Jun-17	<b>POLICY NO. :</b>	

**NATURE OF WORKS**

**Parts Description**

NO	QTY		REVISED	PRICES
1	1	ROOF TOP REINFORCEMENT MD09H-70-663	\$ 40.90	\$ 40.90
2	1	ROOF LINING MDA6R-68-03ZC75	\$ 1,248.70	\$ 1,248.70
3	1	ROOF TOP PANEL MD0YH-70-600	\$ 790.50	\$ 790.50
4	1	MOULD, FRONT WINDSCREEN MD09L-50-601	\$ 46.90	\$ 46.90
		<b>TOTAL PARTS</b>	<b>\$ 2,127.00</b>	<b>\$ 2,127.00</b>
		<b>LESS 10%</b>	<b>\$ 212.70</b>	<b>\$ 212.70</b>
		<b>TOTAL PARTS COST</b>	<b>\$ 1,914.30</b>	<b>\$ 1,914.30</b>

**Labour Description**

1		TO REPLACE ROOF TOP PANEL.	\$ 1,890.00	\$ 2,520.00
2		TO RESPRAY ROOF TOP PANEL.	\$ 600.00	\$ 1,200.00
3	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	\$ 150.00	\$ 250.00
4	MZ-BR-LINING	TO REMOVE & INSTALL ROOF LINING.	\$ 630.00	\$ 630.00
5	MZ-BR-GLASS1	TO REMOVE & REFIT THE WINDSCREEN GLASS.	\$ 560.00	\$ 560.00
6	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.	\$ 120.00	\$ 120.00
7	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 150.00	\$ 250.00
8	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 180.00	\$ 350.00
9	MZ-BR-SUNDRI	SUNDRIES.	\$ 30.00	\$ 100.00
		<b>TOTAL LABOUR</b>	<b>\$ 4,310.00</b>	<b>\$ 5,980.00</b>

TOTAL PARTS	\$ 1,914.30	\$ 1,914.30
TOTAL	\$ 6,224.30	\$ 7,894.30
LESS EXCESS	\$ 1,000.00	\$ -
TOTAL AFTER EXCESS	\$ 5,224.30	
GST 7%	\$ 365.70	\$ -
<b>GRAND TOTAL</b>	<b>\$ 5,590.00</b>	<b>\$ -</b>

REMARKS: SLQ765U

**8 REPAIR DAYS** (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)