


SYNOPSIS

Kalvin

REF: CC3/TML18001954/KIRB2

ASSIGNMENT

From \_\_\_\_\_ Date \_\_\_\_\_  
Estimated Cost \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
To inspect Vehicle No \_\_\_\_\_  
at Workshop no \_\_\_\_\_  
of \_\_\_\_\_  
Insured **SIX 908L**  
Policy No **M6001195**  
Claims No **M1800659**  
Sum Insured \_\_\_\_\_ Excess **£800**  
(Client's Record) \_\_\_\_\_  
Make of Veh. \_\_\_\_\_  
  
(Policy Condition) \_\_\_\_\_  
Remark **The veh had commenced its repair at the time of inspection.**  
  
Bal. or Market Value. \_\_\_\_\_  
IDAC Accident Report: \_\_\_\_\_ Consistent? Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? Yes or No  
Est. Repairs: \_\_\_\_\_ days Res: Yes or No  
Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No  
  
CA / REV / REP. / 24 HRS  
Date: \_\_\_\_\_ Person Contacted \_\_\_\_\_ Vehicle IN / OUT \_\_\_\_\_



Vehicle No **SH 9787L** Regn **23 Jun 2011**  
Type: M.Car / M.Cycle / Bus / Van / Lorry / T/B / Prime Mover /  
Truck / Trailer or \_\_\_\_\_  
Make **Hyundai Sonata** 199  
Colour **B/4E** Insured **6** / Std / NI / NA  
Sp Reading **254365** Radio Insured **6** / Std / NI / NA  
Eng No \_\_\_\_\_  
C No: **KMHET41VMDA811785**  
Gen Cond: Good / Fair / Poor / Burnt  
Steering In order **6** / Jammed / Leaked / Burnt or  
Brake In order **6** / Jammed / Leaked / Burnt or  
Mod: Nil / S/Rim / STD **6** / Rim or  
Tyre Size F: **215/60 R16**  
R: \_\_\_\_\_  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or **Maxxis**  
  
Front \_\_\_\_\_ Rear \_\_\_\_\_  
R Bal **7** mm R Bal **7** mm  
L Bal **7** mm L Bal **7** mm  
D.O.A **30/1/18** D.O.I **31/1/18**  
Survey held at **LOKE (107my)**  
Des. of Damages Frt / Rear / O/S / N/S / U/C / Rooftop or  
**Rear**  
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction  
**SH 9787L - CC3/ML12010139/HIS233p**  
**SIX 908L -**

DO: 210512 **To Kio**  
**4/2**

**Sent GIA and EST to Shirley**  
**6/4/8** **Cost 4.5/12.50/2 Pgs.**  
**Ref: \$1692.10, 581.**

**1 FEB 2018**

Date/Time File Pass to: ☐ Preli. Report  
**typist** ☒ Final Report  
Date/Time File Return to: \_\_\_\_\_

Days Of Repair: **2**  
Resurvey No. of Trip: **1**


Report Format: **TP**  
Lump Sum / LB: **1250**

Add Fee: ☐ Site Insp \$  
☐ Inter \$  
☐ Tel \$  
☐ \_\_\_\_\_

Survey Fee **250**  
Transportation **10**  
**260**



**LKK Auto Consultants Pte Ltd**  
 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933  
 TEL: 6256 3561 FAX: 6256 4315  
 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
TOKIO MARINE INSURANCE SINGAPORE LTD		Ref : CC3/TMI18001954/K1rb		
20 MCCALLUM STREET #09-01 TOKIO MARINE CENTRESINGAPORE 069046		Date : 31-01-2018		
		Code : TMI		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SJX 908L	Veh. Inspected	SH 9787L	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	31/01/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	30/01/2018	Inspection Date	31/01/2018	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

## Janice Lee (LKKAuto)

---

**From:** Janice Lee (LKKAuto)  
**Sent:** Thursday, February 01, 2018 12:31 PM  
**To:** Too Joon Hwa  
**Cc:** SUR; priscilla@tokiomarine.com.sg  
**Subject:** DIRECT SURVEY INSPECTION ON WORKSHOP - COMFORTDELGRO ENGINEERING PTE LTD DOA: 30/01/2018, SH 9787L (TP VEHICLE), SJX 908L (OI VEHICLE)  
**Attachments:** SH 9787L ESTIMATE.pdf; SH 9787L GIA.pdf

Dear Shirley,

Please be informed that we had inspected the vehicle **SH 9787L** M/s: COMFORTDELGRO ENGINEERING PTE LTD, 59 LOYANG DRIVE SINGAPORE 508969 on 31/01/2018.

Enclosed herewith a copy of TP's GIA report and estimated cost of repair.

Meanwhile, kindly create claim in merimen for our necessary action.

Thank you.

Best Regards,

**Janice Lee (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [janicelee@lkkauto.com](mailto:janicelee@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

eam: ARC Repair TP(CLS0)1

**JOB CARD** Sales Order:

JC NO.305112375

TOMER

REGN NO:  
**SH 9787L**

MILEAGE

AS COMFORT TRANSPORTATION PTE LTD

TOMER NO 7010045

MAKE:  
**HYUNDAI**

FUEL

RESS 383 SIN MING DRIVE  
Singapore SINGAPORE 575717

MODEL  
**SONATA**

DATE/TIME IN  
**30.01.2018 20:10**

(R) 65508755

(O)

YR OF MANU  
**23.06.2011**

TARGET DATE

(P)

CHASSIS CODE  
**KMHET41VMEBA811785**

COMPLETION DATE/TIME:

OUNT CARD NO.

*Tofio Marine*

JOB DESCRIPTION

ccident Date: 30.01.2018

ATURE: 3P 30.01.2018

/NO                      LABOR CODE                      DESCRIPTION

CKED & PASSED OUT BY: \_\_\_\_\_

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

wedgement Slip

Exit Pass

No.: **SH 9787L**

**LARRY**

Vehicle No.:

**SH 9787L**

of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	31/01/2018 09:34
Date Of Accident	30/01/2018 19:10
Exact Location Of Accident	FUSION0POLIS WAY X AYER RAJAH AVENUE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SH9787L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	SONATA

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category TAXI

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	

### Driver

Name of Driver	CHIANG SENG GOK
NRIC No	S1368631I
Date Of Birth	07/01/1959
Occupation	OUTDOOR
Date Of Driving Pass	13/11/1984
Driving Experience	33 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	CHIANGSG59@GMAIL.COM

Address	BLK 313 HOUGANG AVENUE 5 #04-169
Postcode	530313
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLS REFER TO ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJX908L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	NEO KIM CHUAN
NRIC/Passport Number	S1154463J
Contact Number	
Address	
Postcode	
Insurance Company Name	TOKIO MARINE INSURANCE SINGAPORE LTD
Nature Of Damage	FRT
No. Of Passenger (Including Driver)	

**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time:


Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

GIAIAC Sketch Plan Page 1/1



### SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As seen in the video, I moved on the slip road towards Ayer Rajah Avenue after exiting Fusionopolis Way yesterday (30/1/18) evening at about 7-10 pm and while I stopped on the slip road junction to check on-coming traffic, I felt an impact when it was car B (SIX90PL) behind branged into the rear of my car. I took photos at the scene and also took down particulars of the driver of car B. No passenger in my taxi.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R





Policyholder's Signature  
Date & Time:



Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Lim Ee Soon  
CSO

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:







**ComfortDelGro Engineering Pte Ltd** (Co.Reg.No:199506048W)

59 Loyang Drive  
Singapore 508969  
Tel: 6214 8300

**TP INSURER:**  
**CTPL**

**Tokio Marine Insurance Singapore Ltd (HQ)**

Singapore

**PARTICULARS OF CLAIM**

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	30/01/2018
Vehicle Reg. No.:	SH9787L	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI SONATA, 2.0 CRDI (A)	Vehicle Reg. Date:	23/06/2011
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	D4EAB967337	Chassis No:	KMHET41VMBA811785
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

<b>COST OF CLAIMS</b>	<b>Amount</b>
Parts	2,012.10
Miscellaneous Items	10.00
Labour	920.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (\$\$)</b>	<b>2,942.10</b>
<b>+ GST 7.00% (\$\$)</b>	<b>205.95</b>
<b>Nett Amount (\$\$)</b>	<b>3,148.05</b>

**This claim is handled by: LIM KWOK ENG**

*Generated using Merlimen e-Claims Internet Estimation & Adjusting System*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 31 Jan 2018)  
**Parts:** 143      HYUNDAI SONATA 2.0 CRDI (A) (Catalogue:Merimen Singapore 1.0)  
**Labour:** Repairer's      (Price-denominated Standard List)  
**Print Code:** ComfortDelGro Engineering Pte Ltd/SH9787L/31/01/2018 17:21  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER / <i>Reformed</i>	20.00	0.00	*578.40 FL
2	1		*REAR BUMPER REINFORCEMENT <i>x svc</i>	20.00	0.00	*483.30 FL
3	10		*REAR BUMPER CLIPS <i>/ rec</i>	20.00	0.00	*22.00 FL
4	1		*REAR BUMPER SPONGE <i>x svc</i>	20.00	0.00	*137.40 FL
5	1		*REAR BUMPER UNDER COVER <i>x svc</i>	20.00	0.00	*185.80 FL
6	1		*REAR BUMPER PROTECTOR LH <i>x Repair</i>	20.00	0.00	*38.00 FL
7	1		*REAR BUMPER PROTECTOR RH <i>x Repair</i>	20.00	0.00	*38.00 FL
8	1		*REAR PANEL <i>x repair</i>	20.00	0.00	*391.80 FL
9	1		*REAR PANEL GARNISH <i>/ Ltr</i>	20.00	0.00	*95.80 FL
10	1		*REAR BUMPER REVERSE SENSOR <i>/ Shunted</i>	0.00	0.00	*135.70 F
11	1		*REAR BUMPER RUBBER MAT <i>/ rec</i>	0.00	0.00	*50.00 F
12	1		*REAR BUMPER ADVERTISEMENT LOGO <i>- rec</i>	0.00	0.00	*50.00 F
13	1		*REAR FENDER ADVERTISEMENT LOGO LH <i>/ rec</i>	0.00	0.00	*100.00 F
14	1		*REAR FENDER ADVERTISEMENT LOGO RH <i>/ rec</i>	0.00	0.00	*100.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	2,406.20
- List Item Discount on L Items (S\$)	394.10
<b>Total Parts (S\$)</b>	<b>2,012.10</b>

ComfortDelGro Engineering Pte Ltd/SH9787L/31/01/2018 17:21. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<b>Miscellaneous Items</b>			
1	1	OD/TP Case (Insurer)	10.00
<b>Sub Total (\$\$)</b>			<b>10.00</b>

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	PANEL BEATING	New	200 350.00
2	SPRAY PAINTING CHARGE	New	300 400.00
3	WIRING CHARGE	New	50 50.00
4	REMOVE/REFIX REVERSE SENSOR	New	20 120.00
<b>Gross Labour Cost (\$\$)</b>			<b>920.00</b>

ComfortDelGro Engineering Pte Ltd/SH9787L/31/01/2018 17:21. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

MAXX18

LKK/Kalvin

H/Sun

VEHICLE NO : SH 9787L

DATE 31/1/2018 9:34

MAKE :

MODEL : HYUNDAI SONATA

Larry

Zukio Maru

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper — <i>Rehlt</i>			\$ 578.40	
	Rear Bumper Reinforcement <i>X</i>			\$ 483.30	
	Rear Bumper Clip — <i>ndc</i>			\$ 22.00	
	Rear Bumper Sponge <i>X</i>			\$ 137.40	
	Rear Bumper Under Cover <i>X</i>			\$ 185.80	
	Rear Bumper Protector (LH/RH) <i>X repair</i>		\$ 38.00	\$ 76.00	
	Rear Panel <i>X repair</i>			\$ 391.80	
	Rear Panel Garnish — <i>on</i>			\$ 95.80	
	<i>Rear Bumper 2</i>				
	<b>SUB TOTAL</b>			<b>\$ 1,970.50</b>	
	<b>LESS 20%</b>			<b>\$ 394.10</b>	
	<b>DISCOUNTED TOTAL</b>			<b>\$ 1,576.40</b>	
	Rear Bumper Reverse Sensor — <i>slk</i>			\$ 135.70	Nett
	Rear Bumper Rubber Mat — <i>on</i>			\$ 50.00	Nett
	Rear Bumper Advertisement Logo — <i>on</i>			\$ 50.00	Nett
	Rear Fender Advertisement Logo (LH/RH) — <i>on</i>		\$ 100.00	\$ 200.00	Nett
				<b>\$ 435.70</b>	
	<b>Labour Charge</b>				
	Panel Beating			<del>\$ 350.00</del>	<i>2-0</i>
	Spray Painting Charge			<del>\$ 400.00</del>	<i>360</i>
	Wiring Charge			<del>\$ 50.00</del>	<i>X on</i>
	Remove/Refix Reverse Sensor			<del>\$ 120.00</del>	<i>20</i>
	<b>TOTAL LABOUR</b>			<b>\$ 920.00</b>	
	<b>ESTIMATE TOTAL</b>			<b>\$ 2,932.10</b>	
	<i>Kelvin</i>				
	<i>31/1/18 1500hrs</i>				
	<i>2 Days</i>				
	<i>45</i>				
	<i>After Repair photo</i>				
	<div> <p><b>LKK Auto Consultants hence notify the Repairer of the following:</b></p> <ul style="list-style-type: none"> <li>• To resurvey before/after spray painting</li> <li>• To display damaged part(s) during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "Without Prejudice" basis</li> <li>• No illegal modification is allowed</li> <li>• Supplementary item must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged: Signature: Date:</p> </div>				
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

# COMFORTDELGRO ENGINEERING

Our Job Ref No : 305112375

Date : 05/02/18

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

## FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN

Vehicle Reg No. : SH 9787L

Date of Accident: 30.01.2018

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO SJX908L
2. The finalized amount shall be:
  - (a) Spare Parts after List discount
  - (b) Labour Charges
  - Total for Part-By-Part Repair Cost**
  - (c.) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: **Final Lumpsum Repair cost** \$1,250.00
3. Estimated normal period for repairs: 2 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance.

We confirm the estimates and  
finalized amount

Signature : 

Name : Larry Ng

Tel : 6214 8316

Fax : 6546 8156

Signature : 

Name : Kaly

Date : 6/2/18

## For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	31 Jan 2018 17:11 Sendback Est	31 Jan 2018 17:21 <b>S\$2,942.10</b>	01 Feb 2018 13:43 Edit Adj Rpt	<b>S\$1,250.00</b> Edit Estimates	<b>S\$1,250.00</b> View Rpt		<b>Pending for Survey Report</b> Cancel Case

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<b>Show All</b>
-------------	------------------	----------------------	------------------	-----------------

#### CLAIM SUBFOLDER DETAILS

Insured:	CTPL, Co. Reg. No.: 199302821R		
Main Claimant:	CTPL		
Vehicle Reg. No.:	SH9787L	Date of Loss:	30/01/2018 18:00 - :59
Claim Type:	TP / M1800659	Policy/Cover Note No.:	MG001195 (Comprehensive) Coverage: 07/12/2017 - 06/12/2018
Vehicle Reg. No. (Insured):	SJX908L	Policy No. (Claimant):	
		Excess:	S\$800.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Fiona Gan Bee Song - 65926378]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN ] ... [Final Rpt due 12/02/2018]		

#### ASSOCIATED MAIL RECEIVED

There are no mail for this case.

#### ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

SH9787L (M1800659)  
[SJX908L]  
TP  
CTPL  
Jan 30 2018 6:00PM  
[CTPL]  
ComfortDelGro Engineering Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View <div>View in Browser</div>		
Assessment Reports									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)							Thumbnail	Print	
1	31/01/18 17:21	Repairer Estimates							1	Load HTM	
Photos/Images									3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print
1	01/02/18 18:12	General View							1	Load JPG	<input checked="" type="checkbox"/>
2	01/02/18 18:12	General View							1	Load JPG	<input checked="" type="checkbox"/>
3	01/02/18 18:12	General View							1	Load JPG	<input checked="" type="checkbox"/>
4	01/02/18 18:12	General View							1	Load JPG	<input checked="" type="checkbox"/>
5	01/02/18 18:12	General View							2	Load JPG	<input checked="" type="checkbox"/>
6	01/02/18 18:12	General View							1	Load JPG	<input checked="" type="checkbox"/>
7	01/02/18 18:12	General View							1	Load JPG	<input checked="" type="checkbox"/>
8	01/02/18 18:12	General View							1	Load JPG	<input checked="" type="checkbox"/>
9	01/02/18 18:12	General View							1	Load JPG	<input checked="" type="checkbox"/>
10	01/02/18 18:12	General View							1	Load JPG	<input checked="" type="checkbox"/>
11	01/02/18 18:12	General View							1	Load JPG	<input checked="" type="checkbox"/>
12	01/02/18 18:12	General View							1	Load JPG	<input checked="" type="checkbox"/>
13	01/02/18 18:12	General View							1	Load JPG	<input checked="" type="checkbox"/>
14	01/02/18 18:12	General View							1	Load JPG	<input checked="" type="checkbox"/>
15	01/02/18 18:12	General View							2	Load JPG	<input checked="" type="checkbox"/>
16	01/02/18 18:12	General View							1	Load JPG	<input checked="" type="checkbox"/>
17	01/02/18 18:12	General View							1	Load JPG	<input checked="" type="checkbox"/>
18	01/02/18 18:12	General View							1	Load JPG	<input checked="" type="checkbox"/>
19	01/02/18 18:12	General View							1	Load JPG	<input checked="" type="checkbox"/>
20	01/02/18 18:12	General View							1	Load JPG	<input checked="" type="checkbox"/>
21	01/02/18 18:12	General View							1	Load JPG	<input checked="" type="checkbox"/>
22	01/02/18 18:12	General View							1	Load JPG	<input checked="" type="checkbox"/>
23	01/02/18 18:12	General View							1	Load JPG	<input checked="" type="checkbox"/>
24	01/02/18 18:12	General View							1	Load JPG	<input checked="" type="checkbox"/>
25	01/02/18 18:12	General View							1	Load JPG	<input checked="" type="checkbox"/>
26	01/02/18 18:12	General View							1	Load JPG	<input checked="" type="checkbox"/>
27	01/02/18 18:12	General View							1	Load JPG	<input checked="" type="checkbox"/>
28	01/02/18 18:12	General View							1	Load JPG	<input checked="" type="checkbox"/>
29	01/02/18 18:12	General View							1	Load JPG	<input checked="" type="checkbox"/>
30	01/02/18 18:12	General View							1	Load JPG	<input checked="" type="checkbox"/>
31	01/02/18 18:12	General View							1	Load JPG	<input checked="" type="checkbox"/>
32	01/02/18 18:12	General View							1	Load JPG	<input checked="" type="checkbox"/>

33	01/02/18 18:12	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
34	02/02/18 08:40	<b>Reinspection Photo</b>		Load JPG	<input checked="" type="checkbox"/>
35	02/02/18 08:40	<b>Reinspection Photo</b>		Load JPG	<input checked="" type="checkbox"/>
36	02/02/18 08:40	<b>Reinspection Photo</b>		Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>					
			1 per page		<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
1	31/01/18 17:24	<b>E-filed GIA report</b>		Load PDF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<a href="#">Reset</a>	<a href="#">Save</a>	<a href="#">Print</a>
There are no document checklists configured.			

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:**
☐ Repairer
 ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI18001954/K1RBE2

Date: 09/02/2018

### REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MG001195

Claimant Vehicle No : SH9787L

Insured Vehicle No : SJX908L

Date of Loss: 30/01/2018

Nature of Claim: TP

Claim No: M1800659

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SH9787L

Make &amp; Model: HYUNDAI SONATA, 2.0 CRDI (A)

Engine No: D4EAB967337

Reg. Date: 23/06/2011 (Man. Year: 2011)

Chassis No: KMHET41VMBA811785

Colour: Blue

Odometer: 254365 km

Engine Capacity: 1991 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition: Good

### CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Maxxis 7 mm

Rear Left Side: Maxxis 7 mm

Front Right Side: Maxxis 7 mm

Rear Right Side: Maxxis 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,012.10	992.66	1,019.44	50.67
Miscellaneous Items	10.00	10.00	0.00	0.00
Labour	920.00	580.00	340.00	36.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>2,942.10</b>	<b>1,582.66</b>	<b>1,359.44</b>	<b>46.21</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>1,250.00</b>		
	<b>(\$\$)</b>	<b>2,942.10</b>	<b>1,250.00</b>	<b>1,692.10</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>205.95</b>	<b>87.50</b>	<b>118.45</b>	<b>57.51</b>
<b>Nett Amount (\$\$)</b>	<b>3,148.05</b>	<b>1,337.50</b>	<b>1,810.55</b>	<b>57.51</b>

### INSPECTION

Date of Assignment: 01/02/2018 Present Location:

ComfortDelGro Engineering Pte Ltd  
(Loyang)

Date Inspected: 31/01/2018 Inspected At:

59 Loyang Drive  
Singapore 508969

Estimated Period of Repair: 2.0 days

**Adjuster:** KALVIN ANG WEI KUN

**Manager:** Janice Lee Si Hua

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 09 Feb 2018)  
**Parts:** 143      HYUNDAI SONATA 2.0 CRDI (A) (Catalogue:Merimen Singapore 1.0)  
**Labour:** Repairer's      (Price-denominated Standard List)  
**Print Code:** (Unsubmitted, no print-code for SH9787L)  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	578.40 FL	*578.40 FL
2	1		*REAR BUMPER REINFORCEMENT	Serviceable	483.30 FL	*- FL
3	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
4	1		*REAR BUMPER SPONGE	Serviceable	137.40 FL	*- FL
5	1		*REAR BUMPER UNDER COVER	Serviceable	185.80 FL	*- FL
6	1		*REAR BUMPER PROTECTOR LH	Repair	38.00 FL	*- FL
7	1		*REAR BUMPER PROTECTOR RH	Repair	38.00 FL	*- FL
8	1		*REAR PANEL	Repair	391.80 FL	*- FL
9	1		*REAR PANEL GARNISH	Cracked	95.80 FL	*95.80 FL
10	1		*REAR BUMPER REVERSE SENSOR	Shorted	135.70 F	*135.70 F
11	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 F	*50.00 F
12	1		*REAR BUMPER ADVERTISEMENT LOGO	Necessary	50.00 F	*50.00 F
13	1		*REAR FENDER ADVERTISEMENT LOGO LH	Necessary	100.00 F	*100.00 F
14	1		*REAR FENDER ADVERTISEMENT LOGO RH	Necessary	100.00 F	*100.00 F

F=Franchise part. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>2,406.20</b>	<b>1,131.90</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	<b>394.10</b>	<b>139.24</b>
<b>Total Parts (S\$)</b>	<b>2,012.10</b>	<b>992.66</b>

Report was unsubmitted during this print-out.

**Recommended Miscellaneous Items**

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	OD/TP Case (Insurer)	10.00	10.00
<b>Sub Total (\$\$)</b>			<b>10.00</b>	<b>10.00</b>

**Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	350.00	200.00
2	SPRAY PAINTING CHARGE	New	400.00	360.00
3	WIRING CHARGE	New	50.00	0.00
4	REMOVE/REFIX REVERSE SENSOR	New	120.00	20.00
<b>Gross Labour Cost (\$\$)</b>			<b>920.00</b>	<b>580.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >