



Your Ref: DMPU1600034H/JG

Date: 12<sup>th</sup> February 2018

Our Ref: CS1/ICS18001956/Dtbs2

**M/s ECICS Ltd**

7 Temasek Boulevard  
#10-01 Suntec Tower One  
Singapore 038987  
(The Motor Claims Department)

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:**  
**SKW 5411M**  
**INSURED VEHICLE: SKP 5869M**  
**ACCIDENT DATE: 17/06/2016**

We thank you for your instruction on 30/01/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SKW 5411M from M/s WG Appraisal Services.
- b) Singapore Accident Statement of Vehicles SKW 5411M and SKP 5869M.
- c) Colour damaged vehicle photographs of SKW 5411.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

|                      |  |
|----------------------|--|
| Registration Number  | : SKW 5411M                                |
| Make & Model         | : B.M.W 523I 2.5 AT ABS D/AB 2WD 4DR GAS/D |
| Year of Registration | : 2011                                     |
| Chassis Number       | : WBAFP32060C866933                        |

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.