

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/III18001957/K1HB3S2**Date:** 27/02/2018REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

**Claimant Vehicle No :** SHC6059G**Insured Vehicle No :** SLT364C

Date of Loss: 30/01/2018

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHC6059G**

Make &amp; Model: KIA OPTIMA, 1.7 D (A)

Engine No: D4FDDH308340

Reg. Date: 10/07/2014 (Man. Year: 2013)

Chassis No: KNAGM414ME5463940

Colour: Silver

Odometer: 224440 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/65R16

Rear Tyre Size: 205/65R16

Front Left Side: Achilles 7 mm

Rear Left Side: Achilles 7 mm

Front Right Side: Achilles 7 mm

Rear Right Side: Achilles 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,862.40	1,972.40	890.00	31.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,790.00	680.00	1,110.00	62.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,652.40</b>	<b>2,652.40</b>	<b>2,000.00</b>	<b>42.99</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,100.00</b>		
<b>(S\$)</b>	4,652.40	2,100.00	2,552.40	54.86
<b>+ GST 7.00/7.00% (S\$)</b>	325.67	147.00	178.67	54.86
<b>Nett Amount (S\$)</b>	<b>4,978.07</b>	<b>2,247.00</b>	<b>2,731.07</b>	<b>54.86</b>

INSPECTION

Date of Assignment: 31/01/2018

Date Inspected: 31/01/2018 Inspected At:

Premier Automotive Services Pte Ltd (HQ)

23 Changi South Ave 2, #01-02

Singapore 486443

Estimated Period of Repair: 3.0 days

**Adjuster:** KALVIN ANG WEI KUN**Manager:** VIC ALPEH*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 26 Feb 2018)
<b>Parts:</b>	143	KIA OPTIMA 1.7 D (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHC6059G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET GRILLE	Cracked	386.00 FL	*386.00 FL
2	1		*FRONT BUMPER	Deformed	531.00 FL	*531.00 FL
3	1		*FRONT BUMPER EMBLEM	Necessary	44.00 FL	*44.00 FL
4	1		*FRONT BUMPER REINFORCEMENT UPPER	Serviceable	40.00 FL	*- FL
5	1		*FRONT BUMPER CENTRE GRILLE	Serviceable	174.00 FL	*- FL
6	1		*FRONT BUMPER LOWER STIFFER	Repair	134.00 FL	*- FL
7	1		*FRONT BUMPER TOW HOOK COVER	Serviceable	14.00 FL	*- FL
8	1		*FRONT BUMPER LIP	Serviceable	52.00 FL	*- FL
9	1		*FRONT BUMPER INNER SPONGE	Serviceable	110.00 FL	*- FL
10	1		*FRONT BUMPER REINFORCEMENT	Serviceable	328.00 FL	*- FL
11	1		*FRONT BUMPER N/S SIDE RETAINER	Serviceable	16.00 FL	*- FL
12	1		*FRONT BUMPER N/S UPPER BRACKET	Serviceable	16.00 FL	*- FL
13	1		*FRONT BUMPER N/S SUPPORT BRACKET	Serviceable	16.00 FL	*- FL
14	1		*N/S HEADLAMP	Broken	1,028.00 FL	*1,028.00 FL
15	1		*FRONT BUMPER N/S FOG LAMP COVER	Cut	66.00 FL	*66.00 FL
16	1		*FRONT BUMPER N/S PROTECTOR	Cut	51.00 FL	*51.00 FL
17	1		*FRONT NO. PLATE WITH CASING	Serviceable	50.00 FS	*- FS
18	1		*FRONT BUMPER CLIPS	Necessary	48.00 FS	*48.00 FS
19	1		*FRONT N/S HEAD LAMP LOWER CLIP	Necessary	6.00 FS	*6.00 FS
20	1		*FRONT N/S HEAD LAMP SIDE CLIP	Necessary	3.00 FS	*3.00 FS
21	1		*SUNDRY	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>3,163.00</b>	<b>2,183.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	300.60	210.60
<b>Total Parts (\$)</b>	<b>2,862.40</b>	<b>1,972.40</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK FOR WIRING AND TO FOCUS HEAD LAMPS.	New	120.00	20.00
2	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE SUPPORT PANEL ETC.	New	750.00	300.00
3	TO PUTTY AND SPRAY PAINTING ON BONNET, BONNET GRILLE, FRONT BUMPER, FRONT N/S FENDER.	New	800.00	360.00
4	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	New	120.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,790.00</b>	<b>680.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >