

INS. CASE OWNER:

CC 4 / ASM1800

1976, W

LKK:

IDAC:

Sun Art
28419

ASSIGNMENT

DOI: 11/3/18

Date / Time:

21/01/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SDR 835R

Name of Insured:

GHIN BOON LENG RAYMOND

Insured Tel No.:

HP:

Claim No.:

SRM 00854

Policy No.:

GTA 03007

Make / Model:

T. nish

Place of Accident:

X of Tampines Ave 2
2 ST 32 2 PIE

Excess Sec II :SS

D.O.A:

30/01/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

My Y: Long

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

46673093

(V/L: YES / NO)

Insured Liability:

%

Final ? Yes / No

PC3431 P



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

13/3/18
1st

PC3431P - X;

SDR 835R - CCL51A/A13005819 / Gg6k3-1 ; 08.10.10/2013

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

> THIN By Email
21/3

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

16/3/18 @ 11:40

Spoke to OI, she confirmed the accident details. Informed TP claim and she agree to settle.

No Authorization to Art. workshop and claimant same.

RECEIVED 22 OCT 2018

PRELIMINARY ADVICE Date/Time:

21/3/18

Sent By:

Bm

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

19/10/18

Confirm with:

Karen

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

4708.00

Loss of Rental (LOR):

S\$

963.00

(

5

days)

x 1180 + gst

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

(Tick only one)

GIA/LTA Search

S\$

2.00

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

S\$

5673.00

Global Sum S\$:

5606.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

5600.00

Name 1:

THINK ONE AUTOCARE PTE LTD

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

REF: ASM (ARA)

ASSIGNMENT

From: Date: 01/03/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: PC 3431P

at Workshop m/s

Think One

of No. 18 Deft Lane Ave 2

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

10am - 12pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
X	X

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: PC 3431P Vt Reg: 29/3/2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Hiace DO 1982.00

Colour: white A/C Insured / Std / NI / NA

Sp. Reading: 160993 T. Radio: Insured / Std / NI / NA

Eng No:

C/No: KDH2010158255

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 106/104 R

R: 195 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

CST (F) F. neway (R)

Front

Rear

R/Bal: 3 mm

R/Bal: 4 mm

L/Bal: 3 mm

L/Bal: 4 mm

D.O.A: 30/1/2018

D.O.I: 1/3/2018

Survey held at

As Above

Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

Wilson,

Pls see me.

L/S - \$4400E (Red: \$ 5760.83 / 57%)

2/3

Date/Time: File Pass to:

☐

: Preli. Report

Days Of Repair:

1)

☐

: Final Report

Resurvey No. of Trip:

Survey Fee:

Date/Time: File Return to:

Transportation:

2)

Add Fee:

☐

Site Insp: \$

☐

Interview: \$

☐

Tech. Insp: \$

☐

Miscellaneous: \$

Phone:

Fax:

Report Format:

Lump Sum / I.B.I: \$

TOTAL:

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18001976/Wua3		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 01-02-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SDR 835R	Veh. Inspected	PC 3431P	
Policy No.		Coverage (\$)	0.00	
Claim No.	S8M00854	Excess (\$)	0.00	
Assign From		Assign Date	01/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	30/01/2018	Inspection Date	01/03/2018	
Survey held at	THINK ONE AUTOCARE PTE LTD NO.18 DEFU AVENUE 2 SINGAPORE 539522			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522
Tel: 6844 3300 Fax: 6842 4988

not Allowed
2/s to 4400?
5th...

PC3431P Toyota Hiace

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy ✓ DD/CRA 599.30	\$ 1,260.00 ✓
2	2	Rear bumper bracket ✓ Bent	\$ 172.00 ✓
3	1	Rear bumper inner beam ✓ Rnt/h-1	\$ 287.00 ✓
4	1	Rear tailgate assy ✓ 5.0500	\$ 1,862.00 ✓
5	1	Rear tailgate lock mechanism ✓ twi/gm	\$ 266.00 ✓
6	1	Rear tailgate lock catch ✓ twi	\$ 53.00 ✓
7	2	Rear tailgate hinges X NN 11	\$ 162.00 X
8	2	Rear tailgate damper X NN 11	\$ 375.00 X
9	1	Rear tailgate weatherstrip ✓ DEC twi	\$ 288.00 ✓
10	1	Rear tailgate inner board X 11	\$ 190.00 X
11	1	Rear tailgate centre logo ✓ DEC nu	\$ 69.00 ✓
12	1	Rear tailgate windscreen glass moulding seg nu 110	\$ 395.00 ✓
13	1	Rear tailgate lock actuator ✓ X 11	\$ 189.00 X
14	1	Rear tailgate top garnish X ND 11	\$ 280.00 X
15	2	Rear tailgate side garnish X 11	\$ 220.00 X
16	1	Rear tailgate outer garnish X 11	\$ 176.00 X
17	1	Rear left taillamp X 11	\$ 785.00 X
18	1	Rear right taillamp X 11	\$ 785.00 X
19)		Rear End Panel — DD 699.10 ✓	\$ 7,814.00
		Less 25%	\$ 1,953.50
20)		Rear Exhaust Pipe — 11 X	\$ 5,860.50
			6384.83

4405-4
252
330405

Special Nett Items

1	10	Rear bumper clips ✓ DEC	nu \$ 50.00 ✓
2	12	Rear tailgate inner board clips nu	nu \$ 30.00 ✓
3	4	Rear tailgate outer garnish clips 11	11 \$ 20.00 X
4	1	Rear tailgate '70km/h' sticker ✓ DEC	nu \$ 30.00 10
5	6	Rear tailgate top garnish clips X 11	11 \$ 30.00 X
6	6	Rear tailgate side garnish clips X NN	11 \$ 30.00 X
7	1	Rear windscreen glass sealant ✓ DEC	nu \$ 80.00 40
8	1 set	Rear bumper reverse sensor 2	should \$ 250.00 200
9	1	Rear no plate	11 \$ 60.00 X
10)		HIACE sticker — 48.00 ✓ } DEC	\$ 580.00
11)		1250 kg sticker — 38.00 ✓ } DEC	696.00
Total Parts			\$ 6,440.50
12)		Emergency Door Sticker — 15.00 ✓ } DEC	
13)		Full To Open Sticker — 15.00 ✓ } DEC	

446 S.W

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522
Tel: 6844 3300 Fax: 6842 4988

PC3431P Toyota Hiace

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts.	\$ 1,200.00 750
2	To putty and spray painting rear portion.	\$ 1,200.00 700
3	To check rear lighting and wiring.	\$ 50.00 30
4	To remove and install rear tailgate lock mechanism.	\$ 80.00 60
5	To remove and install rear inner garnish and trim to facilitate the repair.	\$ 150.00 X
6	To apply anti rust proofing to rear affected area.	\$ 120.00 60
7	To remove and install rear windscreen glass to facilitate the repair.	\$ 120.00 ✓
8	To remove and install rear bumper reverse sensor.	\$ 60.00 50
9	Towing service.	\$ 100.00 30 X

Total labour : \$ 3,080.00

Total parts : \$ 6,440.50

Total labour : \$ 3,080.00

Total repair cost : \$ 9,520.50

Without Prejudice
hump Sun Repair
Part Price subject to confirmation

Resurvey dismantling / Parts
Require

Resurvey after Paint,
2-3 days.

Wilson, LKK
Tel = 67418434
wilson@lkkauto.com

[Signature]

1/3/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P- 4405.4
252
3304.05

S.N- 446
1770
TOTAL \$ 5520.05
4416

880

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522
Tel: 6844 3300 Fax: 6842 4988

PC3431P Toyota Hiace

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy ✓ DD/CRA	\$ 1,260.00
2	2	Rear bumper bracket ✓ NEC D	\$ 172.00
3	1	Rear bumper inner beam ?	\$ 287.00
4	1	Rear tailgate assy X ✓ DD/BUC	\$ 1,862.00
5	1	Rear tailgate lock mechanism ?	\$ 266.00
6	1	Rear tailgate lock catch ?	\$ 53.00
7	2	Rear tailgate hinges X NN	\$ 162.00
8	2	Rear tailgate damper X NN	\$ 375.00
9	1	Rear tailgate weatherstrip ✓ NEC D	\$ 288.00
10	1	Rear tailgate inner board X	\$ 190.00
11	1	Rear tailgate centre logo ✓ NEC	\$ 69.00
12	1	Rear tailgate windscreen glass moulding ✓ NEC	\$ 395.00
13	1	Rear tailgate lock actuator ✓ ?	\$ 189.00
14	1	Rear tailgate top garnish X NN	\$ 280.00
15	2	Rear tailgate side garnish X	\$ 220.00
16	1	Rear tailgate outer garnish X NS	\$ 176.00
17	1	Rear left taillamp ?	\$ 785.00
18	1	Rear right taillamp ?	\$ 785.00
			\$ 7,814.00
Less 25%			\$ 1,953.50
			\$ 5,860.50

Special Nett Items

1	10	Rear bumper clips ✓ NEC	\$ 50.00	30 D
2	12	Rear tailgate inner board clips ✓ NEC	\$ 30.00	20
3	4	Rear tailgate outer garnish clips ✓ NEC	\$ 20.00	15
4	1	Rear tailgate '70km/h' sticker ✓ NEC	\$ 30.00	20
5	6	Rear tailgate top garnish clips X RPT	\$ 30.00	20
6	6	Rear tailgate side garnish clips X NN	\$ 30.00	20
7	1	Rear windscreen glass sealant ✓ NEC	\$ 80.00	50
8	1	Rear bumper reverse sensor ?	\$ 250.00	200
9	1	Rear no plate X NEC NC	\$ 60.00	X NC D
			\$ 580.00	

Total Parts

\$ 6,440.50

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522
Tel: 6844 3300 Fax: 6842 4988

PC3431P Toyota Hiace

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts.	\$ 1,200.00 <i>500</i>
2	To putty and spray painting rear portion.	\$ 1,200.00 <i>250</i>
3	To check rear lighting and wiring.	\$ 50.00 <i>30</i>
4	To remove and install rear tailgate lock mechanism.	\$ 80.00 <i>X</i>
5	To remove and install rear inner garnish and trim to facilitate the repair.	\$ 150.00 <i>X</i>
6	To apply anti rust proofing to rear affected area.	\$ 120.00 <i>X</i>
7	To remove and install rear windscreen glass to facilitate the repair.	\$ 120.00 <i>✓</i>
8	To remove and install rear bumper reverse sensor.	\$ 60.00 <i>50</i>
9	Towing service.	\$ 100.00 <i>50</i>
Total labour :		\$ 3,080.00

Total parts : \$ 6,440.50

Total labour : \$ 3,080.00

Total repair cost : \$ 9,520.50

*Without Prejudice
 Lump Sum Repair
 Part Price Subject To Confirmation
 Resurvey dismantling / Parts
 Required*

*Resurvey After Paint,
 2-3 Days.
 Wilson, LKK*

*Tel = 67418434
 wilson@lkkauto.com*

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: S8M00854

Our ref: CC4/ASM18001976/Wua3

Date: 02.03.2018

The Motor Claims Department
M/s AXA INSURANCE PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

PC 3431P


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 01.03.2018 at the premises of M/s Think One Autocare Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	9,520.50
Revised Estimate Amount	: S\$	4,169.50
"Check" Items Amount	: S\$	1,973.75
Total (Including Check Items)	: S\$	6,143.25
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 2~3 days

Yours faithfully,

WILSON TEO
Licensed Appraiser



SERVICE REQUESTS

MESSAGES

CLAIMS

<< RE: Request for Mandate approval S8M00854

Type

Question

Message

Dear Sir / Madam, OI rear-ended to TP. We have send letter to OI to inform TP claim and NCD issue.
Liability(TP) 100% Proposed repair cost \$4,708.00 w/gst Loss of rental \$963.00 no. of 5 days x \$ 180
w/gst LTA search fees \$2.00 Proposed Total \$5,673.00 Thanks. Best Regards, Thin Thin

[Reply](#)



SERVICE REQUESTS

MESSAGES

CLAIMS

<< Re:RE: Request for Mandate approval S8M00854

Type

Question

Message

Hi LKK, pls proceed as per mandate. Thank you.

[Reply](#)

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SDR 835R (Insd veh)	Model:	TOYOTA
	PC 3431P (TP veh)		HIACE 3.0 DX DIESEL
Date of Accident:	30/01/2018		TURBO AT

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	:	\$	10,872.09
Final Repair Cost	:	\$	4,708.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	963.00 days
LTA / GIA Search Fee	:	\$	2.00

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum (GLOBAL SUM)	:	\$	5,600.00

Is Third Party Workshop GIA Registered?		☐ YES	☒ NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability ____ 100 ____ (%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: ____		
BOLA Liability: ____ (%)		Assessed Liability (*): ____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____ _____				

Payment Instruction: Payee's Breakdown			
1)	THINK ONE AUTOCARE PTE LTD	:	\$ 5,600.00

NUR SHAQILAH BTE ABDOL
WAHAB

05/11/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18001976/Wua3s2

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 05-11-2018



ATTN: RICHARD ANG

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SDR 835R	Veh. Inspected	PC 3431P
Policy No.	GA030027	Coverage (\$)	0.00
Claim No.	S8M00854	Excess (\$)	0.00
Assign From	RICHARD ANG	Assign Date	31/01/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HIACE	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	KDH2010158205	Colour	WHITE
Odometer	160993	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	106/104R	CST	3 mm
L/H Front Tyre	106/104R	CST	3 mm
R/H Rear Tyre	195 R15	FINEWAY	4 mm
L/H Rear Tyre	195 R15	FINEWAY	4 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	30/01/2018	Inspection Date	01/03/2018
Survey held at	THINK ONE AUTOCARE PTE LTD NO.18 DEFU AVENUE 2 SINGAPORE 539522		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 3431P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER ASSY (CONSISTENT)	DENTED / CRACKED	1,260.00	599.30
2	REAR BUMPER BRACKET (CONSISTENT)	BENT	172.00	172.00
1	REAR BUMPER INNER BEAM (CONSISTENT)	BENT / TWISTED	287.00	287.00
1	REAR TAILGATE ASSY (CONSISTENT)	BADLY DENTED	1,862.00	1,862.00
1	REAR TAILGATE LOCK MECHANISM (CONSISTENT)	TWISTED / JAMMED	266.00	266.00
1	REAR TAILGATE LOCK CATCH (CONSISTENT)	TWISTED	53.00	53.00
2	REAR TAILGATE HINGES (CONSISTENT)	NOT NECESSARY	162.00	-
2	REAR TAILGATE DAMPER (CONSISTENT)	NOT NECESSARY	375.00	-
1	REAR TAILGATE WEATHERSTRIP (CONSISTENT)	TWISTED	288.00	288.00
1	REAR TAILGATE INNER BOARD (CONSISTENT)	NOT NECESSARY	190.00	-
1	REAR TAILGATE CENTRE LOGO (CONSISTENT)	NECESSARY	69.00	69.00
1	REAR TAILGATE WINDSCREEN GLASS MOULDING SEAL (CONSISTENT)	NECESSARY	395.00	110.00
1	REAR TAILGATE LOCK ACTUATOR (CONSISTENT)	NOT NECESSARY	189.00	-
1	REAR TAILGATE TOP GARNISH (CONSISTENT)	NOT NECESSARY	280.00	-
2	REAR TAILGATE SIDE GARNISH (CONSISTENT)	NOT NECESSARY	220.00	-
1	REAR TAILGATE OUTER GARNISH (CONSISTENT)	NOT NECESSARY	176.00	-
1	REAR LEFT TAILLAMP (CONSISTENT)	NOT NECESSARY	785.00	-
1	REAR RIGHT TAILLAMP (CONSISTENT)	NOT NECESSARY	785.00	-
1	REAR END PANEL (CONSISTENT) (ADDITIONAL)	DENTED	699.10	699.10
1	REAR EXHAUST PIPE (NPA) (CONSISTENT) (ADDITIONAL)	NOT NECESSARY	-	-
	LESS 25% DISCOUNT		-2,128.27	-1,101.35
			6,384.83	3,304.05
SPECIAL NETT ITEMS				
10	REAR BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	50.00	50.00
12	REAR TAILGATE INNER BOARD CLIPS (SN) (CONSISTENT)	NECESSARY	30.00	30.00
4	REAR TAILGATE OUTER GARNISH CLIPS (SN) (CONSISTENT)	NOT NECESSARY	20.00	-
1	REAR TAILGATE '70KM/H' STICKER (SN) (CONSISTENT)	NECESSARY	30.00	10.00

Report Ref No. CC4/ASM18001976/Wua3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
6	REAR TAILGATE TOP GARNISH CLIPS (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
6	REAR TAILGATE SIDE GARNISH CLIPS (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
1	REAR WINDSCREEN GLASS SEALANT (SN) (CONSISTENT)	NECESSARY	80.00	40.00
1	SET REAR BUMPER REVERSE SENSOR (SN) (CONSISTENT)	SHORTED	250.00	200.00
1	REAR NO PLATE (SN) (CONSISTENT)	NOT NECESSARY	60.00	-
1	HIACE STICKER (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	48.00	48.00
1	1250KG STICKER (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	38.00	38.00
1	EMERGENCY DOOR STICKER (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	15.00	15.00
1	PULL TO OPEN STICKER (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	15.00	15.00
			696.00	446.00
	LABOUR			
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN REAR AFFECTED AREA AND REPLACE REAR DAMAGED PARTS.		1,200.00	750.00
	TO PUTTY AND SPRAY PAINTING REAR PORTION.		1,200.00	700.00
	TO CHECK REAR LIGHTING AND WIRING.		50.00	30.00
	TO REMOVE AND INSTALL REAR TAILGATE LOCK MECHANISM.		80.00	60.00
	TO REMOVE AND INSTALL REAR INNER GARNISH AND TRIM TO FACILITATE THE REPAIR.	NOT NECESSARY	150.00	-
	TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA.		120.00	60.00
	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO FACILITATE THE REPAIR.		120.00	120.00
	TO REMOVE AND INSTALL REAR BUMPER REVERSE SENSOR.		60.00	50.00
	TOWING SERVICE.	NOT NECESSARY	100.00	-
			3,080.00	1,770.00
GRAND TOTAL			10,160.83	5,520.05
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,400.00

Report Ref No. CC4/ASM18001976/Wua3s2



Report Ref No. CC4/ASM18001976/Wua3s2

A handwritten signature in black ink, appearing to be 'Wilson Teo'.

WILSON TEO CHENG MING

Automotive Assessor

A handwritten signature in black ink, appearing to be 'Ho Leong Chuan'.

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.