

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522
Tel: 6844 3300 Fax: 6842 4988

PC3431P Toyota Hiace

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy ✓ DD/CRA	\$ 1,260.00
2	2	Rear bumper bracket ✓ NEC. D	\$ 172.00
3	1	Rear bumper inner beam ?	\$ 287.00
4	1	Rear tailgate assy X ✓ DD/BUC.	\$ 1,862.00
5	1	Rear tailgate lock mechanism ?	\$ 266.00
6	1	Rear tailgate lock catch ?	\$ 53.00
7	2	Rear tailgate hinges X NN	\$ 162.00
8	2	Rear tailgate damper X NN	\$ 375.00
9	1	Rear tailgate weatherstrip ✓ NEC D	\$ 288.00
10	1	Rear tailgate inner board X	\$ 190.00
11	1	Rear tailgate centre logo ✓ NEC	\$ 69.00
12	1	Rear tailgate windscreen glass moulding ✓ NEC	\$ 395.00
13	1	Rear tailgate lock actuator ✓ ?	\$ 189.00
14	1	Rear tailgate top garnish X NN	\$ 280.00
15	2	Rear tailgate side garnish X	\$ 220.00
16	1	Rear tailgate outer garnish X NS	\$ 176.00
17	1	Rear left taillamp ?	\$ 785.00
18	1	Rear right taillamp ?	\$ 785.00
			<hr/>
			\$ 7,814.00
Less 25%			\$ 1,953.50
			<hr/>
			\$ 5,860.50

Special Nett Items

1	10	Rear bumper clips ✓ NEC	\$ 50.00	30 D
2	12	Rear tailgate inner board clips ✓ NEC	\$ 30.00	20
3	4	Rear tailgate outer garnish clips ✓ NEC	\$ 20.00	15
4	1	Rear tailgate '70km/h' sticker ✓ NEC	\$ 30.00	20
5	6	Rear tailgate top garnish clips X RPT	\$ 30.00	20
6	6	Rear tailgate side garnish clips X NN	\$ 30.00	20
7	1	Rear windscreen glass sealant ✓ NEC	\$ 80.00	50
8	1	Rear bumper reverse sensor ?	\$ 250.00	200
9	1	Rear no plate X NEC NC	\$ 60.00	X NC D
			<hr/>	
			\$ 580.00	

Total Parts

\$ 6,440.50

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522
Tel: 6844 3300 Fax: 6842 4988

PC3431P Toyota Hiace

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts.	\$ 1,200.00 <i>500</i>
2	To putty and spray painting rear portion.	\$ 1,200.00 <i>250</i>
3	To check rear lighting and wiring.	\$ 50.00 <i>30</i>
4	To remove and install rear tailgate lock mechanism.	\$ 80.00 <i>X</i>
5	To remove and install rear inner garnish and trim to facilitate the repair.	\$ 150.00 <i>X</i>
6	To apply anti rust proofing to rear affected area.	\$ 120.00 <i>X</i>
7	To remove and install rear windscreen glass to facilitate the repair.	\$ 120.00 <i>✓</i>
8	To remove and install rear bumper reverse sensor.	\$ 60.00 <i>50</i>
9	Towing service.	\$ 100.00 <i>50</i>
Total labour :		\$ 3,080.00

Total parts : \$ 6,440.50

Total labour : \$ 3,080.00

Total repair cost : \$ 9,520.50

Without Prejudice.
hump Sum Repair
Part Price Subject To Confirmation
Resurvey dismantling / Parts
Require

Resurvey After Paint,
2 - 3 Days.

Wilson, LKK

Tel = 67418434

wilson@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: