

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
		0		TO RUST PROOF ACCIDENT AFFECTED AREAS.		40		0	Reviewing		
		0		TO R&R REAR BOOT MECHANISM.		60		0	Reviewing		
		0		TO R&R REAR LUGGAGE COMPARTMENT		60		0	Reviewing		
		0		TO R&R REAR BUMPER REVERSE SENSOR & CHECK FUNCTION.		50		0	Reviewing		
		0		TO CHECK WIRING LAYOUT OF TAIL LAMP.		30		0	Reviewing		
		0		TO R&R EXHAUST PIPE ASSY.		80		0	Reviewing		
		0		TO DO WHEEL ALIGNMENT.		0		0	Reviewing		
		0		TO CHECK FOR WATER SEEPAGE.		0		0	Reviewing		

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
		0	1		REAR BUMPER RETAINER (LH) (DISC 25%)	Necessary	0	66.82	No		0			66.82	Reviewing	
		0	1		REAR BUMPER RETAINER (RH) (DISC 25%)	Necessary	0	66.82	No		0			66.82	Reviewing	
		0	1		REAR BUMPER BRACKET (LH)	Serviceable	0	0	No		0			0	Reviewing	
		0	1		REAR BUMPER BRACKET (RH)	Serviceable	0	0	No		0			0	Reviewing	
		0	1		REAR BUMPER REINFORCEMENT (DISC 25%)	Bent	0	291.75	No		0			291.75	Reviewing	
		0	1		REAR BUMPER SPONGE	Serviceable	0	0	No		0			0	Reviewing	
		0	1		REAR BUMPER REFLECTOR (RH) (DISC 25%)	Cracked	0	97.5	No		0			97.5	Reviewing	
		0	1		TAIL LAMP (RH) (DISC 25%)	Cracked	0	299.92	No		0			299.92	Reviewing	
		0	2		TAIL LAMP CLIP (RH)	Serviceable	0	0	No		0			0	Reviewing	
		0	1		TAIL LAMP BRACKET (RH)	Serviceable	0	0	No		0			0	Reviewing	
		0	1		REAR FENDER (RH)	Serviceable	0	0	No		0			0	Reviewing	
		0	1		REAR FENDER COWLING (RH)	Serviceable	0	0	No		0			0	Reviewing	

Original Capacity	POLICY INFORMATION	1070 LL
CATEGORY	ASSESSMENT INFORMATION	
Sum Insured		0
Market Value		0

Claim Portal

CATEGORY	FNOL INFORMATION	POST SURVEY
License Type		
License Issue Date		mm/dd/yyyy 
License Expiration Date		mm/dd/yyyy 
Address	6 MARINE VISTA #21-21, 449030, Singapore	
Address type	Personal Correspondence	
Gender	Male	
Marital status	Unknown	
Identification #	S9038940H	

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
LOH Cynthia	2/1/18 10:18 AM	5296.17	5296.17	Open	Share	Clone

Claim Portal

NAME	TYPE	SUB-TYPE	AUTHOR	UNLOADED DATE
 Accident Statement	Reports & Statement		Merimen	UNLOADED
 LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	October 12, 2019
 LKK RESURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	October 12, 2019
 MANDATE IA DD 12102019.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	October 12, 2019
 LOD AND OTHER DOCUMENTS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	October 12, 2019
 PARF COE REBATE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	October 12, 2019
 TP FINAL EST LIST.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	October 12, 2019
 GIA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	June 4, 2018
 RENTAL RECEIPT.pdf	Invoice	Other Service	LKK AUTO CONSULTANTS PTE LTD (TP)	June 4, 2018
 LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	June 4, 2018
 SLC6860L.mp4	Evidence	Videos	LKK AUTO CONSULTANTS PTE LTD (TP)	May 9, 2018
 TP-SJE-LKK.tif	Letters and Correspondence	Third Party	LOH Cynthia	February 1, 2018
 Email received from workshop with TP	Letters and Correspondence	Others	PATIL Amol	January 31, 2018