

CHARN'S

Accident Claim Repair, Corrosion Welding, Body Dent Repairs, Spray-Painting, Mechanical Repair And Customizing of Cars BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724 BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723 TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg Bus. Reg. No. 251513/00M

AXA/AIG(GBD4082D) DOA:29/01/2018@1100

AIG ASIA PACIFIC INSURANCE PTE LTD

1/2/2018

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:

EM 1313 M - HONDA AIRWAVE 1.5 A

CHASSIS NO: GJ11114589 (2007)

1 pc	Rear bumper	\$ 741.00ak
1 pc	Rear bumper retainer LH	\$ 28.00 7
1 pc	Rar taillamp LH bootlid lamp.	\$ 392.0000
1 pc	Rear boot lower	\$ 451.00 de
1 pc	Rear boot 'logo'	\$ 26.00 101
		\$ 1,638.00
	LESS 20%	\$ 327.60
		\$ 1,310.40
1 set	Reverse Sensor (S/NETT)	\$ 200.00 ?
	Check wiring function	\$ 40.00 30
	Remove necessary action: jacking, panel beating, repair and straighten rear inner panel, rear boot,	\$ 500.00
	rear bumper and affected areas.	\$ 500.00
	Putty and respray rear inner panel,r ear boot	
	and rear bumper.	\$ 400.00
		\$ 2,450.40
	ADD 7% GST	\$ 171.53
		\$ 2,621.93
	Note: The above is an estimate only. IF other parts requested	Taupun 97495749
	during the course of repair, we will inform you accordingly.	0 6/2/1801/45
	, , , , , , , , , , , , , , , , , , ,	9-11- (1813

All parts are subject to availability.

CHARN'S QUSTOMCRAFT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey (Leout)
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis V
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Reparen

Signature:

Date: