

22/03/2017

ASS. REC. BY:

REF: CS3/MSG17023035/WNB-1

Special Instruction:

SURVIVOR

Menmen

Wilson

ASSIGNMENT (Office)

From (Person):

Lionel Tan

of

MSIG

Date/Time: 01-02-2018

Estimated Cost:

Bill to:

OD: TP/WS/TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SJW 5337 G

Insured:

SLG1431D

at Workshop n/s

Hock Motors

Tel:

68469707

of No. 1 Kaki Bukit Ave 6 # 02-22 Autobay

Policy No:

29002101MCX

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 3/12/17

CA / REV / REP. / REV 24 HRS

w/p

Date/Time: 9.51am @ 5/12/17

Person Contacted:

Kelvin

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate	Do Not Finalize
	SJW 5337 G - NA / INC17022985/24	D.O.A. 3/12/2017
	SLG1431D - NA / INC17022985/24	D.O.A. 3/12/2017
	Dismantle Part: 06/12/2017	
	After repair: 11.12.2017	

18/12/17 11:31 pm Email to Lionel Tan from Menmen

Wilson,

Pls see my remarks.

Submit Lts \$4700, 7 days

Red: \$2500, 35%.

21/2/2018

MS16

Date 5/12/17

Estimated Cost

OD TRAVEL TP RES / OD RES / EVA / INV / M.

Truck Trailer SJW 5337G

Hock Motors

No. 1 Kaki Bukit Ave 6, # 02-02 Autobay 22

Status

Policy No.

Carrier

Sum Insured

Excess

Client's Record

Make of Van

Policy Condition

Remark: The van had commenced its repair at the time of inspection

Sell or Market value

QAC Accident Report Consistent? Yes or No

QAC App Seen Consistent? Yes or No

Est. Repair 7 days Rep. Yes or No

Lift Sdn Yes or No

CA / REV / REP / 24 HRS 1 up

Date Person Contacted

Date Time Action Instruction

SJW 5337G 2007 Jul 05

Type of Van: Box Van, Lorry, Taxi, Home Motor

Truck Trailer

Van Model JAZZ 14A 1339

Color Blue 248363

Engine

Cyls 4 JHMG 1855 575 223796

Gear Drive Gear (Auto) Gear Burnt

Steering Jockey Jammed / Leaked / Burnt

Brake Jockey Jammed / Leaked / Burnt

Mod (S) STD A/Rim

Tyre size 185/65 R15

195/65 R15

BS / DUN / EXNOVA / GY / FS / L2A / MID / DHTSU / RR / SUM

TOYO / YOKO Dunlop (F)

Front 3 Rear Kumho (R)

RBS 3 LBS 3

DOA 3/12/2017 5/12/2017

Surveyed at Ac Above 3.35pm

Date of Damage 3/12/2017

Type of Damage Fr / Rear O/S / NS / L/C / Roofed

The L/C / Chassis frame / Body Structure damaged due to fire

Range \$5,000 - \$6,000
~~\$8700 - \$9700~~

7 Repair Days

30/1/2018

Date Time Pre-Report

30012018

☐ Pre-Report
☐ Final Report

Days Of Repair

Resurvey No. of Trip

Survey Fee

Date Time Post-Report

Add Fee

Report Format PR3

Comp Sum / B

☐ Insurance
☐ Other
☐ Other

☐ Other
☐ Other
☐ Other



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS3/MSG17023035/Wrb-1	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 01-02-2018	
		Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLG 1431D	Veh. Inspected	SJW 5337G
Policy No.	29002101MCX	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MERIMEN (LIONEL TAN)	Assign Date	01/02/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	03/12/2017	Inspection Date	01/02/2018
Survey held at	HOCK MOTORS WORKSHOP NO.1 KAKI BUKIT AVE 6 #02-38 AUTOBAY @KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Dec 2017		04 Dec 2017 17:17 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	YEOCHEM (S) PTE LTD, Co. Reg. No.: 198306127D								
Main Claimant:	EDDIE SEAH, Co. Reg. No.: 53358269E								
Vehicle Reg. No.:	SJW5337G	Date of Loss:	03/12/2017 00:00 - :59						
Claim Type:	TP / 539451	Policy/Cover Note No.:	B29002101MCX (Comprehensive) Coverage: 22/09/2017 - 21/09/2018						
Vehicle Reg. No. (Insured):	SLG1431D	Policy No. (Claimant):							
		Excess:	S\$1,000.00						
Repairer:	Hock Motors Workshop (HQ) NO 1 KAKI BUKIT AVENUE 6, #02-38 AUTOBAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel: 68469707								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pel - 6643 1307]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Imm.Advice due 05/12/2017]								
Driver/Custodian (Insured):	YEO KIM DEK (/ Male), NRIC: S8225868Z								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/12/2017 12:32
Date Of Accident	03/12/2017 12:15
Exact Location Of Accident	PIE (TUAS) AFTER STEVEN RD EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJW5337G
Insured/Policyholder	
Name Of Registered Owner	EDDIE SEAH
Co Reg No	53358269E
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-89999999

Vehicle Particulars

Manufacturer	HONDA
Model	JAZZ 1.4A
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5092168758
Cover Note Number	

Driver

Name of Driver	SEAH ENG SENG
NRIC No	S1737814G
Date Of Birth	30/06/1966
Occupation	OUTDOOR
Date Of Driving Pass	09/09/1991
Driving Experience	26 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97802952
Fax Number	
Contact Number	OFFICE-97802952
Email Address	NOEMAIL

Address	BLK 14 KAMPONG ARANG ROAD #08-47
Postcode	431014
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	YES
Foreign Vehicle Registration Number	MCN3065 (PRIVATE CAR)
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	KAMPONG GLAM NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: 17A BEACH ROAD , POSTCODE: 199596 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2989999 - FAX NO: 62936498
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20171203/2057.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLG1431D
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	2

Details of Witness

Name

Phone Number

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number MCN3065

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver) 3

Details of Witness

Name

Phone Number

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SJS9447S

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver) 2

Details of Witness

Name

Phone Number

Email Address

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

EDDIE SEAH
Co Reg No: 53358269E

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN

Sketch Plan details:

- Vehicle A: SJW 5357G
- Vehicle B: SLG 1431D
- Vehicle C: MCN 3065
- Vehicle D: SJS 9447S

Diagram description: A vertical column of four boxes labeled A, B, C, and D. To the left of the column, the text 'PIC (TMS) after Steven Rd' is written vertically. To the right of the column, the vehicle details are listed.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report. 1/207/203/2057.

[The remaining lines of the section are empty, with a diagonal line drawn across the middle.]

DECLARATION

I/We declare the foregoing particulars are true in every respect.

EDDIE SEAH
Co Reg No: 53358209E

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Police Report



**SINGAPORE
POLICE FORCE**



T/20171203/2057

1 of 3

Report No. T/20171203/2057

Police Station Of Origin:
Kampong Glam NPP
17A Beach Road SINGAPORE 199596
Tel No: 1800-2989999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made:
03/12/2017 14:37

Vide Report No.:
E/20171203/0122

Station Diary No.:
20

Informant's Particulars

Name of Informant: SEAH ENG SENG			Address: APT BLK 14 KAMPONG ARANG ROAD #08-47 SINGAPORE 431014		
ID Type / ID No.: NRIC NO / S1737814G			Contact No.: Home/Office: Mobile: 97802952		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 51	Date of Birth: 30/06/1966	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: UBER DRIVER			Driving Licence Information: Class: 3		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 03/12/2017 12:15	Type of Location: Straight Road
Location: PAN ISLAND EXPRESSWAY PIE Towards Tuas (After Steven Road exit)				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Chain Collision				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
MCN3065 (Not Accurate)	Car	PROTON		White	Seriously Damaged	2
SJS9447S	Car	CHEVROLET	AVEO 1.4AT 5DR T255	White	Seriously Damaged	1
SJW5337G	Car	HONDA	JAZZ 1.4A	Blue	Seriously Damaged	3
SLG1431D	Car	TOYOTA	CAMRY 2.5 AUTO	Blue	Seriously Damaged	1

Police Report



**SINGAPORE
POLICE FORCE**



T/20171203/2057

2 of 3

Police Station Of Origin:
Kampong Glam NPP
17A Beach Road SINGAPORE 199596
Tel No: 1800-2989999

Report No: T/20171203/2057

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No		Use of Pedestrian Crossing: NA	
No. of Pedestrians Injured: NIL			
Driver			
Name	SEAH ENG SENG	ID No.	S1737814G
Related Vehicle	SJW5337G (Car)	Contact No.	97802952
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 03/12/2017 at about 1215hrs, I was driving my car (SJW5337G) along PIE towards Tuas (After Steven Road Exit). It was three lanes and I was in the centre lane. Traffic was heavy and I do have three passengers inside my vehicle as I am working as a part time UBER driver.

While driving, in front of me there was a vehicle (could not remember the plate number) jam brake all of the sudden. I quickly jam brake and I was able to stop in time. But suddenly I felt a strong impact coming from my rear of my car.

I quickly came out of the vehicle and saw three cars behind me (2nd car: SLG1431D, 3rd car: MCN3065 and 4th car: SJS9447S) chain collision. Ambulance came and my three passengers were then conveyed to the hospital where the rest of the vehicle some were also conveyed to the hospital.

Traffic police came and advised all four drivers including myself to lodge a traffic police report. That is all.

Police Report



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Kampong Glam NPP
17A Beach Road SINGAPORE 199596
Tel No: 1800-2989999



T/20171203/2057

3 of 3

Report No. T/20171203/2057

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

A /

Sgt 1 MUHAMMAD ALIF BIN ALIAS

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIT /

Contact No.:

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:
03/12/2017 14:37

Classification Of Case:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/12/2017 12:02
Date Of Accident	03/12/2017 12:10
Exact Location Of Accident	PIE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLG1431D
Insured/Policyholder	
Name Of Registered Owner	YEOCHEM (S) PTE LTD
Co Reg No	0
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-96225701

Vehicle Particulars

Manufacturer	TOYOTA
Model	CAMRY
Exact Purpose for which vehicle was being used at time of accident	

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B29002101 MCX
Cover Note Number	

Driver

Name of Driver	YEO KIM DEK
NRIC No	S8225868Z
Date Of Birth	31/08/1982
Occupation	INDOOR
Date Of Driving Pass	12/04/2002
Driving Experience	15 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - FATHER COMPANY

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident CHAIN COLLISION

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? YES

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

POLICE STATION NAME [OTHER] TRAFFIC POLICE DIV HQ

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

PLS REFER ATTACHED ACCIDENT REPORT FROM THE DRIVER. POLICE REPORT NO. T/20171203/2071 ATTENDED BY LYNDA

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number MCN3065

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SJS9447S

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SJW5337G

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF INJURED PERSON 1

Name PASSENGER

Approximate Age

Injuries Sustain

Injured person in which vehicle? MCN3065

Were seat belts worn?

Was injured conveyed to hospital by ambulance? YES

Address

Postcode

DETAILS OF INJURED PERSON 2

Name 3 PASSENGERS

Approximate Age

Injuries Sustain

Injured person in which vehicle? SJW5337G

Were seat belts worn?

Was injured conveyed to hospital by ambulance? YES

Address

Postcode

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
YBOCHEM (S) PTE LTD
20 Penjuru Lane
Singapore 609193
Co. Reg. No.: 198306127D
Tel: 6264 3633 Fax: 6265 7987
www.ybochem.com.sg
04/12/17
12:00 Noon


Driver's Signature
(If driver is not the policyholder)
Date & Time:
04/12/17
12:00 Noon

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along Rte towards Tux on the middle of 2 lanes, after Stephens Road Exit. When the car ^{in front} of me, SJS 5337 G, suddenly jammed brake, I followed suite, and managed to brake in time but the car behind me, MCN 3065 did not stop in time and collided with my vehicle (SLG 1431 D) which caused my vehicle to surge forward, leading to my car, colliding with SJS 5337 G. The car, SJS 9447 S that was behind MCN 3065 had collided with MCN 3065 causing MCN 3065 to hit us a 2nd time.

DECLARATION

1/We declare the foregoing particulars are true in every respect.

VERIFIED (S) PSE LTD

P.O. Box 609193
 Singapore 609193
 Co. Reg. No.: 198306127D
 Tel: 6264 3653 Fax: 6265 7847
 www.yeochem.com.sg
 041117
 12:00 Noon

Driver's Signature: _____
(if driver is not the policyholder)
Date & Time: 04/12/12

17:30 Noon

Reporting Centre Personnel's Signature
Name:
NRIC/TFN No.:



**SINGAPORE
POLICE FORCE**



T/20171203/2071

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408665
Tel No: 65470000

1 of 4

Report No. T/20171203/2071

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 03/12/2017 15:58		Vide Report No.: E/20171203/0122		Station Diary No.:	
Informant's Particulars					
Name of Informant: YEO KIM DEK			Address: 74 CHENG SOON GDN CHENG SOON GARDEN SINGAPORE 599850		
ID Type / ID No.: NRIC NO / S8225868Z			Contact No.: Home/Office:		Mobile: 96225701
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 35	Date of Birth: 31/08/1982	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: BUSINESS DEVELOPMENT MANAGER			Driving Licence Information: Class: 3		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 03/12/2017 12:10	Type of Location: EXPRESSWAY
Location: Along Road 1 PAN ISLAND EXPRESSWAY AFTER STEVENS ROAD EXIT				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: CHAIN COLLISION 4 CARS				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
MCN3065	Car					2
SJS9447S	Car	CHEVROLET	AVEO 1.4AT 5DR T255	White		1
SJW5337G	Car	HONDA	JAZZ 1.4A	Blue		3
SLG1431D	Car	TOYOTA	CAMRY 2.5 AUTO	Blue	Slightly Damaged	1



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20171203/2071

2 of 4

Report No. T/20171203/2071

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	CHUI LEONG SONG	ID No.	A30175018
Related Vehicle	MCN3065 (Car)	Contact No.	60126827922
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	LUM E-SHAN	ID No.	S7697256G
Related Vehicle	SJS9447S (Car)	Contact No.	97966331
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	SEAH ENG SENG	ID No.	S1737814G
Related Vehicle	SJW5337G (Car)	Contact No.	97802952
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL



**SINGAPORE
POLICE FORCE**



T/20171203/2071

3 of 4

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20171203/2071

CONTINUATION OF REPORT

Driver			
Name	YEO KIM DEK	ID No.	S8225868Z
Related Vehicle	SLG1431D (Car)	Contact No.	96225701
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

ON THE ABOVE MENTIONED DATE AND TIME,

I WAS DRIVING ALONG PIE TOWARDS TUAS ON THE MIDDLE OF 3 LANES, AFTER STEVENS ROAD EXIT, WHEN THE CAR INFRONT OF ME, SJW5337G, SUDDENLY JAMMED BRAKE WHICH CAUSE A CHAIN COLLISION BETWEEN MY VEHICLE, SLG1431D, AND THE 2 VEHICLES BEHIND ME, MCN3065 AND SJS9447S.

AFTER THE COLLISION, WE MOVED TO THE ROAD SHOULDER, THE AMBULANCE WERE CALLED AND 2 AMBULANCE ARRIVED, AND CONVEYED THE INJURED PEOPLE TO TAN TOCK SENG HOSPITAL. AETOS POLICE OFFICERS ARRIVED SHORTLY AFTER TO TAKE DOWN PARTICULARS OF ALL THE DRIVERS AND WHEN THE TRAFFIC POLICE ARRIVED, WE WERE INSTRUCTED TO HEAD DOWN TO THE TRAFFIC POLICE HEADQUARTERS TO MEET I/O DANIEL.

I WISH TO STATE THAT I HAVE AN IN-CAR CAMERA.

I WAS DRIVING
ROAD
CAUSE A CHAIN
COLLISION

STEVENS
ROAD
CAUSE A CHAIN
COLLISION

ATTACHED
AND
H



**SINGAPORE
POLICE FORCE**



T/20171203/2071

4 of 4

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20171203/2071

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
TP /
ZENG ZI CONG

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIT /

Contact No.:

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:
03/12/2017 15:58

Classification Of Case:



**SINGAPORE
POLICE FORCE**

Signature:

HOCK MOTORS WORKSHOP

No 1 Kaki Bukit Avenue 6 #02-38 AutoBay @ Kaki Bukit

Singapore 417883

Tel : 68469707 Fax : 67535346

Reg No. 53038012M

Email : hockmotors@hotmail.com

Name : Eddie Seah

Address : C/o: No.1 Kaki Bukit Ave 6 #02-38
AutoBay, Singapore 417883

Vehicle Model : Honda Jazz

Date of accident : 3-Dec-17

Final repair cost SJW 5337 G

Lump Sum Repair Costs

\$ 7,200.00

Singapore Dollars : Seven Thousand And Two Hundred Only.

CL APPRAISER PTE LTD

47A Edgefield Plains #13-16 Singapore 828714
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783
Reg No: 201000228E

INVOICE

Eddie Seah
C/o: Hock Motors Workshop
No.1 Kaki Bukit Ave 6 #02-02
AutoBay, Singapore 417883

Invoice No: CL/17889

Ref No: HM/12/1703/TP

Date: 12 December 2017

DESCRIPTION	AMOUNT
OUR SERVICE FEE CHARGES:	
<ul style="list-style-type: none">SURVEY INSPECTION FOR VEHICLE NO. <u>SJW 5337 G</u>RESURVEY INSPECTIONDIGITAL PHOTOGRAPHS SERVICES (INCLUSIVE OF STORAGE AND SUBMISSION OF DIGITAL PHOTOGRAPHS)TRANSPORTATION	
GRAND TOTAL	S\$ 628.00

E & O. E

All cheque payment should be "Crossed" and made payable to "CL APPRAISER PTE LTD"

We shall be grateful if you could forward our payment at your early convenience.



CL Appraiser Pte Ltd

LCL APPRAISER PTE LTD

47A Edgefield Plains #13-16 Singapore 828714
Hp: 90688689 Email: clappraiser@yahoo.com
Reg No: 201000228E

VEHICLE INSPECTION REPORT

To: Eddie Seah
C/o: Hock Motors Workshop
No.1 Kaki Bukit Ave 6 #02-02
AutoBay, Singapore 417883

Date : 12 December 2017
Our ref : HM/12/1703/TP

Accident Date : 03 December 2017
Inspection Date : 04 December 2017
Repairer Name : Hock Motors Workshop
No.1 Kaki Bukit Ave 6 #02-02
AutoBay, Singapore 417883

Type of Survey : Third Party

PARTICULARS OF VEHICLE

Registration No : SJW 5337 G
Make / Model : Honda Jazz
Chassis No : JHMGD18507S223796
Engine No : L13A54002214

Year / Capacity : 2007 / 1339 cc
Colour : Blue
Mileage : 248363

CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front Nearside	: Dunlop	185/65 R15	5 mm	Sport
Front Offside	: Dunlop	185/65 R15	5 mm	Sport
Rear Nearside	: Dunlop	185/65 R15	5 mm	Sport
Rear Offside	: Dunlop	185/65 R15	5 mm	Sport

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the rear portion.
(Details refer to the photographs attached)

Enclosed number of photographs: 83 copies

REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis
and we have not given authorization and instruction to the repairer to proceed with the repair

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of S 7,200.00** on a contractual basis.

Under normal circumstances, the repair period would be about 8 (Eight) working days.

C L APPRAISER PTE LTD

Vehicle Registration No: SJW 5337 G

Our Ref No: HM/12/1703/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

SPARE PARTS - LIST ITEMS

1	Rear windscreen inner seal ✓ NEC	Necessary	\$ 83.00	\$ 83.00 ✓
1	Rear tailgate ✓ BUC	Damage	\$ 903.60	\$ 903.60 ✓
2	Rear tailgate dampers X SVC	Damage	\$ 282.40	\$ 282.40 X
1	Rear tailgate inner trim board X NN	Damage	\$ 296.50	\$ 296.50 X
1	Rear tailgate inner pull pocket X SVC	Damage	\$ 89.60	\$ 89.60 X
1	Rear tailgate lock ✓ 3M	Damage	\$ 183.80	\$ 183.80 ✓
1	Rear tailgate weather strip ✓ NEBT	Necessary	\$ 110.60	\$ 110.60 ✓
1	Rear tailgate number plate garnish ✓ CRA	Damage	\$ 115.80	\$ 115.80 ✓
1	Rear wiper arm X SVC	Damage	\$ 65.20	\$ 65.20 X
1	Rear wiper arm cover ✓ NN	Damage	\$ 12.50	\$ 12.50 X
1	Rear wiper motor X SVC	Damage	\$ 237.10	\$ 237.10 X
2	Rear taillamps ✓ CRA / SC R	Damage	\$ 681.20	\$ 681.20 ✓
2	Rear taillamp panels X R	Damage	\$ 129.00	\$ 129.00 X
2	Rear taillamp lower brackets ✓ BT	Damage	\$ 37.00	\$ 37.00 ✓
1	Rear end panel ✓ DD	Damage	\$ 396.60	\$ 396.60 ✓
1	Rear end panel inner garnish ✓ CRA	Damage	\$ 86.90	\$ 86.90 ✓
1	Rear bumper ✓ DD	Damage	\$ 660.90	\$ 660.90 ✓
2	Rear bumper brackets ✓	Damage	\$ 65.40	\$ 65.40 ✓
2	Rear bumper side retainers ✓ DIS	Necessary	\$ 65.40	\$ 65.40 ✓
1	Rear floor panel X R	Damage	\$ 737.00	\$ 737.00 X
1	Rear floor board (complete) ✓ DIS	Damage	\$ 184.20	\$ 184.20 ✓
1	Rear spare wheel retainer X SVC	Damage	\$ 48.00	\$ 48.00 X
1	Rear exhaust silencer X R	Damage	\$ 456.90	\$ 456.90 X
2	Rear exhaust mountings ✓ Defined	Necessary	\$ 37.00	\$ 37.00 ✓
1	Rear o/s fender X R	Repair	\$ 641.50	X
2	Rear fender inner trims DIS / CRA ✓	Damage	\$ 277.20	\$ 277.20 ✓
			\$ 6,884.30	\$ 6,242.80
Less 20%			\$ 1,376.86	\$ 1,248.56
Total Cost - List Items			\$ 5,507.44	\$ 4,994.24

SPECIAL NETT ITEMS

1	Rear windscreen sealant ✓ NEC	Necessary	\$ 80.00	\$ 50.00 ✓
1	Rear bumper clip (1 set) ✓ NEC	Necessary	\$ 45.00	\$ 45.00 ✓
1	Rear reverse sensor (1 set) ✓ SC	Damage	\$ 350.00	\$ 280.00 200
1	Rear floor panel insulator X NN	Necessary	\$ 150.00	\$ 150.00 X
Total Cost - Special Nett items			\$ 625.00	\$ 525.00
Total cost of parts			\$ 6,132.44	\$ 5,519.24

CCL APPRAISER PTE LTD

Vehicle Registration No: SJW 5337 G

Our Ref No: HM/12/1703/TP

S/No	Description	Repairer's Estimate	Revised Amount
	Total cost of parts c/f	\$ 6,132.44	\$ 5,519.24

LABOUR

- | | | | |
|---|--|-------------|-----------------------------|
| 1 | To remove, refit, replaced damaged lamps and check up rear electrical wiring | \$ 80.00 | \$ 50.00 30 |
| 2 | To remove and refit inner garnishes, inner trim to assist repair. | \$ 150.00 | \$ 120.00 70 |
| 3 | To remove and refit rear reverse sensor. | \$ 120.00 | \$ 80.00 40 |
| 4 | To transfer rear tailgate mechanism and wiring assembly to assist repair. | \$ 80.00 | \$ 60.00 ✓ |
| 5 | To remove and refit rear windscreen glass. | \$ 180.00 | \$ 120.00 ✓ |
| 6 | To remove, refit and ^{repair} replace exhaust silencer and mountings. | \$ 120.00 | \$ 80.00 ✓ |
| 7 | To apply undercoating on repaired and replaced panel. | \$ 180.00 | \$ 120.00 80 |
| 8 | To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident. | \$ 1,800.00 | \$ 1,500.00 1000 |
| 9 | To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident. | \$ 1,600.00 | \$ 1,320.00 1000 |

GRAND TOTAL

\$ 10,442.44 \$ 8,969.24 2480

CCL APPRAISER PTE LTD

Vehicle Registration No: SJW 5337 G

Our Ref No: HM/12/1703/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 7,200.00**


By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deem to be valid.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD


Cheong K/H
Automotive Appraiser

Parts (List)
Discount 20%

Paint (3/Nett)

Labour

Discount 20% (Lump)

3888.60
- # 777.72
<hr/>
3110.88
+ # 295.00
<hr/>
3405.88
+ # 2480.00
<hr/>
5885.88
- # 1177.18
<hr/>
4708.70

* Lump Sum → \$ 4700
7 Repair Days

...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Dec 2017		04 Dec 2017 17:17 Edit Adj Rpt	S\$4,700.00 Edit Estimates	S\$4,700.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	YEOCHEM (S) PTE LTD, Co. Reg. No.: 198306127D		
Main Claimant:	EDDIE SEAH, Co. Reg. No.: 53358269E		
Vehicle Reg. No.:	SJW5337G	Date of Loss:	03/12/2017 00:00 - :59
Claim Type:	TP / 539451	Policy/Cover Note No.:	B29002101MCX (Comprehensive) Coverage: 22/09/2017 - 21/09/2018
Vehicle Reg. No. (Insured):	SLG1431D	Policy No. (Claimant):	
		Excess:	S\$1,000.00
Repairer:	Hock Motors Workshop (HQ) NO 1 KAKI BUKIT AVENUE 6, #02-38 AUTOBAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel: 68469707		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Imm.Advice due 05/12/2017]		
Driver/Custodian (Insured):	YEO KIM DEK (/ Male), NRIC: S8225868Z		

[View All](#)[Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

- MSIG_LTP (05/02/2018): UPLOAD PAPER SURVEY - SJW5337G

ALL ASSOCIATED TASKS ☐[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJW5337G (539451)

[SLG1431D]

TP

EDDIE SEAH

Dec 3 2017 12:00AM

[YEOCHEM (S) PTE LTD]

Hock Motors Workshop

Upload Documents Upload Photos Compose New Letter			View View in Browser ▾	
Video			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	09/01/18 10:45	SJS9447S (4/4) Video - Accident	Load MP4	<input checked="" type="checkbox"/>
Photos/Images			3 per page ▾	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/01/18 08:51	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
2	31/01/18 08:51	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
3	31/01/18 08:51	General View	Load JPG	<input checked="" type="checkbox"/>
4	31/01/18 08:51	General View	Load JPG	<input checked="" type="checkbox"/>
5	31/01/18 08:51	General View	Load JPG	<input checked="" type="checkbox"/>
6	31/01/18 08:51	General View	Load JPG	<input checked="" type="checkbox"/>
7	31/01/18 08:51	General View	Load JPG	<input checked="" type="checkbox"/>
8	31/01/18 08:51	General View	Load JPG	<input checked="" type="checkbox"/>
9	31/01/18 08:51	General View	Load JPG	<input checked="" type="checkbox"/>
10	31/01/18 08:51	General View	Load JPG	<input checked="" type="checkbox"/>
11	31/01/18 08:51	General View	Load JPG	<input checked="" type="checkbox"/>
12	31/01/18 08:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
13	31/01/18 08:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
14	31/01/18 08:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
15	31/01/18 08:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
16	31/01/18 08:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
17	31/01/18 08:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
18	31/01/18 08:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
19	31/01/18 08:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
20	31/01/18 08:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
21	31/01/18 08:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
22	31/01/18 08:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
23	31/01/18 08:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
24	31/01/18 08:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
25	31/01/18 08:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
26	31/01/18 08:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
27	31/01/18 08:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
28	31/01/18 08:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
29	31/01/18 08:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
30	31/01/18 08:51	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

31	31/01/18 08:51	Photographs of Damaged Parts	1	Load JPG	✓
32	31/01/18 08:51	Photographs of Damaged Parts	1	Load JPG	✓
33	31/01/18 08:51	Photographs of Damaged Parts	1	Load JPG	✓
34	31/01/18 08:51	Photographs of Damaged Parts	1	Load JPG	✓
35	31/01/18 08:51	Photographs of Damaged Parts	1	Load JPG	✓
36	31/01/18 08:51	Photographs of Damaged Parts	1	Load JPG	✓
37	31/01/18 08:51	Photographs of Damaged Parts	1	Load JPG	✓
38	31/01/18 08:52	Photographs of Damaged Parts	1	Load JPG	✓
39	31/01/18 08:52	Photographs of Damaged Parts	1	Load JPG	✓
40	31/01/18 08:52	Photographs of Damaged Parts	1	Load JPG	✓
41	31/01/18 08:52	Photographs of Damaged Parts	1	Load JPG	✓
42	31/01/18 08:52	Photographs of Damaged Parts	1	Load JPG	✓
43	31/01/18 08:52	Photographs of Damaged Parts	1	Load JPG	✓
44	31/01/18 08:52	Photographs of Damaged Parts	1	Load JPG	✓
45	31/01/18 08:52	Photographs of Damaged Parts	1	Load JPG	✓
46	31/01/18 08:52	Photographs of Damaged Parts	1	Load JPG	✓
47	31/01/18 08:52	Photographs of Damaged Parts	1	Load JPG	✓
48	31/01/18 08:52	Photographs of Damaged Parts	1	Load JPG	✓
49	31/01/18 08:52	Photographs of Damaged Parts	1	Load JPG	✓
50	31/01/18 08:52	Photographs of Damaged Parts	1	Load JPG	✓
51	31/01/18 08:52	Photographs of Damaged Parts	1	Load JPG	✓
52	31/01/18 08:52	Photographs of Damaged Parts	1	Load JPG	✓
53	31/01/18 08:52	Photographs of Damaged Parts	1	Load JPG	✓
54	31/01/18 08:52	Photographs of Damaged Parts	1	Load JPG	✓
55	31/01/18 08:52	Photographs of Damaged Parts	1	Load JPG	✓
56	31/01/18 08:52	Photographs of Damaged Parts	1	Load JPG	✓
57	31/01/18 08:52	Photographs of Damaged Parts	1	Load JPG	✓
58	31/01/18 08:52	Photographs of Damaged Parts	1	Load JPG	✓
59	31/01/18 08:52	Photographs of Damaged Parts	1	Load JPG	✓
60	31/01/18 08:52	Photographs of Damaged Parts	1	Load JPG	✓
61	31/01/18 08:52	Photographs of Damaged Parts	1	Load JPG	✓
62	31/01/18 08:52	Photographs of Damaged Parts	1	Load JPG	✓
63	31/01/18 08:52	Photographs of Damaged Parts	1	Load JPG	✓
64	31/01/18 08:52	Photographs of Damaged Parts	1	Load JPG	✓
65	31/01/18 08:52	Photographs of Damaged Parts	1	Load JPG	✓
66	31/01/18 08:52	Photographs of Damaged Parts	1	Load JPG	✓
67	31/01/18 08:52	Photographs of Damaged Parts	1	Load JPG	✓
68	31/01/18 08:52	Photographs of Damaged Parts	1	Load JPG	✓
69	31/01/18 08:52	Photographs of Damaged Parts	1	Load JPG	✓
70	31/01/18 08:52	Photographs of Damaged Parts	1	Load JPG	✓
71	31/01/18 08:52	Photo After Spray	1	Load JPG	✓
72	31/01/18 08:52	Photo After Spray	1	Load JPG	✓
73	31/01/18 08:52	Photo After Spray	1	Load JPG	✓
74	31/01/18 08:52	Photo After Spray	1	Load JPG	✓
75	31/01/18 08:52	Photo After Spray	1	Load JPG	✓
76	31/01/18 08:52	Photo After Spray	1	Load JPG	✓
77	31/01/18 08:52	Photo After Spray	1	Load JPG	✓
78	31/01/18 08:52	Photo After Spray	1	Load JPG	✓

79	31/01/18 08:52	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
80	31/01/18 08:52	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
81	31/01/18 08:52	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
			1 per page		
Documentation				Thumbnail	Print
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Load PDF	
1	04/12/17 16:59	SJW5337G E-FILE & POLICE REPORT		Load PDF	
2	04/12/17 17:02	PRI from C Yogarajah LLC		Load PDF	
3	04/12/17 17:17	Survey Disagree on SJE		Load PDF	
4	04/12/17 17:17	Survey Workshop		Load PDF	
5	05/12/17 16:57	E-filed GIA report From:OD - Reg. No: SLG1431D, Claimant: YEOCHEM (S) PTE LTD		Load PDF	
6	09/01/18 17:03	TPD SJW5337G - FINAL REPAIR		Load PDF	
7	09/01/18 17:03	TPD SJW5337G - SURVEY REPORT & TAX INVOICE		Load PDF	
8	09/01/18 17:03	TPD SJW5337G - COLOUR PHOTO		Load PDF	
9	09/01/18 17:03	TPD SJW5337G - COLOUR PHOTO		Thumbnail	Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Load PDF	
1	23/02/18 08:53	PRS INVOICE			

Documents Checklist

DOCUMENTS CHECKLIST

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG17023035/WRBS2-1
Date: 23/02/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.
Claimant Vehicle No: SJW5337G
Date of Loss: 03/12/2017

Policy No: B29002101MCX
Insured Vehicle No: SLG1431D
Nature of Claim: TP
Claim No: 539451

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJW5337G**
Make & Model: HONDA JAZZ, 1.4 (A)
Reg. Date: 05/07/2007 (Man. Year: 2007)
Colour: Blue
Engine Capacity: 1339 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

Engine No: L13A54002214
Chassis No: JHMGD18507S223796
Odometer: 248363 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65R15
Front Left Side: Dunlop 3 mm
Front Right Side: Dunlop 3 mm
Rear Tyre Size: 195/65R15
Rear Left Side: Kumho 3 mm
Rear Right Side: Kumho 3 mm

The above values represent the remaining tyre treads depth

	Repairer's	Adjuster's	Difference	Diff %
COST OF CLAIMS				
Parts	6,132.44	3,405.88	2,726.56	44.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,310.00	2,480.00	1,830.00	42.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,442.44	5,885.88	4,556.56	43.64
Approved Total (Overridden) (S\$)		4,700.00		
Nett Amount (S\$)	10,442.44	4,700.00	5,742.44	54.99

INSPECTION

Date of Assignment: 04/12/2017
Date Inspected: 05/12/2017 Inspected At:
Estimated Period of Repair: 7.0 days

Hock Motors Workshop (HQ)
NO 1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY @
KAKI BUKIT
Singapore 417883

Adjuster: Teo Cheng Ming Wilson

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 23 Feb 2018)
Parts: 144	HONDA JAZZ 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJW5337G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN INNER SEAL	Necessary	83.00 FL	*83.00 FL
2	1		*REAR TAILGATE	Buckled	903.60 FL	*903.60 FL
3	2		*REAR TAILGATE DAMPERS	Serviceable	282.40 FL	*- FL
4	1		*REAR TAILGATE INNER TRIM BOARD	Not Necessary	296.50 FL	*- FL
5	1		*REAR TAILGATE INNER PULL POCKET	Serviceable	89.60 FL	*- FL
6	1		*REAR TAILGATE LOCK	Jammed	183.80 FL	*183.80 FL
7	1		*REAR TAILGATE WEATHER STRIP	Bent	110.60 FL	*110.60 FL
8	1		*REAR TAILGATE NUMBER PLATE GARNISH	Cracked	115.80 FL	*115.80 FL
9	1		*REAR WIPER ARM	Serviceable	65.20 FL	*- FL
10	1		*REAR WIPER ARM COVER	Not Necessary	12.50 FL	*- FL
11	1		*REAR WIPER MOTOR	Serviceable	237.10 FL	*- FL
12	2		*REAR TAILLAMPS	Cracked / Scratched	681.20 FL	*681.20 FL
13	2		*REAR TAILLAMP PANELS	Repair	129.00 FL	*- FL
14	2		*REAR TAILLAMPS LOWER BRACKETS	Bent	37.00 FL	*37.00 FL
15	1		*REAR END PANEL	Dented	396.60 FL	*396.60 FL
16	1		*REAR END PANEL INNER GARNISH	Cracked	86.90 FL	*86.90 FL
17	1		*REAR BUMPER	Dented	660.90 FL	*660.90 FL
18	2		*REAR BUMPER BRACKETS	Damaged	65.40 FL	*65.40 FL
19	2		*REAR BUMPER SIDE RETAINERS	Distorted	65.40 FL	*65.40 FL
20	1		*REAR FLOOR PANEL	Repair	737.00 FL	*- FL
21	1		*REAR SPARE WHEEL RETAINER	Serviceable	48.00 FL	*- FL
22	1		*REAR EXHAUST SILENCER	Repair	456.90 FL	*- FL
23	2		*REAR EXHAUST MOUNTINGS	Deformed	37.00 FL	*37.00 FL
24	1		*REAR O/S FENDER	Repair	641.50 FL	*- FL
25	2		*REAR FENDER INNER TRIMS	Distorted / Cracked	277.20 FL	*277.20 FL
26	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*50.00 FS
27	1		*SET REAR BUMPER CLIP	Necessary	45.00 FS	*45.00 FS
28	1		*SET REAR REVERSE SENSOR	Scratched	350.00 FS	*200.00 FS
29	1		*REAR FLOOR PANEL INSULATOR	Not Necessary	150.00 FS	*- FS
30	1		*REAR FLOOR BOARD (COMPLETE SET)	Distorted	184.20 FL	*184.20 FL

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	7,509.30	4,183.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,376.86	777.72
Total Parts (\$\$)	6,132.44	3,405.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REFIT, REPLACED DAMAGED LAMPS AND CHECK UP REAR ELECTRICAL WIRING.	New	80.00	30.00
2	TO REMOVE AND REFIT INNER GARNISHES, INNER TRIM TO ASSIST REPAIR.	New	150.00	70.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR.	New	120.00	40.00
4	TO TRANSFER REAR TAILGATE MECHANISM AND WIRING ASSEMBLY TO ASSIST REPAIR.	New	80.00	60.00
5	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.	New	180.00	120.00
6	TO REMOVE, REFIT AND REPAIR EXHAUST SILENCER AND MOUNTINGS.	New	120.00	80.00
7	TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL.	New	180.00	80.00
8	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIR INCLUDING CUT AND WELD; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT.	New	1,800.00	1,000.00
9	TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT.	New	1,600.00	1,000.00
Gross Labour Cost (S\$)			4,310.00	2,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >