



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18002049/Gyb3		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 01-02-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJU 2098B	Veh. Inspected	SHB 1807C	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	01/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	31/01/2018	Inspection Date	02/02/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Bevan Ref. 13002049/Gmb3

Celine Fong (LKKAUTO)

From: Celine Fong (LKKAUTO)
Sent: Friday, 23 March 2018 12:54 PM
To: 'Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)'; Guo Qiang (LKKAUTO)
Cc: SUR; CS A Team
Subject: RE: SHB1807C

Dear Poh Suan,

Confirmed part by part \$5,867.01, 8 days.

Best Regards,

Celine Fong

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: celinefong@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) [mailto:YeoPohsuan@smrt.com.sg]
Sent: Monday, 26 February 2018 6:44 PM
To: Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Subject: SHB1807C

Hi Guo Qiang,

Attached herewith the repair estimate of SHB 1807C having Case No: TAX/01/18/2181.

There is no change to the approved amount of \$5,867.01 @ 8 working days under part by part repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards

Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Sent: Monday, 26 February 2018 2:21 PM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Subject: Scan Data from FX-D421D6



10-2-18 / 10:45
 PPV: 10-2-18 / 12:45
 10-2-18 / 16:45


SMRT Automotive Service Pte Ltd
 60 Woodlands Industrial Park E4, Singapore 757705
 FAX Number : 63685592
 Estimator Telephone Number : 68662623
 Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

2-2-18 / 16:45

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB1807C
 Ref. No : TAX/01/18/2181
 Reg. Date : 11/02/2015
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : OW LEONG SAN
 Type of Accident : CHAIN COLLISION
 Date / Time of Accident : 31/01/2018 08:35:00 AM
 Accident Reported Date / Time : 31/01/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : *Guoqiang*
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time : 31/01/2018
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024094387
 Special Instruction to ARC, if any :
 TOWED \$90 / SJU2098B - AXA
 BEFORE PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR guoqiang (LKK) &
 Email : guoqiang@lkkauto.com HP: 82880282
 Prepared Date : 31/01/2018 11:07:06 AM



Recording Camera ☐ ☒

Radio Antenna ☐ ☒

1st witness *N*

Date

2-2-18

2nd witness

Date

347838km

1 $\frac{1}{4}$ $\frac{1}{2}$ $\frac{3}{4}$ F

347773km

1 $\frac{1}{4}$ $\frac{1}{2}$ $\frac{3}{4}$ F 9格油

Supplementary
 to Report to the Supplementary part list

QC 10/2/18 13:45 LEE SHENG AUTO PTE LTD

Reject RAR Side Bumper Vehicle Return Date: 10/09/2018

Retainer crack

Vehicle Return Time:

10:10

14/2/18 11:00 pm

SMRT staff sign:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U205758530


Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,352.00	1,000.00
Total Spray Painting Charges	: 2,214.00	900.00
Total Material Charges	: 4,725.96	3,330.13
Other Charges	: 1,952.88	636.88
TOTAL	: 10,244.84	5,867.01
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 8.00	8.00
Prepared / Adjusted By	:	GUO QIANG (LKK)
Arc / Surveyor Sign Off Date	: 01/02/2018 11:58:33 AM	02/02/2018 04:45:29 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 01/02/2018 11:58:33 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1802-0500

Invoice No :

Quotation Date : 22/2

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,352.00	1,000.00 ✓
Total Labour	1,352.00	1,000.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	200.00
TO RESPRAY REAR PANEL	180.00	150.00
TO RESPRAY REAR SPARE TYRE PANEL	180.00	150.00
TO RESPRAY REAR MEMBER, LH	180.00	0.00
TO RESPRAY REAR MEMBER, RH	180.00	0.00
TO RESPRAY REAR FLOOR SIDE PANEL LH	180.00	0.00
TO RESPRAY REAR FLOOR SIDE PANEL RH	180.00	0.00
TO RESPRAY TAIL GATE	378.00	200.00
TO RESPRAY REAR FENDER RH	378.00	200.00
Total Spray Painting & Panel Beating	2,214.00	900.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	126.00	90.00 ✓
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	60.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	40.00
TO ALIGN CHASSIS	350.00	0.00
REMOVE AND REPLACE BOTH RR EXHAUST MUFFLER	120.00	60.00
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00
TO REMOVE AND REFIX REAR WINDSCREEN	120.00	0.00
TO REMOVE & REFIT REAR QUARTER GLASS RH	120.00	0.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	60.00
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88 SN NCC	296.88
Total Other Costs	1,952.88	636.88

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace	No <i>BT</i>
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.27	Replace	Replace	No <i>BT</i>
52016-47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace	Replace <i>S</i>	No <i>BT</i>
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Replace <i>S</i>	No <i>BT</i>
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No <i>BT</i>
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace	No <i>rec</i>
52576-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace	No <i>rec</i>
			PIXEL STICKER	2	60.00 <i>120</i>	0.00	120.00	Replace	Replace	No <i>rec</i>
76088-47020		6505617	BUMPER LIP COVER RR/LH	1	72.20	25.00	54.15	Replace	Replace	No <i>mis</i>
76087-47020		6505618	BUMPER LIP COVER RR/RH	1	118.10	25.00	88.57	Replace	Replace	No <i>mis</i>
76891-47020		6505619	BUMPER LIP REAR	1	228.90	25.00	171.67	Replace	Replace	No <i>mis</i>
58308-47011			UNDER COVER SUB-ASSY, RR FLOOR	1	514.50	25.00	385.87	Replace	Replace	No <i>se</i>
58307-47060		6505522	END PANEL	1	602.10	25.00	451.57	Replace	Replace	No <i>BT</i>
	COMMON	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace	No <i>rec</i>
58311-47071		6505523	SPARE TYRE PANEL	1	667.70	100.00	0.00	Replace	Repair	No <i>R</i>
57604-47030			MEMBER SUB-ASSY, RR LH	1	174.10	25.00	130.58	Replace	Check	No <i>X NN</i>
57603-47030			MEMBER SUB-ASSY, RR RH	1	174.10	25.00	130.58	Replace	Check	No <i>X NN</i>
58303-47301			FLOOR PANEL RR/LH	0	102.00	25.00	0.00	Replace	Not given	No <i>X NN</i>
58302-47030			FLOOR PANEL RR/RH	0	209.90	25.00	0.00	Replace	Not given	No <i>X NN</i>
17430-37380			EXHAUST TAIL PIPE	1	656.20	25.00	492.15	Replace	Check	No <i>X NN</i>
67005-47241			TAILGATE ASY	1	1,007.90	100.00	0.00	Replace	Repair	No <i>R</i>
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace	No <i>rec</i>
75575-47030			MOULDING BACK WINDOW, LOWER NO.1	0	29.40	25.00	0.00	Replace	Not given	No <i>X NN</i>
	COMMON		SEALANT W/SCREEN	0	37.00	0.00	0.00	Replace	Not given	No <i>X NN</i>
75574-47020			TAIL GATE DOOR GLASS MOULDING, LH	0	29.40	25.00	0.00	Replace	Not given	No <i>X NN</i>
75573-47080			TAIL GATE DOOR GLASS MOULDING, RH	0	29.40	25.00	0.00	Replace	Not given	No <i>X NN</i>
	COMMON		SEALANT W/SCREEN	0	37.00	0.00	0.00	Replace	Not given	No <i>X NN</i>
			NUMBER PLATE FRAME	0	12.00	0.00	0.00	Replace	Not given	No <i>X NN</i>

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
67881-47022			TAILGATE DOOR WEATHER STRIP	1	353.40	25.00	265.05	Replace	Replace <i>S</i>	No <i>TN</i>
64718-47031B0			END PANEL COVER, DECK TRIM HOLE	1	46.10	25.00	34.57	Replace	Replace	No <i>CRA</i>
64716-47031B0			END PANEL COVER, DECK TRIM, RR	1	121.10	25.00	90.82	Replace	Replace	No <i>CRA</i>
64993-47020			BOX, DECK FLOOR, RR	1	649.70	25.00	487.28	Replace	Check	No <i>XNN</i>
58416-47030B3			BOX, RR FLOOR, BOARD	1	679.60	25.00	509.70	Replace	Replace <i>S</i>	No <i>DE</i>
61604-47090			FENDER RR/RH	1	766.80	100.00	0.00	Replace	Repair	No <i>R</i>
65637-47021		6505480	FENDER LINER RR/RH	1	141.30	25.00	105.98	Replace	Check	No <i>XNN</i>
52591-47021			BUMPER SEAL, RR RH	1	65.70	25.00	49.28	Replace	Check	No <i>XNN</i>
65631-47041			SILL MEMBER PLATE RR/RH	0	57.50	25.00	0.00	Replace	Not given	No <i>XNN</i>
	COMMO N		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No <i>rel</i>
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No <i>rel</i>
52562-47010			TAIL LAMP BRACKET, RH	1	30.70	25.00	23.03	Replace	Replace <i>S</i>	No <i>CRA</i>
62710-47130			QUARTER GLASS RR/RH	0	846.50	25.00	0.00	Replace	Not given	No <i>XNN</i>
	COMMO N		SEALANT W/SCREEN	0	37.00	0.00	0.00	Replace	Not given	No <i>XNN</i>
TOTAL MATERIALS							4,726.00	3,330.14		
TOTAL MATERIALS(Discounted)							4,725.96	3,330.13		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

15567.58

$$\begin{array}{r}
 3330.13 \\
 + 1000.00 \\
 + 1536.88 \\
 \hline
 5867.01
 \end{array}$$

REQUEST FOR SUPPLEMENTARY PARTS

Contractor			
Accident Case Number	TAX/01/18/218/	Date of Collision	1 / 1
Vehicle No	SHB 1807 C	Date of Request	05/02/2018
Vehicle Model	TOYOTA PRUIS	Number of Days to Extend (if any)	2

S/N	Part Number	Part Description	Quantity	Unit Price
		ARM SUB ASSY, REAR BUMPER LH	1 pc	15 BT
		ARM SUB ASSY, REAR BUMPER RH	1 pc	15 BT
		TAIL LAMP BRACKET, RH	1 pc	1 ORA
		TAIL GATE DOOR WEATHERSTRIP	1 pc	1 TV
		BOX, REAR FLOOR BOARD	1 pc	1 RL
		Labor to Repair Spare Time parts		\$ 370

<< Please submit photographs for damaged parts >>

200

I, (Name) _____

(Position) _____

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

Signature of person making this declaration
[to be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	1 Day
Approval By	Surveyor / In-house Staff	Gino Q. P.
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

6745 7138.



ISLAND RECOVERY SERVICES

Blk 3026, Ubi Road 1 #04-146 Singapore 408719

Telephone: 6747 7400

Email: islandrecovery@gmail.com

Facsimile: 6844 7233

Web: www.islandrecovery.com.sg

GST Reg.No: M90370499P

Co. Reg. 58120055L

Cash Sales/ Work Order

NO. 1165930

Date: 31.01.18

24 HOTLINE: 9182 8211

MS: SMRT

Vehicle No: SHB 1807C Model: Toyota
08-55

From: Braddell Rd Time Start: 09:30

To: SMRT @ Woodland Time End: 10:20

Remarks: Rear Bumper stuck at Tyre

☐ Change Tyres / Jump Start

☒ Accident

☐ Use Car Carrier

☐ Basement / Multi Carpark

☐ Crane Up / Winch Out

☐ Open Door

☒ Using King Dolly

☐ Dismantle Shaft / Brake

☐ Loaded

AMOUNT S\$ 90

GST S\$

TOTAL S\$



Received By

bizSAFE₃

Important Note:

8019
Island Recovery Services

Vehicle is transported at owner's risk. The company accepts no responsibility for damaged or other misdemeanour to your vehicle whilst being transported.

Call Mr. 8:42am



SMRT Automotive Service Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB1807C
Ref. No : TAX/01/18/2181
Reg. Date : 11/02/2015
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS
Name of Driver : OW LEONG SAN
Type of Accident : CHAIN COLLISION
Date / Time of Accident : 31/01/2018 08:35:00 AM
Accident Reported Date / Time : 31/01/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by :
Vehicle is Towed Back? : Yes
Towed Back Date/Time : 31/01/2018
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024094387
Special Instruction to ARC, if any :
TOWED \$90 / SJU2098B
Prepared Date : 31/01/2018 11:07:06 AM



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

7 Days.
part by part.
refuse paint photos.
Guo Qiao - 8288082
02/2/18

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U205758530

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	1,352.00	0.00
Total Spray Painting Charges :	2,214.00	0.00
Total Material Charges :	7,732.78	7,732.78
Other Charges :	1,952.88	0.00
TOTAL :	13,251.66	0.00
Lum Sum Total :	0.00	0.00
No. of Repair Days :	8.00	0.00
Prepared / Adjusted By :		
Arc / Surveyor Sign Off Date :	01/02/2018 11:58:33 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 01/02/2018 11:58:33 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,352.00	0.00 800
Total Labour	1,352.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY REAR PANEL	180.00	0.00 150
TO RESPRAY REAR SPARE TYRE PANEL	180.00	0.00 150
TO RESPRAY REAR MEMBER,LH	180.00	0.00 X
TO RESPRAY REAR MEMBER,RH	180.00	0.00 X
TO RESPRAY REAR FLOOR SIDE PANEL LH	180.00	0.00 X
TO RESPRAY REAR FLOOR SIDE PANEL RH	180.00	0.00 X
TO RESPRAY TAIL GATE	378.00	0.00 200
TO RESPRAY REAR FENDER RH	378.00	0.00 200
Total Spray Painting & Panel Beating	2,214.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	126.00	0.00 ?
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 30
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 60
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 40
TO ALIGN CHASSIS	350.00	0.00 ?
REMOVE AND REPLACE BOTH RR EXHAUST MUFFLER	120.00	0.00 60
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00 X
TO REMOVE AND REFIX REAR WINDSCREEN	120.00	0.00 X
TO REMOVE & REFIT REAR QUARTER GLASS RH	120.00	0.00 X
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00 ?
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 60
TO REPLACE SUNDRY PARTS	100.00	0.00 ?
TO WASH AND VACUUM	60.00	0.00 ?
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	0.00 ✓
Total Other Costs	1,952.88	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR / RL	1	458.60	25.00	343.95	Replace	Replace	No
52023-12240		6505547	BUMPER REINFORCEMENT REAR / BT	1	205.70	25.00	154.27	Replace	Replace	No
52016-47030			ARM SUB-ASSY, RR BUMPER LH ?	1	139.60	25.00	104.70	Replace	Replace	No
52015-47050			ARM SUB-ASSY, RR BUMPER RH ?	1	139.60	25.00	104.70	Replace	Replace	No
			SENSOR REVERSE DM	1	180.00	0.00	180.00	Replace	Replace	No
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH / MC	1	94.80	25.00	71.10	Replace	Replace	No
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH / MC	1	94.80	25.00	71.10	Replace	Replace	No
			PIXEL STICKER / MC	2	60.00	0.00	120.00	Replace	Replace	No
76088-47020		6505617	BUMPER LIP COVER RR/LH / MIS	1	72.20	25.00	54.15	Replace	Replace	No
76087-47020		6505618	BUMPER LIP COVER RR/RH / MIS	1	118.10	25.00	88.57	Replace	Replace	No
76891-47020		6505619	BUMPER LIP REAR / MIS	1	228.90	25.00	171.67	Replace	Replace	No
58308-47011			UNDER COVER SUB-ASSY, RR FLOOR / MC	1	514.50	25.00	385.87	Replace	Replace	No
58307-47060		6505522	END PANEL / BT	1	602.10	25.00	451.57	Replace	Replace	No
	COMMON	4006314	SEALANT SIKAFLEX / MC	1	37.00	0.00	37.00	Replace	Replace	No
58311-47071		6505523	SPARE TYRE PANEL X REPAIR	1	667.70	25.00	500.77	Replace	Replace	No
57604-47030			MEMBER SUB-ASSY, RR LH ?	1	174.10	25.00	130.57	Replace	Replace	No
57603-47030			MEMBER SUB-ASSY, RR RH ?	1	174.10	25.00	130.57	Replace	Replace	No
58303-47301			FLOOR PANEL RR/LH X NN	1	102.00	25.00	76.50	Replace	Replace	No
58302-47030			FLOOR PANEL RR/RH X NN	1	209.90	25.00	157.42	Replace	Replace	No
17430-37380			EXHAUST TAIL PIPE ?	1	656.20	25.00	492.15	Replace	Replace	No
67005-47241			TAILGATE ASY X Repair	1	1,007.90	25.00	755.92	Replace	Replace	No
75374-47051			NAME PLATE (HYBRID) / MC	1	51.90	25.00	38.92	Replace	Replace	No
75575 - 47030			MOULDING BACK WINDOW, LOWER NO.1 X NN	1	29.40	25.00	22.05	Replace	Replace	No
	COMMON		SEALANT W/SCREEN X NN	1	37.00	0.00	37.00	Replace	Replace	No
75574-47020			TAIL GATE DOOR GLASS MOULDING, LH X NN	1	29.40	25.00	22.05	Replace	Replace	No
75573-47080			TAIL GATE DOOR GLASS MOULDING, RH X NN	1	29.40	25.00	22.05	Replace	Replace	No
	COMMON		SEALANT W/SCREEN X NN	2	37.00	0.00	74.00	Replace	Replace	No
			NUMBER PLATE FRAME X NN	1	12.00	0.00	12.00	Replace	Replace	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
67881-47022			TAILGATE DOOR WEATHER STRIP ?	1	353.40	25.00	265.05 ?	Replace	Replace	No
64718-47031B0			END PANEL COVER, DECK TRIM HOLE / CMA	1	46.10	25.00	34.57 /	Replace	Replace	No
64716-47031B0			END PANEL COVER, DECK TRIM, RR / Cut	1	121.10	25.00	90.82 /	Replace	Replace	No
64993-47020			BOX, DECK FLOOR, RR ?	1	649.70	25.00	487.27 /	Replace	Replace	No
58416-47030B3			BOX, RR FLOOR, BOARD ?	1	679.60	25.00	509.70 ?	Replace	Replace	No
61604-47090			FENDER RR/RH X Repair	1	766.80	25.00	575.10 /	Replace	Replace	No
65637-47021		6505480	FENDER LINER RR/RH ? X Repair	1	141.30	25.00	105.97 ?	Replace	Replace	No
52591-47021			BUMPER SEAL, RR RH ?	1	65.70	25.00	49.27 ?	Replace	Replace	No
65631-47041			SILL MEMBER PLATE RR/RH X NN	1	67.50	25.00	43.12 /	Replace	Replace	No
	COMMO N		SMRT LOGO / MC	1	7.80	0.00	7.80 /	Replace	Replace	No
			STICKER DECAL 6555 8888 / MC	1	21.60	0.00	21.60 /	Replace	Replace	No
52562-47010			TAIL LAMP BRACKET, RH ?	1	30.70	25.00	23.02 ?	Replace	Replace	No
62710-47130			QUARTER GLASS RR/RH X NN	1	846.50	25.00	634.87 /	Replace	Replace	No
	COMMO N		SEALANT W/SCREEN X NN	1	37.00	0.00	37.00 /	Replace	Replace	No
TOTAL MATERIALS							7,695.88	7,695.78		
TOTAL MATERIALS(Discounted)							7,732.78	7,732.78		


Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB1807C
 Ref. No : TAX/01/18/2181
 Reg. Date : 11/02/2015
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : OW LEONG SAN
 Type of Accident : CHAIN COLLISION
 Date / Time of Accident : 31/01/2018 08:35:00 AM
 Accident Reported Date / Time : 31/01/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time : 31/01/2018
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024094387
 Special Instruction to ARC, if any :
 TOWED \$90 / SJU2098B
 Prepared Date : 31/01/2018 11:07:06 AM



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

7 Days .
 part by mt.
 before paint photos.
 Eric Qiap - 8288 0882
 02/2/18

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U205758530

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,352.00	0.00
Total Spray Painting Charges	: 2,214.00	0.00
Total Material Charges	: 7,732.78	7,732.78
Other Charges	: 1,952.88	0.00
TOTAL	: 13,251.66	0.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 8.00	0.00
Prepared / Adjusted By	:	
Arc / Surveyor Sign Off Date	: 01/02/2018 11:58:33 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 01/02/2018 11:58:33 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,352.00	0.00 800
Total Labour	1,352.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY REAR PANEL	180.00	0.00 150
TO RESPRAY REAR SPARE TYRE PANEL	180.00	0.00 150
TO RESPRAY REAR MEMBER,LH	180.00	0.00 X
TO RESPRAY REAR MEMBER,RH	180.00	0.00 X
TO RESPRAY REAR FLOOR SIDE PANEL LH	180.00	0.00 X
TO RESPRAY REAR FLOOR SIDE PANEL RH	180.00	0.00 X
TO RESPRAY TAIL GATE	378.00	0.00 200
TO RESPRAY REAR FENDER RH	378.00	0.00 200
Total Spray Painting & Panel Beating	2,214.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	126.00	0.00 ?
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 30
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 60
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 40
TO ALIGN CHASSIS	350.00	0.00 ?
REMOVE AND REPLACE BOTH RR EXHAUST MUFFLER	120.00	0.00 60
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00 X
TO REMOVE AND REFIX REAR WINDSCREEN	120.00	0.00 X
TO REMOVE & REFIT REAR QUARTER GLASS RH	120.00	0.00 X
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00 ?
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 60
TO REPLACE SUNDRY PARTS	100.00	0.00 ?
TO WASH AND VACUUM	60.00	0.00 ?
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	0.00 ✓
Total Other Costs	1,952.88	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR / <i>ll</i>	1	458.60	25.00	343.95	Replace	Replace	No
52023-12240		6505547	BUMPER REINFORCEMENT REAR / <i>BT</i>	1	205.70	25.00	154.27	Replace	Replace	No
52016-47030			ARM SUB-ASSY, RR BUMPER LH ?	1	139.60	25.00	104.70 <i>l</i>	Replace	Replace	No
52015-47050			ARM SUB-ASSY, RR BUMPER RH ?	1	139.60	25.00	104.70 <i>l</i>	Replace	Replace	No
			SENSOR REVERSE / <i>DM</i>	1	180.00	0.00	180.00	Replace	Replace	No
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH / <i>MC</i>	1	94.80	25.00	71.10	Replace	Replace	No
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH / <i>MC</i>	1	94.80	25.00	71.10	Replace	Replace	No
			PIXEL STICKER / <i>MC</i>	2	60.00	0.00	120.00	Replace	Replace	No
76088-47020		6505617	BUMPER LIP COVER RR/LH / <i>MS</i>	1	72.20	25.00	54.15	Replace	Replace	No
76087-47020		6505618	BUMPER LIP COVER RR/RH / <i>MS</i>	1	118.10	25.00	88.57	Replace	Replace	No
76891-47020		6505619	BUMPER LIP REAR / <i>MS</i>	1	228.90	25.00	171.67	Replace	Replace	No
58308-47011			UNDER COVER SUB-ASSY, RR FLOOR / <i>MC</i>	1	514.50	25.00	385.87	Replace	Replace	No
58307-47060		6505522	END PANEL / <i>BT</i>	1	602.10	25.00	451.57	Replace	Replace	No
	COMMO N	4006314	SEALANT SIKAFLEX / <i>MC</i>	1	37.00	0.00	37.00	Replace	Replace	No
58311-47071		6505523	SPARE TYRE PANEL <i>X REPAIR</i>	1	667.70	25.00	500.77 <i>l</i>	Replace	Replace	No
57604-47030			MEMBER SUB-ASSY, RR LH ?	1	174.10	25.00	130.57 <i>l</i>	Replace	Replace	No
57603-47030			MEMBER SUB-ASSY, RR RH ?	1	174.10	25.00	130.57 <i>l</i>	Replace	Replace	No
58303-47301			FLOOR PANEL RR/LH <i>X NN</i>	1	102.00	25.00	76.50 <i>l</i>	Replace	Replace	No
58302-47030			FLOOR PANEL RR/RH <i>X NN</i>	1	209.90	25.00	157.42 <i>l</i>	Replace	Replace	No
17430-37380			EXHAUST TAIL PIPE ?	1	656.20	25.00	492.15 <i>l</i>	Replace	Replace	No
67005-47241			TAILGATE ASY <i>X Repair</i>	1	1,007.90	25.00	755.92 <i>l</i>	Replace	Replace	No
75374-47051			NAME PLATE (HYBRID) / <i>MC</i>	1	51.90	25.00	38.92	Replace	Replace	No
75575 - 47030			MOULDING BACK WINDOW, LOWER NO.1 <i>X NN</i>	1	29.40	25.00	22.05 <i>l</i>	Replace	Replace	No
	COMMO N		SEALANT W/SCREEN <i>X NN</i>	1	37.00	0.00	37.00 <i>l</i>	Replace	Replace	No
75574-47020			TAIL GATE DOOR GLASS MOULDING, LH <i>X NN</i>	1	29.40	25.00	22.05 <i>l</i>	Replace	Replace	No
75573-47080			TAIL GATE DOOR GLASS MOULDING, RH <i>X NN</i>	1	29.40	25.00	22.05 <i>l</i>	Replace	Replace	No
	COMMO N		SEALANT W/SCREEN <i>X NN</i>	2	37.00	0.00	74.00 <i>l</i>	Replace	Replace	No
			NUMBER PLATE FRAME <i>X NN</i>	1	12.00	0.00	12.00 <i>l</i>	Replace	Replace	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
67881-47022			TAILGATE DOOR WEATHER STRIP ?	1	353.40	25.00	265.05 ?	Replace	Replace	No
64718-47031B0			END PANEL COVER, DECK TRIM HOLE / <i>CPA</i>	1	46.10	25.00	34.57 /	Replace	Replace	No
64716-47031B0			END PANEL COVER, DECK TRIM, RR / <i>Cut</i>	1	121.10	25.00	90.82 /	Replace	Replace	No
64993-47020			BOX, DECK FLOOR, RR ?	1	649.70	25.00	487.27 ?	Replace	Replace	No
58416-47030B3			BOX, RR FLOOR, BOARD ?	1	679.60	25.00	509.70 ?	Replace	Replace	No
61604-47090			FENDER RR/RH <i>X Repair</i>	1	766.80	25.00	575.10 ?	Replace	Replace	No
65637-47021		6505480	FENDER LINER RR/RH ? <i>Repair</i>	1	141.30	25.00	105.97 ?	Replace	Replace	No
52591-47021			BUMPER SEAL, RR RH ?	1	65.70	25.00	49.27 ?	Replace	Replace	No
65631-47041			SILL MEMBER PLATE RR/RH <i>X NN</i>	1	57.50	25.00	43.12 ?	Replace	Replace	No
	COMMON		SMRT LOGO / <i>MC</i>	1	7.80	0.00	7.80 /	Replace	Replace	No
			STICKER DECAL 6555 8888 / <i>MC</i>	1	21.60	0.00	21.60 /	Replace	Replace	No
52562-47010			TAIL LAMP BRACKET, RH ?	1	30.70	25.00	23.02 ?	Replace	Replace	No
62710-47130			QUARTER GLASS RR/RH <i>X NN</i>	1	846.50	25.00	634.87 ?	Replace	Replace	No
	COMMON		SEALANT W/SCREEN <i>X NN</i>	1	37.00	0.00	37.00 ?	Replace	Replace	No
TOTAL MATERIALS							7,695.88	7,695.78		
TOTAL MATERIALS(Discounted)							7,732.78	7,732.78		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM


(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : _____ Vehicle Registration No: SJU 2098 B
Name (as shown in NRIC) : TENG TAI YANG NRIC/FIN/Passport No : S7804164A
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address : _____ Singapore ()
Contact (Tel) : _____ Mobile No. : 97603108
Email Address : davidteng.sg@gmail.com
Date of Accident : 31/1/18 Time of Accident : _____
Place of Accident : BRADELL RD EXIT TO TOA PAYOH LOR 6.
Insurance Company : AXA

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

THIS IS A 3 VEHICLE CHAIN COLLISION. THE VEHICLE IS
SJL 5119C (1ST), SHB 1807C (2ND) AND SJU 2098B (3RD).
THAT ALL.


Policyholder / Driver's Signature
Date: 18th May 2018

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:
Date:

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJU 2098B (Insd veh)	Model:	TOYOTA PRIUS
	SHB 1807C (TP veh)		
Date of Accident:	31/01/2018		

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	:	\$	15,567.58
Final Repair Cost	:	\$	5,867.01
Loss of Token Sum	:	\$	625.00
			12.5 days at \$50.00 per day
Rental (if any)	:	\$	1,431.13
			12.5 days
LTA / GIA Search Fee	:	\$	7.00

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum (GLOBAL SUM)	:	\$	7,930.00

Is Third Party Workshop GIA Registered?		☐ YES	☒ NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ (%)		Assessed Liability (*): _____ 100 _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____ _____				

Payment Instruction: Payee's Breakdown			
1)	SMRT TAXIS PTE LTD	:	\$ 7,930.00

NUR SHAQILAH BTE ABDOL
WAHAB

19/03/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18002049/Ghb3s2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: CYNTHIA LOH		Date : 19-03-2019		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJU 2098B	Veh. Inspected	SHB 1807C	
Policy No.	GA036853	Coverage (\$)	0.00	
Claim No.	S8M0085Z	Excess (\$)	0.00	
Assign From	CYNTHIA LOH	Assign Date	01/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JTDKN36U205758530	Colour	MAROON	
Odometer	347773	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65R15	FALKEN	6 mm	
L/H Front Tyre	195/65R15	FALKEN	6 mm	
R/H Rear Tyre	195/65R15	FALKEN	6 mm	
L/H Rear Tyre	195/65R15	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	31/01/2018	Inspection Date	02/02/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 1807C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER REAR (DISC 25%) (CONSISTENT)	DEFORMED	458.60	343.95
1	BUMPER REINFORCEMENT REAR (DISC 25%) (CONSISTENT)	BENT	205.70	154.27
1	ARM SUB-ASSY, RR BUMPER LH (DISC 25%) (CONSISTENT)	BENT	139.60	104.70
1	ARM SUB-ASSY, RR BUMPER RH (DISC 25%) (CONSISTENT)	BENT	139.60	104.70
1	BUMPER SIDE RETAINER RR/LH (DISC 25%) (CONSISTENT)	NECESSARY	94.80	71.10
1	BUMPER SIDE RETAINER RR/RH (DISC 25%) (CONSISTENT)	NECESSARY	94.80	71.10
1	BUMPER LIP COVER RR/LH (DISC 25%) (CONSISTENT)	MISSING	72.20	54.15
1	BUMPER LIP COVER RR/RH (DISC 25%) (CONSISTENT)	MISSING	118.10	88.57
1	BUMPER LIP REAR (DISC 25%) (CONSISTENT)	MISSING	228.90	171.67
1	UNDER COVER SUB-ASSY, RR FLOOR (DISC 25%) (CONSISTENT)	DEFORMED	514.50	385.87
1	END PANEL (DISC 25%) (CONSISTENT)	BENT	602.10	451.57
1	NAME PLATE (HYBRID) (DISC 25%) (CONSISTENT)	NECESSARY	51.90	38.92
1	TAILGATE DOOR WEATHER STRIP (DISC 25%) (CONSISTENT)	TORN	353.40	265.05
1	END PANEL COVER, DECK TRIM HOLE (DISC 25%) (CONSISTENT)	CRACKED	46.10	34.57
1	END PANEL COVER, DECK TRIM, RR (DISC 25%) (CONSISTENT)	CUT	121.10	90.82
1	BOX, RR FLOOR, BOARD (DISC 25%) (CONSISTENT)	DEFORMED	679.60	509.70
1	TAIL LAMP BRACKET, RH (DISC 25%) (CONSISTENT)	CRACKED	30.70	23.02
1	SENSOR REVERSE (SN) (CONSISTENT)	DAMAGED	180.00	180.00
2	PIXEL STICKER @ \$60.00 (SN) (CONSISTENT)	NECESSARY	120.00	120.00
1	SEALANT SIKAFLEX (SN) (CONSISTENT)	NECESSARY	37.00	37.00
1	SMRT LOGO (SN) (CONSISTENT)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN) (CONSISTENT)	NECESSARY	21.60	21.60
1	MEMBER SUB-ASSY, RR LH (CONSISTENT)	NOT NECESSARY	174.10	-
1	MEMBER SUB-ASSY, RR RH (CONSISTENT)	NOT NECESSARY	174.10	-
1	FLOOR PANEL RR/LH (CONSISTENT)	NOT NECESSARY	102.00	-

Report Ref No. CC4/ASM18002049/Ghb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FLOOR PANEL RR/RH (CONSISTENT)	NOT NECESSARY	209.90	-
1	EXHAUST TAIL PIPE (CONSISTENT)	NOT NECESSARY	656.20	-
1	MOULDING BACK WINDOW, LOWER NO.1 (CONSISTENT)	NOT NECESSARY	29.40	-
1	SEALANT W/SCREEN (CONSISTENT)	NOT NECESSARY	37.00	-
1	TAIL GATE DOOR GLASS MOULDING, LH (CONSISTENT)	NOT NECESSARY	29.40	-
1	TAIL GATE DOOR GLASS MOULDING, RH (CONSISTENT)	NOT NECESSARY	29.40	-
1	SEALANT W/SCREEN (CONSISTENT)	NOT NECESSARY	37.00	-
1	NUMBER PLATE FRAME (CONSISTENT)	NOT NECESSARY	12.00	-
1	BOX, DECK FLOOR, RR (CONSISTENT)	NOT NECESSARY	649.70	-
1	FENDER LINER RR/RH (CONSISTENT)	NOT NECESSARY	141.30	-
1	BUMPER SEAL, RR RH (CONSISTENT)	NOT NECESSARY	65.70	-
1	SILL MEMBER PLATE RR/RH (CONSISTENT)	NOT NECESSARY	57.50	-
1	QUARTER GLASS RR/RH (CONSISTENT)	NOT NECESSARY	846.50	-
1	SEALANT W/SCREEN (CONSISTENT)	NOT NECESSARY	37.00	-
1	SPARE TYRE PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	667.70	-
1	TAILGATE ASY (CONSISTENT)	TO REPAIR SEE LABOUR	1,007.90	-
1	FENDER RR/RH (CONSISTENT)	TO REPAIR SEE LABOUR	766.80	-
1	ADVERTISEMENT STICKER (SN)	NECESSARY	296.88	296.88
			10,345.58	3,627.01
	LABOUR			
	PANEL BEATING & BODYWORK. INCLUSIVE OF THE REPAIR OF SPARE TYRE PANEL, TAILGATE ASY AND FENDER RR/RH.		1,352.00	1,000.00
	SPRAY PAINT.		2,214.00	900.00
	TOWING CHARGE.		126.00	90.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	30.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		100.00	60.00
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.		120.00	40.00
	TO ALIGN CHASSIS.	NOT NECESSARY	350.00	-
	REMOVE AND REPLACE BOTH RR EXHAUST MUFFLER.		120.00	60.00
	TO TRANSFER REAR TAILGATE MECHANISM.	NOT NECESSARY	120.00	-

Report Ref No. CC4/ASM18002049/Ghb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIX REAR WINDSCREEN.	NOT NECESSARY	120.00	-
	TO REMOVE & REFIT REAR QUARTER GLASS RH.	NOT NECESSARY	120.00	-
	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE.	NOT NECESSARY	120.00	-
	TO REMOVE AND INSTALL LUGAGGE COMPARTMENT TRIM TO FACILITATE REPAIR.		120.00	60.00
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			5,222.00	2,240.00
	GRAND TOTAL		15,567.58	5,867.01
RECOMMENDED COST OF REPAIRS				5,867.01

Report Ref No. CC4/ASM18002049/Ghb3s2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.