

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Lee Chen Sin
CLAIM DEPARTMENT
DID : 66547520
FAX :

Date : 30/01/2018
To : EQ INSURANCE COMPANY LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : IRAWAN ADI PRASETYO
: AIG ASIA PACIFIC INSURANCE PTE. LTD.
Certificate No : 2100508560
Vehicle No : SJT-934-G
Accident Date : 25/01/2018
Make & Model : HONDA CITY 1.5L I-VTEC AUTO 1497 cc

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
List Item			
1	FRONT BONNET	615.20	bt-
1	FRONT BONNET HINGE LH	84.80	bt-
1	FRONT BONNET HINGE RH	84.80	bt-
1	FRONT BONNET INSULATOR	75.60	de-
10	FRONT BONNET INSULATOR CLIPS	35.00	nei-
1	FRONT BONNET AIR VENT LH	68.90	?
1	FRONT BONNET SEAL LH	9.10	?
1	FRONT BONNET SEAL RH	9.10	?
1	FRONT BONNET LOCK	235.40	?

Date : 30/01/2018

To : EQ INSURANCE COMPANY LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : IRAWAN ADI PRASETYO

: AIG ASIA PACIFIC INSURANCE PTE. LTD.

Certificate No : 2100508560

Accident Date : 25/01/2018

Vehicle No : SJT-934-G

Make & Model : HONDA CITY 1.5L I-VTEC AUTO 1497 cc

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	FRONT BONNET CLIPS	7.00	?
1	FRONT FENDER LH		RESTORE
1	FRONT FENDER RH	326.70	que
1	FRONT FENDER INNER SHIELD RH	96.40	de
10	FRONT FENDER INNER SHIELD CLIPS	96.20	per
1	FRONT FENDER OUTER GARNISH RH	112.30	?
1	"A" PILLAR RH		RESTORE
1	FRONT DOOR RH		RESTORE
1	HEADLAMP LH	451.70	?
1	HEADLAMP RH	451.70	one

Date : 30/01/2018

To : EQ INSURANCE COMPANY LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : IRAWAN ADI PRASETYO

: AIG ASIA PACIFIC INSURANCE PTE. LTD.

Certificate No : 2100508560

Accident Date : 25/01/2018

Vehicle No : SJT-934-G

Make & Model : HONDA CITY 1.5L I-VTEC AUTO 1497 cc

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	HEADLAMP LOWER BRACKET LH	95.50	X
1	HEADLAMP LOWER BRACKET RH	95.50	ADL
1	FRONT GRILLE BASE	246.30	CH
1	FRONT GRILLE MOULDING	255.40	ADL
1	FRONT GRILLE LOGO	45.70	ADL
10	FRONT GRILLE CLIPS	35.00	ADL
1	FRONT BUMPER	610.40	ADL
10	FRONT BUMPER CLIPS	35.00	ADL
1	FOG LAMP COVER RH	45.60	X
1	FOG LAMP RH	386.40	X

Date : 30/01/2018

To : EQ INSURANCE COMPANY LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : IRAWAN ADI PRASETYO

: AIG ASIA PACIFIC INSURANCE PTE. LTD.

Certificate No : 2100508560

Accident Date : 25/01/2018

Vehicle No : SJT- 934-G

Make & Model : HONDA CITY 1.5L I-VTEC AUTO 1497 cc

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	FRONT BUMPER REINFORCEMENT	334.50	*
1	SUPPORT PANEL	596.40	but ✓
1	CONDENSER	753.10	?
1	RADIATOR	1,582.40	?
1	AIR COND FAN COWLING	141.60	?
1	AIR COND FAN MOTOR	396.40	?
1	AIR COND FAN BLADE	85.90	?
1	RADIATOR FAN COWLING	121.60	?
1	RADIATOR FAN MOTOR	405.30	?
1	RADIATOR FAN BLADE	95.30	?

Date : 30/01/2018

To : EQ INSURANCE COMPANY LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : IRAWAN ADI PRASETYO

: AIG ASIA PACIFIC INSURANCE PTE. LTD.

Certificate No : 2100508560

Accident Date : 25/01/2018

Vehicle No : SJT-934-G

Make & Model : HONDA CITY 1.5L I-VTEC AUTO 1497 cc

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	AIR COND HOSE (DISCHARGE)	181.60	?
1	AIR COND HOSE (SUCTION)	242.30	?
1	AIR COND HOSE (LIQUID)	275.40	?
1	WIPER TANK	134.50	?
1	WIPER TANK MOTOR	95.40	?
1	ENGINE MOUNTING RH	262.90	?
1	ABS PUMP	2,954.30	X
1	ABS PUMP BRACKET	75.40	?
1	FRONT WHEEL HOUSE EXTENSION RH	275.60	Ry
1	FRONT SIDE FRAME BRACKET RH	69.90	Ry

Date : 30/01/2018

To : EQ INSURANCE COMPANY LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : IRAWAN ADI PRASETYO

: AIG ASIA PACIFIC INSURANCE PTE. LTD.

Certificate No : 2100508560

Accident Date : 25/01/2018

Vehicle No : SJT-934-G

Make & Model : HONDA CITY 1.5L I-VTEC AUTO 1497 cc

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	FRONT SIDE FRAME PLATE RH	95.60	?
1	FRONT SIDE FRAME GUSSET RH	85.70	?
1	SIDE MIRROR RH	495.20	Rx
1	REAR FENDER LH		
1	REAR FENDER RH	962.40	bu
1	REAR FENDER INNER SHIELD RH	42.10	X
10	REAR FENDER INNER SHIELD CLIPS	35.00	X
1	REAR BOOTLID	755.90	HA
1	REAR BOOTLID HINGE LH	95.50	HA
1	REAR BOOTLID HINGE RH	95.50	HA

RESTORE