



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS/LCR18002058/Svbs2

78 SHENTON WAY #08-16
CHARTIS BUILDINGS SINGAPORE 079120

Date : 13-02-2018



ATTN: ANGIE GAN

Code : LCR

1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

| | | | |
|--------------|-----------------|----------------|------------|
| Insured Veh. | SLE 8053B | Veh. Inspected | PC 7188R |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | 2073632085SG003 | Excess (\$) | 0.00 |
| Assign From | ANGIE GAN | Assign Date | 18/01/2018 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|-------------------|--------------|----------|
| Make & Model | TOYOTA HIACE | c.c | 2985 |
| Engine No. | HIDDEN | Year of Reg. | 2016 |
| Chassis No. | JTFJT02P900001225 | Colour | SILVER |
| Odometer | 338435 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | NIL |
| General | FAIR | | |

3. Conditions of Tyres

| | | | |
|----------------|---------|-------|---------|
| | Size | Make | Balance |
| R/H Front Tyre | 195 R15 | OHTSU | 6 mm |
| L/H Front Tyre | 195 R15 | OHTSU | 6 mm |
| R/H Rear Tyre | 195 R15 | OHTSU | 6 mm |
| L/H Rear Tyre | 195 R15 | OHTSU | 6 mm |

4. Description of Damages

| |
|--|
| THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS. |
|--|

5. General Information

| | | | |
|----------------|--------------------------------------|-----------------|------------|
| Accident Date | 06/09/2017 | Inspection Date | 06/02/2018 |
| Survey held at | NO 29 SUNGEI KADUT LOOP SPORE 729469 | | |
| Repairer | SHENG LI LAI | | |

5a. Remarks

| |
|--|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|--|

5b. Estimate Days of Repair

| | |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 6 Working Days |
|-------------------------------------|----------------|