



CYCLE & CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

**ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info	
Mr LIM HUAT SENG Blk 773 Woodlands Dr 60 #11-210 Singapore 730773 Contact No	Cust No/Name	/Mr Lim Huat Seng
	Reg No/Reg Date	SLG7924J*1F / 14/10/2016
	Date In/Mileage	29/01/2018/ 0
	Chassis No	MMBSTA13AH002801
	Engine No	3A92UDL1724
	Make/Model	MIT/17MY Attrage 1.2 CVT
	Colour/Trim	A06 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00001	Cash	29/01/2018/ 15:46	DS	218 / MarsLer	51512			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
S	MIPNT88088	TO SUPPLY AND REPLACE REAR REVERSE SENSOR	1 set			280.00		
M	SUNDRY	C & C LOGO				35.00		
M	SUNDRY	MIVEC EMBLEM				45.00		
S	MIPNT88088	TO CHECK LIGHTING & WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS				80.00		
S	MIPNT88088	TO REPLACE REAR REVERSE CAMERA LENS				300.00		
S	MIPNT88088	TO REMOVE AND RE-INSTALL TRIMMING AND CAPERTING TO GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS				600.00		
S	MIPNT88088	TO REPLACE REAR BUMPER,REAR BOOT,ETC -CUT & RE-WELD REAR END PANEL STRAIGHTEN,REFORM,ALIGN ON REAR ACCIDENT AFFECTED AREAS	600			3000.00		
S	MIPNT88088	TO APPLY SEALANT KIT ON NEW PANEL -TO CONDUCT WATER LEAK TEST ON REAR ACCIDENT ON REAR ACCIDENT AFFECTED AREAS				200.00		
S	MIPNT98088	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS	420			2520.00		
P	JJ6410C750	FACE, RR BUMPER	1.00			740.00	10.00	666.00
M	JJ6410C433	LH BRACKET, RR BUMPER	1.00			27.00	10.00	24.30
M	JJ6410C434	RH BRACKET, RR BUMPER	1.00			27.00	10.00	24.30
M	JJMU001623	CLIP,RR BUMPER	10.00			3.00	10.00	27.00
P	JJ5281A631	PANEL,RR END	1.00			421.00	10.00	378.90
M	JJ7240A172XA	TRIM, RR END	1.00			65.00	10.00	58.50
M	JJ5921A017	WEATHERSTRIP, TRUNK	1.00			155.00	10.00	139.50
M	JJ5920A203	PANEL, TRUNK LID	1.00			865.00	10.00	778.50
M	JJ5927A042	LATCH, TRUNK LID	1.00			216.00	10.00	194.40

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD

EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
Mr LIM HUAT SENG Blk 773 Woodlands Dr 60 #11-210 Singapore 730773	Cust No/Name /Mr Lim Huat Seng Reg No/Reg Date SLG7924J*1F / 14/10/2016 Date In/Mileage 29/01/2018/ 0 Chassis No MMBSTA13AHH002801 Engine No 3A92UDL1724 Make/Model MIT/17MY Attrage 1.2 CVT Colour/Trim A06 / BK
Contact No	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00001	Cash	29/01/2018/ 15:46	DS	218 / MarsLer	51512

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
P JJ7415A389 MARK, THREE-DIA	1.00	43.00	10.00	38.70
M JJ7415A438 MARK, ATTRAGE	1.00	21.00	10.00	18.90
P JJ8637B366 BUZZER, KEYLESS OPER	1.00	88.00	10.00	79.20
M JJ8637B115 ANTENNA, KEYLESS OPE	1.00	91.00	10.00	81.90
M JJ8330A852 RHR LAMP ASSY, COMBI	1.00	332.00	10.00	298.80
P JJ8330A851 LHR LAMP ASSY, COMBI	1.00	332.00	10.00	298.80
M JJ8355A082 RH REFLECTOR	1.00	21.00	10.00	18.90
M JJ8355A081 LH REFLECTOR	1.00	21.00	10.00	18.90

Z NOTES

ACCIDENT ON 28/01/2018 ALONG JOHORE CAUSEWAY TOWARDS WOODLANDS

OWNER CLAIMING THIRD PARTY

REQUIRED REPLACEMENT CAR

TP : SJY1254C TP INS : AXA

Estimate

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Authorized
 21/1/18
 Tel: 62563564
 6/2/18
 take photo before party.
 4/2/18

Confirm & accepted by

Parts	3,145.50
Labour	0.00
Standard Menu	0.00
Specialist Job	6,980.00
Others(Lub,etc)	0.00
Sundry	80.00
Total(w/o GST)	10,205.50

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.