

23/03/2001

ASS. REC. BY:

REF: CS/FCI 18002101/Dgd3n2 Special Instruction:

Surveyor: Brylin ASSIGNMENT (Office)From (Person): Karen Tan of FCI Date/Time: 02/02/18 @ 11:59am

Estimated Cost: _____ Bill to: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SKH 3322D Insured: SHA 4496Bat Workshop m/s Teamwork Garage Tel: 6844 2475of Blk 53 Ubi Ave 1 #01-24Policy No: _____ Claim No: D17008932MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 17/09/2017
(Client's Record)CA / REV / REP. / REV 24 HRS lwp H.O.D. Endorsement: _____Date/Time: 12:39pm @ 2/2/18 Person Contacted: Chnis Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SKH 3322D-X
	SHA 4496B-CS/FCI 17011954/G/H 3e2
<u>12/4/18 @ 2.50pm</u>	<u>revised to Karen Tan by email.</u>

D.O.A. = 16/6/17

REF:

Surveyor

ASSIGNMENT

COE Feb 2028

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKH3322D Yr Regn: 2008 / FebType: M.Ca / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Lotus Elise S c.c. 1794Colour: Red A/C: Insured / Std / NI / NASp. Reading: N.A. T/Radio: Insured / Std / NI / NAEng/No: 1222996556C/No: 5CCYC11138HN30577Gen. Cond: Good / Fair / Poor / BurntSteering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/50 R16R: ---

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Toys

Front

Rear

R/Bal. S mm R/Bal. S mmL/Bal. S mm L/Bal. S mmD.O.A. 17/09/2017 D.O.I. 02/02/2018Survey held at Technic Page Ubi

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

First Rep SHH 4496 B

24/04/18 financed L/S 5500/- with 4 days 8 m
(Lum & 2815.55, 36%)

RECEIVED 25 APR 2018

Date/Time, File Pass to?

1) 25/4 2018

Date/Time, File Return to?

2)

☐ : Preli. Report☐ : Final ReportDays Of Repair: 4Resurvey No. of Trip: 2

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)Report Format: TPLump Sum / L.B.I. (\$) 5500

160

50

50+50

64

374



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18002101/Dqd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 02-02-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 4496B	Veh. Inspected	SKH 3322D
Policy No.		Coverage (\$)	0.00
Claim No.	D17008932MFSH	Excess (\$)	0.00
Assign From	CWS (KAREN TAN)	Assign Date	02/02/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	17/09/2017	Inspection Date	02/02/2018
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17008932MFSH
Our Ref: CS/FCI18002101/Dqd3

Date: 19 April 2018

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SKH 3322D .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 02/02/2018 at the premises of M/s TEAMWORK GARAGE, and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 8,415.55</u> .
Revised Estimate Amount	: <u>S\$ 7,384.98</u> .
"Check" Items Amount	: <u>S\$ -</u> .
Market Value	: <u>S\$ -</u> .
LTA Reimbursement Value	: <u>S\$ -</u> .
Nett Value	: <u>S\$ -</u> .

Description of Damage:

The vehicle sustained damages
at the front portion.



Yours faithfully

Bryan Ang Tani
Motor Surveyor / Investigator

MOTOR SURVEY ASSIGNMENT

Date	19-09-2017	Our Ref No. D17008932MFSH
Accident Date	17-09-2017	Claim Type. Third Party
Insured Vehicle	SHA4496B	Third Party Vehicle. SKH3322D
Survey Location	BLK 53 UBI AVE 1 #01-24 PAYA UBI INDUSTRIAL PARK	
Contact Person.	DARREN NG	
Contact No.	68442475/ 0	Fax No. 68442474
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TEAMWORK GARAGE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/228186)



PRI Documents



Close



PRI Header Details

Claim No	D17008932MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & TEAMWORK
Workshop Name	TEAMWORK GARAGE PTE LTD (Contact Person : DARREN NG)	Survey Location & Contact Details	BLK 53 UBI AVE 1 #01-24 PAYA UBI INDUSTRIAL PARK Mobile: 0 , Phone: 68442475 , Fax: 68442474 EmailId: CLAIMS@TEAMWORKGARAGE.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA4496B	TP Vehicle No	SKH3322D
PRI Recieved Date	01-02-2018 09:42:23 PM	Surveyor Appointed Date	02-02-2018 11:58:13 AM	Surveyor Accept Date	02-02-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	02-02-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▾	Model	Please Select Model ▾	Year	Select Year ▾
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 19 April 2018 3:50 PM
To: 'Claim Workflow System'
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR; assignments
Subject: RE: SURVEY ASSESSMENT - D17008932MFSH/1
Attachments: CSFCI18002101Dqb.pdf

Dear Karen,

Enclosed herewith preliminary advice of SKH 3322D.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sjewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nivitha (LKK Auto) [<mailto:admin-d@lkkauto.com>]
Sent: Friday, 2 February, 2018 12:40 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; ASSIGNMENTS@LKKAUTO.COM
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; 'SUR' <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17008932MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 2 February 2018 11:59 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; KARENTAN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17008932MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited



Pte Ltd

Teamwork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel : 6844 2475 Fax : 6844 2474

E-mail : claims@teamworkgarage.com

ROC number : 201015366H

3RD PARTY CLAIM ESTIMATION

First Capital Insurance Ltd

36 Robinson Road

#16-01 City House

Singapore 068877

Vehicle number	: SKH3322D
Make / Model	: LOTUS/ELISE
Chassis number	: SCCYC11138HN30577
Accident date	: 17 September 2017
Reference	: 1802-01

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	FRONT BUMPER ASSY <i>crack</i>	6888.00 ✓
4	WASHER-CAPTIVE M8 NYLON <i>HM</i>	61.80 ×
2	RUBBER SEAL FRONT HEADER <i>HM</i>	66.96 ×
4	INTAKE GRILLE SIDE CLIP <i>HM</i>	43.64 ×
6	FRONT GRILLE CLIP RETAINER <i>HM</i>	36.34 ×
6	RECEPTACLE -FRONT GRILLE <i>HM</i>	36.34 ×
1	FRONT GRILLE WITHOUT DRIVING LIGHTS <i>crack</i>	428.64 ✓
		7561.72
	Less 10%	756.17
	Subtotal	6805.55
	Balance C/F	6805.55
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
S/No		
	Balance B/F	6805.55
1	CHECK FRONT WIRING AND LIGHTNING SYSTEM	60.00 <i>HM</i>
2	PANEL BEATING ON AFFECTED AREAS	800.00 <i>400/-</i>
3	SPRAY PAINTING ON AFFECTED AREAS	600.00 <i>400/-</i>
4	APPLY ANTI RUST ON AFFECTED AREAS	150.00 <i>HM</i>
	Subtotal	1610.00
	Grand total	8415.55
		7384.97

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

02/02/2018 e 1130m

Wist Antenna
L/Smm

[Signature]

2 & K Auto

[Signature]

4 days.

L/S 5500/-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18002101/Dqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 26-04-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 4496B	Veh. Inspected	SKH 3322D	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17008932MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	02/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	LOTUS ELISE S	c.c	1794	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	SCCYC11138HN30577	Colour	RED	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/50 R16	TOYO	5 mm	
L/H Front Tyre	195/50 R16	TOYO	5 mm	
R/H Rear Tyre	195/50 R16	TOYO	5 mm	
L/H Rear Tyre	195/50 R16	TOYO	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/09/2017	Inspection Date	02/02/2018	
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKH 3322D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER ASSY	CRACKED	6,888.00	6,888.00
4	WASHER-CAPTIVE M8 NYLON	NOT NECESSARY	61.80	-
2	RUBBER SEAL FRONT HEADER	NOT NECESSARY	66.96	-
4	INTAKE GRILLE SIDE CLIP	NOT NECESSARY	43.64	-
6	FRONT GRILLE CLIP RETAINER	NOT NECESSARY	36.34	-
6	RECEPTACLE-FRONT GRILLE	NOT NECESSARY	36.34	-
1	FRONT GRILLE WITHOUT DRIVING LIGHTS	CRACKED	428.64	428.64
	LESS 10% DISCOUNT		-756.17	-731.66
			6,805.55	6,584.98
LABOUR				
	CHECK FRONT WIRING AND LIGHTING SYSTEM.	NOT NECESSARY	60.00	-
	PANEL BEATING ON AFFECTED AREAS.		800.00	400.00
	SPRAY PAINTING ON AFFECTED AREAS.		600.00	400.00
	APPLY ANTI RUST ON AFFECTED AREAS.	NOT NECESSARY	150.00	-
			1,610.00	800.00
GRAND TOTAL			8,415.55	7,384.98
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,500.00

Report Ref No. CS/FC118002101/Dqd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.