

22/03/2018

ASS. REC. BY:

REF:

C3 / MSH / 800 2107 / Tirb ⁷²

Special Instruction:

ASSIGNMENT (Office)

From (Person): Mu Men of MSL Date/Time: 02022018 11:01am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLK 1294L Insured: GZ 5392Rat Workshop m/s Kah Motor Tel: _____of 255 Alexandra RdPolicy No: 28650317 MKC Claim No: 540780

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 12.12.2017
(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement: _____

Date/Time: 02022018 11:09am Person Contacted: Sin Hui Vehicle IN / OUT IN

Date/Time	Action/Instruction (✓) Estimate
	SLK 1294L - X
	GZ 5392R - C3 / MSH 18000 870 / J3
	\$6883.00 @ 5 days
	Red: \$6926.44, 481.

Signature: Tanjiah


REF: MS19

ASSIGNMENT

From: _____ Date: 28/5/18
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SLK 1294 L
at Workshop m/s: Kah Motor
of No. 255 Alexandra Road
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS ^{1up}

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLK 1294 L Yr Regn: 20/7/Jan
Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Honda HRV cc: 1496
Colour: Grey A/C: Insured / Std / NI / NA
Sp. Reading: 21964 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: JHMR4 18.306X 201569
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Mod: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 215/60R16
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front Rear
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. _____ D.O.I. 28/5/18 e/pur.

Survey held at Kah Motor Alexandra

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 10 OCT 2018

Date/Time: File Pass to?



: Preli. Report

1) Typist



: Final Report

Date/Time: File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation

) S + RS. SI

) Photos

) Others

TOTAL

Report Format: TP

Lump Sum / I.B.I: (\$ 6883.00

300
10

310

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Dec 2017		02 Feb 2018 11:01 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETAILS		[Created by insurer]		
Insured:	DRYCLEAN EXPRESS SERVICES, Co. Reg. No.: 53003586C			
Main Claimant:	TAN AI LIANG IRENE, ID: S1692182C			
Vehicle Reg. No.:	SLK1294L	Date of Loss:	12/12/2017 17:00 - :59	
Claim Type:	TP / 540780	Policy/Cover Note No.:	28650317MKC (TP, Fire & Theft) Coverage: 06/12/2017 - 05/12/2018	
Vehicle Reg. No. (Insured):	GZ5392R	Policy No. (Claimant):		
		Excess:		
Repairer:	Kah Motor Co Sdn Bhd (ALEXANDRA) 255 ALEXANDRA ROAD, - Alexandra - Tel:			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 03/02/2018]			
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail		
There are no mail for this case.				
ALL ASSOCIATED TASKS				
View All Search Tasks Create New Task Complete				
Due Date	Priority	Type	Task Group	Subject
				Handler
				Assigned By
				Completed On
				Created On
				Done?
No results.				

0202792 @ 11:08am
Sim Hui veh not in

Janice Lee (LKKAuto)

From: Ng Sin Hai <shng@kahmotor.onmicrosoft.com>
Sent: Tuesday, June 19, 2018 9:54 AM
To: Taufikh (LKKAuto); SUR
Subject: RE: Submission Pre-Invoice for vehicle SLK1294R
Attachments: 3368_001.pdf; DSCF4790.jpg; DSCF4791.jpg; DSCF4792.jpg; DSCF4793.jpg; DSCF4794.jpg; DSCF4795.jpg; DSCF4797.jpg; DSCF4785.jpg; DSCF4786.jpg; DSCF4787.jpg; DSCF4788.jpg; DSCF4789.jpg; DSCF4784.jpg

Dear Mr Taufikh,

Kindly refer to the attached pdf for the pre-invoice final repair cost amount for abovementioned vehicle .

Cost of repair : S\$6,883.00 (before GST)
No of working days : 05 days. (LOU)

We will proceed for closing after 1 week of submission to you.
Kindly contact me if there is any discrepancy

Thank you and have a nice day,☺

Warmest Regards,


Ng Sin Hai
Kah Motor Co. Sdn. Bhd
(A member of Oriental Holdings Berhad)
Body Repair & Paint Centre
255 Alexandra Road
Singapore 159937
DID: 6471 5419
HP: 9072 1769
E-mail: shng@honda.com.sg



BLUE SKIES FOR
OUR CHILDREN



Visit our
Facebook page



CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1692182C



Name
TAN AI LIANG IRENE
陈艾连

Race
CHINESE

Date of Birth
09-11-1965

Sex
F

Country of Birth
SINGAPORE




REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: S1692182C

Name
TAN AI LIANG IRENE

Birth Date: 09 Nov 1965
Issue Date: 10 Nov 2003




1000979777B

2710413



NRIC No. S1692182C

Allergies:
Amozycillin
Cotrimoxazole

Blood Group: O+ Date of issue: 12-10-1995

APT BLK 93 DAWSON ROAD #29-36
SINGAPORE 142093

NRIC No. S1692182C Date: 13/05/2015



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE
11 Nov 1992

NP 428A

Licence No: S1692182C



**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Irene Tan

QUOTATIONGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : MSIG INSURANCE (SINGAPORE) PTE
16 RAFFLES QUAY
HONG LEONG BUILDING
SINGAPORE 048581

Registration No : SLK1294L

Chassis No : JHMRU1830GX201569

Model : HRV LX-SIN CVT YM 2016

Owner's Name : TAN AI LIANG IRENE

Ins Policy No. :

Date of Accident : 12/12/2017

Document No. : SQT17005077

Date : 13. Dec 2017

Customer No. : WZM003

Svc Advisor : NG SIN HAI

Engine No : L15B4531570

Date | Time : 13. Dec 2017 7:15:26 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:TAN AI LIANG IRENE OWNER INSURER:LIBERTY ACC DATE:12/12/2017 SURVEYED BY: DATE: REF NO: TP INSURER:MSIG INSURANCE (SINGAPORE) PTE LTD TP VEH:GZ5392R						
BOSUN	SUNDRIES	1 ³⁰	100.00		100.00	7.00	107.00 <i>net</i>
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1 ✓	180.00		180.00	12.60	192.60
BOJSE	SEALANT FOR REAR END PANEL	1 ^{nnx}	80.00		80.00	5.60	85.60
BOJSE	SEALANT FOR TAILGATE	1 ✓	80.00		80.00	5.60	85.60
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1 ✓	180.00		180.00	12.60	192.60
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1 ⁿⁿ	560.00		560.00	39.20	599.20
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1 ✓	560.00		560.00	39.20	599.20
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST	1 ✓	560.00		560.00	39.20	599.20
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1 ✓	560.00		560.00	39.20	599.20
BODAMKIT	WINDSCREEN DAM KIT. <i>Repair 1680v</i>	1 ✓	80.00		80.00	5.60	85.60
BKRP02M	CUT OFF & RENEW RR PANEL. <i>Replace 2240</i>	1	3500.00		3500.00	245.00	3745.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1 ^{1350v} ₂₇₀₀	3000.00		3000.00	210.00	3210.00
BKBU01R	REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA	1 ✓	380.00		380.00	26.60	406.60
Sum Labor					9820.00	687.40	10,507.40
RS-TMP3040L	VPC 4PCS REAR SENSORS	1 ⁿⁿ	320.00		320.00	22.40	342.40
33502-T7A-J01	LAMP UNITR.	1 ⁿⁿ	419.10	25	314.32	22.00	336.32
33552-T7A-J01	LAMP UNITL.	1 ⁿⁿ	419.10	25	314.32	22.00	336.32



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer : MSIG INSURANCE (SINGAPORE) PTE
16 RAFFLES QUAY
HONG LEONG BUILDING
SINGAPORE 048581
Registration No : SLK1294L
Chassis No : JHMRU1830GX201569
Model : HRV LX-SIN CVT YM 2016
Owner's Name : TAN AI LIANG IRENE
Ins Policy No :
Date of Accident : 12/12/2017

Document No. : SQT17005077
Date : 13. Dec 2017
Customer No. : WZM003
Svc Advisor : NG SIN HAI
Engine No : L15B4531570
Date | Time : 13. Dec 2017 7:15:26 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
34150-T7A-J01	LIGHT ASSY,R.LID	1 <i>new</i>	264.60	25	198.45	13.89	212.34
34155-T7A-J01	LIGHT ASSY,L.LID	1 <i>new</i>	264.60	25	198.45	13.89	212.34
68100-T7A-J20ZZ	TAILGATE COMP /	1 <i>bt</i>	838.90	25	629.17	44.04	673.21
74440-T7A-003	WEATHERSTRIPTAILGATE	1 <i>new</i>	96.80	25	72.60	5.08	77.68
74800-T7A-J02	LOCK ASSYTAILGATE	1 <i>new</i>	74.90	25	56.17	3.93	60.10
84431-T7A-J01ZA	LINING ASSYTAILGATE	1 <i>new</i>	133.40	25	100.05	7.00	107.05
75722-T7W-A01	EMBLEMRR. /	1 <i>new</i>	12.60	25	9.45	0.66	10.11
75725-T8N-T00	EMBLEM,RR. I-VTEC /	1 <i>new</i>	13.70	25	10.27	0.72	10.99
33505-T7A-J01	REFLECTOR ASSYR.RR.	1 <i>new</i>	148.40	25	111.30	7.79	119.09
33555-T7A-J01	REFLECTOR ASSYL.RR.	1 <i>new</i>	148.40	25	111.30	7.79	119.09
04717-T7A-000ZZ	FACER.RR.BUMPER CORNER	1 <i>new</i>	92.20	25	69.15	4.84	73.99
04718-T7A-000ZZ	FACEL.RR.BUMPER CORNER	1 <i>new</i>	92.20	25	69.15	4.84	73.99
71593-T7A-000	SPACERR.RR.BUMPER SIDE /	1 <i>new</i>	11.50	25	8.62	0.60	9.22
71598-T7A-000	SPACERL.RR.BUMPER SIDE /	1 <i>new</i>	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIPBUMPER /	8 <i>new</i>	2.00	25	12.00	0.84	12.84
66100-T7A-300ZZ	PANEL COMPRR.	1 <i>Rx</i>	415.60	25	311.70	21.82	333.52
84640-T7A-J01ZA	LINING ASSYRR.PANEL /	1 <i>del</i>	43.00	25	32.25	2.26	34.51
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER /	1 <i>new</i>	19.30	25	14.47	1.01	15.48
73226-SZW-000	DAMPERSTD 5X5 /	1 <i>new</i>	8.30	25	6.22	0.44	6.66
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER /	1 <i>new</i>	19.30	25	14.47	1.01	15.48
76711-T6A-003	CAPPVOT /	1 <i>new</i>	4.70	25	3.52	0.25	3.77
91501-S70-003	FASTENER BW/SHIELD /	4 <i>new</i>	3.20	25	9.60	0.67	10.27
91502-S70-003	FASTENER B /	2 <i>new</i>	4.90	25	7.35	0.51	7.86
91536-SS0-J01	FASTENER AW/SHIELD /	2 <i>new</i>	3.50	25	5.25	0.37	5.62
BO-WS-SEALANT	WINDSCREEN SEALANT (N) /	2 <i>new</i>	60.00		120.00	8.40	128.40
Sum Item					3138.22	219.65	3,357.87

Survey By

Date & Time

Excess

Taufik 97495749
28/5/18 @ 1pm
WP

5-7 days
Recovery before print
Sur@Tikant.com

Total Amount 12,958.22 907.05 13,865.27
Total (Inclusive of GST) 13,309.44 13,865.27

Printed on 13/12/2017 7:26:42 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)
Service and Body Repair
Tel: +65 6841 3838 Website: www.honda.com.sg
For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : MSIG INSURANCE (SINGAPORE) PTE
16 RAFFLES QUAY
HONG LEONG BUILDING
SINGAPORE 048581
Registration No : SLK1294L
Chassis No : JHMRU1830GX201569
Model : HRV LX-SIN CVT YM 2016
Owner's Name : TAN AI LIANG IRENE
Ins Policy No. :
Date of Accident : 12/12/2017

Document No. : SQT17005077 **Page** 3
Date : 13. Dec 2017
Customer No. : WZM003
Svc Advisor : NG SIN HAI
Engine No : L15B4531570
Date | Time : 13. Dec 2017 7:15:26 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incl GST
Status							
Signature							

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 13/12/2017 7:26:42 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MSIG INSURANCE (SINGAPORE) PTE
16 RAFFLES QUAY
HONG LEONG BUILDING
SINGAPORE 048581
Registration No : SLK1294L
Chassis No : JHMRU1830GX201569
Model : HRV LX-SIN CVT YM 2016
Owner's Name : TAN AI LIANG IRENE
Ins Policy No. :
Date of Accident : 12/12/2017

Document No. : SQT18002495
Date : 19. Jun 2018
Customer No. : WZM003
Svc Advisor :
Engine No : L15B4531570
Date | Time : 19. Jun 2018 9:33:29 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:						
	OWNER INSURER:						
	ACC DATE:						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:						
	TP VEH:						
	SUPPLEMENTARY						
90661-SC7-003	GROMMET SCREW	2	2.30	25	3.45	0.24	3.69
04715-T7A-900ZZ	FACE,RR.BUMPER	1	463.70	25	347.77	24.34	372.11
					Sum Item	351.22	24.58
							375.80

Survey By _____
Date & Time _____
Excess _____
Status _____
Signature _____

Total Amount 351.22 24.58 375.80
Total (Inclusive of GST) 375.80

Printed on 19/6/2018 9:36:38 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZM003 / MSIG INSURANCE
Chassis No: JHMRU1830GX201569
License No: SLK1294L
Mileage: 15185
Engine No: L15B4531570

Document No: SVO18030701
Printed By: SHNG
Order Date: 28. May 2018
Order Time: 1:10:34 PM
Service Advisor: NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:TAN AI LIANG IRENE OWNER INSURER:LIBERTY ACC DATE:12/12/2017 SURVEYED BY:TAUFIHK DATE:28/05/2018 REF NO: TP INSURER:MSIG INSURANCE (SINGAPORE) PTE LTD TP VEH:GZ5392R ADDITIONAL PART						
68100-T8P-U10ZZ	TAILGATE COMP	1	838.90	25	629.17	44.04	673.21
75722-T7W-A01	EMBLEMRR.	1	12.90	25	9.67	0.68	10.35
75725-T8N-T00	EMBLEM,RR. I-VTEC	1	14.10	25	10.57	0.74	11.31
71593-T7A-000	SPACERR.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
71598-T7A-000	SPACERL.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIPBUMPER	8	2.00	25	12.00	0.84	12.84
84640-T7A-J01ZA	LINING ASSYRR.PANEL	1	43.00	25	32.25	2.26	34.51
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
73226-SZW-000	DAMPERSTD 5X5	1	8.30	25	6.22	0.44	6.66
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
76711-T6A-003	CAPPVOT	1	4.70	25	3.52	0.25	3.77
91501-S70-003	FASTENER BW/SHIELD	4	3.20	25	9.60	0.67	10.27
91502-S70-003	FASTENER B	2	4.90	25	7.35	0.51	7.86
91536-SS0-J01	FASTENER AW/SHIELD	2	3.50	25	5.25	0.37	5.62
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
90661-SC7-003	GROMMET SCREW	2	2.30	25	3.45	0.24	3.69
04715-T7A-900ZZ	FACE,RR.BUMPER	1	463.70	25	347.77	24.34	372.11
	SUM PARTS:				1,243.00	87.00	1,330.00
BOSUN	0701 SUNDRIES	1	30.00		30.00	2.10	32.10
BA02R	0701 REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00		180.00	12.60	192.60
BOJSE	0701 SEALANT FOR TAILGATE	1	80.00		80.00	5.60	85.60
BML02I	0701 INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	180.00		180.00	12.60	192.60
BMI02D	0701 REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK LININGS GARNISHES & ETC.(N)	1	560.00		560.00	39.20	599.20
BKTG02R	0701 REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	560.00		560.00	39.20	599.20
BG02D	1757 REMOVE & INSTALL RR. WINDSCREEN. (N)	1	560.00		560.00	39.20	599.20



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZM003 / MSIG INSURANCE
Chassis No: JHMRU1830GX201569
License No: SLK1294L
Mileage: 15185
Engine No: L15B4531570

Document No: SVO18030701
Printed By: SHNG
Order Date: 28. May 2018
Order Time: 1:10:34 PM
Service Advisor: NG SIN HAI

BODAMKIT	1757	1	80.00	80.00	5.60	85.60
	WINDSCREEN DAM KIT.					
BKRP02M	1466	1	1,680.00	1,680.00	117.60	1,797.60
	CUT OFF & RENEW RR PANEL.					
	RR FLOOR PAN & RENEW DAMAGE					
	PARTS.					
BP06R	1718	1	1,350.00	1,350.00	94.50	1,444.50
	SPRAY PAINTING ON REPAIRED OR					
	REPLACED AREAS. (6P)					
	REAR PORTION					
BKB01R		1	380.00	380.00	26.60	406.60
	REMOVE, RE-FIX AND ALIGN REAR					
	VIEW CAMERA					
			SUM LABOUR:	5,640.00	394.80	6,034.80
			TOTAL SGD	6,883.00	481.80	7,364.80
Total Payable (SGD)						7,364.80

GST Amount is calculated from individual line(s)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18002107/T1RBN2

Date: 11/10/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28650317MKC
Claimant Vehicle No :	SLK1294L	Insured Vehicle No :	GZ5392R
Date of Loss:	12/12/2017	Nature of Claim:	TP
		Claim No:	540780

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK1294L	Engine No:	L15B4531570
Make & Model:	HONDA HR-V, 1.5 LX CVT (A)	Chassis No:	JHMRU1830GX201569
Reg. Date:	05/01/2017 (Man. Year: 2016)	Odometer:	21964 km
Colour:	Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,589.96	1,273.00	2,316.96	64.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,720.00	5,610.00	4,110.00	42.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	13,309.96	6,883.00	6,426.96	48.29
+ GST 7.00/7.00% (\$\$)	931.70	481.81	449.89	48.29
Nett Amount (\$\$)	14,241.66	7,364.81	6,876.85	48.29

INSPECTION

Date of Assignment:	02/02/2018	
Date Inspected:	28/05/2018	Inspected At:
		Kah Motor Co Sdn Bhd (ALEXANDRA) 255 ALEXANDRA ROAD Singapore -
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 11 Oct 2018)	
Parts:	N/A	HONDA HR-V 1.5 LX CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK1294L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS
2	1		*VPC 4 PCS RERA SENSORS	Not Necessary	320.00 FS	*- FS
3	1		*LAMP UNITR	Not Necessary	314.32 FS	*- FS
4	1		*LAMP UNITL	Not Necessary	314.32 FS	*- FS
5	1		*LIGHT ASSY,R LID	Not Necessary	198.45 FS	*- FS
6	1		*LIGHT ASSYL LID	Not Necessary	198.45 FS	*- FS
7	1		*TAILGATE COMP	Bent	629.17 FS	*629.17 FS
8	1		*WEATHERSTRIP TAILGATE	Not Necessary	72.60 FS	*- FS
9	1		*LOCK ASSY TAILGATE	Not Necessary	56.17 FS	*- FS
10	1		*LINING ASSY TAILGATE	Not Necessary	100.05 FS	*- FS
11	1		*EMBLEMRR	Necessary	9.67 FS	*9.67 FS
12	1		*EMBLEMRR I-VTEC	Necessary	10.57 FS	*10.57 FS
13	1		*REFLECTOR ASSYRR RR	Not Necessary	111.30 FS	*- FS
14	1		*REFLECTOR ASSYL RR	Not Necessary	111.30 FS	*- FS
15	1		*FACER RR BUMPER CORNER	Not Necessary	69.15 FS	*- FS
16	1		*FACEL RR BUMPER CORNER	Not Necessary	69.15 FS	*- FS
17	1		*SPACERR RR BUMPER SIDE	Necessary	8.62 FS	*8.62 FS
18	1		*SPACERL RR BUMPER SIDE	Necessary	8.62 FS	*8.62 FS
19	8		*CLIPBUMPER	Necessary	12.00 FS	*12.00 FS
20	1		*PANEL COMPRR	Repair	311.70 FS	*- FS
21	1		*LINING ASSYRR PANEL	Deformed	32.25 FS	*32.25 FS
22	1		*RUBBER CR WINDSHIELD DAMPER	Necessary	14.47 FS	*14.47 FS
23	1		*DAMPERSTD 5X5	Necessary	6.22 FS	*6.22 FS
24	1		*RUBBER CL WINDSHIELD DAMPER	Necessary	14.47 FS	*14.47 FS
25	1		*CAPPIVOT	Necessary	3.52 FS	*3.52 FS
26	4		*FASTENER BW/SHIELD	Necessary	9.60 FS	*9.60 FS
27	1		*FASTENER B (2 Pcs)	Necessary	7.35 FS	*7.35 FS
28	1		*FASTENER A/W SHIELD (2 Pcs)	Necessary	5.25 FS	*5.25 FS
29	2		*WINDSCREEN SEALANT	Necessary	120.00 FS	*120.00 FS
30	1		*GROMMET SCREW (2 Pcs)	Necessary	3.45 FS	*3.45 FS
31	1		*FACE RR BUMPER	Deformed	347.77 FS	*347.77 FS
					Total Parts (\$\$)	3,589.96 1,273.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & RENEW REVERSE SENSOR-4 PCS	New	180.00	180.00
2	SEALANT FOR REAR END PANEL	New	80.00	-
3	SEALANT FOR TAILGATE	New	80.00	80.00
4	INSPECT RR LIGHTING MECHANISMS.PERFORM WATER	New	180.00	180.00
5	RREMOVE & INSTALL FUEL TANK FUEL PIPES	New	560.00	-
6	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	New	560.00	560.00
7	REMOVE & TRANSFER ITEMS TO NEW TAILGATE,ADJUST	New	560.00	560.00
8	REMOVE & INSTALL RR WINDSCREEN	New	560.00	560.00
9	WINDSCREEN DAM KIT	New	80.00	80.00
10	CUT OFF & RENEW RR PANEL	New	3,500.00	1,680.00
11	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (6P)	New	3,000.00	1,350.00
12	REMOVE,RE-FIX AND ALIGN REAR CIEW CAMERA	New	380.00	380.00
Gross Labour Cost (S\$)			9,720.00	5,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >