



## SMRT Accident Vehicle Repair Estimates

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SG5516J  
 Ref. No : BUS/01/18/7042  
 Reg. Date : 26/10/2017  
 Vehicle Type : DOUBLE DECK  
 Make : VOLVO  
 Model : Volvo B9TL DD  
 Name of Driver : Shahrizam Bin Zainal Abidin  
 Type of Accident : SIDE SWIPE  
 Date / Time of Accident : 19/01/2018 09:23:00 AM  
 Accident Reported Date / Time : 26/01/2018 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by : AXA  
 Vehicle is Towed Back? : No  
 Towed Back Date/Time : 01/01/2000  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No : 000024094494  
 Special Instruction to ARC,if any :  
 rear right portion  
 xb8440r (tp) - insured with AXA  
 Prepared Date : 30/01/2018 12:32:14 PM



**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : YV3S4P921HA183233

Mileage : 0

Work Shop :

Repair Completed Date / Time : 01/01/2000

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,325.00	1,060.00
Total Spray Painting Charges	: 432.00	300.00
Total Material Charges	: 5,980.65	5,980.65
Other Charges	: 0.00	0.00
<b>TOTAL</b>	<b>: 7,737.65</b>	<b>7,340.65</b>
<b>Lump Sum Total</b>	<b>: 0.00</b>	<b>0.00</b>
No. of Repair Days	: 3.00	2.00
Prepared / Adjusted By	:	RASUL LKK
Arc / Surveyor Sign Off Date	: 01/02/2018 01:46:49 PM	04/05/2018 06:35:19 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 01/02/2018 01:46:31 PM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

**Section D - Details of Repair Estimates****Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	1,325.00	1,060.00
<b>Total Labour</b>	<b>1,325.00</b>	<b>1,060.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	432.00	300.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>432.00</b>	<b>300.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
<b>Total Other Costs</b>		



**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
7612002L21		6011099	LIGHT, REVERSE: LED	1	861.86	10.00	775.67	Replace	Replace <i>CRK</i>	No
7612001L21		6011100	LAMP LED STOP-TAIL-FLASHER	1	362.39	10.00	326.15	Replace	Replace <i>CRK</i>	No
ATP-03414			EXT REAR N/S CORNER	1	1,648.08	10.00	1,483.27	Replace	Replace <i>CRK</i>	No
A12-03302			FLYSCREEN ASSEMBLY	1	900.80	10.00	810.72	Replace	Replace <i>CRK</i>	No
A12-03438			COOLER DOOR ASSEMBLY	1	2,872.05	10.00	2,584.84	Replace	Replace <i>CRK</i>	No
TOTAL MATERIALS								5,980.66	5,980.65	
TOTAL MATERIALS(Discounted)								5,980.65	5,980.65	

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
A12-03302		FLYSCREEN ASSEMBLY	1	900.80	10.00	810.72	Replace	Replace	No
A12-03438		COOLER DOOR ASSEMBLY	1	2,872.05	10.00	2,584.84	Replace	Replace	No
TOTAL SUPPLEMENTARY MATERIALS						3,395.56			

5980.65  
 1360.00  
 7340.65  
 2 days