

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD (B) WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s SMRT
 of _____
 Insured: SKD 66215
 Policy No. 5088247137 030317 -260618
 Claims No. MT/0980412-002
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt.: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: SHF248B Yr Regn: 14 Dec 2017
 Type: M.Car / M.Cycle / Bus / Van / Lorry / (B) Prime Mover /
 Truck / Trailer or Hybrid
 Make: Toyota Prius C.C. 1798
 Colour: Brown maroon A/C: Insured / Std / NI / NA
 Sp. Reading: 8376 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: ITD KB 3FU X03576384
 Gen. Cond: (B) Good / Fair / Poor / Burnt
 Steering: (B) In order / Jammed / Leaked / Burnt or
 Brake: (B) In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195/65 R15
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / (B) YOKO or _____
 Front _____ Rear _____
 R/Bal. 9 mm R/Bal. 9 mm
 L/Bal. 9 mm L/Bal. 9 mm
 D.O.A. 31/1/18 D.O.I. 02-02-18
 Survey held at W/S Qin Yopm
 Des. of Damages: Frt / (B) Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>SHF 248B - X</u>
	<u>SKD 66215 - NA/DAZ/14022542 / 114</u> <u>DA: 03/2/14</u>
<u>15/2/18</u>	<u>Final fig \$1489.06 (Red 2075.74, 589)</u>

RECEIVED 20 FEB 2018

Date/Time, File Pass to? ☐ : Preli. Report
☐ : Final Report
 1) _____
 Date/Time, File Return to? _____
 2) 15/2- typust
 Report Format : _____
 Lump Sum / I.B.I: (\$) 1489.06
 Days Of Repair: 3
 Resurvey No. of Trip: 1
 Add Fee: ☐ Site Insp (\$ _____) ☐ S + RS. (\$ _____)
☐ Interview (\$ _____) ☐ Photos
☐ Tech. Invs (\$ _____) ☐ Others
☐ Weekend (\$ _____)
 Survey Fee: 160
 Transportation: _____
 TOTAL 195

Survey Department Check List (Case Handler)

Reference No. : NS | NC 18002196 | 61v6
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 15/2/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18002196/Gvb

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 05-02-2018

189556



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKD 6621S	Veh. Inspected	SHF 248B
Policy No.	5088247237	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	02/02/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	31/01/2018	Inspection Date	02/02/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

TP Claims against NTUC Income: Follow-Through Survey

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident
1	MT/0980348-002	SMRT TAXIS	SHB 1220U	SGB 4394T	30/1/2018
2	MT/0971146-002	SMRT BUS	SG 5580Y	SJS 5536U	25/11/2017
3	MT/0982534-001	COMFORT TRANSPORTATION PTE LTD	SHC 3146H	SLL 8920L	10/2/2018
4	MT/0982203-002	CITYCAB	SHA 9342D	SDD 8298L	12/2/2018
5	MT/0978056-002	SMRT TAXIS	SHB 1892E	SFY 6726Y	12/1/2018
6	MT/0982536-001	COMFORT TRANSPORTATION PTE LTD	SHC 2230D	PC 7662M	13/2/2018
7	MT/0980412-002	SMRT TAXIS	SHF 248B	SKD 6621S	31/1/2018
8	MT/0980980-002	SMRT TAXIS	SHD 6289D	SIH 7534U	3/2/2018
9	MT/0980928-002	SMRT TAXIS	SHB 1319U	FBC 5857Y	4/2/2018
10	MT/0982537-001	SMRT TAXIS	SHB 628J	FBH 2102K	4/2/2018
11	MT/0981878-002	COMFORT TRANSPORTATION PTE LTD	SHC 7245D	SJF 9837T	11/2/2018
12	MT/0982037-002	COMFORT TRANSPORTATION PTE LTD	SHC 8089G	GBG 9309R	10/2/2018

eBaoTech

General Claim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.		Date of Accident	31/01/2018 13:32						
Vehicle No.(For Motor)	SKD6621S								
Search									
Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☒	5088247237	PHUA AIK CHEW ALWYN	S8509870E	GPC	drive CLASSIC	SKD6621S	SKD6621S	03/03/2017	26/06/2018
Continue									

Enquire Transfer Fee

Vehicle Details	
Vehicle No. :	SHF248B
Vehicle Type :	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1 :	Air-Con (Taxi)
Vehicle Scheme :	Taxi (Company)
Vehicle Make :	TOYOTA
Vehicle Model :	PRIUS HYBRID 1.8 CVT
Chassis No. :	JTDKB3FUX03576384
Propellant :	Petrol-Electric
Engine No. :	2ZR8257332
Motor No. :	1NM8257332
Engine Capacity :	1798 cc
Power Rating :	53.0 kW
Maximum Power Output :	90.0 kW (120 bhp)
Maximum Laden Weight :	1790 kg
Unladen Weight :	1375 kg
Year Of Manufacture :	2017
Original Registration Date :	14 Dec 2017
Lifespan Expiry Date :	13 Dec 2025
COE Category :	A - Car up to 1600cc & 97kW (130bhp)

NTUC

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHF248B
 Ref. No : TAX/01/18/2191
 Reg. Date : 14/12/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS4
 Name of Driver : KOH POH KOK
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 31/01/2018 07:00:00 PM
 Accident Reported Date / Time : 01/02/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024094417
 Special Instruction to ARC, if any :
 SKD6621S
 Prepared Date : 01/02/2018 12:01:01 PM



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

*2 Days.
 part by part.
 before paint photos.
 Gino Ricap - 8288 0282
 02/2/18.*

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FUX03576384

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 676.00	0.00
Total Spray Painting Charges	: 738.00	0.00
Total Material Charges	: 1,238.08	1,238.08
Other Charges	: 340.00	0.00
TOTAL	: 2,992.08	0.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 4.00	0.00
Prepared / Adjusted By	:	
Arc / Surveyor Sign Off Date	: 02/02/2018 08:49:25 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 02/02/2018 08:49:25 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH REAR PORTION	676.00	0.00
Total Labour	676.00	0.00 200

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY FILLER RR BUMPER RH	180.00	0.00 X LNA
TO RESPRAY REAR BUMPER REINFORCEMENT	180.00	0.00 X LNA
Total Spray Painting & Panel Beating	738.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 X
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	340.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
5215947913			COVER, RR BUMPER ASSY / <i>let</i>	1	423.90	25.00	317.92	Replace	Replace	No
5257547040			RETAINER, RR BUMPER, RH / <i>RLC</i>	1	112.70	25.00	84.52	Replace	Replace	No
5256547900			FILLER, RR BUMPER, RH / <i>NN</i>	1	119.90	25.00	89.92	Replace	Replace	No
5246247030			PAD, RR BUMPER, RH & LH, 1 / <i>RLC</i>	1	3.80	25.00	2.85	Replace	Replace	No
5246247020			PAD, RR BUMPER, RH & LH, 2 / <i>RLC</i>	1	3.80	25.00	2.85	Replace	Replace	No
5246247010			PAD, RR BUMPER, RH & LH, 3 / <i>RLC</i>	1	3.80	25.00	2.85	Replace	Replace	No
5219147030			SEAL, RR BUMPER ARM, RH & LH / <i>RLC</i>	1	11.00	25.00	8.25	Replace	Replace	No
5245347010			GUARD, RR BUMPER, LOWER / <i>SCR</i>	1	558.30	25.00	418.72	Replace	Replace	No
5216947020			COVER, GUARD RR BUMPER LOWER / <i>MIS</i>	1	14.80	25.00	11.10	Replace	Replace	No
5202347030			REAR BUMPER REINFORCEMENT / <i>NN</i>	1	318.80	25.00	239.10	Replace	Replace	No
			PIXEL STICKER / <i>RLC</i>	1	60.00	0.00	60.00	Replace	Replace	No
TOTAL MATERIALS							1,238.10	1,238.08		
TOTAL MATERIALS(Discounted)							1,238.08	1,238.08		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									



747

SMRT Automotive Service Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

5-2-18 / 12:44
5-2-18 / 16:44

2-2-18 / 16:44

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHF248B
 Ref. No : TAX/01/18/2191
 Reg. Date : 14/12/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS4
 Name of Driver : KOH POH KOK
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 31/01/2018 07:00:00 PM
 Accident Reported Date / Time : 01/02/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : Guoqiang
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024094417
 Special Instruction to ARC, if any :
 SKD6621S
 BEFORE PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR guoqiang (LKK) &
 Email : guoqiang@lkkauto.com HP: 82880282
 Prepared Date : 01/02/2018 12:01:01 PM



17:30 6.2.18 - pass.

Recording Camera

☐ ☒

Radio Antenna

☐ ☒

1st witness

Date 22-18

2nd witness

Date 6.2.18

Vehicle to Wega Date In: 3/2/18	Towing: 747
Time In: -	Driver: 747
Wega Job No: 02/0100	
Vehicle sent to SMRT Date In: 6-2-2018	Towing: -
Time In: 4-25	Driver: -
Received by (SMRT):	

Section B - To be Completed by Service Advisor, Accident Repair Centre


Chassis No : JTDKB3FUX03576384

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 676.00	200.00
Total Spray Painting Charges	: 738.00	200.00
Total Material Charges	: 1,089.06	1,089.06
Other Charges	: 340.00	0.00
TOTAL	: 2,843.06 3564.80	1,489.06
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 4.00	3.00
Prepared / Adjusted By	:	GUO QIANG (LKK)
Arc / Surveyor Sing Off Date	: 02/02/2018 08:49:25 AM	02/02/2018 04:44:47 AM
		

Prepared / Adjusted Date :

Remarks :

Prepared Date : 02/02/2018 08:49:25 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1802-0264

Invoice No :

Quotation Date : 2/8

Invoice Date :

Invoice Amount :

Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH REAR PORTION ✓	676.00	200.00
Total Labour	676.00	200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER ✓	378.00	200.00
TO RESPRAY FILLER RR BUMPER RH ✗	180.00	0.00
TO RESPRAY REAR BUMPER REINFORCEMENT ✗	180.00	0.00
Total Spray Painting & Panel Beating	738.00	200.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
Total Other Costs	340.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
5215947913			COVER, RR BUMPER ASSY <i>cut</i>	1	423.90	25.00	317.92	Replace	Replace	No ☒
5257547040			RETAINER, RR BUMPER, RH <i>MC</i>	1	112.70	25.00	84.52	Replace	Replace	No ☒
5256547900			FILLER, RR BUMPER, RH <i>XNN</i>	1	119.90	25.00	89.93	Replace	Check	No ☒
5246247030			PAD, RR BUMPER, RH & LH, 1 <i>MC</i>	1	3.80	25.00	2.85	Replace	Replace	No ☒
5246247020			PAD, RR BUMPER, RH & LH, 2 <i>MC</i>	1	3.80	25.00	2.85	Replace	Replace	No ☒
5246247010			PAD, RR BUMPER, RH & LH, 3 <i>MC</i>	1	3.80	25.00	2.85	Replace	Replace	No ☒
5219147030			SEAL, RR BUMPER ARM, RH & LH <i>MC</i>	1	11.00	25.00	8.25	Replace	Replace	No ☒
5245347010			GUARD, RR BUMPER, LOWER <i>scr</i>	1	558.30	25.00	418.72	Replace	Replace	No ☒
5216947020			COVER, GUARD RR BUMPER LOWER <i>ms</i>	1	14.80	25.00	11.10	Replace	Replace	No ☒
5202347030			REAR BUMPER REINFORCEMENT <i>XNN</i>	1	318.80	25.00	239.10	Replace	Check	No ☒
			PIXEL STICKER <i>MC</i>	1	60.00	0.00	60.00	Replace	Replace	No ☒
			SENSOR REVERSE <i>NW</i>	1	180.00	0.00	180.00	Replace	Replace <i>S</i>	No ☒
TOTAL MATERIALS							1,418.10	1,089.06		
TOTAL MATERIALS(Discounted)							1,418.08	1,089.06		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
		SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No
TOTAL SUPPLEMENTARY MATERIALS						180.00			

1,089.06
200
+ 200

1,489.06



Thatcham escribe

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18002196/Gvbn2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 21-02-2018



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKD 6621S	Veh. Inspected	SHF 248B
Policy No.	5088247237	Coverage (\$)	0.00
Claim No.	MT/0980412-002	Excess (\$)	0.00
Assign From		Assign Date	02/02/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS HYBRID	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FUX03576384	Colour	MAROON
Odometer	8376	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	YOKOHAMA	9 mm
L/H Front Tyre	195/65 R15	YOKOHAMA	9 mm
R/H Rear Tyre	195/65 R15	YOKOHAMA	9 mm
L/H Rear Tyre	195/65 R15	YOKOHAMA	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	31/01/2018	Inspection Date	02/02/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 248B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	COVER RR BUMPER ASSY (DISC 25%)	CUT	423.90	317.92
1	RETAINER,RR BUMPER,RH (DISC 25%)	NECESSARY	112.70	84.52
1	PAD,RR BUMPER,RH & LH,1 (DISC 25%)	NECESSARY	3.80	2.85
1	PAD,RR BUMPER,RH & LH,2 (DISC 25%)	NECESSARY	3.80	2.85
1	PAD,RR BUMPER,RH & LH,3 (DISC 25%)	NECESSARY	3.80	2.85
1	SEAL RR BUMPER ARM RH & LH (DISC 25%)	NECESSARY	11.00	8.25
1	GUARD,RR BUMPER LOWER (DISC 25%)	SCRATCHED	558.30	418.72
1	COVER,GUARD RR BUMPER LOWER (DISC 25%)	MISSING	14.80	11.10
1	PIXEL STICKER (SN)	NECESSARY	60.00	60.00
1	SENSOR REVERSE (SN)	NOT WORKING	180.00	180.00
1	FILLER RR BUMPER RH	NOT NECESSARY	119.90	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	318.80	-
			1,810.80	1,089.06
LABOUR				
THATCHAM STANDARD REPAIR TIME ON BODY WORKS.			756.00	200.00
THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.			838.00	200.00
TO REPLACE SUNDRY PARTS.			100.00	-
TO WASH AND VACUUM.			60.00	-
			1,754.00	400.00
GRAND TOTAL			3,564.80	1,489.06
RECOMMENDED COST OF REPAIRS (CONFIRMED)				1,489.06

Report Ref No. NS/INC18002196/Gvbn2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.