

320 UBI ROAD 3 SINGAPORE 408649 ACCIDENT REPAIR ESTIMATES

Our Ref:			
Type of Claim :	TP	Vehicle No.	: GBA9690U
Type of Glaim .		Make & Model	: NISSAN URVAN PANEL L
		Year of Manufacture	: 2008
		Chassis No.	: JN1MG4E25Z0781103
Ins Company :	AIG	Engine No.	: ZD30166046K
Excess :		Policy No.	:
Date of Accident :	31/01/2018	Time of Accident	1650
Suggested Days of Repair	: <u></u> -	In-house Vehicle Asses	ssor
Repair Estimates	1	Case Owner	: ANIKKA
		Signature	
Parts (a) Cost / List Price I	tems \$5,046.50	Contact No	HERBORY STEEL
Plus/Less30	% \$(1,513.95)		
Total of Cost / Lis	st \$3,532.55	68485725 – ANIKKA	
(b) Nett Price Items	\$-		
Less			
Total of Nett Item			
(c) Special Nett Items	\$417.00		
Total Parts Cost (Appendi	(x A) \$3,949.55		
Labour (Appendix B)	\$3,300.00		
Total Repair Cost	\$7,249.55		
The above total will be subj	ected to 7% G.S.T.		
Name of Surveyor	. (· Biana - 8	2880282
Company	- Gu	o aigng - 8	
Survey conducted on	07/	2/18 at	
Remarks By Surveyor	./	7	lung gun Nepat.
(a) The repair of this veh	icle is authorized / is not auti	norized until further notice.	After near phos.
(b) Recommended Days	A	day(s)	After near phosis
(c) Resurvey	: Required / No		
(d) Excess	:\$		
(e) Signature of surveyor		Date:	

Spark Car Care

ComfortDelGro Engineering Pte Ltd 320 UBI ROAD 3 SINGAPORE 408649 TEL:68438723/68438736 Fax:67436072

Spare Parts

Vehicle No	: GBA9690U Case Owner : TP	
Make & Model	: NISSAN URVAN PANEL LWB 3.0 Year Manufacture : 2008	
Chassis No	: JN1MG4E25Z0781103 Engine No : ZD30166	046K
Sales Order	: Supplier :	
Order By	: Type of Claim :	

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition Surveyor
1	REAR WINDSCREEN X	1		\$255.00			
2	REAR WINDSCREEN MOULDING X	1		no use			
3	INNER SEAL TAPE / (MCL	1		-		\$20.00	1
4	SEALANT /	1		-		\$40.00	/
5	TAIL GATE / the	1		\$1,875.50	/		
6	TAILGATE LAMP LH ASSY 1 (COA	1		\$80.00	1		
7	TAILGATE LAMP RH ASSY 7	1		\$80.00	/		
8	TAILGATE LAMP CLIPS 8 / MGC .	8		\$40.00	/		
9	TAILGATE WEATHERSTRIP ? / Tim .	1		\$136.00	1		
10	TAILGATE LOCK / 67	1		\$323.00	/		
11	TAILGATE GATCH / 5T	1		\$35.00	/		
12	HYDROLIC HINGE RH X /	1		\$68.00			
13	HYDROLIC HINGE LH X	1		\$68.00			
14	LHR CORNER PANEL X	1					
15	RHR CORNER PANEL X	1		-			
16	EMBLEM LOGO (REAR) / 166	1		\$59.50	/		
17	FLOOR PANEL X Regar.	1					
18	FLOOR PANEL TOP GARNISH ".	1		-			
19	REAR BUMPER / Cut	1		\$255.00	1		
20	REAR BUMPER CLIPS / MC.	10		\$50.00	/		
21	REVERSE SENSOR ?	1				\$200.00	
22	REAR NUMBER PLATE / SUI	1				\$45.00	/
23	THIRD BRAKE LIGHT X NV	1		no use			
24	REAR BUMPER REINFORCEMENT ?	1		\$154.00			
25	REAR BUMPER SPONGE .	1		no use			
26	REAR BUMPRR BRACKET RH ?	1		\$15.00			
27	REAR BUMPRR BRACKET LH ?	1		\$15.00			
28	REAR BUMPER RETAINER RH	1		\$25.00			
29	REAR BUMBER RETAINER LH	1		\$25.00			
30	REAR NUMBER PLATE LAMP GARNISH / 2	21		\$127.50	/		

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

305

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax:62844284,62815767

Spare Parts

Vehicle No	:	GBA9690U	Case Owner		TP
Make & Model	:	NISSAN URVAN PANEL LWB 3.0	Year Manufacture	:	2008
Chassis No	:	JN1MG4E25Z0781103	Engine No	***	ZD30166046K
Sales Order	:	0	Supplier		0
Order By		0	Type of Claim		0

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition Surveyor
31	SPARE TYER BRACKET X	1		\$85.00			
32	EXHAUST MUFFLER X	1		\$1,275.00			
33		1					
34		1					
35		1					
36		1					
37		1					
38		1					
39		1					
40		1					
41		1					
42		1					
43		1					
44		1					
45		1					
46		1					
47		1					
48		1					
49		1					
50		1					
51		1					
52		1					
53		1					
54		1					
55		1					
56		1					
57		1					
58		1					
59		1					
60		1					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care ComfortDelGro Engineering Pte Ltd

320 UBI ROAD 3 SINGAPORE 408649 Tel: 68438723/68438736 FAX: 67436072

Labour

Vehicle No. :	GBA9690U	Case Owner	:	ANIKKA	
Make & Model:	SAN URVAN PANEL LWB 3.0	Year of Manufacture	:	2008	

S/No	Labour Description	Esimated Price	Adjusted Price
1	TO KNOCK,WELD,STRAIGHTEN AND REPLACE DAMAGE PARTS	\$1,800.00	400
2	TO PUTTY AND SPRAY TAILGATE,FLOOR PANEL,REAR-BUMPER, AND AFFECTED AREA	\$1,200.00	406
3	TO REMOVE AND REFIX REAR WINDSCREEN	\$200.00	120
4	TO REWIRING REFIX REVERSE SENSOR	\$100.00	40
			960
	LKK Auto Consultants hence notify the Repairer of the following:		
\exists	To display damaged part(s) during resurvey		
	Third party survey is on a "Without Prejudice" basis No slegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company		
	Acknowledged by Repairer Signature:		
	Date		
=			

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.