

Surveyor: Adrian

ASSIGNMENT (Office)

From (Person): Julie Mangubet of AGI Date/Time: 2/2/18 @ 4:46pm

Estimated Cost: _____ Bill to: _____

OD / TT / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: BDL 3137 Insured: SLE 8511Xat Workshop m/s: MG solution Tel: 62431373of 23 Kaki Bkt Ave 4 #02-03BPolicy No: _____ Claim No: C10001334

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 01/02/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement: _____

Date/Time: 11:47am @ 5/2/18Person Contacted: Ms. HoneyVehicle IN/OUT

Date/Time	Action/Instruction (—) Estimate
	<u>BDL 3137 -X</u>
	<u>SLE 8511X -X</u>
	<u>Adrian finalize L/s \$2400, 7 days</u>
	<u>Red: \$8511.30, 7.8%</u>

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

BDL3137.

Yr Regn:

1992 / Feb.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Hiace

C.C. 2779

Colour:

White.

A/C: Insured / Std / NI / NA

Sp. Reading:

648585

T/Radio: Insured / Std / NI / NA

Eng/No:

LH1138003090

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185 R14C

R:

185 R14C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Viking

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

05/02/18.

Survey held at

MG Solution.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front o/s, Rear o/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP Budget Direct.

RECEIVED 27 APR 2018

Date/Time, File Pass to?



: Preli. Report

1) Typist



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

1

Resurvey No. of Trip:

-

Survey Fee:

Transportation:

) \$ + RS \$ SI

) Photos

) Others

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Report Format:

TP

Lump Sum / L.B. (\$

2400

TOTAL

350



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY

Ref : CS/GAI18002239/Ard3

3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

Date : 05-02-2018



Code : GAI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLE 8511X	Veh. Inspected	BDL 3137
Policy No.		Coverage (\$)	0.00
Claim No.	C10001334	Excess (\$)	0.00
Assign From	JULIE MANGUBAT	Assign Date	05/02/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	01/02/2018	Inspection Date	05/02/2018
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Nivitha (LKK Auto)

From: Julie Mangubat <julie.m@budgetdirect.com.sg>
Sent: Friday, 2 February 2018 4:46 PM
To: sur@lkkauto.com; assignments@lkkauto.com
Cc: Albert Hong
Subject: FW: BDL3137-Pre-Inspection; DOA: 01/02/2018
Attachments: BDL3137 (Pre-Inspection).pdf

Hi Team

Please accept TP survey on a without prejudice basis.
TP workshop requested for Adrian to survey.

Thank you,
-Julie

From: MG Solution [mailto:mg3solution@gmail.com]
Sent: Friday, 2 February, 2018 3:35 PM
To: Claims <claims@budgetdirect.com.sg>
Subject: BDL3137-Pre-Inspection; DOA: 01/02/2018

Dear person in charge,

Please refer to attach file and arrange for pre-inspection.

We prefer our single joint expert as below:

- **ADRIAN LING WAI PING (LKK AUTO CONSULTANTS PTE LTD)**

Thank you.

Best Regards,

Su Wong
MG SOLUTION PTE LTD
No 23 Kaki Bukit Avenue 4
AAS Kaki Bukit Centre
#02-03B Singapore 415933
Tel: 6243 1373 | Fax: 6243 1376

MG SOLUTION PTE LTD

23 Kaki Bukit Ave 4 (South Wing) #02-03B
Vicom Inspection Centre, Singapore 415933
Tel: 6243 1373 Fax: 6243 1376
Co. Reg. No. : 201427944N

Date : 02/02/2018

To : AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED By Fax & Email
Tel : 6721 2111
Fax : 6725 0611
Email : claims@budgetdirect.com.sg #Vehicle In#
BDL 3137

Attn: Motor Claims Department

Dear Sir,

Re: **Accident involving motor vehicle Nos.** BDL 3137 and SLE 8511X along
EWBDS LINK TOWARDS HOUGANG AVE 2 on 01/02/2018

We are instructed by Nh CHOW JOO (Name of Claimant) to notify
you of a road traffic accident on the above mentioned. A copy of the Singapore Accident
Statement / Traffic Police Report filed is enclosed.

As a result of the accident, our client's / customer's vehicle has been damaged. Before our client
/ we proceed to repair the damaged vehicle, please let us know within **2 working days** of your
receipt of this notice whether you or your insurer would like to conduct a **Pre- Repair Survey** of
the vehicle. If we do not receive any reply from you within the stipulated timeline, our client / we
shall proceed to repair the vehicle without further reference to you.

Thank you.

Yours faithfully,



MS. HENG YOKE HONG
HP: 9188 6931

FOR SURVEYOR

Please initial here after completion of pre-repair
inspection. Thank you.

Appointed Surveyor: _____
(Name & Signature)

Date & Time of Inspection: _____



Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 01/02/2018 17:23		Vide Report No.: G/20180201/0122		Station Diary No.:	
Informant's Particulars					
Name of Informant: YAP SEE YEE			Address: APT BLK 402 WOODLANDS ST 41 #5-122 HDB- WOODLANDS SINGAPORE 730402		
ID Type / ID No.: FIN NO / G2239551W			Contact No.: Home/Office: Mobile: 84591484		
Nationality: MALAYSIAN			Email:		
Sex: Male	Age: 34	Date of Birth: 07/06/1983	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: CONSTRUCTION WORKER			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 01/02/2018 14:30	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 EUNOS LINK HOUGANG AVENUE 3				
Weather: Drizzling		Road Surface: Wet		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
BDL3137	Van				Slightly Damaged	0
SLE8511X	Car				Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20180201/2137

CONTINUATION OF REPORT

Driver			
Name	YAP SEE YEE	ID No.	G2239551W
Related Vehicle	BDL3137 (Van)	Contact No.	84591484
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	LAI LIEW MIN	ID No.	G0841256T
Related Vehicle	SLE8511X (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

ON THE ABOVE MENTIONED DATE AND TIME

I WAS DRIVING ALONG EUNOS LINK TOWARDS HOUGANG AVENUE 2 ON THE 4TH LANE WHEN SUDDENLY A CAR(SLE8511X) TURNED LEFT OUT OF 3RD LANE INTO MY LANE. I SWERVED LEFT TO TRY AND AVOID THE CAR BUT WE STILL COLLIDED. THE RIGHT SIDE OF MY VEHICLE COLLIDED WITH THE LEFT SIDE OF THE CAR. I CALLED THE AMBULANCE BUT NO ONE WAS CONVEYED. POLICE ALSO CAME.



**SINGAPORE
POLICE FORCE**



T/20180201/2137

3 of 3

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20180201/2137

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

TP /

MUHAMMAD SYUKRI BIN ABU BAKAR

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

Staff Sgt MOHAMED SUFIAN BIN SUDIN

Contact No.: 65476367

Signature Of Informant:

Date/Time:

01/02/2018 17:23

Classification Of Case:



**SINGAPORE
POLICE FORCE**

Authentication Stamp

NP168

JABATAN PENGANGKUTAN JALAN MALAYSIA

PENDAPATAN PERAKUAN PENDAFTARAN KENDERAAN



NO PENDAFTARAN: BDL3137

MSR 0545097

Nama Pemunya Berdaftar: NG CHOON JOO

191002016043
[MAL]

Alamat: NO 95-B LORONG MARIAM PONTIAN
82000 JOHOR BAHRU JOHOR D.T.

No. Enjin	3L-2108876	B D M/B.G.K	-
No. Chasis	LH113-8003090	B T T	-
Buatan	TOYOTA	Berat Kerb	-
Nama Model	HIACE LH113R-RRMR5	B T M	-
Kapasiti Enjin	2779 C.P	B G 1	-
Bahan Bakar	DIESEL	B G 2	-
Warna	PUTIH	B G 3	-
Kelas Kegunaan	P50N-JIP/VAN/BAS/XVN IND	B G 4	-
Jenis Badan	WINDOW VAN	B G 5	-
Tahun Dibuat	1992	B G 6	-
Tarikh Pendaftaran	26/02/1992	B G 7	-
Status Pemunya	PERSENDIRIAN	B G 8	-
Muatan Tempak		B G 9	-
Duduk	12 (2 termasuk pemandu dihadapan)	B G 10	-
Kadar Lesen		B G 11	-
Kenderaan Motor	6 bulan 12 bulan	B G 12	-
	RM643.20 RM1,226.40		

Tandatangan Pemunya Berdaftar

Pendaftaran ini dikeluarkan
oleh Pengerah JPJ Negeri: KUALA LUMPUR JPJ, NEGARA JOHOR KED

PERAKUAN TERPAPAN

UNTUK KEGUNAAN PEJABAT

1
2
3
4
5
6
7
8
9
10
11
12
13

NOTA PENTING

1. Simpan perakuan ini di tempat yang selamat. Jika perakuan ini hilang, anda dikehendaki melaporkan kepada belia polis dengan segera dan memohon salinan perakuan pendaftaran daripada Pengerah Jabatan Pengangkutan Jalan (JPJ).
2. Semak butiran-butiran kenderaan di muka ini dan laporkan dengan segera kepada Pengerah JPJ jika terdapat sebarang perubahan.
3. Lesen kenderaan motor yang sah hendaklah semasa dipamerkan. Anda boleh membatalkan lesen LD dan sebelum tempohnya tamat.
4. Anda dikehendaki melaporkan secara bertulis dengan segera kepada Pengerah JPJ sekiranya kenderaan anda tidak berfungsi.
5. Jika anda menjual kenderaan, beritahu perakuan pendaftaran ini kepada pembeli. Anda dan pembeli dikehendaki mengisi dan menyerahkan borang JPJ 3 JPJ 3A kepada Pengerah JPJ dalam tempoh 14 hari dari tarikh penjualan itu.
6. Pemunya berdaftar kenderaan adalah bertanggungjawab di atas segala urusan berkaitan dengan kenderaan sehingga pertukaran matrik telah disempurnakan dan kenderaan telah didaftarkan dengan matrik penuh.
7. Jika sahaja anda bertukar, kemukakan perakuan pendaftaran ini kepada Pengerah JPJ dalam tempoh 14 hari dari tarikh pertukaran itu.

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email : mg3solution@gmail.com

TO	: AUTO & GENERAL INSURANCE	DATE	: 02/02/2018
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: TP CLAIM
ESTIMATE REPORT	:		
VEHICLE DETAILS			
VEHICLE NO	: BDL3137		
MODEL	: TOYOTA HIACE DIESEL		
CHASSIS NO			
ACCIDENT DETAILS		DATE	: 1-Feb-18
		TIME	: 14:30HRS
THIRD PARTY REQUESTOR / CONTACT		:	JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT WINDSCREEN MOULDING <i>new</i>	1	\$ 180.00	\$ 180.00
2	FRONT PANEL <i>Dented</i>	1	\$ 1,600.00	\$ 1,600.00
3	FRONT BUMPER <i>replaced</i>	1	\$ 511.20	\$ 511.20
4	FRONT BUMPER RETAINER RH <i>new</i>	1	\$ 55.00	\$ 55.00
5	HEADLAMP RH <i>new</i>	1	\$ 255.60	\$ 255.60
6	HEADLAMP HOUSING RH <i>cracked</i>	1	\$ 103.00	\$ 103.00
7	SIDE LAMP RH <i>cracked</i>	1	\$ 185.00	\$ 185.00
8	FRONT DOOR <i>Dented</i>	1	\$ 1,233.60	\$ 1,233.60
9	FRONT DOOR SIDE MIRROR <i>Replaced</i>	1	\$ 380.00	\$ 380.00
10	REAR FENDER <i>Repaired</i>	1	\$ 2,500.00	\$ 2,500.00
11	REAR FENDER MUDFLAP <i>2pc</i>	1	\$ 95.00	\$ 95.00
12	REAR END PANEL	1	\$ 650.00	\$ 650.00

3786.8

2840.10

TOTAL PRICE \$ 7,748.40

MINUS 25% \$ 1,937.10

SUB TOTAL PRICE \$ 5,811.30

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT PANEL SEALANT <i>new</i>	1	\$ 120.00	\$ 120.00

2	FRONT BUMPER CLIP(SET) <i>m</i>	1	\$ 20.00	\$ 20.00	
3	FRONT WIDSCREEN SEALANT <i>3m</i>	1	\$ 120.00	\$ 120.00	40
4	FRONT WIDSCREEN INNER SEAL	1	\$ 120.00	\$ 120.00	40
5	REAR FENDER SEALANT <i>3m</i>	1	\$ 120.00	\$ 120.00	x 140
6	REAR END PANEL SEALANT <i>3m</i>	1	\$ 120.00	\$ 120.00	x

TOTAL \$ 620.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$1,800.00	<i>8w.</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$1,600.00	<i>600</i>	
3	WIRING CHECK	\$80.00	<i>30</i>	
4	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$250.00	<i>50</i>	
5	REFOCUS HEADLAMP BEAM	\$80.00	<i>x</i>	
6	REMOVE AND REFIX DASHBOARD AND INTERNAL WIRING	\$550.00	<i>x</i>	
7	REMOVE AND REFIX FRONT WINDSCREEN	\$120.00	<i>100</i>	

TOTAL \$ 4,480.00

1580

ESTIMATE REPORT

TOTAL PARTS COST : \$ 6,431.30

TOTAL LABOUR COST : \$ 4,480.00

TOTAL REPAIR COST : \$ 10,911.30

EXCESS :

NO. OF DAYS :

RE-SURVEY :

PART BY PART OR LUMP SUM :

DATE & TIME OF SURVEY :

SURVEYED BY :

CONTACT NUMBER :

FAX NUMBER :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj *total 4560.10*
L/s 05/02/18 *L/s: 2.4K*
07 days.
L/s \$2.4K.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI18002239/Ard3n2

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHOPPING CENTRESINGAPORE

239924

Date : 03-05-2018



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLE 8511X	Veh. Inspected	BDL 3137
Policy No.		Coverage (\$)	0.00
Claim No.	C10001334	Excess (\$)	0.00
Assign From	JULIE MANGUBAT	Assign Date	02/02/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HIACE	c.c	2779
Engine No.	HIDDEN	Year of Reg.	1992
Chassis No.	LH1138003090	Colour	WHITE
Odometer	648585	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185 R14C	VIKING	6 mm
L/H Front Tyre	185 R14C	VIKING	6 mm
R/H Rear Tyre	185 R14C	VIKING	6 mm
L/H Rear Tyre	185 R14C	VIKING	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S AND REAR O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	01/02/2018	Inspection Date	05/02/2018
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **7 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. BDL 3137

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT WINDSCREEN MOULDING	NECESSARY	180.00	180.00
1	FRONT PANEL	DENTED	1,600.00	1,139.00
1	FRONT BUMPER	DEFORMED	511.20	511.20
1	FRONT BUMPER RETAINER RH	NECESSARY	55.00	55.00
1	HEADLAMP RH	NOT NECESSARY	255.60	-
1	HEADLAMP HOUSING RH	CRACKED	103.00	103.00
1	SIDE LAMP RH	CRACKED	185.00	185.00
1	FRONT DOOR	DENTED	1,233.60	1,233.60
1	FRONT DOOR SIDE MIRROR	DAMAGED	380.00	380.00
1	REAR FENDER	TO REPAIR SEE LABOUR	2,500.00	-
1	REAR FENDER MUDFLAP	NOT NECESSARY	95.00	-
1	REAR END PANEL	NOT NECESSARY	650.00	-
	LESS 25% DISCOUNT		-1,937.10	-946.70
			5,811.30	2,840.10
<u>SPECIAL NETT ITEMS</u>				
1	FRONT PANEL SEALANT (SN)	NECESSARY	120.00	40.00
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	20.00	20.00
1	FRONT WINDSCREEN SEALANT (SN)	NECESSARY	120.00	40.00
1	FRONT WINDSCREEN INNER SEAL (SN)	NECESSARY	120.00	40.00
1	REAR FENDER SEALANT (SN)	NOT NECESSARY	120.00	-
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	120.00	-
			620.00	140.00
<u>LABOUR</u>				
	PANEL BEATING, REMOVING AND REPLACING PARTS. INCLUSIVE OF THE REPAIR OF REAR FENDER.		1,800.00	800.00
	SPRAY PAINTING TO AFFECTED AREA.		1,600.00	600.00
	WIRING CHECK.		80.00	30.00
	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR.		250.00	50.00
	REFOCUS HEADLAMP BEAM.	NOT NECESSARY	80.00	-
	REMOVE AND REFIX DASHBOARD AND INTERNAL WIRING.	NOT NECESSARY	550.00	-

Report Ref No. CS/AGI18002239/Ard3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE AND REFIX FRONT WINDSCREEN.		120.00	100.00
			4,480.00	1,580.00
	GRAND TOTAL		10,911.30	4,560.10
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,400.00

Report Ref No. CS/AGI18002239/Ard3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.