

PRS

ASS. REC BY: REF: (33) 491761 0953 / 0961 Special Instruction:

Surveyor: Richard ASSIGNMENT (Officer)

From (Person): Khoo Kay Eng of LCR Date/Time: 02-07-2018

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SR3172D Insured: SHAWEN

at Workshop m/s: 3 motorweldz Tel: 9797 2800

of: 25 Kak Bukit Road 4 #01-42

Policy No: 00PMA95145 Claim No: 4116 028 108567

Sum Insured: Excess:

Make of Veh: D.O.A. 5/6/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS / up

Date/Time: 6/6/2017 10:10AM Person Contacted: say Vehicle: IN / OUT

H.O.D. Endorsement

Date/Time	Action/Instruction (*) Estimate
	survey: 6/6/2017; dismantle: 6/6/2017; other repair: 8/6/2017
08/02/18	To submit 1/S 3250/- with 4 days of rep. (Red to 4650, 59% PRS photos scan)

- Most parts cannot clearly see the damage.

- MERCEDES, accident at Customs. low impact speed accident.

- OI GIA report not available.

ACCIDENT

R.

RECEIVED 6 6 JUL 2018

M23

PICHAYO

REF: 016

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SJR 31720
 at Workshop in/s: 3 motor vehicle
 of: 25kaki Bukit Road 4 #01-42

Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Ven: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bar or Market Value _____
 (DAC Accident Report) Consistent? Yes or No _____
 G/A PR Seen Consistent? Yes or No _____
 Est. Repairs 4 days Res: Yes or No _____
 Lum Sum: _____ % 3 Val Yes or No _____

CA / REV / REP. / 24 HRS imp

Vehicle IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJR 31720 Yr Regn: 2009 18/1
 Type: (M.Car) M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA CAMRY cc: 1998
 Colour: WHITE A/C: Insured / Std / NI / NA
 So Reading: 17547 TRadio: Insured / Std / NI / NA
 Eng No: _____

C/No: MR 53 B 010 3524Gen Cond: Good / Fair / Poor / BurntSteering: (Inorder) Jammed / Leaked / Burnt orBrake: (Inorder) Jammed / Leaked / Burnt orModi: Nil / SiRim / STD A/Rim orTyre Size F: 215/60 R16R: 215/60 R16BS / DUN / EXNOVA / GY / FS / LIZA / (MIC) OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R Bal: _____ mm R Bal: _____ mm

L Bal: _____ mm L Bal: _____ mm

D.O.A. 07/6/12 D.O.I. 6/6 12pmSurvey held at: 3 Motor VehicleDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date: _____ Time: _____ Action / Instruction: _____

08/12 Date File Pass to?

1516-19019

Date/Time File Return to?

☐ : Prelim. Report
☐ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: _____

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee

Transportation

} S+RS S:

} Photos

} Others

}

TOTAL

180

20

200

Report Format: pre 7PLump Sum / I.B.A. (\$) 3750



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CS3/LCR17010953/qb-1		
78 SHENTON WAY #08-16 CHARTIS BUILDINGS SINGAPORE 079120		Date : 05-02-2018		
		Code : LCR		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLG 2500G	Veh. Inspected	SJR 3172D	
Policy No.		Coverage (\$)	0.00	
Claim No.	4716038108SG003	Excess (\$)	0.00	
Assign From	KHOO KAY ENG	Assign Date	02/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	05/06/2017	Inspection Date	05/02/2018	
Survey held at	3 MOTORWERKZ 25 KAKI BUKIT ROAD 4 SYNERGY @ KB #01-42 SINGAPORE 417800			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Catherine Chong (LKK Auto)

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Sent: Friday, 2 February, 2018 10:02 AM
To: assignments
Subject: FW: Paper Reinspection SJR3172D: Our Ref: 4716038108SG003; Your Ref: CS3/LCR17010953/JH3E2
Attachments: 4716038108SG LKK TO DO PAPER SURVEY.pdf
Importance: High

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Khoo, Kay-Eng [mailto:Kay-Eng.Khoo@aig.com]

Sent: Friday, 2 February 2018 9:40 AM

To: SUR <sur@lkkauto.com>

Subject: Paper Reinspection SJR3172D: Our Ref: 4716038108SG003; Your Ref: CS3/LCR17010953/JH3E2

Importance: High

Dear M/S LKK Auto Consultants,

We refer to the above captioned matter and attach TP survey report and photos on said vehicle SJR3172D for your reference.

We note that pre and post repair inspection were done by your good office earlier.

Please proceed with a paper inspection (taking reference to the earlier inspections done at your end) and let us have your recommendation for repair cost for the said vehicle.

Appreciate if you can let us have the report within the next 7 days (ie by 08th Feb 2018)

Thank you in anticipation.

Khoo Kay Eng

AIG

Senior Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1026 | Fax +(65) 6835 7416

kay-eng.khoo@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/06/2017 12:52
Date Of Accident	05/06/2017 08:30
Exact Location Of Accident	SINGAPORE TUAS CHECK POINT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJR3172D
Insured/Policyholder	
Name Of Registered Owner	SAMSIAM BTE MOHAMED AMIN
NRIC No	S1289503H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91064417
Alternative Phone No	OFFICE-68469975

Vehicle Particulars

Manufacturer	TOYOTA
Model	CAMRY-2.0 ABS AIRBAG (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5069822498-02
Cover Note Number	5069822498-02

Driver

Name of Driver	OMAR BIN SELAMAT
NRIC No	S1163970D
Date Of Birth	12/02/1956
Occupation	INDOOR
Date Of Driving Pass	03/01/1980
Driving Experience	37 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	OMARSELAMAT2003@YAHOO.COM.SG

Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured SPOUSE

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION- HEAD TO REAR (TP HIT INSURED)

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? YES

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

ON 5/6/17 @ 8.30AM WHILE QUEUING UP AT SINGAPORE TUAS CHECK POINT SURENLY A CAR SLG2500G HIT MY CAR FROM BEHIND. BOTH OF US ALIGHTED AND EXCHANGE PARTICULARS.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Remarks/ Reasons: UPOUN REQUEST

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLG2500G

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF INJURED PERSON 1

Name	OMAR BIN SELAMAT
Approximate Age	61
Injuries Sustain	REFER TO MEDICAL REPORT
Injured person in which vehicle?	SJR3172D
Were seat belts worn?	YES
Was injured conveyed to hospital by ambulance?	NO
Address	BLK 104 LENGKONG TIGA #02-355
Postcode	S410104

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time
12:42
Sketch Plan

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

TUAS CHECK POINT

ICA
COUNTER A = 5JR317

[B] [A] [] [] []

B = 526 2500

Print
Print size: 100%

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 9503H

Vehicle Details

Vehicle No: SJR3172D
Vehicle to be Exported: No
Intended De-registration Date: 06 Jun 2017
Vehicle Make: TOYOTA
Vehicle Model: CAMRY 2.0 AUTO ABS AIRBAG
Primary Colour: White
Manufacturing Year: 2009
Engine No.: 1AZE131566
Chassis No: MR053BK4107043526
Maximum Power Output: 108.0 kW (144 bhp)
Open Market Value: \$25,948.00
Original Registration Date: 18 Jun 2009
First Registration Date: 18 Jun 2009
Transfer Count: 4
Actual ARF Paid: \$25,948.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 17 Jun 2019
PARF Rebate Amount: \$15,568.00

Intended COE Rebate Details

COE Expiry Date: 17 Jun 2019
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
QP Paid: \$7,552.00
COE Rebate Amount: \$1,533.00
Total Rebate Amount: \$17,101.00

The information contained herein is correct as at 06 Jun 2017

OK

Land Transport Authority

Please read through the [Privacy Statement](#), [Terms of Use](#) and [Disclaimer](#).
Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.
Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution.
Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate the e-Service](#)
Last updated on 28 May 2017 at 12:58 AM

MOTORCAR PARTS

2JR 3172 D

NAME	QTY	UNIT	CONCAT
1171 990126 Rear Number Plate			
1172 990127 Rear Number Plate Base			
1173 990130 Rear Number Plate Trim			
1174 990132 Rear Number Plate Lamp			
1175 990133 Rear Bumper			BB ✓
1176 990134 Rear Bumper Upper			
1177 990135 Rear Bumper Lower			
1178 990136 Rear Bumper Side			
1179 990137 Rear Bumper Top Cover			
1180 990138 Rear Bumper Cross			NR ✓ 1
1181 990139 Rear Bumper Bracket			
1182 990140 Rear Bumper Side Panel			BS ✓ 2
1183 990141 Rear Bumper Front Mounting			BR ✓ 1
1184 990142 Rear Bumper Beam			
1185 990143 Rear Bumper Springs			
1186 990144 Rear Bumper Damper			
1187 990145 Rear Bumper Protector			
1188 990146 Rear Bumper Pad			
1189 990147 Rear Bumper Mounting			
1190 990148 Rear Bumper Reflector			SR ✓ 1
1191 990149 Rear Bumper Lower Spoiler			
1192 990150 Reverse Sensor			SR ✓ 1
1193 990151 Rear End Panel			DS ✓ 1
1194 990152 Rear End Panel Top Garnish			DS ✓ 1
1195 990153 Rear End Panel Inner Trim			
1196 990154 Boot Compartment Inner Trim			
1197 990155 Rear LH Tail Lamp			
1198 990156 Rear LH Tail Lamp Garnish			
1199 990157 Rear LH Tail Lamp Panel			
1200 990158 Rear LH Tail Lamp Base			
1201 990159 Rear LH Tail Lamp Reflector			
1202 990160 Rear LH Tail Lamp Mounting			
1203 990161 Rear LH Tail Lamp Bracket			
1204 990162 Rear LH Tail Lamp Cross			
1205 990163 Rear LH Tail Lamp Side			
1206 990164 Rear LH Tail Lamp Top			
1207 990165 Rear LH Tail Lamp Bottom			
1208 990166 Rear LH Tail Lamp Mounting			
1209 990167 Rear LH Tail Lamp Bracket			
1210 990168 Rear LH Tail Lamp Cross			
1211 990169 Rear LH Tail Lamp Side			
1212 990170 Rear LH Tail Lamp Top			
1213 990171 Rear LH Tail Lamp Bottom			
1214 990172 Rear LH Tail Lamp Mounting			
1215 990173 Rear LH Tail Lamp Bracket			
1216 990174 Rear LH Tail Lamp Cross			
1217 990175 Rear LH Tail Lamp Side			
1218 990176 Rear LH Tail Lamp Top			
1219 990177 Rear LH Tail Lamp Bottom			
1220 990178 Rear LH Tail Lamp Mounting			
1221 990179 Rear LH Tail Lamp Bracket			
1222 990180 Rear LH Tail Lamp Cross			
1223 990181 Rear LH Tail Lamp Side			
1224 990182 Rear LH Tail Lamp Top			
1225 990183 Rear LH Tail Lamp Bottom			
1226 990184 Rear LH Tail Lamp Mounting			
1227 990185 Rear LH Tail Lamp Bracket			
1228 990186 Rear LH Tail Lamp Cross			
1229 990187 Rear LH Tail Lamp Side			
1230 990188 Rear LH Tail Lamp Top			
1231 990189 Rear LH Tail Lamp Bottom			
1232 990190 Rear LH Tail Lamp Mounting			
1233 990191 Rear LH Tail Lamp Bracket			
1234 990192 Rear LH Tail Lamp Cross			
1235 990193 Rear LH Tail Lamp Side			
1236 990194 Rear LH Tail Lamp Top			
1237 990195 Rear LH Tail Lamp Bottom			
1238 990196 Rear LH Tail Lamp Mounting			
1239 990197 Rear LH Tail Lamp Bracket			
1240 990198 Rear LH Tail Lamp Cross			
1241 990199 Rear LH Tail Lamp Side			
1242 990200 Rear LH Tail Lamp Top			
1243 990201 Rear LH Tail Lamp Bottom			
1244 990202 Rear LH Tail Lamp Mounting			
1245 990203 Rear LH Tail Lamp Bracket			
1246 990204 Rear LH Tail Lamp Cross			
1247 990205 Rear LH Tail Lamp Side			
1248 990206 Rear LH Tail Lamp Top			
1249 990207 Rear LH Tail Lamp Bottom			
1250 990208 Rear LH Tail Lamp Mounting			
1251 990209 Rear LH Tail Lamp Bracket			
1252 990210 Rear LH Tail Lamp Cross			
1253 990211 Rear LH Tail Lamp Side			
1254 990212 Rear LH Tail Lamp Top			
1255 990213 Rear LH Tail Lamp Bottom			
1256 990214 Rear LH Tail Lamp Mounting			
1257 990215 Rear LH Tail Lamp Bracket			
1258 990216 Rear LH Tail Lamp Cross			
1259 990217 Rear LH Tail Lamp Side			
1260 990218 Rear LH Tail Lamp Top			
1261 990219 Rear LH Tail Lamp Bottom			
1262 990220 Rear LH Tail Lamp Mounting			
1263 990221 Rear LH Tail Lamp Bracket			
1264 990222 Rear LH Tail Lamp Cross			
1265 990223 Rear LH Tail Lamp Side			
1266 990224 Rear LH Tail Lamp Top			
1267 990225 Rear LH Tail Lamp Bottom			
1268 990226 Rear LH Tail Lamp Mounting			
1269 990227 Rear LH Tail Lamp Bracket			
1270 990228 Rear LH Tail Lamp Cross			
1271 990229 Rear LH Tail Lamp Side			
1272 990230 Rear LH Tail Lamp Top			
1273 990231 Rear LH Tail Lamp Bottom			
1274 990232 Rear LH Tail Lamp Mounting			
1275 990233 Rear LH Tail Lamp Bracket			
1276 990234 Rear LH Tail Lamp Cross			
1277 990235 Rear LH Tail Lamp Side			
1278 990236 Rear LH Tail Lamp Top			
1279 990237 Rear LH Tail Lamp Bottom			
1280 990238 Rear LH Tail Lamp Mounting			
1281 990239 Rear LH Tail Lamp Bracket			
1282 990240 Rear LH Tail Lamp Cross			
1283 990241 Rear LH Tail Lamp Side			
1284 990242 Rear LH Tail Lamp Top			
1285 990243 Rear LH Tail Lamp Bottom			
1286 990244 Rear LH Tail Lamp Mounting			
1287 990245 Rear LH Tail Lamp Bracket			
1288 990246 Rear LH Tail Lamp Cross			
1289 990247 Rear LH Tail Lamp Side			
1290 990248 Rear LH Tail Lamp Top			
1291 990249 Rear LH Tail Lamp Bottom			
1292 990250 Rear LH Tail Lamp Mounting			
1293 990251 Rear LH Tail Lamp Bracket			
1294 990252 Rear LH Tail Lamp Cross			
1295 990253 Rear LH Tail Lamp Side			
1296 990254 Rear LH Tail Lamp Top			
1297 990255 Rear LH Tail Lamp Bottom			
1298 990256 Rear LH Tail Lamp Mounting			
1299 990257 Rear LH Tail Lamp Bracket			
1300 990258 Rear LH Tail Lamp Cross			
1301 990259 Rear LH Tail Lamp Side			
1302 990260 Rear LH Tail Lamp Top			
1303 990261 Rear LH Tail Lamp Bottom			
1304 990262 Rear LH Tail Lamp Mounting			
1305 990263 Rear LH Tail Lamp Bracket			
1306 990264 Rear LH Tail Lamp Cross			
1307 990265 Rear LH Tail Lamp Side			
1308 990266 Rear LH Tail Lamp Top			
1309 990267 Rear LH Tail Lamp Bottom			
1310 990268 Rear LH Tail Lamp Mounting			
1311 990269 Rear LH Tail Lamp Bracket			
1312 990270 Rear LH Tail Lamp Cross			
1313 990271 Rear LH Tail Lamp Side			
1314 990272 Rear LH Tail Lamp Top			
1315 990273 Rear LH Tail Lamp Bottom			
1316 990274 Rear LH Tail Lamp Mounting			
1317 990275 Rear LH Tail Lamp Bracket			
1318 990276 Rear LH Tail Lamp Cross			
1319 990277 Rear LH Tail Lamp Side			
1320 990278 Rear LH Tail Lamp Top			
1321 990279 Rear LH Tail Lamp Bottom			
1322 990280 Rear LH Tail Lamp Mounting			
1323 990281 Rear LH Tail Lamp Bracket			
1324 990282 Rear LH Tail Lamp Cross			
1325 990283 Rear LH Tail Lamp Side			
1326 990284 Rear LH Tail Lamp Top			
1327 990285 Rear LH Tail Lamp Bottom			
1328 990286 Rear LH Tail Lamp Mounting			
1329 990287 Rear LH Tail Lamp Bracket			
1330 990288 Rear LH Tail Lamp Cross			
1331 990289 Rear LH Tail Lamp Side			
1332 990290 Rear LH Tail Lamp Top			
1333 990291 Rear LH Tail Lamp Bottom			
1334 990292 Rear LH Tail Lamp Mounting			
1335 990293 Rear LH Tail Lamp Bracket			
1336 990294 Rear LH Tail Lamp Cross			
1337 990295 Rear LH Tail Lamp Side			
1338 990296 Rear LH Tail Lamp Top			
1339 990297 Rear LH Tail Lamp Bottom			
1340 990298 Rear LH Tail Lamp Mounting			
1341 990299 Rear LH Tail Lamp Bracket			
1342 990300 Rear LH Tail Lamp Cross			
1343 990301 Rear LH Tail Lamp Side			
1344 990302 Rear LH Tail Lamp Top			
1345 990303 Rear LH Tail Lamp Bottom			
1346 990304 Rear LH Tail Lamp Mounting			
1347 990305 Rear LH Tail Lamp Bracket			
1348 990306 Rear LH Tail Lamp Cross			
1349 990307 Rear LH Tail Lamp Side			
1350 990308 Rear LH Tail Lamp Top			
1351 990309 Rear LH Tail Lamp Bottom			
1352 990310 Rear LH Tail Lamp Mounting			
1353 990311 Rear LH Tail Lamp Bracket			
1354 990312 Rear LH Tail Lamp Cross			
1355 990313 Rear LH Tail Lamp Side			
1356 990314 Rear LH Tail Lamp Top			
1357 990315 Rear LH Tail Lamp Bottom			
1358 990316 Rear LH Tail Lamp Mounting			
1359 990317 Rear LH Tail Lamp Bracket			
1360 990318 Rear LH Tail Lamp Cross			
1361 990319 Rear LH Tail Lamp Side			
1362 990320 Rear LH Tail Lamp Top			
1363 990321 Rear LH Tail Lamp Bottom			
1364 990322 Rear LH Tail Lamp Mounting			
1365 990323 Rear LH Tail Lamp Bracket			
1366 990324 Rear LH Tail Lamp Cross			
1367 990325 Rear LH Tail Lamp Side			
1368 990326 Rear LH Tail Lamp Top			
1369 990327 Rear LH Tail Lamp Bottom			
1370 990328 Rear LH Tail Lamp Mounting			
1371 990329 Rear LH Tail Lamp Bracket			
1372 990330 Rear LH Tail Lamp Cross			
1373 990331 Rear LH Tail Lamp Side			
1374 990332 Rear LH Tail Lamp Top			
1375 990333 Rear LH Tail Lamp Bottom			
1376 990334 Rear LH Tail Lamp Mounting			
1377 990335 Rear LH Tail Lamp Bracket			
1378 990336 Rear LH Tail Lamp Cross			
1379 990337 Rear LH Tail Lamp Side			
1380 990338 Rear LH Tail Lamp Top			
1381 990339 Rear LH Tail Lamp Bottom			
1382 990340 Rear LH Tail Lamp Mounting			
1383 990341 Rear LH Tail Lamp Bracket			
1384 990342 Rear LH Tail Lamp Cross			
1385 990343 Rear LH Tail Lamp Side			
1386 990344 Rear LH Tail Lamp Top			
1387 990345 Rear LH Tail Lamp Bottom			
1388 990346 Rear LH Tail Lamp Mounting			
1389 990347 Rear LH Tail Lamp Bracket			
1390 990348 Rear LH Tail Lamp Cross			
1391 990349 Rear LH Tail Lamp Side			
1392 990350 Rear LH Tail Lamp Top			
1393 990351 Rear LH Tail Lamp Bottom			
1394 990352 Rear LH Tail Lamp Mounting			
1395 990353 Rear LH Tail Lamp Bracket			
1396 990354 Rear LH Tail Lamp Cross			
1397 990355 Rear LH Tail Lamp Side			
1398 990356 Rear LH Tail Lamp Top			
1399 990357 Rear LH Tail Lamp Bottom			
1400 990358 Rear LH Tail Lamp Mounting			
1401 990359 Rear LH Tail Lamp Bracket			
1402 990360 Rear LH Tail Lamp Cross			
1403 990361 Rear LH Tail Lamp Side			
1404 990362 Rear LH Tail Lamp Top			
1405 990363 Rear LH Tail Lamp Bottom			
1406 990364 Rear LH Tail Lamp Mounting			
1407 990365 Rear LH Tail Lamp Bracket			
1408 990366 Rear LH Tail Lamp Cross			
1409 990367 Rear LH Tail Lamp Side			
1410 990368 Rear LH Tail Lamp Top			
1411 990369 Rear LH Tail Lamp Bottom			
1412 990370 Rear LH Tail Lamp Mounting			
1413 990371 Rear LH Tail Lamp Bracket			
1414 990372 Rear LH Tail Lamp Cross			
1415 990373 Rear LH Tail Lamp Side			
1416 990374 Rear LH Tail Lamp Top			
1417 990375 Rear LH Tail Lamp Bottom			
1418 990376 Rear LH Tail Lamp Mounting			
1419 990377 Rear LH Tail Lamp Bracket			
1420 990378 Rear LH Tail Lamp Cross			
1421 990379 Rear LH Tail Lamp Side			
1422 990380 Rear LH Tail Lamp Top			
1423 990381 Rear LH Tail Lamp Bottom			
1424 990382 Rear LH Tail Lamp Mounting			
1425 990383 Rear LH Tail Lamp Bracket			
1426 990384 Rear LH Tail Lamp Cross			
1427 990385 Rear LH Tail Lamp Side			
1428 990386 Rear LH Tail Lamp Top			
1429 990387 Rear LH Tail Lamp Bottom			
1430 990388 Rear LH Tail Lamp Mounting			
1431 990389 Rear LH Tail Lamp Bracket			
1432 990390 Rear LH Tail Lamp Cross			
1433 990391 Rear LH Tail Lamp Side			
1434 990392 Rear LH Tail Lamp Top			
1435 990393 Rear LH Tail Lamp Bottom			
1436 990394 Rear LH Tail Lamp Mounting			
1437 990395 Rear LH Tail Lamp Bracket			
1438 990396 Rear LH Tail Lamp Cross			
1439 990397 Rear LH Tail Lamp Side			
1440 990398 Rear LH Tail Lamp Top			
1441 990399 Rear LH Tail Lamp Bottom			
1442 990400 Rear LH Tail Lamp Mounting			
1443 990401 Rear LH Tail Lamp Bracket			
1444 990402 Rear LH Tail Lamp Cross			
1445 990403 Rear LH Tail Lamp Side			
1446 990404 Rear LH Tail Lamp Top			
1447 990405 Rear LH Tail Lamp Bottom			
1448 990406 Rear LH Tail Lamp Mounting			
1449 990407 Rear LH Tail Lamp Bracket			
1450 990408 Rear LH Tail Lamp Cross			
1451 990409 Rear LH Tail Lamp Side			
1452 990410 Rear LH Tail Lamp Top			
1453 990411 Rear LH Tail Lamp Bottom			
1454 990412 Rear LH Tail Lamp Mounting			
1455 990413 Rear LH Tail Lamp Bracket			
1456 990414 Rear LH Tail Lamp Cross			
1457 990415 Rear LH Tail Lamp Side			
1458 990416 Rear LH Tail Lamp Top			
1459 990417 Rear LH Tail Lamp Bottom			
1460 990418 Rear LH Tail Lamp Mounting			
1461 990419 Rear LH Tail Lamp Bracket			
1462 990420 Rear LH Tail Lamp Cross			
1463 990421 Rear LH Tail Lamp Side			
1464 990422 Rear LH Tail Lamp Top			
1465 990423 Rear LH Tail Lamp Bottom			
1466 990424 Rear LH Tail Lamp Mounting			
1467 990425 Rear LH Tail Lamp Bracket			
1468 990426 Rear LH Tail Lamp Cross			
1469 990427 Rear LH Tail Lamp Side			
1470 990428 Rear LH Tail Lamp Top			
1471 990429 Rear LH Tail Lamp Bottom			
1472 990430 Rear LH Tail Lamp Mounting			
1473 990431 Rear LH Tail Lamp Bracket			
1474 990432 Rear LH Tail Lamp Cross			
1475 990433 Rear LH Tail Lamp Side			
1476 990434 Rear LH Tail Lamp Top			
1477 990435 Rear LH Tail Lamp Bottom			
1478 990436 Rear LH Tail Lamp Mounting			
1479 990437 Rear LH Tail Lamp Bracket			
1480 990438 Rear LH Tail Lamp Cross			
1481 990439 Rear LH Tail Lamp Side			
1482 990440 Rear LH Tail Lamp Top			
1483 990441 Rear LH Tail Lamp Bottom			
1484 990442 Rear LH Tail Lamp Mounting			
1485 990443 Rear LH Tail Lamp Bracket			
1486 990444 Rear LH Tail Lamp Cross			
1487 990445 Rear LH Tail Lamp Side			
1488 990446 Rear LH Tail Lamp Top			
1489 990447 Rear LH Tail Lamp Bottom			
1490 990448 Rear LH Tail Lamp Mounting			

Claim Documents

*SJR3172D (4716038108SG)
[SLG2500G]








































TP

SAMSIAH BTE MOHAMED AMIN

Jun 5 2017 12:00AM

[LION CITY RENTALS PTE LTD]

3 Motorwerkz Concepts Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View	Use Viewer
Photos/Images							3 per page
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print			
1	07/06/17 13:08	General View	 Load JPG	<input checked="" type="checkbox"/>			
2	07/06/17 13:08	General View	 Load JPG	<input checked="" type="checkbox"/>			
3	07/06/17 13:08	General View	 Load JPG	<input checked="" type="checkbox"/>			
4	07/06/17 13:08	General View	 Load JPG	<input checked="" type="checkbox"/>			
5	07/06/17 13:08	General View	 Load JPG	<input checked="" type="checkbox"/>			
6	07/06/17 13:08	General View	 Load JPG	<input checked="" type="checkbox"/>			
7	07/06/17 13:08	General View	 Load JPG	<input checked="" type="checkbox"/>			
8	07/06/17 13:08	General View	 Load JPG	<input checked="" type="checkbox"/>			
9	07/06/17 13:08	General View	 Load JPG	<input checked="" type="checkbox"/>			
10	07/06/17 13:08	General View	 Load JPG	<input checked="" type="checkbox"/>			
11	07/06/17 13:08	General View	 Load JPG	<input checked="" type="checkbox"/>			
12	07/06/17 13:08	General View	 Load JPG	<input checked="" type="checkbox"/>			
13	07/06/17 13:08	General View	 Load JPG	<input checked="" type="checkbox"/>			
14	07/06/17 13:08	General View	 Load JPG	<input checked="" type="checkbox"/>			
15	07/06/17 13:08	General View	 Load JPG	<input checked="" type="checkbox"/>			
16	07/06/17 13:08	General View	 Load JPG	<input checked="" type="checkbox"/>			
17	07/06/17 13:08	General View	 Load JPG	<input checked="" type="checkbox"/>			
18	07/06/17 13:08	General View	 Load JPG	<input checked="" type="checkbox"/>			
19	07/06/17 13:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>			
20	07/06/17 13:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>			
21	07/06/17 13:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>			
22	07/06/17 13:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>			
23	07/06/17 13:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>			
24	07/06/17 13:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>			
25	07/06/17 13:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>			
26	07/06/17 13:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>			
27	07/06/17 13:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>			
28	07/06/17 13:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>			
29	07/06/17 13:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>			
30	07/06/17 13:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>			
31	07/06/17 13:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>			
32	07/06/17 13:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>			
33	07/06/17 13:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>			
34	07/06/17 13:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>			
35	07/06/17 13:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>			
36	07/06/17 13:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>			
37	07/06/17 13:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>			
38	07/06/17 13:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>			
39	07/06/17 13:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>			

Documents Checklist

DOCUMENTS CHECKLIST

There are no document checklists configured.

Reset

Save

Print

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg No 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com,assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/LCR17010953/JH3E2
Date: 15/06/2017

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999995145
Claimant Vehicle No: SJR3172D Insured Vehicle No: SLG2500G
Date of Loss: 05/06/2017 Nature of Claim: TP Claim No: 4716038108SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJR3172D
Make & Model: TOYOTA CAMRY, 2.0 ABS AIRBAG (A) Engine No: 1AZE131566
Reg. Date: 18/06/2009 (Man. Year: 2009) Chassis No: MR053BK4107043526
Colour: White Odometer: 167547 km
Engine Capacity: 1998 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/60/16 Rear Tyre Size: 215/60/16
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 06/06/2017
Date Inspected: 06/06/2017 Inspected At: 3 Motorwerkz Concepts Pte Ltd (HQ)
25 Kaki Bukit Road 4, Synergy @ KB
#01-40
Singapore 417800
Estimated Period of Repair: 4.0 days

Adjuster: Richard Harjanto

Manager: Ashley Chong Chin Yan

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	0.00 F	*-F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*-F
3	2		*REAR BUMPER SIDE RETAINER	Distorted	0.00 F	*-F
4	1		*REAR BUMPER REINFORCEMENT	Buckled	0.00 F	*-F
5	2		*REAR BUMPER REFLECTOR	Scratched	0.00 F	*-F
6	1		*REVERSE SENSOR	Scratched	0.00 F	*-F
7	1		*REAR END PANEL	Repair	0.00 F	*-F
8	1		*REAR END PANEL TOP GARNISH	Dented	0.00 F	*-F
9	1		*BOOTLID LOCK	Dented	0.00 F	*-F
10	1		*BOOTLID RUBBER WEATHERSTRIP	Buckled	0.00 F	*-F
F=Franchise part						
Total Parts (\$\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

PHOTOCOPY

3 Motorwerkz Concept Pte Ltd

No 25 Kaki Bukit Road 4 #01-40

Singapore 417800

Business Reg. no: 201537992W

INVOICE

Name: Samsiah Bte Mohamed Amin	Date of Invoice: 14/6/2017
3 Motorwerkz Concept Pte Ltd No 25 Kaki Bukit Road 4 #01-40 Singapore 417800	

Claim Type: Third Party	Date of Accident: 5/6/2017
Vehicle Reg No: SJR3172D	Claimant: Samsiah Bte Mohamed Amin
Vehicle Make/Model: Toyota Camry 2.0 Auto	
Description	Amount (S\$)
Lump Sum Repair as per recommendation	7,900.00
Total	7,900.00
Singapore Dollar: Seven thousand and nine hundred dollars only.	

Sincere Appraisal Services

81 Ubi Avenue 4 #06-28 UB.One Singapore 408830

Tel : 6636 4628 Fax : 6636 4638 E-mail : sincereappraisal@gmail.com

Company Registration No. 53159958B

INVOICE

Samsiah Bte Mohamed Amin
C/O 3 Motorwerkz Concept Pte Ltd
25 Kaki Bukit Road 4
#01-40
Singapore 417800

Invoice No: 140617-321
Our ref: 321/TP/2017
Date: 14/6/2017

Claim Type: Third Party

Date of Loss: 5/6/2017

Vehicle Reg No: SJR3172D

Claimant: Samsiah Bte Mohamed Amin

Vehicle Make/Model: Toyota Camry 2.0 Auto

Description	Amount (S\$)
1. Professional Fee (including Transport, 48 Photographs and Miscellaneous charges)	593
Total	593

Singapore Dollar: Five hundred and ninety three dollars only.

Cheques should be crossed A/C PAYEE and made payable to Sincere Appraisal Services



Sincere Appraisal Services

Sincere Appraisal Services

81 Ubi Avenue 4 #06-28 UB.One Singapore 408830

Tel : 6636 4628 Fax : 6636 4638 E-mail : sincereappraisal@gmail.com

Company Registration No. 53159958B

VEHICLE DAMAGE INSPECTION REPORT

Our Ref: 321/TP/2017

Date: 14/6/2017

REFERENCE

Date of loss: 5/6/2017

Claimant: Samsiah Bte Mohamed Amin

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJR3172D	Make &	Toyota
Reg date:	18/6/2009	Model	Camry 2.0 Auto
Colour:	White	Engine No:	1AZE131566
Type:	Motor Car	Chassis No:	MR053BK4107043526
Type of Claims:	Third Party	Odometer No:	167547km
		Engine Cap:	1998cc

CONDITION OF VEHICLE AT THE TIME OF SURVEY (STATIC ONLY)

General Condition: Good	Steering: Good	Engine Modification: Nil
Paint work: Good	Handbrake: Good	Pre-accident
	Footbrake: Good	Damage: Nil

CONDITION OF TYRES

Front Left Size:	Michelin 215/60R16 70%	Front Right Size:	Michelin 215/60R16 70%
Rear Left Size:	Michelin 215/60R16 70%	Rear Right Size:	Michelin 215/60R16 70%

The above percentages represent the remaining life of the tyre threads

COST OF REPAIRS

Parts	Repairer S\$	Adjuster S\$
	\$ 7,852.30	\$ 7,066.08
Labour	\$ 3,380.00	\$ 2,790.00
Calculated Cost (S\$) :	\$ 11,232.30	\$ 9,856.08

Recommended Lump Sum Repair Cost (S\$) : \$ 7,900.00


Date of Assignment: 6/6/2017

Date Inspected: 6/6/2017

Est. repair Period: 07 days

Inspected At: 3 Motorwerkz Concept Pte Ltd
25 Kaki Bukit Road 4
#01-40
Singapore 417800

POINT OF IMPACT



BRIEF CIRCUMSTANCES OF ACCIDENT

The Insured's vehicle collided onto the Third Party's vehicle along Singapore Tuas Check Point.

GENERAL DESCRIPTION OF DAMAGES


Our visual inspection of the vehicle revealed that the damages noted are at the rear portion.

SPECIAL REMARKS

We have inspected the actual damages found on the vehicle and recommend the replacement of parts and repairs accordingly. The estimated repair cost is \$11,232.30. The repairer has agreed to undertake the repairs at our adjusted lump sum amount of \$7,900.

We have not authorised the repair. Under normal circumstances, estimated 07 working days are required to repair the vehicle.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Inspection Report and photographs.



Dave Chang
Automotive Appraiser
AUTO, ENG, CAE, CGI
MIRTE, MSAAA, MTM

Automotive Appraiser: Dave Chang

Please note that this report is solely based on our findings at the time and place of inspection. This inspection has been carried out to our best knowledge and ability. Any other liability is hereby excluded.

ANNEX A

REPAIR DETAILS

Recommended Parts

No	Qty	Description	Condition	Repairer's Amount	Adjuster's Amount	
1	1	Rear bumper assy	dented/cracked	\$ 1,288.90	\$ 1,288.90	✓
2	2	Rear bumper reflector	bent/necessary	\$ 167.10	\$ 167.10	HH -
3	1	Rear bumper right retainer	bent/necessary	\$ 86.40	\$ 86.40	✓
4	1	Rear bumper left retainer	bent/necessary	\$ 86.40	\$ 86.40	✓
5	1	Rear bumper right bracket	bent/necessary	\$ 88.70	\$ 88.70	✓
6	1	Rear bumper left bracket	bent/necessary	\$ 88.70	\$ 88.70	✓
7	1	Rear bumper reinforcement	dented	\$ 393.30	\$ 393.30	✓
8	1	Rear bootlid assy	warped/buckled	\$ 1,476.90	\$ 1,476.90	✓
9	1	Rear bootlid centre logo	necessary	\$ 68.80	\$ 68.80	✓
10	1	Rear bootlid 'Camry' emblem	necessary	\$ 66.40	\$ 66.40	✓
11	1	Rear bootlid '2.0' emblem	necessary	\$ 62.60	\$ 62.60	✓
12	1	Rear bootlid lock mechanism	bent	\$ 252.40	\$ 252.40	✓
13	1	Rear bootlid lock catch	bent	\$ 97.60	\$ 97.60	✓
14	1	Rear bootlid right taillamp	bent/cut	\$ 385.20	\$ 385.20	HH
15	1	Rear bootlid left taillamp	bent/cut	\$ 385.20	\$ 385.20	HH
16	1	Rear bootlid weatherstrip	warped/necessary	\$ 288.10	\$ 288.10	✓
17	1	Rear left taillamp	bent/cut	\$ 792.30	\$ 792.30	HH
18	1	Rear right taillamp	bent/cut	\$ 792.30	\$ 792.30	HH
19	1	Rear end lower panel	repair	\$ 1,048.30	\$ -	
20	1	Rear end lower panel top garnish	bent/necessary	\$ 224.60	\$ 224.60	HH
21	1	Rear exhaust muffler tail end pipe	bent	\$ 179.70	\$ 179.70	HH
22	1	Rear exhaust muffler assy	bent	\$ 1,179.90	\$ 1,179.90	HH
23	2	Rear exhaust muffler rubber mounting	necessary	\$ 36.60	\$ 36.60	HH
Less 25%				\$ 9,536.40	\$ 8,488.10	
				\$ 2,384.10	\$ 2,122.03	
				\$ 7,152.30	\$ 6,366.08	
<u>Special Nett Items</u>						
1	10	Rear bumper clips	necessary	\$ 50.00	\$ 50.00	30/-
2	4	Rear end lower panel top garnish clips	necessary	\$ 20.00	\$ 20.00	20/-
3	2	Rear bumper reverse sensor	malfunction	\$ 250.00	\$ 250.00	220/-
4	1	Rear view camera	malfunction	\$ 300.00	\$ 300.00	42
5	1	Rear no plate with garnish	necessary	\$ 80.00	\$ 80.00	HH
				\$ 700.00	\$ 700.00	
Total parts				\$ 7,852.30	\$ 7,066.08	

ANNEX B

REPAIR DETAILS

Recommended Labour

No	Description	Repairer's Amount	Adjuster's Amount
1	Labour for panel beating, cut, weld, straighten rear affected area and rear damaged parts.	\$ 1,200.00	\$ 1,000.00 800/-
2	To putty and spray painting rear portion.	\$ 1,200.00	\$ 1,000.00 800/-
3	To check rear lighting and wiring.	\$ 50.00	\$ 30.00 40/-
4	To remove and install rear bootlid lock mechanism.	\$ 80.00	\$ 60.00 20/-
5	To remove and install rear exhaust muffler assy.	\$ 100.00	\$ 80.00 40/-
6	To remove and install rear inner trim to facilitate the repair.	\$ 120.00	\$ 100.00 80/-
7	To apply anti rust proofing to rear affected area.	\$ 120.00	\$ 100.00 40/-
8	To remove and install rear bumper reverse sensor.	\$ 80.00	\$ 60.00 40/-
9	To remove and install rear view camera.	\$ 80.00	\$ 60.00 40/-
10	To repair, straighten and align both rear fender assy.	\$ 350.00	\$ 300.00 40/-
Total labour :		\$ 3,380.00	\$ 2,790.00

ANNEX C

REPAIR DETAILS

Adjusted Repair Cost

	Repairer's Amount	Adjuster's Amount
Total parts :	\$ 7,852.30	\$ 7,066.08
Total labour :	\$ 3,380.00	\$ 2,790.00
Total repair cost :	\$ 11,232.30	\$ 9,856.08

Adjusted Repair Cost (Lump Sum Repair)

\$ 7,900.00

4108.02

1/5 3250/-

4 days

Reference No.: C93/LCR70/0953/D36-1
Policy Type: OD/TP/TP RES/TL/EVA

53R 3172D

Typist

(1) Office Assign Form

[illegible]

(1) Assignment Form

[illegible]

C Damaged Vehicle Photographs Uploaded


--	--	--	--

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

✓	
✓	

C Resurvey photo Uploaded

--	--	--	--

	08/18
Case Handler	Date

21/05/2014




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD			Ref : CS3/LCR17010953/Dqbe2-1	
78 SHENTON WAY #08-16 CHARTIS BUILDINGS SINGAPORE 079120			Date : 08-02-2018	
			Code : LCR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLG 2500G	Veh. Inspected	SJR 3172D	
Policy No.	0999995145	Coverage (\$)	0.00	
Claim No.	4716038108SG003	Excess (\$)	0.00	
Assign From	KHOO KAY ENG	Assign Date	02/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA CAMRY 2.0	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	MR053BK4107043526	Colour	WHITE	
Odometer	167547	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	MICHELIN	6 mm	
L/H Front Tyre	215/60 R16	MICHELIN	6 mm	
R/H Rear Tyre	215/60 R16	MICHELIN	6 mm	
L/H Rear Tyre	215/60 R16	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/06/2017	Inspection Date	06/06/2017	
Survey held at	3 MOTORWERKZ 25 KAKI BUKIT ROAD 4 SYNERGY @ KB #01-42 SINGAPORE 417800			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJR 3172D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER ASSY	DENTED / CRACKED	1,288.90	1,288.90
2	REAR BUMPER REFLECTOR	NOT NECESSARY	167.10	-
1	REAR BUMPER RIGHT RETAINER	BENT / NECESSARY	86.40	86.40
1	REAR BUMPER LEFT RETAINER	BENT / NECESSARY	86.40	86.40
1	REAR BUMPER RIGHT BRACKET	BENT / NECESSARY	88.70	88.70
1	REAR BUMPER LEFT BRACKET	BENT / NECESSARY	88.70	88.70
1	REAR BUMPER REINFORCEMENT	DENTED	393.30	393.30
1	REAR BOOTLID ASSY	TO REPAIR SEE LABOUR	1,476.90	-
1	REAR BOOTLID CENTRE LOGO	NECESSARY	68.80	68.80
1	REAR BOOTLID 'CAMRY' EMBLEM	NECESSARY	66.40	66.40
1	REAR BOOTLID '2.0' EMBLEM	NECESSARY	62.60	62.60
1	REAR BOOTLID LOCK MECHANISM	BENT	252.40	252.40
1	REAR BOOTLID LOCK CATCH	TO REPAIR SEE LABOUR	97.60	-
1	REAR BOOTLID RIGHT TAILLAMP	NOT NECESSARY	385.20	-
1	REAR BOOTLID LEFT TAILLAMP	NOT NECESSARY	385.20	-
1	REAR BOOTLID WEATHERSTRIP	WARPED / NECESSARY	288.10	288.10
1	REAR LEFT TAILLAMP	NOT NECESSARY	792.30	-
1	REAR RIGHT TAILLAMP	NOT NECESSARY	792.30	-
1	REAR END LOWER PANEL	TO REPAIR SEE LABOUR	1,048.30	-
1	REAR END LOWER PANEL TOP GARNISH	NOT NECESSARY	224.60	-
1	REAR EXHAUST MUFFLER TAIL END PIPE	NOT NECESSARY	179.70	-
1	REAR EXHAUST MUFFLER ASSY	NOT NECESSARY	1,179.90	-
2	REAR EXHAUST MUFFLER RUBBER MOUNTING	NOT NECESSARY	36.60	-
	LESS 25% DISCOUNT		-2,384.10	-692.68
			7,152.30	2,078.02

Report Ref No. CS3/LCR17010953/Dqbe2-1

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
10	REAR BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
4	REAR END LOWER PANEL TOP GARNISH CLIPS (SN)	SERVICEABLE	20.00	-
2	REAR BUMPER REVERSE SENSOR (SN)	MALFUNCTION	250.00	220.00
1	REAR VIEW CAMERA (SN)	NOT NECESSARY	300.00	-
1	REAR NO PLATE WITH GARNISH (SN)	NOT NECESSARY	80.00	-
			700.00	250.00
	LABOUR			
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN REAR AFFECTED AREA AND REAR DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF REAR BOOTLID ASSY, REAR BOOTLID LOCK CATCH AND REAR END LOWER PANEL.		1,200.00	800.00
	TO PUTTY AND SPRAY PAINTING REAR PORTION.		1,200.00	800.00
	TO CHECK REAR LIGHTING AND WIRING.	NOT NECESSARY	50.00	-
	TO REMOVE AND INSTALL REAR BOOTLID LOCK MECHANISM.		80.00	20.00
	TO REMOVE AND INSTALL REAR EXHAUST MUFFLER ASSY.	NOT NECESSARY	100.00	-
	TO REMOVE AND INSTALL REAR INNER TRIM TO FACILITATE THE REPAIR.		120.00	80.00
	TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA.		120.00	40.00
	TO REMOVE AND INSTALL REAR BUMPER REVERSE SENSOR.		80.00	40.00
	TO REMOVE AND INSTALL REAR VIEW CAMERA.	NOT NECESSARY	80.00	-
	TO REPAIR, STRAIGHTEN AND ALIGN BOTH REAR FENDER ASSY.	NOT NECESSARY	350.00	-
			3,380.00	1,780.00
GRAND TOTAL			11,232.30	4,108.02
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,250.00

Report Ref No. CS3/LCR17010953/Dqbe2-1

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.