

INS. CASE OWNER:

CC 6/CTI1800 VV49, AKB302

LKK:

IDAC:

Surveyor:

Adrian

DOI:

ASSIGNMENT

2/2/18

Date / Time:

2/2/18

Registered in Merimen:

Pre-assign / CCU / FTE

YL 7101L



Insured Vehicle No.:

Name of Insured:

NAM KUP PRODUCTIONS P/L

Insured Tel No.:

HP:

Excess Sec II :S\$

D.O.A.:

01/02/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

TAY SOON PHORN

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

SNM8D00652021

Policy No.:

DMC VSN 307261700

Make / Model:

ISUZU

Place of Accident:

UNE RD PARKING LOT

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SGY 9997A



INSRS:

WSP:

Tel:

Liability:

RMKS:

LEUNG



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

8/2/18

2A1M

09022018

4.25pm

SGY 9997A - 8

YL 7101L - 7

Spoke to OIO (Mr. Tay), confirmed accident details and OIO reversed and collided into TP vehicle. Informed act TP claims aware of 100% liability and agree to settle. Send letter to 27.

3-7-18

FOR MANDATE

RECEIVED 11 AUG 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

9 09022018

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

☒☐

After call ltr to OI:

☒☐

Authorisation To Act:

☒☐

Release Voucher:

☒☐

Final Repair Bill:

☒☐

Car Rental Invoice:

☒☐

Towing Invoice

☒☐

LTA / GIA:

☒☐

Medical Bill:

☒☐

PIR:

☒☐

Mandate/Reject Instruction:

☒☐

LOD

☒☐

Payment Breakdown Form:

☒☐

Post-Repair Photos:

☐☐

Others:

☐☐

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email ☐Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐Call ☐

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

NIL

Repair Cost:

S\$

6,400

Loss of Rental (LOR):

S\$

750

(

5 days)

x 150

Loss of Use (LOU):

S\$

-

(\$

x

days)

Loss of Income (LOI):

S\$

-

(\$

x

days)

LOR only ☐LOU only ☐☐LOR + LOU ☐☐LOR + LOI ☐☐

[Tick only one]

GIA/LTA Search

S\$

-

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/ Independent)

Legal Cost

S\$

-

Total:

S\$

7,150

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐Call ☐

Payee 1:

S\$

7,150.xx

Name 1:

LEANG AUTOMOTIVE

Payee 2: (Strike if N.A.)

S\$

x

Name 2:

x

Payee 3: (Strike if N.A.)

S\$

Name 3:

Surveyor

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGY9997A. Yr Regn: 2017 / Feb.Type: M.Cycle / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Lexus NX200 c.c. 1998Colour: St Grey A/C: Insured / Std / NI / NASp. Reading: 21046 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTJBARBZ302116199.Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/60R18R: 225/60R18.BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 06 mmL/Bal. 06 mm

D.O.A. _____

Rear

R/Bal. 06 mmL/Bal. 06 mmD.O.I. 02/02/18Survey held at LeanyDes. of Damages: Frt / Rear / O/S / NIS / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP China.

11/4/18 L/S \$6,400

RC \$13,368.08 / 687.1

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$) 3 + RS 51

) Photos

) Others

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

26711E.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CTI18002249/Akb3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 05-02-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YL 7101L	Veh. Inspected	SGY 9997A	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	05/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	01/02/2018	Inspection Date	02/02/2018	
Survey held at	LEANG AUTOMOTIVE BLK 1 KAKI BUKIT AVE 6 #01-68 AUTOBAY@ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Shu Pei (LKKAUTO)

From: Angie Foo <angie.foo@sg.cntaiping.com>
Sent: Wednesday, 7 February 2018 4:23 PM
To: Shu Pei (LKKAUTO)
Cc: Chong Boon Sen; Admin A; Hsiao Tong (LKKAUTO); Zaini (LKK Auto)
Subject: OUR REF: SNM18D00652C02/1/LKKDS & YR REF: SGY9997A (TP : LKK REF - CC6/CTI18002249/Akb3) on 01.02.2018
Attachments: SNM18D00652C02 20180207 TO INSURED -LKKDirectSettlementAccidentLtr.pdf; MCAB18016736-YL7101L.pdf

Dear Shu Pei,

We refer to your email of 6th February 2018.

We attached our Insured's SAS Report and Assignment Letter for your necessary action.

Kindly take note, the claim handler is Chong Boon Sen 63896171.

Thank you.

Regards,
Angie Foo
Executive
Motor Division
Claims Department
China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road #16-00
Springleaf Tower
Singapore 079909
Co.Reg.No.200208384E
DID: 6389 6186
Fax: 6224 7478 /6224 7175
Email: angie.foo@sg.cntaiping.com
Email: claimsdept@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer:

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Tuesday, 6 February, 2018 7:25 PM
To: Claims Dept of CTI
Cc: Chong Boon Sen; Admin A; Hsiao Tong (LKKAUTO); Zaini (LKK Auto)
Subject: Direct Settlement - Accident Involving YL7101L (OI : CAI - TBA) and SGY9997A (TP : LKK REF - CC6/CTI18002249/Akb3) on 01.02.2018

WITHOUT PREJUDICE

Dear Boon Sen,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SGY 9997A at M/s Leang Automotive.

Enclosed for your perusal is:

- TP GIA report

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Hsiao Tong and she can be contacted at DID: 6742 3197.

Thank you

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Tel: 6389 6111 Fax: 6222 1033

Website: www.sg.cntaping.com

Cn. Reg. No. 200208384E

Our Reference: **SNM18D00652/C02/1**

Date : **07 FEBRUARY 2018**

via Ordinary & Registered Mail

**NAM HUP PRODUCTIONS PTE LTD
9 LINK ROAD**

SINGAPORE 619031

Dear Sir / Madam

**ACCIDENT INVOLVING YL7101L AND SGY9997A ON 01 FEBRUARY 2018
ALONG LINK ROAD PARKING LOT**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SGY9997A** , is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,

Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd

Attn : HIAO TONG

Ref : TP : LKK REF - CC6/CT118002249/Akb3

Contact No : HIAO TONG

via Email : chewht@lkkauto.com

CC : Agent - (AN0435A) - YETTA INSURANCE AGENCY PTE LTD

F01/LKKDS-2013

TP China
Zaini

86Y9997A.

Lexus NX200 1998cc

JTJBABZ302116159.

	Date	No.
Rear Number Plate	30(SN) X	
Rear Number Plate Holder	30(SN) X.	
Rear Bumper Deformed	627.30 ✓	
Rear Bumper Clips. New	50 30 ✓	
Rear Bumper Side Holder x02 New	92.5x2=185 ✓	
Rear Bumper Reinforcement Belt	598.70 ✓	
Rear Bumper Lower Garnish Deformed	597.80 ✓	
Rear Bumper Lower Garnish Reflector x02 Not New	75.4x2=150.80 X	
Reverse Sensor x 04. 2 pieces damaged	397.9x4=1589.60 530	
Rear End Panel Repair	627.50 X.	
Rear End Panel Top Garnish Deformed	397.90 ✓	
Rear End Panel Sealant. Not New	60(SN) X	
Taillamp x02 Not New	688.60x2=1377.20 X	
Tailgate Dented	1489.50 ✓	
Tailgate Lock Damaged	961.50 745	
Tailgate Lock Sensor Not New	277.40 X.	
Tailgate Weatherstripe Not New	298.90 X	
Tailgate Outer Garnish. Cracked	997.60 ✓ 585	
Tailgate Outer Garnish Chrome Moulding.	==	
Tailgate Outer Garnish Clips. New	10 ✓	
Tailgate Reflector x02 Not New	769.8x2=1539.60 X	
Tailgate Glass Moulding. Not New	277.80 ✓	
Tailgate Glass Sealant. Not New	60(SN) ✓	
Tailgate Inner Trim Board cracked	1277.50 750	
Tailgate Inner Trim Board Clips. New	50 30	
Lexus Logo	85.70 ✓	
Lexus Wordmark	92.90 ✓	
NX200T Wordmark	88.60 ✓	
Rear Camera. Not New	680(SN) X	
Spare Tyre Panel Top Cover. Not New	1270.50 X	



8649557A.

Tools Sponge Tray. Not over
Rear Exhaust Pipe
Rear Exhaust Chrome Pipe x02
Rear Exhaust Mounting.

327.40 X
1175.90 X
359.8 x 2 = 719.60 X
89. X

15,940.70
107.
14,346.63

Panel Beating
Spray Painting
Wiring
To undress
To remove reverse sensor
To remove rear camera
To remove upholstery
To transfer tailgate fittings
To remove tailgate glass
To remove exhaust pipe

1200 600
1200 600
55 30
150 X
100 50
120 50
150 60
180 80
180 120
150 X.

List 71212
un 10% 6409.08
SN: 60

Labour 1550
Total: 8059.08
H/S: 64K.
05 May

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged parts, during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



TRANSMISSION VERIFICATION REPORT

TIME : 27/07/2018 02:34
NAME :
FAX : 67414108
TEL :
SER.# : E69899L3N245962

DATE, TIME	27/07 02:34
FAX NO./NAME	69093046
DURATION	00:00:18
PAGE(S)	01
RESULT	OK
MODE	STANDARD
	ECM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI18002249/Ajb3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 15-08-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YL 7101L	Veh. Inspected	SGY 9997A
Policy No.	DMCVSN307261700	Coverage (\$)	0.00
Claim No.	SNM18D00652C02/1	Excess (\$)	0.00
Assign From		Assign Date	02/02/2018

2. Vehicle Particulars & Condition

Make & Model	LEXUS NX200	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTJBARBZ302116199	Colour	GREY
Odometer	21046	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/60 R18	BRIDGESTONE	6 mm
L/H Front Tyre	225/60 R18	BRIDGESTONE	6 mm
R/H Rear Tyre	225/60 R18	BRIDGESTONE	6 mm
L/H Rear Tyre	225/60 R18	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	01/02/2018	Inspection Date	02/02/2018
Survey held at	LEANG AUTOMOTIVE BLK 1 KAKI BUKIT AVE 6 #01-68 AUTOBAY@ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGY 9997A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	627.30	627.30
1	REAR BUMPER CLIPS	NECESSARY	50.00	30.00
2	REAR BUMPER SIDE HOLDER @\$92.50	NECESSARY	185.00	185.00
1	REAR BUMPER REINFORCEMENT	BENT	598.70	598.70
1	REAR BUMPER LOWER GARNISH	DEFORMED	597.80	597.80
2	REAR BUMPER LOWER GARNISH REFFLECTOR @\$75.40	NOT NECESSARY	150.80	-
4	REVERSE SENSOR @\$397.90	DAMAGED (2 PCS ONLY)	1,589.60	530.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	627.50	-
1	REAR END PANEL TOP GARNISH	DEFORMED	397.90	397.90
2	TAILLAMP @\$688.60	NOT NECESSARY	1,377.20	-
1	TAILGATE	DENTED	1,489.50	1,489.50
1	TAILGATE LOCK	DAMAGED	961.50	745.00
1	TAILGATE LOCK SENSOR	NOT NECESSARY	277.40	-
1	TAILGATE WEATHERSTRIPE	NOT NECESSARY	298.90	-
1	TAILGATE OUTER GARNISH	CRACKED	997.60	585.00
1	TAILGATE OUTER GARNISH CLIPS	NECESSARY	10.00	10.00
2	TAILGATE REFFLECTOR @\$769.80	NOT NECESSARY	1,539.60	-
1	TAILGATE GLASS MOULDING	NECESSARY	277.80	277.80
1	TAILGATE INNER TRIM BOARD	CRACKED	1,277.50	750.00
1	TAILGATE INNER TRIM BOARD CLIPS	NECESSARY	50.00	30.00
1	LEXUS LOGO	NECESSARY	85.70	85.70
1	LEXUS WORDING	NECESSARY	92.90	92.90
1	NX 200T WORDING	NECESSARY	88.60	88.60
1	SPARE TYRE PANEL TOP COVER	NOT NECESSARY	1,270.50	-
1	TOOLS SPONGE TRAY	NOT NECESSARY	327.40	-
1	REAR EXHAUST PIPE	NOT NECESSARY	1,175.90	-
2	REAR EXHAUST CHROME PIPE @\$359.80	NOT NECESSARY	719.60	-
1	REAR EXHAUST MOUNTING	NOT NECESSARY	89.00	-

Report Ref No. CC6/CTI18002249/Ajb3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-	-712.12
			17,231.20	6,409.08
	SPECIAL NETT ITEMS			
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	30.00	-
1	REAR NUMBER PLATE HOLDER (SN)	NOT NECESSARY	30.00	-
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	60.00	-
1	TAILGATE GLASS SEALANT (SN)	NECESSARY	60.00	60.00
1	REAR CAMERA (SN)	NOT NECESSARY	680.00	-
			860.00	60.00
	LABOUR			
	PANEL BEATING . INCLUSIVE OF THE REPAIR OF REAR END PANEL .		1,200.00	600.00
	SPRAY PAINTING.		1,200.00	600.00
	WIRING.		50.00	30.00
	TO UNDERSEAL .	NOT NECESSARY	150.00	-
	TO REMOVE REVERSE SENSOR .		100.00	50.00
	TO REMOVE REAR CAMERA .		100.00	50.00
	TO REMOVE UPHOLSTERY.		150.00	60.00
	TO TRANSFER TAILGATE FITTINGS .		180.00	80.00
	TO REMOVE TAILGATE GLASS.		180.00	120.00
	TO REMOVE EXHAUST PIPE.	NOT NECESSARY	150.00	-
			3,460.00	1,590.00
	GRAND TOTAL		21,551.20	8,059.08
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,400.00

Report Ref No. CC6/CT118002249/Ajb3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.