

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS18002301/AVD3N2
Date: 19/06/2018

REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	WPK8988	Insured Vehicle No :	SJW9567H
Date of Loss:	03/02/2018	Nature of Claim:	TP
		Claim No:	DMPU180019H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	WPK8988	Engine No:	1TR6275549
Make & Model:	TOYOTA INNOVA, 2.0 (A)	Chassis No:	PN111NV4008403807
Reg. Date:	14/09/2006 (Man. Year: 2006)	Odometer:	240208 km
Colour:	Silver		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/65R15	Rear Tyre Size:	205/65R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,178.95	3,949.22	1,229.73	23.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,790.00	1,700.00	2,090.00	55.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,968.95	5,649.22	3,319.73	37.01
Approved Total (Overridden) (\$\$)		4,500.00		
(\$\$)	8,968.95	4,500.00	4,468.95	49.83
+ GST 7.00/7.00% (\$\$)	627.83	315.00	312.83	49.83
Nett Amount (\$\$)	9,596.78	4,815.00	4,781.78	49.83

INSPECTION

Date of Assignment:	05/02/2018		
Date Inspected:	06/02/2018	Inspected At:	MG Solution Pte Ltd (HQ) 23 Kaki Bukit Avenue 4 #02-03B, VICOM Inspection Centre Singapore 415933
Estimated Period of Repair:	6.0 days		

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 May 2018)
Parts:	M1-MPV	TOYOTA INNOVA 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	LKK Auto Consultants Pte Ltd/WPK8988/19/06/2018 13:27	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,588.30 FL	*1,043.00 FL
2	1		*TAIL GATE LOGO	Necessary	72.00 FL	*45.00 FL
3	1		*TAIL GATE EMBLEM TOYOTA	Necessary	85.00 FL	*40.00 FL
4	1		*TAIL GATE EMBLEM INNOVA	Necessary	85.00 FL	*55.00 FL
5	1		*TAIL GATE EMBLEM 2.0	Necessary	85.00 FL	*48.00 FL
6	1		*TAIL GATE EMBLEM E	Necessary	85.00 FL	*60.00 FL
7	1		*TAIL GATE TOP LOCK	Damaged	280.00 FL	*280.00 FL
8	1		*TAIL GATE LOWER CATCH	Not Necessary	62.00 FL	*- FL
9	1		*TAILGATE WEATHER STRIP	Cut	266.00 FL	*266.00 FL
10	1		*TAILGATE WINDSCREEN MOULDING	Necessary	122.00 FL	*122.00 FL
11	1		*REAR BUMPER	Deformed	688.30 FL	*688.30 FL
12	2		*REAR BUMPER SIDE RETAINER	Necessary	144.00 FL	*144.00 FL
13	1		*TAILLAMP RH	Cracked	366.00 FL	*366.00 FL
14	1		*REAR END PANEL	Dented	760.00 FL	*680.00 FL
15	1		*REAR EXHAUST PIPE	Bent	930.00 FL	*695.00 FL
16	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
17	1		*TAIL GATE SEALANT	Not Necessary	60.00 FS	*- FS
18	1		*TAIL GATE WINDSCREEN SEALANT	Necessary	60.00 FS	*30.00 FS
19	1		*TAIL GATE WINDSCREEN INNER SEAL	Necessary	60.00 FS	*30.00 FS
20	1		*TAILGATE STICKER	Necessary	300.00 FS	*200.00 FS
21	1		*SET REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
22	1		*SET TAIL LAMP CLIP	Not Necessary	35.00 FS	*- FS
23	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
24	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,583.60	5,082.30
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,404.65	1,133.08
Total Parts (\$\$)	5,178.95	3,949.22

LKK Auto Consultants Pte Ltd/WPK8988/19/06/2018 13:27. Not valid without Reference section.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,REMOVING AND REPLACING PARTS	New	1,400.00	700.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,200.00	600.00
3	WIRING CHECK	New	150.00	30.00
4	TUFF COAT	New	200.00	-
5	REMOVE AND REFIX UPHOLSTERY TO FACILITATE REPAIR	New	180.00	60.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	180.00	50.00
7	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	100.00
8	REMOVE AND REFIX REAR EXHAUST PIPE	New	180.00	80.00
9	TRANSFER TAILGATE MECHANISM	New	180.00	80.00
Gross Labour Cost (S\$)			3,790.00	1,700.00

LKK Auto Consultants Pte Ltd/WPK8988/19/06/2018 13:27. Not valid without Reference section.

< END OF ESTIMATES >