HIN LUNG WORKSHOP

Blk 1008 Bukit Merah Lane 3 #01-20, S'pore 159722. Tel: 68583000 Fax: 64760075

Website: www.hinlung.com.sg GST Regn. No: M2-0065859-X

Page: 1

Date: 05/02/2018

Your Ref:

Our Ref : 0591/02/18

: INDIA INTERNATIONAL INSURANCE P.LTD

64 CECIL STREET

#04/#05 IOB BUILDING SINGAPORE 049711

Attn

M/s

: MOTOR CLAIM DEPARTMENT

Dear Sir/Madam,

ACCIDENT REPAIR ON : SLP3172R - MAZDA 3 1.5A 0

INSURED : BOLT CAR LEASING PTE LTD

DATE OF ACCIDENT : 01/02/2018

YOUR INSURED VEH NO: SHB4014D

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & PARTS TO BE REPLACED: -

				S\$	S\$	S\$
REPLACEMENT OF PARTS						
1	REAR BOOT LID		@	1,053.40	1,053.40 Ap b	0-
2	REAR BOOT WEATHER STRIP		6	142.00	142.00×	
3	REAR BOOT LID BADGE	. 1	@	72.60	72.60Ver	
	(SKYACTIV TECHNOLOGY).					
4	REAR BOOT LID BADGE (MADZA 3)	1	(g	58.70	58.702	
5	REAR BOOT LID LAMP RH	1	@	488.70	488.70⊀	1 1 2
6	REAR END PANEL	1	(g	555.00	555.00X-PI	lioto!
7	REAR LAMP PANEL RH	1	6	415.00	555.00X-PC 415.00Ry	
8	REAR LAMP RH	1	(g	1,008.00	1,008.00 ara	
9	REAR VENTILATION AIR GRILLE RH	1	@	78.70	78.70で	
10	REAR BUMPER	1	(g	1,184.00	1,184.00 de -	
11	REAR BUMPER REINFORCEMENT	1	@	591.40	591.40~	
12	REAR BUMPER CLIPS	10	(g	5.00	50.00 neg	
13	REAR BUMPER REFLECTOR RH	1.	6	55.40.	55.40cut -	
14	REAR BUMPER RETAINER RH	1	@	39.80	39.80	
15	REVERSE SENSOR 1 SET	1	@	220.00	220.00 cut	
16	REAR TOW HOOK COVER RH	1	(ĝ	17.80	17.80 mis	
	Total				6	,030.50

LABOUR CHARGES

1 REMOVE AND REPAIR REAR BOOT LID, REAR BUMPER, REAR FENDER RH, REINFORCEMENT , REAR END PANEL AND ETC., AND REPLACEMENT OF PARTS FOR THE EFFECTED AREAS.

2 SPRAY PAINT ON THE EFFECTED AREAS WITH 2K PAINT.

3 REMOVE AND REPLACE REAR WINDSCREEN TO

700 700 1,400.00 %

600 500 1,200.00 En

150.00 ₺

LUNG WORKSHOP

Blk 1008 Bukit Merah Lane 3 #01-20, S'pore 159722. Tel: 68583000 Fax: 64760075

Website: www.hinlung.com.sg

GST Regn. No: M2-0065859-X

Your Ref:

Our Ref : 0591/02/18

Page:

Date: 05/02/2018

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & PARTS TO BE REPLACED:-

8\$

S\$

5\$

FACILITATE REPAIR.

4 DISCONNECT AND CHECK ELECTRICAL WIRING, HARNESS, WIRE SOCKETS, ETC., REMOVE AND REINSTALL DAMAGED PARTS, TEST AND RECTIFY FOR PROPER FUNCTIONING.

LINING AND GARNISH TO FACILITATE REP.

5 REMOVE AND REFIT REAR END PANEL

Nett Total Before GST

100.00 40

60.00 20

8,940.50

Yours faithfully,

(Workshop Manager)

LKK Auto Consultants hence notify

the Repairer of the following: To resurvey before/after spray painting

To display damaged part(s) during resurvey

Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

No illegal modification(s) is allowed

· Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: