



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

WONG WOEI WEI

06/02/2018

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP A16.

Thin Thin

Accident date: 02/02/2018

Estimated repair cost for vehicle no: SKB5113J TOYOTA LEXUS 3.4 A '09

CHASSIS: JTHBC96S005018724

S/N	QTY	ITEMS	U/PRICE	AMOUNT
1	1	Front Bonnet <i>Rys</i>		\$1,624.50 +
2	1	Front Bonnet Lock <i>2 m</i>		\$203.20 ✓
3	1	Front Bonnet Inner Rubber <i>1 m</i>		\$69.90 x.
4	1	Front Grille <i>couled</i>		\$654.70 ✓
5	6	Front Grille Clip <i>m</i>	\$6.50	\$39.00 20
6	1	Front Grille Emblem Logo <i>new</i>		\$1,945.20 60.
7	1	Front Grille Chrome <i>couled</i>		\$414.80 ✓
8	2	Front Head Lamp <i>LH couled</i>	\$2,395.20	\$4,790.40 2395.20
9	2	Front Head Lamp Chrome <i>2 m</i>	\$512.40	\$1,024.80 x.
10	1	Front Bumper <i>deformed</i>		\$789.80 ✓
11	8	Front Bumper Clip <i>m</i>	\$6.50	\$52.00 30.
12	2	Front Bumper Side Retainer <i>new</i>	\$69.00	\$138.00 ✓
13	1	Front Bumper Number Plate <i>deformed</i>		\$50.00 ✓
14	1	Front Bumper Number Plate Garnish <i>deformed</i>		\$69.90 ✓
15	1	Front Bumper Towing Cover <i>deformed</i>		\$49.90 ✓
16	1	Front Bumper Lower Cover <i>2 m</i>		\$632.90 +
17	1	Front Bumper Centre Lower Garnish <i>deformed</i>		\$149.90 ✓
18	2	Front Bumper Fog Lamp <i>2 m</i>	\$491.20	\$982.40 x
19	1	Front Bumper Inner Sponge <i>deformed</i>		\$129.90 ✓
20	1	Front Bumper Reinforcement <i>Bent</i>		\$478.20 ✓
21	2	Front Bumper Reverse Sensor <i>1 piece damaged</i>	\$403.90	\$807.80 260
22	2	Front Bumper Reverse Sensor Cover <i>1 piece damaged</i>	\$25.90	\$51.80 25.80
23	1	Front Support Panel Top Cover <i>2 m</i>		\$786.90 x
24	10	Front Support Panel Top Cover Clip <i>1 m</i>	\$6.50	\$65.00 x.

5716.20

5144.58

Subtotal:- \$16,000.90

Labour charges

To remove & refit air-con condenser, radiator, fan motor & top up gas		\$380.00 X
To check wiring		\$100.00 30
Tuff kote		\$150.00 X
Panel beating	890.	\$1,000.00 400
Spray painting		\$1,000.00 400
To remove front bumper sensor	60 120	
Subtotal:-		\$2,630.00
Total:-		\$18,630.90

total: 6034.58

H/S: 4.8K
04 Days.

4.8K
04 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: