

ASS. REC. BY

REF: CS/FCI 18002335/R17d3 72

Survivor

ASSIGNMENT (Office)

CWS

From (Person): Sifhara of FCI Date/Time: 6/2/18 @ 9:32am

Estimated Cost: Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBF8601H Insured: SHA 8692A

at Workshop m/s: Sin Sheng Engineering Tel: 6863 9595

of 3tech Park Crescent, Tuas Tech Park

Policy No: Claim No: D18001067MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 1/2/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS up

H.O.D. Endorsement:

Date/Time: 10:32am @ 6/2/18 Person Contacted: Susan Vehicle IN (OUT)

Date/Time	Action/Instruction (✓) Estimate	
	GBF 8601H - NA/DAI17024606/h4	D.O.A. : 27/12/17
	SHA 8692A - CS/FCI 17019055/Aqb	D.O.A. : 30/9/17
	lump sum \$2650. 4 days ctd:	

Kabul

REF

FCI

1196N

ASSIGNMENT

Date 26/2/18

GBF 8601H

2017 MAR

Estimated Cost

OD (P) MS / TP RES / OD RES / EVA / INV / M /

To: (Accident / Incident) GBF 8601 H

at: (Address) Sin Sheng
3 Tech Park Crescent #1405

Insured

Policy No.

Claims No.

Sum Insured

Excess

Client's Record

Make of Veh

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Salvage / Market Value

OD Accident Report Consistent? : Yes or No

OD Police Report Consistent? : Yes or No

Est. Repairs days Fee Yes or No

Est. Cost \$ \$ Value Yes or No

CA / REV / REP. / 24 HRS 'up

Date Person Contacted Vehicle IN / OUT

Date Time Action / Instruction

Ref No

Type M / Car / M / Cycle / Bus / Truck / Lorry / Taxi / Other Motor

Truck / Trailer

Make

TOYOTA HIACE DX 3.0M

2982

Color

RED

St. Record

31273

Engine

Cyls

KOH 2010195186

Get / Long / Good / Poor / Burnt

Steering / Order / Jammed / Leaked / Burnt /

Brake / Order / Jammed / Leaked / Burnt /

Mod / STD / 4 / 2 / 3 / 4 / 5 / 6 / 7 / 8 / 9 / 10 / 11 / 12 / 13 / 14 / 15 / 16 / 17 / 18 / 19 / 20 / 21 / 22 / 23 / 24 / 25 / 26 / 27 / 28 / 29 / 30 / 31 / 32 / 33 / 34 / 35 / 36 / 37 / 38 / 39 / 40 / 41 / 42 / 43 / 44 / 45 / 46 / 47 / 48 / 49 / 50 / 51 / 52 / 53 / 54 / 55 / 56 / 57 / 58 / 59 / 60 / 61 / 62 / 63 / 64 / 65 / 66 / 67 / 68 / 69 / 70 / 71 / 72 / 73 / 74 / 75 / 76 / 77 / 78 / 79 / 80 / 81 / 82 / 83 / 84 / 85 / 86 / 87 / 88 / 89 / 90 / 91 / 92 / 93 / 94 / 95 / 96 / 97 / 98 / 99 / 100

Tyre Size

195R15C

BS / DUN / EXNOVA / GY / FS / LIZA / MID / CHTS / PR / S / M

TOYO / YOKO

Ans run

Front

Rear

FR

RR

LR

RR

OD

OD

Surveyed at

SIN SHENG

Described Damages / Fr / Rear / N / S / U / O / R / L / B / C /

The U / O / Chassis frame / Body Structure affected due to collision

RECEIVED 23 MAY 2018

Date Time For Report



Preliminary Report

Final Report

23/5 Typist

Date Time For Report

Days Of Repair

4

Resurvey No. of Trk

1

Survey Fee

Transport Fee

Other Fee

Total Fee

Add Fee

Site Fee

High Fee

Exp. Fee

Acc. Fee

145
50
50
26

271

Person Reported

Date Time

26/50



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18002335/R1td3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 06-02-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 8692A	Veh. Inspected	GBF 8601H
Policy No.		Coverage (\$)	0.00
Claim No.	D18001067MFSH	Excess (\$)	0.00
Assign From	CWS (SITHARA)	Assign Date	06/02/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	01/02/2018	Inspection Date	
Survey held at	SIN SHENG ENGINEERING SERVICES 3 TECH PARK CRESCENT TUAS TECK PARK SINGAPORE 638129		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

MOTOR SURVEY ASSIGNMENT

Date	05-02-2018	Our Ref No. D18001067MFSH
Accident Date	01-02-2018	Claim Type. Third Party
Insured Vehicle	SHA8692A	Third Party Vehicle. GBF8601H
Survey Location	3 TECH PARK CRESCENT TUAS TECH PARK	
Contact Person.	SUSAN	
Contact No.	68639595/ 0	Fax No. 68636477
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SIN SHENG ENGINEERING SERVICES	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/234663)



PRI Documents



Close



PRI Header Details

Claim No	D18001067MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & SIN SHEN
Workshop Name	SIN SHENG ENGINEERING SERVICES (Contact Person : SUSAN)	Survey Location & Contact Details	3 TECH PARK CRESCENT TUAS TECH PARK Mobile: 0 , Phone: 68639595 , Fax: 68636477 EmailId: SINSHENG1981@GMAIL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHA8692A	TP Vehicle No	GBF8601H
PRI Recieved Date	05-02-2018 08:17:03 PM	Surveyor Appointed Date	06-02-2018 09:31:36 AM	Surveyor Accept Date	06-02-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	06-02-2018	Upload Survey Report *:	Choose File
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make ▾	Model	Please Select Model ▾	Year	Select Year ▾
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002405

Date : 26/02/2018

Vehicle Num. : GBF8601H

Make/Model : TOYOTA KDH 201-2016

Chassis/Eng# : KDH2010195186/1kd2608813

Accident Date : 01/02/2018

Claim No. : D18001067MFSH

Reference :

Policy No. : 29004183

S/N	Quantity	Particular	Unit Price	Amount S\$
		LIST ITEMS :		
1.	1	SLIDING DOOR, RH	1,895.90	
2.	1	SLIDING DOOR ROLLER, LWR, RH	395.48	
3.	1	SIDE PANEL RH	1,321.80	
4.	1	SLIDING DOOR WEATHERSTRIP	298.50	
5.	1	SLIDING DOOR PARTITION	268.50	
6.	1	REAR BUMPER	377.40	
7.	1	BUMPER SIDE BRACKET	123.50	
8.	5	BUMPER CLIP	25.00	
9.	1	REAR LAMP GARNISH	165.20	
		List Total S\$:	4,871.28	
		25.00% Discount S\$:	1,217.82	
			3,653.46	
		NETT ITEMS :		
1.	1	LOGO	650.00	
		Nett Total S\$:	650.00	
		10.00% Discount S\$:	65.00	
			585.00	
		LABOUR :		
		TO PANEL BEAT/REPAIR RH BODY	950.00	

CONTINUE / ...

SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002405

Date : 26/02/2018

Vehicle Num. : GBF8601H

Make/Model : TOYOTA KDH 201-2016

Chassis/Eng# : KDH2010195186/1kd2608813

Accident Date : 01/02/2018

Claim No. : D18001067MFSH

Reference :

Policy No. : 29004183

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS

SPRAY PAINTING

TO APPLY NEW LOGO

TO APPLY TUFF KOTE

LOSS OF USE : 7 DAYS @ \$ 120/DAY

Labour Total S\$:

500
800.00
680
150.00
80 150.00
4 days
4s
26/02/18 @ 1700hrs
Resum after repair

2,050.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total S\$: 6,288.46

=====

SIN SHENG ENGINEERING SERVICES



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18002335/R1td3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 25-05-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 8692A	Veh. Inspected	GBF 8601H	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18001067MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	06/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE DX 3.0 M	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	KDH2010195186	Colour	RED	
Odometer	31273	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	AUSTONE	6 mm	
L/H Front Tyre	195 R15C	AUSTONE	6 mm	
R/H Rear Tyre	195 R15C	AUSTONE	6 mm	
L/H Rear Tyre	195 R15C	AUSTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/02/2018	Inspection Date	26/02/2018	
Survey held at	SIN SHENG ENGINEERING SERVICES 3 TECH PARK CRESCENT TUAS TECK PARK SINGAPORE 638129			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 8601H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SLIDING DOOR,RH	BENT	1,895.90	1,895.90
1	SLIDING DOOR ROLLER,LWR,RH	SERVICEABLE	395.48	-
1	SIDE PANEL RH	TO REPAIR SEE LABOUR	1,321.80	-
1	SLIDING DOOR WEATHERSTRIP	NECESSARY	298.50	298.50
1	SLIDING DOOR PARTITION	CRACKED	268.50	268.50
1	REAR BUMPER	NOT NECESSARY	377.40	-
1	BUMPER SIDE BRACKET	NOT NECESSARY	123.50	-
5	BUMPER CLIP @\$5.00	NOT NECESSARY	25.00	-
1	REAR LAMP GARNISH	NOT NECESSARY	165.20	-
	LESS 25% DISCOUNT		-1,217.82	-615.73
			3,653.46	1,847.17
NETT ITEMS				
1	LOGO (N)	NECESSARY	650.00	400.00
	LESS 10% DISCOUNT		-65.00	-40.00
			585.00	360.00
LABOUR				
	TO PANEL BEAT/REPAIR RH BODY.TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS.INCLUSIVE OF THE REPAIR OF SIDE PANEL RH.		950.00	450.00
	SPRAY PAINTING.		800.00	500.00
	TO APPLY NEW LOGO.		150.00	80.00
	TO APPLY TUFF KOTE.		150.00	80.00
			2,050.00	1,110.00
GRAND TOTAL			6,288.46	3,317.17
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,650.00

Report Ref No. CS/FCI18002335/R1td3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.