

155/2010

INS. CASE OWNER:

Inve

CC6/CT118002344 / Kuf3²

LKK:

IDAC:

Surveyor:

KENNETH

DOI:

05/02/18

Date / Time:

05/02/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJH 2806T

Name of Insured:

Mr. HOOR BIN JUNE RATHMAN

Insured Tel No.:

HP:

96557769

Excess Sec II :SS

D.O.A.:

31/01/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

SNM1807161902

Policy No.:

096557769

Make / Model:

T-Estima

Place of Accident:

Jln Duren 7 km dari Rd

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

GY 7735U



INSRS:

WSP: Hui Yag

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

2/3
1/11

GY 7735U - X; SJH 2806T - X

19.12.18 e App CALLED ON 740 RESPONSE.

19.12.18 FILE PASS TO TYPIST TO PREPARE REPORT.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI: EMAIL 19.12.18.

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time: 20/03/18

Sent By: Shirley Hiew

FINALIZATION

Date/Time:

Confirm with:

Confirm by: KSC

Repair Cost:

SS \$15,100

(

8

days) Reduction:

56 %

Email

Call

FINAL SETTLEMENT

Date/Time: 14.3.19

Confirm with: MARCO

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

5

If NO or B 28, Ass. Lia:

Repair Cost:

SS \$16,571.00

OR MAKE A RM TURN AND PUT TP.

Loss of Rental (LOR):

SS \$1,171.00

(

11

days) x 100

Loss of Use (LOU):

SS -

(\$

x

days)

Loss of Income (LOI):

SS -

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

SS 2.00

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

4400

Total:

SS \$17,336.00

Global Sum SS:

FINAL PAYMENT

Date/Time: 14.3.19

Confirm with: MARCO

Email

Call

Payee 1:

SS \$17,336.00

Name 1:

HUI YANG MOTOR PTE. LTD.

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

ASS. REC. BY:

REF: C721

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____ of _____

Insured: _____

Policy No: _____

Claims No: _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: GY77554 Yr Regn: 10, 0.7

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Mit Cante c.c. 2877

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 400315 T/Radio: Insured / Std / NI / NA

Eng/No: 10129

C/No: 1-B7033A-7705

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: B.S. 185/75R15

R: Mic 185 R15 X8 (10)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 7 mm

R/Bal. 55 mm

L/Bal. 55 mm

D.O.A. 31/1/18

D.O.I. 5/2/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt & U/C

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

6/2 Mr pass to Carhuine

4s: +15,100 (Red: +18,931.01 56%)

Date/Time, File Pass to?

☐ : Prell. Report☐ : Final Report

1)

Date/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S - RS. \$

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CTI18002344/Kua3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 06-02-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJH 2806T	Veh. Inspected	GY 7755U	
Policy No.	DMPCSN3061271803	Coverage (\$)	0.00	
Claim No.	SNM18D00617C02	Excess (\$)	0.00	
Assign From		Assign Date	06/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	31/01/2018	Inspection Date	05/02/2018	
Survey held at	HUI YANG MOTOR SERVICE BLOCK 176 SIN MING DRIVE #04-02/03 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Bldg 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
Reg No. 201629438M

31/01/2018

Owner: KMR Construction & Engineering Pte Ltd

ESTIMATE TO REPAIR MITSUBISHI CENTER - GY7755U

1pc	front centre grille
1pc	front "MITSUBISHI" logo
1pc	front "FUSO" emblem
1pc	front bumper
1pc	front RH corner panel
1pc	front RH headlamp
1pc	front RH corner lamp
1pc	front RH side lamp
1pc	front RH door
2pes	front RH door hinge @\$162.54
1pc	front RH door inner lock
1pc	front RH door inner rubber
1pc	front RH door inner trim panel
1pc	front RH door lower garnish
1pc	front RH door lower garnish rubber
1pc	front RH door glass gear & motor
1pc	front RH door glass moulding
1pc	front RH door front garnish
1pc	front RH door rear garnish
1pc	front RH pillar 1394.55
1pc	front RH pillar rubber
1pc	front RH step panel
1pc	front RH step panel lower rubber
1pc	front RH step panel garnish
1pc	front RH wheel top panel
1pc	front RH wheel top panel rubber
1pc	front RH wheel top panel garnish
1pc	front RH wheel rear garnish
1pc	front RH wheel rear garnish lower rubber
1pc	front RH rim
1pc	front RH top arm
1pc	front RH lower arm 3403.67
1pc	front RH absorber
1pc	front RH knuckle arm 2738.39

balance c/f

mg	\$	527.33	✓
mg	\$	82.54	✓
mg	\$	154.95	✓
bu	\$	821.47	✓
rs	\$	564.37	X
mg	\$	768.10	✓
cm	\$	159.75	✓
cm	\$	227.63	✓
Ry	\$	1,969.30	✓
Ry	\$	325.08	✓
ai	\$	389.21	✓
cu	\$	216.50	501m 108.25m
su	\$	565.92	X
cm	\$	542.70	✓
cu	\$	154.00	✓
BH	\$	1,317.05	✓
di	\$	181.05	✓
su	\$	138.00	X
su	\$	158.00	X
Ry	\$	1,533.24	✓
cu	\$	138.15	501m 69.07m
Ry	\$	496.36	✓
cm	\$	36.15	✓
cm	\$	339.36	✓
Ry	\$	537.95	✓
nu	\$	77.40	✓
cm	\$	175.10	✓
su	\$	173.45	X
su	\$	68.10	X
Ry	\$	612.50	✓
Ry	\$	914.09	✓
Ry	\$	3,812.10	✓
Ry	\$	202.30	✓
Ry	\$	2,400.05	✓

\$ 20,779.25

Chen Taping
Monday
05/02/18
(Kenneth Kang)

Not Authorised
21km @ 15, 100k
Resumy After Pain
Jody



輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
Reg No. 201629438M

31/01/2018

Owner: KMR Construction & Engineering Pte Ltd

ESTIMATE TO REPAIR MITSUBISHI CENTER - GY7755U

balance b/f		\$ 20,779.25
1pc	front RH knuckle bearing	RM \$ 95.68 ✓
1pc	front RH tie rod	RM \$ 206.12 ✓
1pc	front RH steering rack Assy 2413-60	B1/32 \$ 7,430.80 ✓
1pc	front RH rotor disc	RM \$ 440.28 X
1pc	front RH brake caliper	RM \$ 1,786.60 X
1pc	front crossmember	RM \$ 2,131.95 X
1pc	radiator spare tank	RM \$ 184.85 ✓
1pc	air cleaner tank	RM \$ 813.35 X
1pc	air cleaner chamber	RM \$ 184.62 X
1pc	diesel tank	RM \$ 1,609.10 X
less 20%		\$ 35,662.60 35,377.95
25%		\$ 7,122.52 7,061.50
		\$ 28,530.08 29,246.3

remove & refit front windscreen & door glass	\$ 200.00 120
remove & refit front dashboard	\$ 300.00 280
remove & refit front undercarriage	\$ 480.00 240
remove & refit diesel tank	\$ 250.00 60
alignment	\$ 150.00 60
wiring	\$ 180.00 30
tuffkote	\$ 250.00 90
sealant	RM \$ 120.00 X
Spary Painting	\$ 1,800.00 1000
Labour Charge	\$ 1,700.00 1100
Total	\$ 33,960.08

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary (re)cost must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by the Repairer
Signature: _____
Date: _____

34,051.01
33,960.08

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

(Chuan Tapsing)
Monday
05/02/18.
(Kannath Varg)

31/01/2018

Owner: KMR Construction & Engineering Pte Ltd

Not Authorise
1/1 Lamp & ?
Presumy After Paint
8 days

ESTIMATE TO REPAIR MITSUBISHI CENTER - GY7755U

1pc	front centre grille	\$	527.33	?
1pc	front "MITSUBISHI" logo	\$	82.54	?
1pc	front "FUSO" emblem	\$	154.95	?
1pc	front bumper	Bu	\$ 821.47	✓
1pc	front RH corner panel	\$	564.37	?
1pc	front RH headlamp	\$	768.10	?
1pc	front RH corner lamp	CM	\$ 159.75	✓
1pc	front RH side lamp	CM	\$ 227.63	✓
1pc	front RH door	Ry	\$ 1,969.30	✓
2pcs	front RH door hinge @\$162.54	Ry	\$ 325.08	✓
1pc	front RH door inner lock	nu	\$ 389.21	✓
1pc	front RH door inner rubber	cu	\$ 216.50	5012A
1pc	front RH door inner trim panel	\$	565.92	?
1pc	front RH door lower garnish	CM	\$ 542.70	✓
1pc	front RH door lower garnish rubber	cu	\$ 154.00	✓
1pc	front RH door glass gear & motor	B-12	\$ 1,317.05	✓
1pc	front RH door glass moulding	\$	181.05	?
1pc	front RH door front garnish	su	\$ 138.00	X
1pc	front RH door rear garnish	su	\$ 158.00	X
1pc	front RH pillar	Ry	\$ 1,533.24	✓
1pc	front RH pillar rubber	cu	\$ 138.15	5012A
1pc	front RH step panel	Ry	\$ 496.36	✓
1pc	front RH step panel lower rubber	CM	\$ 36.15	✓
1pc	front RH step panel garnish	CM	\$ 339.36	✓
1pc	front RH wheel top panel	Bu	\$ 537.95	✓
1pc	front RH wheel top panel rubber	nu	\$ 77.40	✓
1pc	front RH wheel top panel garnish	CM	\$ 175.10	✓
1pc	front RH wheel rear garnish	\$	173.45	?
1pc	front RH wheel rear garnish lower rubber	\$	68.10	?
1pc	front RH rim	Ry	\$ 612.50	✓
1pc	front RH top arm	\$	914.09	?
1pc	front RH lower arm	\$	3,812.10	?
1pc	front RH absorber	\$	202.30	?
1pc	front RH knuckle arm	Ry	\$ 2,400.05	✓
balance c/f			\$ 20,779.25	



輝 陽 汽 車 有 限 公 司

HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

31/01/2018

Owner: KMR Construction & Engineering Pte Ltd

ESTIMATE TO REPAIR MITSUBISHI CENTER - GY7755U

balance b/f		\$ 20,779.25	
1pc	front RH knuckle bearing	\$ 95.68	✓
1pc	front RH tie rod	\$ 206.12	?
1pc	front RH steering rack	\$ 7,430.80	?
1pc	front RH rotor disc	\$ 440.28	X
1pc	front RH brake caliper	\$ 1,786.60	X
1pc	front crossmember	\$ 2,131.95	?
1pc	radiator spare tank	\$ 184.85	✓
1pc	air cleaner tank	\$ 813.35	?
1pc	air cleaner chamber	\$ 184.62	?
1pc	diesel tank	\$ 1,609.10	X
less 20%		\$ 35,662.60	35,307.95
		\$ 7,132.52	7,061.59
		\$ 28,530.08	29,246.36

remove & refit front windscreen & door glass	\$ 200.00	120
remove & refit front dashboard	\$ 300.00	240
remove & refit front undercarriage	\$ 480.00	240
remove & refit diesel tank	\$ 250.00	60
alignment	\$ 150.00	60
wiring	\$ 180.00	30
tuffkote	\$ 250.00	90
sealant	\$ 120.00	X
Spary Painting	\$ 1,800.00	1000
Labour Charge	\$ 1,700.00	1100
Total	\$ 33,960.08	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

34,031.01



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

SUITE 1, #02-25 PAYA LEBI INDUSTRIAL PARK, SINGAPORE 408933 TEL.: (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC6/CTI18002344/Kus3

Date: 20/03/2018

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

GY 7755U

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 05.02.2018 at the premises of M/s Hui Yang Motor Pte Ltd (Sin Ming) and have the following to report:-

Workshop Estimate Amount	: S\$	34,031.01
Revised Estimate Amount	: S\$	15,024.91
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:
The vehicle sustained damages at the
O/S Front & U/C portion



Comments/Present Status:
Damages Consistent
Estimated normal period for repairs: 8.0 days
Remarks :

Yours faithfully,

KENNETH KONG
Licensed Appraiser

821.47 ✓	527.33	108.25 ✓	108.25 ✓	120.00	80.00
159.75 ✓	82.54	69.08 ✓	69.08 ✓	240.00	60.00
227.63 ✓	154.95			240.00	240.00
1969.30 ✓	564.37			60.00	190.00
325.08 ✓	768.10			60.00	90.00
389.21 ✓	565.92			30.00	150.00
542.70 ✓	181.05			90.00	160.00
154.00 ✓	138.00			1000.00	120.00
1317.05 ✓	158.00			1100.00	800.00
1533.24 ✓	173.45				600.00
496.36 ✓	68.10				
36.15 ✓	914.09			2940.00	
339.36 ✓	3812.10				
537.95 ✓	202.30				2490.00
77.40 ✓	206.12				
175.10 ✓	7430.80				
612.50 ✓	440.28	177.33			
2400.05 ✓	1786.60				
95.68 ✓	2131.95				
184.85 ✓	813.35				
	184.62				
	1609.10				

12394.83

22913.12

35307.95	354.65	177.33	5430.00
12394.83	177.33		2940.00
22913.12	177.32		2490.00

12394.83

2478.97

9915.86

177.33

2940.00

13033.19

527.33 ✓

82.54 ✓

154.95 ✓

564.37 ✓

768.10 ✓

565.92 ✓

181.05 ✓

173.45 ✓

68.10 ✓

914.09 ✓

3812.10 ✓

202.30 ✓

206.12 ✓

7430.80 ✓

2131.95 ✓

813.35 ✓

}

CHECK ITEM

28058.11



184.62

18781.14

3756.23

15024.91

Mei Kwan (LKKAUTO)

From: Lucas Lee <lucas.lee@sg.cntaiping.com>
Sent: Friday, 18 May, 2018 2:50 PM
To: Mei Kwan (LKKAUTO)
Subject: RE: Direct Settlement - Accident Involving SJH2806T (OI : CTI - SNM18D00617C02) AND GY7755U (TP : LKK REF - CC6/CTI18002344/Kus3) on 31/01/2018
Attachments: LeeSZ_SNM18D00617C02-SJH2806T-LKKDirectSettlementAccidentLtr_CLCR95.293.pdf; MSAT18015790-SJH2806T.pdf
Follow Up Flag: Follow up
Flag Status: Completed
Categories: HMK

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Irene Tay

Lucas Lee
Claims Department (Motor)
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6181
Fax (65) 6222 7175
Email: lucas.lee@sg.cntaiping.com
Website: www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Thursday, 17 May, 2018 10:53 AM
To: Claims Dept of CTI
Cc: Irene Tay; Lucas Lee; Admin A; Thin Thin (LKKAUTO); Vivian Lau (LKKAUTO)
Subject: RE: Direct Settlement - Accident Involving SJH2806T (OI : CTI - TBA) AND GY7755U (TP : LKK REF - CC6/CTI18002344/Kus3) on 31/01/2018

Dear Sir/Madam,



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
Tel: 6389 6111 Fax: 6222 1033
Website: www.sg.cntaiping.com
Co. Reg. No. 200208384E

Our Reference: **SNM18D00617/C02/6**

Date : **18 MAY 2018**

via Ordinary & Registered Mail

**MOHAMAD NOOR BIN ABDULRAHMAN
BLK 115 HO CHING ROAD
#02-110
SINGAPORE 610115**

Dear Sir / Madam

**ACCIDENT INVOLVING SJH2806T AND GY7755U ON 31 JANUARY 2018
ALONG JUNCTION OF JALAN BUROH TOWARDS JURONG PORT ROAD**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **GY7755U** , is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,
Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd

Attn : THIN THIN
Ref : CC6/CTI18002344/KUS3
Contact No : 68412360
via Email : THINTHIN@LKKAUTO.COM

CC : Agent - (AN0226A) - SIX PHASE E & T

F01/LKKDS-2013

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CTI18002344/Kea3s2		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 09-04-2019		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJH 2806T	Veh. Inspected	GY 7755U	
Policy No.	DMPCSN3061271803	Coverage (\$)	0.00	
Claim No.	SNM18D00617/C02/6	Excess (\$)	0.00	
Assign From		Assign Date	05/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI FB70BB1SRDEA	c.c	2977	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	FB70BBA10129	Colour	WHITE	
Odometer	400315	Steering	JAMMED	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/75 R15	BRIDGESTONE	7 mm	
L/H Front Tyre	185/75 R15	BRIDGESTONE	7 mm	
R/H Rear Tyre	195 R15X8 (D)	MICHELIN	5/5 mm	
L/H Rear Tyre	195 R15X8 (D)	MICHELIN	5/5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	31/01/2018	Inspection Date	05/02/2018	
Survey held at	HUI YANG MOTOR SERVICE BLOCK 176 SIN MING DRIVE #04-02/03 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GY 7755U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT CENTRE GRILLE	MTG CRACKED	527.33	527.33
1	FRONT "MITSUBISHI" LOGO	NECESSARY	82.54	82.54
1	FRONT "FUSO" EMBLEM	NECESSARY	154.95	154.95
1	FRONT BUMPER	BUCKLED	821.47	821.47
1	FRONT RH CORNER PANEL	TO REPAIR SEE LABOUR	564.37	-
1	FRONT RH HEADLAMP	MTG CRACKED	768.10	768.10
1	FRONT RH CORNER LAMP	CRACKED	159.75	159.75
1	FRONT RH SIDE LAMP	CRACKED	227.63	227.63
1	FRONT RH DOOR	BENT	1,969.30	1,969.30
2	FRONT RH DOOR HINGE @ \$162.54	BENT	325.08	325.08
1	FRONT RH DOOR INNER LOCK	DENTED	389.21	389.21
1	FRONT RH DOOR INNER TRIM PANEL	SERVICEABLE	565.92	-
1	FRONT RH DOOR LOWER GARNISH	CRACKED	542.70	542.70
1	FRONT RH DOOR LOWER GARNISH RUBBER	CUT	154.00	154.00
1	FRONT RH GLASS GEAR & MOTOR	BENT / JAMMED	1,317.05	1,317.05
1	FRONT RH DOOR GLASS MOULDING	DENTED	181.05	181.05
1	FRONT RH DOOR FRONT GARNISH	SERVICEABLE	138.00	-
1	FRONT RH DOOR REAR GARNISH	SERVICEABLE	158.00	-
1	FRONT RH PILLAR	BENT	1,533.24	1,397.55
1	FRONT RH STEP PANEL	BENT	496.36	496.36
1	FRONT RH STEP PANEL LOWER RUBBER	CRACKED	36.15	36.15
1	FRONT RH STEP PANEL GARNISH	CRACKED	339.36	339.36
1	FRONT RH WHEEL TOP PANEL	BUCKLED	537.95	537.95
1	FRONT RH WHEEL TOP PANEL RUBBER	DENTED	77.40	77.40
1	FRONT RH WHEEL TOP PANEL GARNISH	CRACKED	175.10	175.10
1	FRONT RH WHEEL REAR GARNISH	SERVICEABLE	173.45	-
1	FRONT RH WHEEL REAR GARNISH LOWER RUBBER	SERVICEABLE	68.10	-
1	FRONT RH RIM	BENT	612.50	612.50
1	FRONT RH TOP ARM	BENT	914.09	914.09
1	FRONT RH LOWER ARM	BENT	3,812.10	3,403.67

Report Ref No. CC6/CTI18002344/Kea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT RH ABSORBER	BENT	202.30	202.30
1	FRONT RH KNUCKLE ARM	BENT	2,400.05	2,338.39
1	FRONT RH KNUCKLE BEARING	NECESSARY	95.68	95.68
1	FRONT RH TIE ROD	BENT	206.12	206.12
1	FRONT RH STEERING RACK ASSY	BENT / JAMMED	7,430.80	2,413.60
1	FRONT RH ROTOR DISC	SERVICEABLE	440.28	-
1	FRONT RH BRAKE CALIPER	SERVICEABLE	1,786.60	-
1	FRONT CROSSMEMBER	SERVICEABLE	2,131.95	-
1	RADIATOR SPARE TANK	DENTED	184.85	184.85
1	AIR CLEANER TANK	SERVICEABLE	813.35	-
1	AIR CLEANER CHAMBER	SERVICEABLE	184.62	-
1	DIESEL TANK	TO REPAIR SEE LABOUR	1,609.10	-
	LESS 20% DISCOUNT		-7,061.59	-
	LESS 25% DISCOUNT		-	-5,262.81
			28,246.36	15,788.42
1	FRONT RH DOOR INNER RUBBER (50%) (SN)	CUT	216.50	108.25
1	FRONT RH PILLAR RUBBER (50%) (SN)	CUT	138.15	69.07
	LESS 20% DISCOUNT		-70.93	-
			283.72	177.32
<u>SPECIAL NETT ITEMS</u>				
1	SEALANT (SN)	NOT NECESSARY	120.00	-
			120.00	-
<u>LABOUR</u>				
	REMOVE & REFIT FRONT WINDSCREEN & DOOR GLASS.		200.00	120.00
	REMOVE & REFIT FRONT DASHBOARD.		300.00	240.00
	REMOVE & REFIT FRONT UNDERCARRIAGE.		480.00	240.00
	REMOVE & REFIT DIESEL TANK.		250.00	60.00
	ALIGNMENT.		150.00	60.00
	WIRING.		180.00	30.00
	TUFFKOTE.		250.00	90.00

Report Ref No. CC6/CTI18002344/Kea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINTING.		1,800.00	1,000.00
	LABOUR CHARGE. INCLUSIVE OF THE REPAIR OF FRONT RH CORNER PANEL AND DIESEL TANK.		1,700.00	1,100.00
			5,310.00	2,940.00
GRAND TOTAL			33,960.08	18,905.74
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				15,100.00

Report Ref No. CC6/CTI18002344/Kea3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.