

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐	 5	REAR WINDSCREEN INNER SEAL	Reviewing	30	NECESSARY	
☐	 6	RH FRONT TYRE	Reviewing	280	PUNCTURED	
☐	 7	RH FRONT WHEEL RIM	Reviewing	350	BENT	
☐	 8	LH FRONT TYRE	Reviewing	0	NOT NECESSARY	
☐	 9	LH FRONT WHEEL RIM	Reviewing	0	NOT NECESSARY	
☐	 10	LH REAR WHEEL RIM	Reviewing	0	NOT NECESSARY	
☐	 11	LH REAR TYRE	Reviewing	0	NOT NECESSARY	
☐	 12	RH REAR WHEEL RIM	Reviewing	0	NOT NECESSARY	
☐	 13	RH REAR TYRE	Reviewing	0	NOT NECESSARY	

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	PAINT	ACTION (LABOUR)	COMMENT
☐	 65	1			LH FRONT SHOCK ABSORBER			Serviceable	0			0
☐	 66	1			LH FRONT SHOCK ABSORBER TOP MOUNTING			Serviceable	0			0
☐	 67	1			LH FRONT SHOCK ABSORBER STOPPER			Serviceable	0			0
☐	 68	1			LH FRONT LOWER ARM WITH BALL JOINT			Serviceable	0			0
☐	 69	1			LH REAR SHOCK ABSORBER			Serviceable	0			0
☐	 70	1			LH REAR SHOCK ABSORBER TOP MOUNTING			Serviceable	0			0
☐	 71	1			LH REAR SHOCK ABSORBER STOPPER			Serviceable	0			0
☐	 72	1			RH REAR SHOCK ABSORBER			Serviceable	0			0
☐	 73	1			RH REAR SHOCK ABSORBER TOP MOUNTING			Serviceable	0			0
☐	 74	1			RH REAR SHOCK ABSORBER STOPPER			Serviceable	0			0
Labour												

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT
☐	 1		TO MOUNT VEHICLE ON BLACK HAWK FLOOR BENCH IN ORDER TO RE-ALIGN CHASSIS MEMBERS OR BODY STRUCTURE.	0	0	0	Reviewing	

EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)
	39	1			REAR NUMBER PLATE LAMP RH			Serviceable	0				0
	40	1			REAR WINDSCREEN WITH MOULDING			Necessary	25				25
	41	1			REAR WIPER ARM			Serviceable	0				0
	42	1			REAR WIPER ARM COVER			Serviceable	0				0
	43	1			REAR WIPER BLADE			Serviceable	0				0
	44	1			REAR WIPER MOTOR			Serviceable	0				0
	45	1			REAR END PANEL (COMPLETE)			Buckled	180				180
	46	1			REAR END PANEL INNER GARNISH			Damaged	85				85
	47	1			LH REAR FENDER INNER LOWER GARNISH			Serviceable	0				0
	48	1			SPARE TYRE COVER			Damaged	240				240
	49	1			BOOTFLOOR SIDE SPACER LH			Damaged	80				80
	50	1			BOOTFLOOR SIDE SPACER RH			Serviceable	0				0
	51	1			BOOTFLOOR REAR SPACER			Serviceable	0				0
	52	1			EXHAUST SILENCER			Serviceable	0				0

6/20/2018

Claim Portal

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)
	10	1			REAR BUMPER SIDE BRACKET RH			Serviceable	0				0
	11	10			REAR BUMPER CLIPS			Necessary	2				20
	12	1			TAILLAMP LH			Cracked	210				210
	13	1			TAILLAMP RH			Serviceable	0				0
	14	2			TAILLAMP CLIPS			Necessary	2				4
	15	1			TAILGATE			Denied	540				540
	16	1			TAILGATE BADGE LOGO			Necessary	40				40
	17	1			TAILGATE EMBLEM - SUBARU			Necessary	25				25
	18	1			TAILGATE EMBLEM - IMPREZA			Necessary	20				20
	19	1			TAILGATE CHROMED HANDLE			Damaged	180				180
	20	1			TAILGATE UPPER LOCK			Bent	120				120
	21	1			TAILGATE UPPER LOCK ACTUATOR (NPA)			Serviceable	0				0
	22	1			TAILGATE LOWER LOCK			Repair	0				0
	23	1			TAILGATE HINGE LH			Repair	0				0

Detailed Assessment

Inspection Date *

02/07/2018



Condition of Vehicle at time of survey

General condition

Good

Total Loss

Yes No

Steering (Serviceable)

Yes No

Towing Charges

0

Footbrake (Serviceable)

Yes No

Voluntary Excess

0

Handbrake (Serviceable)

Yes No

Compulsory Excess

0

Engine Modification

Yes No

Young/Inexperienced/Unnamed Driver Excess

0

Pre-accident condition

Good

Other Excess

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

205/55R16

Rear Tyre Size

205/55R16

FNOL INFORMATI... BLK 156 BISHAN STREET 13 #07-88,
570156, Singapore

POST SURVEY INF...

CATEGORY

Address type

FNOL INFORMATI...

Personal Correspondence

POST SURVEY INF...

CATEGORY

Gender

FNOL INFORMATI...

Male

POST SURVEY INF...

CATEGORY

Marital status

FNOL INFORMATI...

Unknown

POST SURVEY INF...

CATEGORY

Identification #

FNOL INFORMATI...

S1244845G

CATEGORY	Make	
POLICY INFORMAT...	SUBARU	
ASSESSMENT INFO...	SUBARU	
CATEGORY	Model	
POLICY INFORMAT...	IMPREZA 1.5R	
ASSESSMENT INFO...	IMPREZA 5D 1.5R AWD AT	
CATEGORY	Type	
POLICY INFORMAT...		
ASSESSMENT INFO...		
CATEGORY	Type of Paint	
POLICY INFORMAT...		
ASSESSMENT INFO...		
CATEGORY	Chassis No	
POLICY INFORMAT...	JF1GH3KS58G020087	

CATEGORY	Date of Birth	
FNOL INFORMATI...	March 4, 1957	
POST SURVEY INF...	mm/dd/yyyy	
CATEGORY	Age	
FNOL INFORMATI...	61	
POST SURVEY INF...		
CATEGORY	Occupation	
FNOL INFORMATI...	Unknown	
POST SURVEY INF...		
CATEGORY	Education Qualification	
FNOL INFORMATI...	Other	
POST SURVEY INF...		
CATEGORY	Driving Experience	

Accelerated
workshop survey

TEO Kitty
6568804602
kitty.teo@axa.com.sg

Additional Instructions

- Messages
- Assessment
- Invoices
- Metrics
- History
- Notes
- Documents
- Add

EXCESS \$1800+\$500(UNNAMED)=\$2300

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
User Portal	6/20/18 12:00 PM	1900	1900	Open	Share	Clone
TEO Kitty	2/6/18 2:30 PM	5229	5229	Open	Share	Clone

Accelerated
workshop survey

TEO Kitty
6568804602
kitty.teo@axa.com.sg

Additional Instructions

Messages Invoices History Documents

EXCESS \$1800+\$500(UNNAMED)=\$2300

Assessment Metrics Notes

Document Type

Document SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Accident Statement	Reports & Statement		Merimen	
SJN 8307X.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (OD)	February 8, 2018
SJN 8307X INSPECTION PHOTO.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (OD)	February 8, 2018
SJN 8307X OD IA.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (OD)	February 8, 2018