

# ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

*Not Authorized* ESTIMATE

AXA Insurance Singapore Pte Ltd  
8 Shenton Way,  
#27-01/02 AXA Tower  
Singapore 068811  
Attn: Motor Claims Department

*\$ 291.68*  
*1 day*

Date : 05/02/2018  
Vehicle No : SGH3034H  
Veh Make/Model : Honda Civic 1.8L A  
YOM : 2006  
Chassis No : JHMFD16206S208459  
Date of Accident : 03/02/2018

No	Qty	Description	Amount \$	
<b>List Items:-</b>				
1	1	Rear bumper	\$ <i>R</i> 638.00	X
2	2	Rear bumper side retainer	\$ <i>MSP</i> 29.20	X
3	10	Rear bumper clip	\$ <i>nn</i> 38.00	X
<b>Total - List Item</b>			\$ 705.20	
<b>Less 20%</b>			\$ 141.04	
<b>Total</b>			\$ 564.16	
<b>Special Nett Items:-</b>				
	1 Set	Rear reverse sensor	\$ <i>Sn</i> 380.00	X
<b>Total - SN Item</b>			\$ 380.00	
<b>Labour Charges:-</b>				
1		Spray painting on all affected area.	\$ 300.00	2000
2		Labour remove/refix accident damages parts to knock, jack, cut weld and realign accident affected area.	\$ 350.00	800
3		To apply anti rust treatment.	\$ <i>nn</i> 60.00	X
4		To remove and replace reverse sensor.	\$ <i>nn</i> 120.00	✓
<b>Total - L/C</b>			\$ 830.00	
<div style="border: 1px solid black; padding: 5px;"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>• To resurvey before enter spray painting</li> <li>• To display damaged part(s) during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "Without Prejudice" basis</li> <li>• No illegal modification(s) is allowed</li> <li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer Signature: Date:</p> </div>				
<b>Sub-Total</b>			\$ 1,774.16	
<b>7% GST</b>			\$ 124.19	
<b>Total</b>			\$ 1,898.35	