



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Table with 2 main columns: Invoice Name & Address (ROHIMAN BIN AMAN, Contact No Mobile:98581456) and Owner Name & Vehicle Info (Cust No/Name, Reg No/Reg Date, Date In/Mileage, Chassis No, Engine No, Make/Model, Colour, Trim).

Table with 6 columns: Account No, Terms, Date/Time Printed, CSE, Operator, WIP No.

Main table with 6 columns: Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Includes handwritten notes like 'Estimate', '1260', and '1200'.

Table with 2 columns: Confirm & accepted by, Authorized signatory and company stamp.

Validity of this estimate is 14 days from date of quote. This is a computer generated document... Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced.



CYCLE & CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
ROHIMAN BIN AMAN	Cust No/Name LCV04334/CCKPDI
	Reg No/Reg Date SLV3529P /
	Date In/Mileage 06/02/2018/ 0
	Chassis No KNAHU815VJ7188202
	Engine No D4FDHH109196
Contact No Mobile:98581456	Make/Model KIA/CARENS 1.7 A D SX FL DY6
	Colour/Trim K7N / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00001	Cash	06/02/2018/ 16:08	DS	218 / MarsLer	52014

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M KS 86583 A4 800 HOLDER PARKING ASSIS <i>- LKSC.</i>	1.00	0.00	10.00	
M KS 86584 A4 800 HOLDER PARKING ASSIS <i>- LKSC.</i>	1.00	0.00	10.00	
M KS 95720 A4 100K 7N ULTRASONIC SENSOR <i>- Png</i>	1.00	0.00	10.00	
M KS 91895 A4 020 WIRING HARNESS, FWS <i>- ?</i>	1.00	0.00	10.00	
M KS 92202 A4 500 RHF FOG LAMP ASSY <i>- n/s.</i>	1.00	0.00	10.00	
M KS 86522 A4 810 RHF FOG LAMP COVER <i>- n/s.</i>	1.00	0.00	10.00	
M KS 64101 A4 000 CARRIER ASSY - FRONT <i>?</i>	1.00	628.00	10.00	565.20
M KS 92101 A4 160 LH LAMP ASSY-HEAD <i>?</i>	1.00	1558.00	10.00	1402.20
M KS 92102 A4 160 RH LAMP ASSY-HEAD <i>?</i>	1.00	1558.00	10.00	1402.20
P JJMR200300 CLIP, BUMPER <i>- ?</i>	10.00	2.00	10.00	18.00
M JJMZ313950 COOLANT <i>?</i>	4.00	26.00	10.00	93.60

Z NOTES

ACCIDENT ON 06/02/2018 ALONG BLK 301 UBI AVE 1 OPEN CARPARK
OWNER CLAIMING THIRD PARTY
REQUIRED REPLACEMENT CAR
TP : YP5275K TP INS : AXA

*4 Days.
part by part.
before part photos.
Gmo Qng - 8188 0282
07/2/18.*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Confirm & accepted by	Parts	3,649.50
	Labour	0.00
	Standard Menu	0.00
	Specialist Job	5,910.00
	Others (Lub, etc)	0.00
	Sundry	0.00
Authorized signatory and company stamp	Total (w/o GST)	9,559.50

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.