

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BITTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	F
	10	1			TAPE, REAR SIDE SPOILER		Necessary	Necessary	17.5		10		15.75	F
	11	1			TAPE, REAR SIDE SPOILER		Necessary	Necessary	12.6		10		11.34	F
	12	1			TAPE, REAR SIDE SPOILER		Necessary	Necessary	12.6		10		11.34	F
	13	4			CLIP, REAR SIDE SPOILER		Necessary	Necessary	4.9		10		17.64	F
	14	1			GASKET(LHS), TAILGATE LAMP		Necessary	Necessary	51.7		10		46.53	F
	15	1			GASKET(RHS), TAILGATE LAMP		Necessary	Necessary	51.7		10		46.53	F
	16	1			TRAY, REAR PACKAGE		Serviceable		0		10		0	F

Labour

Add

Approve

Deny

Submit All

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR RAR	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT
	1		TO REPLACE TAILGATE, TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	660	0	0	Reviewing	
	2		TO RESPRAY TAILGATE.	630	0	0	Reviewing	
	3		TO REPLACE REAR WINDSCREEN GLASS.	560	0	0	Reviewing	
	4		TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	0	0	Reviewing	
	5		TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	160	0	0	Reviewing	

Detailed Assessment

Inspection Date *

02/07/2018



Total Loss

Yes No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Tyre Condition

Age of Tyres

Front Tyre Size

185/60R16

Rear Tyre Size

185/60R16

Condition of Vehicle at time of survey

General condition

Good

Steering (Serviceable)

Yes No

Footbrake (Serviceable)

Yes No

Handbrake (Serviceable)

Yes No

Engine Modification

Yes No

Pre-accident condition

-- none --

Spare wheel

FNOL INFORMATI... BLK 527, HOUGANG AVE 6, #11-209,
530527, Singapore

POST SURVEY INF...

CATEGORY Address type

FNOL INFORMATI... Residential

POST SURVEY INF...

CATEGORY Gender

FNOL INFORMATI... Female

POST SURVEY INF...

CATEGORY Marital status

FNOL INFORMATI... Single

POST SURVEY INF...

CATEGORY Identification #

FNOL INFORMATI... S8027918C

CATEGORY Make

POLICY INFORMAT... MAZDA

ASSESSMENT INFO... MAZDA

CATEGORY Model

POLICY INFORMAT... 2 1.5

ASSESSMENT INFO... MAZDA2 5-DOOR HATCHBACK 1.5L S

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... JM6DJ2HAA01100260

CATEGORY Date of Birth

FNOL INFORMATI... September 6, 1980

POST SURVEY INF... mm/dd/yyyy

CATEGORY Age

FNOL INFORMATI... 37

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

Accelerated survey
and authorize

Claim Handler

TEO Kitty
6568804602
kitty.teo@axa.com.sg

- Messages
- Assessment
- Invoices
- Metrics
- History
- Notes
- Documents
- Add

Additional Instructions

EXCESS NIL

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
TEO Kitty	2/6/18 5:56 PM	4287.49	4287.49	Open	Share	Clone

Accelerated survey
and authorize

Claim Handler

TEO Kitty
6568804602
kitty.leo@axa.com.sg

Documents

Messages

Invoices

History

Assessment

Metrics

Notes

Additional Instructions

EXCESS NIL

Document Type

Document SubType

Upload Documents

NAME	TYPE	SUB- TYPE	AUTHOR	DATE UPLOADED
resurvey.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (OD)	August 1, 2018
SKW 8261J photo.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (OD)	March 19, 2018
PHOTO SURVEY.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (OD)	March 19, 2018