



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2016 SUBARU FORESTER 2.0XT (SGN7326H)

Date of Loss

7 February 2018

Time of Loss

7.30

Loss Description

SGN7326H (INSD) HIT GBB1951P (TP) INTO REAR

Comment

Workshop Details

Total Rebate Amount

56426

Nett Loss Amount

\$53,574.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

24/06/2018



Days of work completion *

137



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#
SGN7326H

Registration State

SINGAPORE

Mileage

50272

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2016

ASSESSMENT INFO...

2016

Purchase Date

dd/mm/yyyy



Registration Date *

16/05/2016



Age of Vehicle

1

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

LOH PIH YEN

POST SURVEY INF...

CATEGORY Make

POLICY INFORMAT... SUBARU

ASSESSMENT INFO... SUBARU

CATEGORY Model

POLICY INFORMAT... FORESTER 2.0XT

ASSESSMENT INFO... FORESTER 2.0XT CVT AWD SR

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... JF1SJGK85GG070869

CATEGORY Date of Birth

FNOL INFORMATI... 18 January 1963

POST SURVEY INF... dd/mm/yyyy



CATEGORY Age

FNOL INFORMATI... 55

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

ASSESSMENT INFO...

JF15JGK85GG070869

CATEGORY

Engine No

POLICY INFORMAT... FA20A910997

ASSESSMENT INFO...

FA20A910997

CATEGORY

Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO...

1998

CATEGORY

Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO...

0

CATEGORY

Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO...

110000

FNOL INFORMATI... 16

POST SURVEY INF...

CATEGORY

Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY

License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY

License Issue Date

FNOL INFORMATI...

POST SURVEY INF...

dd/mm/yyyy



CATEGORY

License Expiration Date

FNOL INFORMATI...

POST SURVEY INF...

dd/mm/yyyy



CATEGORY

Address

FNOL INFORMATI... BLK 250 #15-454, CHOA CHU KANG
AVENUE 2, 680250, Singapore

POST SURVEY INF...

CATEGORY Address type

FNOL INFORMATI... Residential

POST SURVEY INF...

CATEGORY Gender

FNOL INFORMATI... Male

POST SURVEY INF...

CATEGORY Marital status

FNOL INFORMATI... Married

POST SURVEY INF...

CATEGORY Identification #

FNOL INFORMATI... S1576360D

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

08/02/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

400

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

225/55R18

Condition of Vehicle at time of survey

General condition

Good

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good

Tyre Condition

Spare wheel

Rear Tyre Size

225/55R18

Front left side

BRIDGESTONE6mm

Front right side

BRIDGESTONE6mm

Rear left side

BRIDGESTONE6mm

Rear right side

BRIDGESTONE6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

20

Settlement%

100

Paint Labour/Material Ratio

Paint Labour Ratio

20

Paint Material Ratio

80

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
☐		1	1			BUMPER FACE - FRONT			Deformed	594		20		475.2	Review
☐		2	1			BARCKET - FRONT BUMPER SIDE, RIGHT			Necessary	12.6		20		10.08	Review
☐		3	1			BRACKET- FRONT BUMPER SIDE, LEFT			Necessary	12.6		20		10.08	Review
☐		4	1			BRACKET- FRONT BUMPER CORNER, RIGHT			Necessary	36		20		28.8	Review
☐		5	1			BRACKET- FRONT BUMPER CORNER, LEFT			Necessary	36		20		28.8	Review
☐		6	1			ENERGY ABSORBER- FRONT BUMPER			Deformed	126		20		100.8	Review
☐		7	1			BACK BEAM COMPLETE- FRONT			Bent	288		20		230.4	Review
☐		8	1			COVER-FRONT BUMPER, RIGHT			Serviceable	0	0	0	0	0	Deny
☐		9	1			COVER-FRONT BUMPER, LIGHT			Missing	12.6		20		10.08	Review
☐		10	1			COVER-FOG LIGHT, RIGHT			Serviceable	0	0	0	0	0	Deny
☐		11	1			COVER-FOG LIGHT, LEFT			Serviceable	0	0	0	0	0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		12	1			COVER - FRONT BUMPER			Deformed	5.4		20		4.32	Review
		13	1			LAMP ASSEMBLY- HEAD RIGHT			Cracked	2380		20		1904	Review
		14	1			LAMP ASSEMBLY- HEAD LEFT			Cracked	2380		20		1904	Review
		15	2			FOG LIGHT ASSEMBLY- FRONT			Serviceable	0	0	0	0	0	Deny
		16	1			HOOD COMPLETE- FRONT			Bent	882		20		705.6	Review
		17	1			DUCT-INNER FRONT HOOD			Serviceable	0	0	0	0	0	Deny
		18	1			LOCK ASSEMBLY- FRONT HOOD			Bent	54		20		43.2	Review
		19	1			HINGE COMPLETE- FRONT HOOD, RIGHT			Serviceable	0	0	0	0	0	Deny
		20	1			HINGE COMPLETE- FRONT HOOD, LEFT			Serviceable	0	0	0	0	0	Deny
		21	1			STAY-HOOD SUPPORT			Serviceable	0	0	0	0	0	Deny
		22	1			INSULATOR- FRONT HOOD RIGHT			Deformed	36		20		28.8	Review
		23	1			INSULATOR- FRONT HOOD LEFT			Deformed	36		20		28.8	Review

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		24	1			COVER ASSEMBLY- LAMP WASHER NOZZLE, RIGHT			Missing	54		20		43.2	Review
		25	1			COVER ASSEMBLY,LAMP WASHER NOZZLE, LEFT			Missing	54		20		43.2	Review
		26	1			NOZZLE-LAMP WASHER, RIGHT			Serviceable	0	0	0	0	0	Deny
		27	1			NOZZLE-LAMP WASHER, LEFT			Damaged	79.2		20		63.36	Review
		28	1			HOSE ASSEMBLY- HEAD LAMP WASHER			Serviceable	0	0	0	0	0	Deny
		29	1			FENDER COMPLETE- FRONT, RIGHT			Bent	270		20		216	Review
		30	1			FENDER COMPLETE- FRONT, LEFT			Bent	270		20		216	Review
		31	1			MUD GUARD, FRONT RIGHT			Serviceable	0	0	0	0	0	Deny
		32	1			MUD GUARD, FRONT LEFT			Serviceable	0	0	0	0	0	Deny
		33	1			CLIP-2PIECE D8 (18PCS)			Necessary	1.8		20		1.44	Review
		34	1			CLIP-BUMPER			Necessary	2.4		20		1.92	Review
		35	1			FRONT GRILLE ASSEMBLY, CENTER			Cut	180		20		144	Review
		36	1			FRONT GRILLE ASSEMBLY, LOWER			Deformed	316.8		20		253.44	Review

EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTRY%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)
	37	1			FRONT GRILLE ASSEMBLY, UPPER			Cut	140.4		20		112.32	Review
	38	1			BRACKET-GRILL LOWER			Damaged	21.6		20		17.28	Review
	39	1			CONDENSER ASSEMBLY			Bent	579.35		20		463.48	Review
	40	1			FAN & MOTOR ASSEMBLY			Damaged	468		20		374.4	Review
	41	1			RADIATOR ASSEMBLY			Bent	810		20		648	Review
	42	1			HOSE- RADIATOR OUTLET			Deformed	28.8		20		23.04	Review
	43	1			HOSE- RADIATOR INLET			Deformed	39.6		20		31.68	Review
	44	1			MOTOR ASSEMBLY			Serviceable	0	0	0	0	0	Deny
	45	1			SHROUD- RADIATOR			Cracked	86.4		20		69.12	Review
	46	1			FAN			Damaged	54		20		43.2	Review
	47	1			NUT ASSEMBLY- CONDENSER			Necessary	1.8		20		1.44	Review
	48	1			BOLT-FAN MOTOR-3PCS			Necessary	3.6		20		2.88	Review
	49	2			TAPPING SCREW- HEXAGON HEAD			Serviceable	0	0	0	0	0	Deny
	50	1			PANEL COMPLETE- RADIATOR			Bent	360		20		288	Review

EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)
	51	1			FRAME COMPLETE- RADIATOR, LOWER			Serviceable	0	0	0	0	0	Deny

Labour

Add Approve Deny										
EDIT		SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	RE
		1		TO CONDUCT WHOLE CAR POLISHING AND NANOSIEL PAIRWORK PROTECTION	0	0	0	Deny		
		2		REPLACE FRONT BOTH SIDE HEADLAMP ASSY, BONNET, FENDER BOTH SIDE, FOG LAMP, BUMPER, BUMPER BEAM	2240	0	0	Reviewing		
		3		ENERGY ABSORBER, GRILLE, TOW COVER, HEADLAMP WASHER (NPA)	0	0	0	Deny		
		4		RESPRAY FRONT BUMPER, BONNET, FENDER BOTH SIDE BEAM	2760	0	0	Reviewing		
		5		REMOVE & REFIX AIR CON CONDENSER & RADIATOR TO FACILITATE REPAIR	300	0	0	Reviewing		
		6		COOLING SYSTEM PRESSURE TEST	100	0	0	Reviewing		

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

EDIT

SR
NO

NAME

ACTION

AMOUNT

COMMENT

REMOVE



1

DAYS OF
REPAIR : 9
DAYS

Reviewing



2

NUMBER
PLATE

Reviewing

50

BENT



3

SUNDRIES

Reviewing

80

NECESSARY



4

TANK
RESERVE
(DISC
20%)

Reviewing

48.96

DEFORMED
(SUPPLEMENTARY)

Assessment Details

General & Workshop Details		Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Claim Amount	\$13,749.32			Claim Amount	\$13,749.32			

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$5,400.00	\$5,400.00
Miscellaneous	\$178.96	\$178.96
Excess	-\$400.00	-\$400.00

[Submit for Review](#)