

ASS. REC. BY:

REF: CS/FCI18002514/ Yqdz n2

Special Instruction:

Surveyor:

Marcus

ASSIGNMENT (Office)

CWS

From (Person):

Lurene jaw

of

FCI

Date/Time

7/2/18 @ 3.18pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBE 146M

Insured:

SHB 3517B

at Workshop m/s

Specialist Motor

Tel:

6747 2112

of

Blk 3018A Ubird 1 # 01-24-26

Policy No:

D/18088937 MFSH

Claim No:

D18001117 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 3/2/18

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time

3.46pm @

Person Contacted:

Hui Lin

Vehicle IN/OUT

OUT

Date/Time	Action/Instruction (✓) Estimate
	GBE 146M-X
	SHB 3517B-CS/FCI14013387/Rqm3u2
15/2 @ 9:20am	Revert prev via email.

REF: TOL

ASSIGNMENT

From: Date: 14032018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

9:30am

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

ID: Accident Report

Consistent? : Yes or No

C/A: PR Seek

Consistent? : Yes or No

Est. Repairs:

4

days

Res:

Yes or No

Lump Sum:

20

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

301000

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: GBE146M Yr Regn: 8 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (M)

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In Order / Jammed / Leaked / Burnt or

Brake: In Order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal:

L/Bal:

D.O.A:

Survey held at

Rear

R/Bal:

L/Bal:

D.O.A:

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision:

Date / Time Action / Instruction

L7A 37133

21/3/18 4/5 * 3350 confirmed with hunkin.
(Cred # 2059-93, 3810)

RECEIVED 22 MAR 2018.

Date/Time File Pass to?



Prel. Report

1) 21/3/18



Final Report

Date/Time File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation

S - RS - SI

Photo

Other

Add Fee:



Site Insp \$



Interview \$



Tech Insp \$



Weekend \$

Report Format:

Lump Sum / L.B.I: (\$

TP

3350

TOTAL

140

50

50

50

290



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18002514/Uqd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 07-02-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 3517B	Veh. Inspected	GBE 146M	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18001117MFSH	Excess (\$)	0.00	
Assign From	CWS (LURENE JAW)	Assign Date	07/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	03/02/2018	Inspection Date		
Survey held at	SPECIALISTS MOTOR PTE LTD BLK 3018A UBI ROAD 1 #01-24-26 SINGAPORE 408711			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

MOTOR SURVEY ASSIGNMENT

Date	06-02-2018	Our Ref No. D18001117MFSH
Accident Date	03-02-2018	Claim Type. Third Party
Insured Vehicle	SHB3517B	Third Party Vehicle. GBE146M
Survey Location	BLK 3018A UBI ROAD 1 #01-24-26	
Contact Person.	HUI LIN	
Contact No.	67472112/ 0	Fax No. 0
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SPECIALISTS MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/234729)



PRI Documents



Close



PRI Header Details

Claim No	D18001117MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & SPECIALI
Workshop Name	SPECIALISTS MOTOR PTE LTD (Contact Person : HUI LIN)	Survey Location & Contact Details	BLK 3018A UBI ROAD 1 #01-24-26 Mobile: 0 , Phone: 67472112 , Fax: 0 EmailId: CARDOC@SINGNET.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHB3517B	TP Vehicle No	GBE146M
PRI Recieved Date	06-02-2018 09:32:54 PM	Surveyor Appointed Date	07-02-2018 03:17:26 PM	Surveyor Accept Date	07-02-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	07-02-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Thursday, 15 February 2018 9:20 AM
To: Admin-D (LKKAuto); 'Claim Workflow System'; assignments
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18001117MFSH/1
Attachments: PRELI ADVISED GBE146M.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **GBE 146M**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 7 February 2018 3:48 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18001117MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 7 February 2018 3:18 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18001117MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18001117MFSH

Date: 15/2/2018

Our Ref: CS/FCI18002514/Uqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. GBE 146M

Please be informed that we had conducted the inspection of the abovementioned vehicle on 14/2/2018 at the premises of M/s Specialists Motor, and have the following to report: -

Workshop Estimate Amount	: S\$ 5,409.93
Revised Estimate Amount	: S\$ 4,196.00
"Check" Items Amount	: S\$ -
Market Value	: S\$ -
LTA Reimbursement Value	: S\$ -
Nett Value	: S\$ -

Description of Damage:

The vehicle sustained damages at the rear o/s.



Comments/ Present Status:
Damages Consistent.

Yours faithfully
Marcus
Automotive Assessor

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3010G
Vehicle Details	
Vehicle No.:	GBE146M
Vehicle to be Exported:	No
Intended De-registration Date:	14 Feb 2018
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA DYNA 150 MANUAL
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	1KD2493408
Chassis No.:	JTFAT35Y70K204530
Maximum Power Output:	-
Open Market Value:	\$27,856.00
Original Registration Date:	19 Aug 2015
First Registration Date:	19 Aug 2015
Transfer Count:	0
Actual ARF Paid:	\$1,393.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	18 Aug 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$49,440.00
COE Rebate Amount:	\$37,133.00
Total Rebate Amount:	\$37,133.00

The information contained herein is correct as at 14 Feb 2018

OK

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/GBE146M/1802036

06th February 2018

The Manager
Motor Claim Department
First Capital Insurance Limited
6 Raffles Quay #21-00,
Singapore 048580.

Date of Accident : 03th February 2018
Location : Geylang Road
Third Party Claim Vehicle No : SHB 3517 B
Repair Cost For Vehicle No : GBE 146 M Toyota Dyna

not Adhered
rule
L/S 3350
4 days.
14/2/18
The photo After repair

Estimated Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts	
1	Tail gate	1	1,055.10	\$ 1,055.10	X
2	Tail gate sticker(TOYOTA)	1	226.60	\$ 226.60	---
3	Tail gate sticker (DYNA)	1	27.10	\$ 27.10	---
4	Side gate RH	1	1,341.20	\$ 1,341.20	---
5	Side gate rubber stopper RH	1	36.50	\$ 36.50	---
6	Side gate bracket RH	1	109.70	\$ 109.70	---
7	Rear lamp assy RH	1	216.20	\$ 216.20	---
8	Rear lamp bracket RH	1	214.2	\$ 214.20	---
9	Rear reinforcement end panel	1	556.20	\$ 556.20	---
10	Rear reinforcement side panel RH	1	193.10	\$ 193.10	---
				\$ 3,975.90	2920.8
		Less	25%	\$ 993.97	2190.60
				\$ 2,981.93	
11	Rear number plate (s/nett)	1	50.00	\$ 50.00	15 S.W
12	Rear bumper reverse sensor (s/nett)	1 set	380.00	\$ 380.00	2005.00
13	Sticker (70km/h) (s/nett)	1	18.00	\$ 28.00	10 S.W
				\$ 3,439.93	

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/GBE146M/1802036

06th February 2018

Balance b/f	\$ 3,439.93
<u>Labour Charges :-</u>	<u>Amounts</u>
Cut out, renew, knocking & welding rear end panel, rear side panel, remove & install all damage parts, straighten & re-align body.	\$ 850.00 800
Remove & install rear bumper sensor	\$ 80.00 50
Tuff-kote on damage parts	\$ 80.00 50
Spray painting on damage parts	\$ 900.00 850
Check lighting after repairs	\$ 60.00 30
Labour Charge	\$ 1,970.00 41956
Total Amount	\$ 5,409.93 3356

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18002514/Uqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 23-03-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 3517B	Veh. Inspected	GBE 146M	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18001117MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	07/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA (M)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JTFAT35Y70K204530	Colour	SILVER	
Odometer	98293	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/70 R15	DUNLOP	6 mm	
L/H Front Tyre	195/70 R15	DUNLOP	6 mm	
R/H Rear Tyre	155 R12 (D)	DUNLOP	6/6 mm	
L/H Rear Tyre	155 R12 (D)	DUNLOP	6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/02/2018	Inspection Date	14/02/2018	
Survey held at	SPECIALISTS MOTOR PTE LTD BLK 3018A UBI ROAD 1 #01-24-26 SINGAPORE 408711			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 146M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAIL GATE	TO REPAIR SEE LABOUR	1,055.10	-
1	TAIL GATE STICKER (TOYOTA)	NECESSARY	226.60	226.60
1	TAIL GATE STICKER (DYNA)	NECESSARY	27.10	27.10
1	SIDE GATE RH	DENTED / BENT	1,341.20	1,341.20
1	SIDE GATE RUBBER STOPPER RH	TORN	36.50	36.50
1	SIDE GATE BRACKET RH	BENT	109.70	109.70
1	REAR LAMP ASSY RH	CRACKED	216.20	216.20
1	REAR LAMP BRACKET RH	BENT	214.20	214.20
1	REAR REINFORCEMENT END PANEL	BENT	556.20	556.20
1	REAR REINFORCEMENT SIDE PANEL RH	BENT	193.10	193.10
	LESS 25% DISCOUNT		-993.97	-730.20
			2,981.93	2,190.60
	SPECIAL NETT ITEMS			
1	REAR NUMBER PLATE (SN)	BENT	50.00	15.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	380.00	200.00
1	STICKER (70KM/H)(SN)	NECESSARY	28.00	10.00
			458.00	225.00
	LABOUR			
	CUT OUT,RENEW,KNOCKING & WELDING REAR END PANEL,REAR SIDE PANEL,REMOVE & INSTALL ALL DAMAGE PARTS,STRAIGHTEN & RE-ALIGN BODY,INCLUSIVE OF THE REPAIR OF TAIL GATE.		850.00	800.00
	REMOVE & INSTALL REAR BUMPER SENSOR.		80.00	50.00
	TUFF-KOTE ON DAMAGE PARTS.		80.00	50.00
	SPRAY PAINTING ON DAMAGE PARTS.		900.00	850.00
	CHECK LIGHTING AFTER REPAIRS.		60.00	30.00
			1,970.00	1,780.00
	GRAND TOTAL		5,409.93	4,195.60
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,350.00

Report Ref No. CS/FCI18002514/Uqd3n2



Report Ref No. CS/FCI18002514/Uqd3n2

A handwritten signature in black ink, appearing to be 'Ch' followed by a stylized flourish.

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.