

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI18002561/GQD3N2**Date:** 11/01/2019REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3075521600
Claimant Vehicle No :	SLP7553Z	Insured Vehicle No :	SLE2464M
Date of Loss:	03/02/2018	Nature of Claim:	TP
			Claim No: SNM18D00694C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP7553Z	Engine No:	P520368134
Make & Model:	MAZDA 2, 1.5 (A)	Chassis No:	JM6DJ2HAA01100950
Reg. Date:	16/06/2017 (Man. Year: 2016)	Odometer:	13873 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R16	Rear Tyre Size:	185/60R16
Front Left Side:	Toyo 8 mm	Rear Left Side:	Toyo 8 mm
Front Right Side:	Toyo 8 mm	Rear Right Side:	Toyo 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,290.48	152.74	5,137.74	97.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,900.00	1,620.00	2,280.00	58.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,190.48	1,772.74	7,417.74	80.71
+ GST 7.00/7.00% (S\$)	643.33	124.09	519.24	80.71
Nett Amount (S\$)	9,833.81	1,896.83	7,936.98	80.71

INSPECTION

Date of Assignment:	07/02/2018	
Date Inspected:	09/02/2018	Inspected At: Trans Eurokars Pte Ltd (Sungei Kadut) 12 Sungei Kadut Ave Singapore 729648
Estimated Period of Repair:	3.0 days	

Adjuster: XING GUO QIANG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Jan 2019)
Parts:	143	MAZDA 2 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	LKK Auto Consultants Pte Ltd/SLP7553Z/11/01/2019 16:06	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	832.10 FL	*- FL
2	1		*RETAINER (LHS) FRONT BUMPER	Not Necessary	16.20 FL	*- FL
3	1		*RETAINER (RHS) FRONT BUMPER	Not Necessary	16.20 FL	*- FL
4	1		*CHROME (LHS) FRONT BUMPER	Scratched	158.60 FL	*158.60 FL
5	1		*CHROME (RHS) FRONT BUMPER	Not Necessary	158.60 FL	*- FL
6	1		*MESH,FRONT BUMPER	Not Necessary	88.40 FL	*- FL
7	1		*COVER (LHS) FRONT BUMPER	Not Necessary	16.50 FL	*- FL
8	1		*COVER (RHS) FRONT BUMPER	Not Necessary	16.50 FL	*- FL
9	1		*COVER (LHS) FOGLAMP	Not Necessary	31.30 FL	*- FL
10	1		*GARNISH (LHS) FOGLAMP	Not Necessary	80.50 FL	*- FL
11	1		*COVER,UNDER	Not Necessary	89.00 FL	*- FL
12	1		*FOAM,FRONT BUMPER	Not Necessary	121.50 FL	*- FL
13	2		*FASTENER,FOAM	Not Necessary	11.80 FL	*- FL
14	1		*FRONT REINFORCEMENT	Not Necessary	500.80 FL	*- FL
15	1		*COVER,TOWING	Not Necessary	38.80 FL	*- FL
16	4		*RIVET,FRONT BUMPER	Not Necessary	34.80 FL	*- FL
17	4		*RIVET,FRONT BUMPER	Not Necessary	15.20 FL	*- FL
18	2		*GROMMET,FRONT BUMPER	Not Necessary	5.40 FL	*- FL
19	11		*CLIP,FRONT BUMPER	Not Necessary	38.50 FL	*- FL
20	5		*FASTENER,FRONT BUMPER	Not Necessary	14.00 FL	*- FL
21	2		*SEAL,FRONT BUMPER	Not Necessary	21.40 FL	*- FL
22	1		*RADIATOR GRILLE	Not Necessary	343.60 FL	*- FL
23	1		*PROTECTOR (LHS) GRILLE	Not Necessary	78.70 FL	*- FL
24	1		*PROTECTOR (RHS) GRILLE	Not Necessary	78.70 FL	*- FL
25	1		*MASCOT,FRONT	Not Necessary	31.40 FL	*- FL
26	1		*GUIDE (LHS) AIR	Not Necessary	11.90 FL	*- FL
27	1		*GUARD (LHS) GRILLE	Not Necessary	13.60 FL	*- FL
28	1		*BRACKET TOP,GRILLE	Not Necessary	93.80 FL	*- FL
29	2		*PIN LOCATOR,GRILLE	Not Necessary	5.40 FL	*- FL
30	2		*GROMMET,GRILLE	Not Necessary	5.40 FL	*- FL
31	2		*RIVET,GRILLE	Not Necessary	7.60 FL	*- FL
32	2		*FASTENER,GRILLE	Not Necessary	6.00 FL	*- FL
33	1		*HEADLAMP LHS	Not Necessary	2,393.60 FL	*- FL
34	2		*CLIP,HEADLAMP	Not Necessary	20.20 FL	*- FL
35	1		*RIVET,HEADLAMP	Not Necessary	3.30 FL	*- FL
36	1		*LHS FOGLAMP	Not Necessary	351.40 FL	*- FL
37	1		*BRACKET (LHS) FOGLAMP	Not Necessary	16.50 FL	*- FL
38	1		*SUNDRIES	Necessary	100.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,867.20	168.60
- List Item Discount on L Items 10.00/10.00% (\$)	576.72	15.86
Total Parts (\$)	5,290.48	152.74

LKK Auto Consultants Pte Ltd/SLP7553Z/11/01/2019 16:06. Not valid without Reference section.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRONT BUMPER AND FRONT REINFORCEMENT,REPAIR ALL AREAS AFFECTED BY THE ACCIDENT	New	1,800.00	660.00
2	TO RESPRAY FRONT BUMPER AND FRONT REINFORCEMENT	New	1,500.00	630.00
3	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	150.00
4	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	350.00	180.00
Gross Labour Cost (\$)			3,900.00	1,620.00

LKK Auto Consultants Pte Ltd/SLP7553Z/11/01/2019 16:06. Not valid without Reference section.

< END OF ESTIMATES >