

ASS. REC. BY:

REF: CS/FCI18002571/4rd3ⁿ² Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person):

of

FCI

Date/Time: 8/2/18 @ 12:31pm

Estimated Cost:

Bill to:

OD-TP-WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLP 6044H

Insured:

SHD 4460M

at Workshop m/s

Pegasus

Tel:

68581846

of

51 Defu Lane 10

Policy No:

Claim No:

D18001161MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 5/2/2018

CA / REV / REP. / REV 24 HRS

lwp

H.O.D. Endorsement:

Date/Time:

12:37pm @ 8/2/18

Person Contacted:

Alvin

Vehicle IN OUT

Date/Time

Action/Instruction () Estimate

SLP 6044H-X

SHD 4460M-CS/MSG18002459/M/d3

D.O.A: 5/2/18

Sent preli thru email

(08/11/13) wef
ASS. REC. BY: Marcus

REF:

Ref

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SLP 60441
at Workshop m/s Regasus
of SHD 4460M
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

N/S	O/S

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Date / Time Action / Instruction
8/2/18 confirmed L/S @ 3750 with Sam.
Red: \$4162.10, 53%.

Veh No: SLP 60441 Yr Regn: 6.17
Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or CA
Make: Toyota Uva c.c. 1496
Colour: Grey A/C: Insured / Std / NI / NA
Sp. Reading: 10839 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: MH/FB29F3X0201102
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 195/50 R16
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front 6 mm Rear 6 mm
R/Bal. 6 mm L/Bal. 6 mm
L/Bal. 6 mm D.O.A. 5/12/18 D.O.I. 8/2/18
Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1) typist

☒

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: -

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

) S + RS. S

) Photos

) Others

)

TOTAL

Report Format: TP

Lump Sum / L.B.I. (\$) 3750

150

50

61

261

MOTOR SURVEY ASSIGNMENT

Date	07-02-2018	Our Ref No. D18001161MFSH
Accident Date	05-02-2018	Claim Type. Third Party
Insured Vehicle	SHD4460M	Third Party Vehicle. SLP6044H
Survey Location	51 DEFU LANE 10	
Contact Person.	ALVIN LOW	
Contact No.	68581846/ 0	Fax No. 64876070
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PEGASUS ENGINEERING & TRADING PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/234783)



PRI Documents



Close



PRI Header Details

Claim No	D18001161MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & PEGASUS PTE LTD
Workshop Name	PEGASUS ENGINEERING & TRADING PTE LTD (Contact Person : ALVIN LOW)	Survey Location & Contact Details	51 DEFU LANE 10 Mobile: 0 , Phone: 68581846 , Fax: 64876070 EmailId: CLAIMS@PEGASUSENGRG.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD4460M	TP Vehicle No	SLP6044H
PRI Recieved Date	07-02-2018 09:42:20 PM	Surveyor Appointed Date	08-02-2018 12:30:25 PM	Surveyor Accept Date	08-02-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	08-02-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18002571/Urd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 08-02-2018



Code : FC12

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 4460M	Veh. Inspected	SLP 6044H
Policy No.		Coverage (\$)	0.00
Claim No.	D18001161MFSH	Excess (\$)	0.00
Assign From	CWS (MAY CHUA)	Assign Date	08/02/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	05/02/2018	Inspection Date	08/02/2018
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18001161MFSH

Our Ref: CS/FCI18002571/Urd3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLP 6044H


Please be informed that we had conducted the inspection of the above mentioned vehicle on 08/02/2017 at the premises of M/s PEGASUS ENGINEERING AND TRADING PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ <u>7,912.10</u>
Revised Estimate Amount	: S\$ <u>4,698.58</u>
"Check" Items Amount	: S\$ _____
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:
The vehicle sustained damages
at rear portion.



Yours faithfully
MARCUS
Automotive Assessor



Register New Vehicle (Acknowledgement)

Vehicle Particulars

Vehicle No.:	SLP6044H		
Vehicle Type:	Z10 - Private Hire (Chauffeur) Motor Car	Vehicle Scheme:	Normal
Vehicle Attachment 1:	No Attachment		
Vehicle Attachment 2:	-	Vehicle Attachment 3:	-
Vehicle Make:	TOYOTA	Vehicle Model:	VIOS 1.5E CVT
Chassis No.:	MHFB29F3X02011802	Engine No.:	2NRX158328
Motor No.:	-	Trailer Chassis No.:	-
Propellant:	Petrol	Passenger Capacity:	4
Engine Capacity:	1496 cc	Power Rating:	-
Maximum Power Output:	79.0 kW (105 bhp)		
Unladen Weight:	1065 kg	Maximum Laden Weight:	1500 kg
Primary Colour:	Gray	Secondary Colour:	-
First Registration Date:	12 Jun 2017	Original Registration Date:	12 Jun 2017
Manufacturing Year:	2017	Open Market Value:	\$12,785.00
PARF Eligibility:	Yes	Minimum PARF Benefit:	\$3,892.00
No. of Transfers:	0	Additional Registration Fee Rate:	First \$12,785.00 (100%)
Actual ARF Paid:	\$7,785.00		

Owner Particulars

Owner Name:	GRAB RENTALS PTE LTD
Owner ID Type:	Company
Owner ID:	201617200G
Registered Address Type:	Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.:	6
Registered Street Name:	SHENTON WAY
Registered Unit No.:	# 38 - 01
Registered Building Name:	OUE DOWNTOWN
Registered Postal Code:	068809
COE No. / Expiry Date:	2017050101002189K / 11 Jun 2027
COE Bid Category:	A - Car up to 1600cc & 97kW (130bhp)
QP Paid:	\$51,600.00

Transaction Details

Business Transaction Ref. No.:	20170612102510919923
Business Transaction Date:	12 Jun 2017
Business Transaction Time:	10:25:10

Message

The above vehicle has been successfully registered.

Please note that \$49,866.00 will be deducted from your GIRO account.

12/06/2017

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 539216 Officer in Charge : WEE TZE FAH Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :
---	---

Not Ackd
1/5 23750/-
5 day
take the other up
8/1/18
Confirmed with Marcus \$3750.00
08/02/2018 / 1410
LKK
Marcus

Quotation No : QO18/02-1046	Quotation Date : 06/02/2018	Terms : 30 DAYS
Vehicle No : SLP6044H	Chassis No : MHFB29F3X02011802	Third Party Insurer :
Model : VIOS	Date of Accident :	
Remarks : TP INSURER: FIRST CAPITAL, INSURED'S VEH NO: SHD4460M, DATE OF ACCIDENT: 05.02.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	BOOTLID <i>762.47</i>	<i>120/3uc</i> 1	1,662.4000	1,662.40
2	BOOTLID E BADGE	<i>neu</i> 1	34.4000	34.40
3	BOOTLID VIOS BADGE	<i>neu</i> 1	44.1000	44.10
4	BOOTLID OUTER GARNISH	<i>11</i> 1	164.7000	164.70
5	BOOTLID CENTRE LOGO BADGE	<i>neu</i> 1	59.8000	59.80
6	BOOTLID WEATHERSTRIP	<i>7m</i> 1	188.8000	188.80
7	BOOTLID LOCK TOP	<i>7m</i> 1	90.4000	90.40
8	BOOTLID LOCK STRIKER	<i>11</i> 1	18.5000	18.50
9	BOOTLID INNER TRIM	<i>11</i> 1	159.2000	159.20
10	BOOTLID INNER TRIM CLIPS	<i>11</i> 4	4.3000	17.20
11	BOOTLID HINGE	<i>11</i> 2	57.8000	115.60
12	REAR END PANEL	<i>body</i> 1	694.7000	694.70
13	REAR END PANEL INNER TRIM	<i>7m</i> 1	234.3000	234.30
14	REAR BUMPER	<i>10/12</i> 1	504.9000	504.90
15	REAR BUMPER REFLECTOR	<i>15cm</i> 2	130.5000	261.00
16	REAR BUMPER SIDE RETAINER	<i>n/s bent</i> 2	115.1000	230.20
17	REAR BUMPER SIDE HOLDER	<i>n/s bent</i> 2	22.3000	44.60
18	REAR BUMPER CLIPS	<i>neu</i> 10	4.3000	43.00
19	REAR BUMPER REINFORCEMENT	<i>op</i> 1	379.2000	379.20
20	REAR LAMP	<i>n/s can</i> 2	375.8000	751.60
21	REAR LAMP CLIP HOLDER	<i>11</i> 4	4.3000	17.20
22	SPARE TYRE CLAMP	<i>11</i> 1	45.6000	45.60
23	SPARE TYRE CARDBOARD	<i>7m</i> 1	145.0000	145.00

C/F 0.00

Page 1 of 2

3824.77
2868.57

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 539216 Officer in Charge : WEE TZE FAH Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :
---	---

Quotation No : QO18/02-1046	Quotation Date : 06/02/2018	Terms : 30 DAYS
Vehicle No : SLP6044H	Chassis No : MHFB29F3X02011802	Third Party Insurer :
Model : VIOS	Date of Accident :	
Remarks : TP INSURER: FIRST CAPITAL, INSURED'S VEH NO: SHD4460M, DATE OF ACCIDENT: 05.02.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
				B/F 0.00
24	REAR LUGGAGE FLOOR PANEL SIDE FOAM	2	108.2000	216.40 X
25	LESS 25% (ITEM 1 - 24)	1	-1,530.7000	-1,530.70
26	REAR BUMPER PARKING SENSOR	1 set	200.0000	200.00 ✓
27	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	1	1,000.0000	1,000.00 600
28	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	1,000.0000	1,000.00 800
29	TO REINSTALL OF REAR BUMPER PARKING SENSOR	1	120.0000	120.00 50
30	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR	1	180.0000	180.00 60
31	TO RUST-PROOFING OF THE AFFECTED AREAS	1	150.0000	150.00 60
32	TO TRANSFER BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	1	120.0000	120.00 60
33	TO PLACE VEHICLE ON JIG BENCH TO OBTAIN CROSS AND DIAGNOSTIC MEASUREMENT AND CORRECT TO MANUFACTURER SPECIFICATION WITH HYDRAULIC PNEUMATIC JACK	1	550.0000	550.00 11 X

4698.57

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Sub Total	7,912.10
GST(7.00%)	553.85
Total (SGD)	8,465.95

Please conduct the survey at
 Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18002571/Urd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 12-02-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 4460M	Veh. Inspected	SLP 6044H	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18001161MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	08/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VIOS (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	MHFB29F3X02011802	Colour	GREY	
Odometer	50839	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/50 R16	BRIDGESTONE	6 mm	
L/H Front Tyre	195/50 R16	BRIDGESTONE	6 mm	
R/H Rear Tyre	195/50 R16	BRIDGESTONE	6 mm	
L/H Rear Tyre	195/50 R16	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/02/2018	Inspection Date	08/02/2018	
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 6044H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOTLID	DENTED / BUCKLED	1,662.40	762.47
1	BOOTLID E BADGE	NECESSARY	34.40	34.40
1	BOOTLID VIOS BADGE	NECESSARY	44.10	44.10
1	BOOTLID OUTER GARNISH	NOT NECESSARY	164.70	-
1	BOOTLID CENTRE LOGO BADGE	NECESSARY	59.80	59.80
1	BOOTLID WEATHERSTRIP	TWISTED	188.80	188.80
1	BOOTLID LOCK TOP	TWISTED	90.40	90.40
1	BOOTLID LOCK STRIKER	NOT NECESSARY	18.50	-
1	BOOTLID INNER TRIM	NOT NECESSARY	159.20	-
4	BOOTLID INNER TRIM CLIPS @\$4.30	NOT NECESSARY	17.20	-
2	BOOTLID HINGE @\$57.80	NOT NECESSARY	115.60	-
1	REAR END PANEL	BADLY DENTED	694.70	694.70
1	REAR END PANEL INNER TRIM	TWISTED	234.30	234.30
1	REAR BUMPER	DENTED / DEFORMED	504.90	504.90
2	REAR BUMPER REFLECTOR @\$130.50	N/S CRACKED	261.00	130.50
2	REAR BUMPER SIDE RETAINER @\$115.10	N/S BENT	230.20	115.10
2	REAR BUMPER SIDE HOLDER @\$22.30	N/S BENT	44.60	22.30
10	REAR BUMPER CLIPS @\$4.30	NECESSARY	43.00	43.00
1	REAR BUMPER REINFORCEMENT	DENTED	379.20	379.20
2	REAR LAMP @\$375.80	N/S CRACKED	751.60	375.80
4	REAR LAMP CLIP HOLDER @\$4.30	NOT NECESSARY	17.20	-
1	SPARE TYRE CLAMP	NOT NECESSARY	45.60	-
1	SPARE TYRE CARDBOARD	TORN	145.00	145.00
2	REAR LUGGAGE FLOOR PANEL SIDE FOAM @\$108.20	NOT NECESSARY	216.40	-
	LESS 25% DISCOUNT		-1,530.70	-956.19
			4,592.10	2,868.58
SPECIAL NETT ITEMS				
1	SET REAR BUMPER PARKING SENSOR (SN)	SHORTED	200.00	200.00
			200.00	200.00

Report Ref No. CS/FCI18002571/Urd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.		1,000.00	600.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,000.00	800.00
	TO REINSTALL OF REAR BUMPER PARKING SENSOR.		120.00	50.00
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMMINGS,GARNISH AND OTHER,TO ENABLE REPAIR.		180.00	60.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		150.00	60.00
	TO TRANSFER BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		120.00	60.00
	TO PLACE VEHICLE ON JIG BENCH TO OBTAIN CROSS AND DIAGNOSTIC MEASUREMENT AND CORRECT TO MANUFACTURER SPECIFICATION WITH HYDRAULIC PNEUMATIC JACK.	NOT NECESSARY	550.00	-
			3,120.00	1,630.00
	GRAND TOTAL		7,912.10	4,698.58
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,750.00

Report Ref No. CS/FCI18002571/Urd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.