

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG18002589/AKS3Q2

**Date:** 11/08/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100504994

**Claimant**  
**Vehicle No :** SJC6006K **Insured Vehicle No :** SLM2207Y

Date of Loss: 04/02/2018 Nature of Claim: TP Claim No: 2562530243SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJC6006K		
Make & Model:	HONDA FIT, 1.3 G (A)	Engine No:	L13A4016811
Reg. Date:	25/02/2008 (Man. Year: 2007)	Chassis No:	GE61014488
Colour:	Pink	Odometer:	285329 km
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,399.24	5,630.32	3,768.92	40.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,490.00	4,380.00	2,110.00	32.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>15,889.24</b>	<b>10,010.32</b>	<b>5,878.92</b>	<b>37.00</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>8,000.00</b>		
<b>Nett Amount (\$\$)</b>	<b>15,889.24</b>	<b>8,000.00</b>	<b>7,889.24</b>	<b>49.65</b>
<b>+ Loss of Use (13.0 x S\$60.00/day) (\$\$)</b>		780.00		
<b>+ Doc/Search Fee (\$\$)</b>		7.49		
<b>Nett Liability (\$\$)</b>		<b>8,787.49</b>		

### INSPECTION

Date of Assignment: 06/02/2018

Date Inspected: 06/02/2018 Inspected At:

T & C Automobile (HQ)  
NO.1 KAKI BUKIT AVENUE 6 #01-71  
AUTOBAY  
Singapore 417883

Estimated Period of Repair: 13.0 days

**Adjuster:** ADRIAN LING

**Manager:** Khanchna Pothuraj

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	538.10 FL	*475.00 FL
2	8		*REAR BUMPER CLIP	Necessary	36.00 FL	*36.00 FL
3	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	29.50 FL	*- FL
4	1		*REAR BUMPER SIDE RETAINER LH	Damaged	29.50 FL	*29.50 FL
5	1		*TOW HOOK COVER	Not Necessary	19.50 FL	*- FL
6	1		*TAIL LAMP LH	Cracked	206.20 FL	*206.20 FL
7	1		*TAIL LAMP LOWER BRACKET LH	Damaged	19.60 FL	*19.60 FL
8	1		*TAIL LAMP PANEL LH	Dented	123.30 FL	*123.30 FL
9	1		*TAIL GATE	Dented	836.00 FL	*836.00 FL
10	1		*TAIL GATE GARNISH	Not Necessary	132.60 FL	*- FL
11	2		*TAIL GATE DAMPER	Not Necessary	272.40 FL	*- FL
12	2		*TAIL GATE HINGES	Not Necessary	59.60 FL	*- FL
13	1		*TAIL GATE TRIM BOARD	Cracked	132.60 FL	*132.60 FL
14	1		*TAIL GATE WEATHERSTRIP	Cut	92.30 FL	*92.30 FL
15	1		*TAIL GATE LOCK	Not Necessary	189.00 FL	*- FL
16	1		*TAIL GATE LOWER CATCH	Not Necessary	24.70 FL	*- FL
17	1		*TAIL GATE FIT EMBLEM	Necessary	51.20 FL	*51.20 FL
18	1		*TAIL GATE H LOGO	Not Necessary	39.50 FL	*- FL
19	2		*REAR WINDSCREEN MOULDING	Necessary	161.00 FL	*161.00 FL
20	1		*REAR END PANEL	Distorted	255.20 FL	*255.20 FL
21	1		*REAR END PANEL GARNISH	Deformed	66.60 FL	*66.60 FL
22	8		*REAR END PANEL GARNISH CLIP	Necessary	46.40 FL	*10.00 FL
23	1		*NUMBER PLATE LAMP	Not Necessary	48.80 FL	*- FL
24	1		*SPARE TYRE PANEL	Repair	737.00 FL	*- FL
25	1		*SPARE TYRE SIDE PANEL LH	Distorted	138.30 FL	*138.30 FL
26	1		*SPARE TYRE BOARD	Not Necessary	214.50 FL	*- FL
27	1		*SPARE TYRE TOOL BOX	Cracked	220.40 FL	*220.40 FL
28	1		*REAR DOOR LH	Repair	798.50 FL	*- FL
29	1		*REAR FENDER LH	Distorted	726.70 FL	*726.70 FL
30	1		*REAR FENDER LINING LH	Deformed	150.80 FL	*150.80 FL
31	8		*REAR FENDER LINING CLIP	Necessary	36.00 FL	*36.00 FL
32	1		*REAR FENDER TRIMBOARD LH	Deformed	551.00 FL	*286.30 FL
33	1		*REAR WHEELHOUSE PANEL LH	Buckled	930.00 FL	*930.00 FL
34	1		*TRIMBOARD CLIP (21 PCS)	Necessary	94.50 FL	*30.00 FL
35	1		*REAR AXLE	Bent	897.00 FL	*897.00 FL
36	1		*REAR SHOCK ABSORBER LH	Bent	277.00 FL	*277.00 FL
37	1		*REAR KNUCKLE ARM LH	Not Necessary	326.60 FL	*- FL
38	1		*REAR KNUCKLE ARM BEARING LH	Necessary	149.90 FL	*149.90 FL
39	1		*REAR CHASSIS LH	Repair	809.00 FL	*- FL
40	1		*REAR FENDER AIR VENT	Cracked	76.00 FL	*76.00 FL
41	1		*REAR NUMBER PLATE	Not Necessary	35.00 FS	*- FS
42	1		*REAR NUMBER PLATE CASING	Not Necessary	50.00 FS	*- FS
43	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
44	1		*INSULATOR TAPE	Not Necessary	160.00 FS	*- FS
45	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
46	1		*TYRE	Cut	300.00 FS	*200.00 FS
47	1		*FENDER GLASS SEALANT	Necessary	60.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$)**      **11,507.80**      **6,912.90**  
**- List Item Discount on L Items 20.00/20.00% (\$\$)**      2,108.56      1,282.58

**Total Parts (\$\$)**      **9,399.24**      **5,630.32**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	PANEL BEATING AND STRAIGHTEN AFFECTED PARTS / AREA.	New	2,200.00	1,600.00
2	PUTTY AND SPRAY PAINTING AFFECTED PARTS / AREA.	New	2,000.00	1,400.00
3	REMOVE AND REPLACE REAR CHASSIS LH.	New	450.00	180.00
4	SPRAY ANTI-RUST UNDERCOAT.	New	150.00	100.00
5	CHECK WIRING.	New	120.00	30.00
6	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.	New	150.00	120.00
7	REMOVE AND REPLACE REAR UNDER SUSPENSION AND UNDERCARRIAGE.	New	350.00	280.00
8	COMPUTERIZED WHEEL ALIGNMENT.	New	120.00	80.00
9	REMOVE, REFIT / REPLACE REAR SEATS, REAR WHEELHOUSE INNER GARNISH, FLOOR CARPET & UPHOLSTERY TO FACILITATE REPAIR.	New	350.00	250.00
10	TO REMOVE REAR FENDER GLASS.	New	100.00	60.00
11	TO TRANSFER TAILGATE FITTINGS.	New	150.00	80.00
12	TO REMOVE FUEL TANK.	New	150.00	80.00
13	TO REMOVE REVERSE SENSOR AND REAR CAMERA.	New	200.00	120.00
<b>Gross Labour Cost (\$\$)</b>			<b>6,490.00</b>	<b>4,380.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >