

ASS. REC. BY:

REF:

CS/FCI18002606/T1qd3

Special Instruction

Surveyor

CWS

Taufich

ASSIGNMENT (Office)

From (Person):

Eileen Lee

of

FCI

Date/Time

8/1/18 @ 12:03pm

Estimated Cost:

Bill to:

OD / (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLH 1126E

Insured:

SHA7798K

at Workshop m/s

Cys Automobile

Tel:

G2192098

of

38 woodlands Ind. Prk Eas + 1 # 07+17

Policy No:

D-18088936 MFSH

Claim No:

D18001122 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

3/2/2018

CA / REV / REP. / REV 24 HRS

'DSI

9/2/18

H.O.D. Endorsement:

Date/Time:

2:12pm @ 8/2/18

Person Contacted:

Wee Sin

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

SLH 1126E-X

SHA7798K-CS/FCI16021814/R1th 302

D.O.A.: 11/11/16

13/2/18 @

11:44am revised to Eileen Lee by email.

Signature: *Taufik*

REF:


FCI

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MY
To Inspect Vehicle No: _____
at Workshop m/s: _____
of: _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / FR Seen: _____ Consistent? : Yes or No
Est. Repairs: 18 days Res.: Yes or No
Lump Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS *wp*
Date: _____ Person Contacted: _____ Vehicle: IN / OUT
wee sin

Veh No: SLH1126 E Yr Regn: 2016 OUT
Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Honda Vezel cc 1496
Colour: Black A/C: _____ Insured / Std / NI / NA
So. Reading: 19403 T.Radio: Insured / Std / NI / NA
Eng No: _____
C.No: RM11112117
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 225/50R18
R: u
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front: 6 Rear: 6
R/Bal: _____ mm R/Bal: _____ mm
L/Bal: 6 mm L/Bal: 6 mm
D.O.A: _____ D.O.I: 9/2/18
Survey held at: cys wc
Des. of Damages: Front / Rear / O/S / NIS / UIC / Rooftop or
The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1/5 \$21,450, 18 days - e-mail to wee sin
UPA 69778.25, 317.7

RECEIVED 25 MAY 2018

Date/Time File Pass to? ☐ : Preli. Report
2/5 ☒ : Final Report
Date/Time File Return to? _____

Days Of Repair: 18
Resurvey No. of Trip: _____

Survey Fee
Transportation

Add Fee: ☐ Site Insp / \$
☐ Interview / \$
☐ Tech. Insp / \$
☐ Meet-end / \$

380
2815/18

21x152 315
170 + 315
50
143
678

Report Format: TP
Lump Sum / 12% / \$ 21450



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18002606/T1qd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 08-02-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 7798K	Veh. Inspected	SLH 1126E	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18001122MFSH	Excess (\$)	0.00	
Assign From	CWS (EILEEN LEE)	Assign Date	08/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	03/02/2018	Inspection Date		
Survey held at	CYS AUTOMOBILE SERVICES PTE LTD 38 WOODLANDS INDUSTRIAL PARK EAST 1 #07-17 ADMIRALTY INDUSTRIAL PARK SINGAPORE 757700			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18001122MFSH

Date: 13 February 2018

Our Ref: CS/FCI18002606/T1qd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLH 1126E .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 09/02/2018 at the premises of M/s CYS AUTOMOBILE, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>29,820.73</u> .
Revised Estimate Amount	: S\$ <u>17,550.57</u> .
"Check" Items Amount	: S\$ <u>9,530.16</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the front & rear portion.



Yours faithfully

Taufikh
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	06-02-2018	Our Ref No. D18001122MFSH
Accident Date	03-02-2018	Claim Type. Third Party
Insured Vehicle	SHA7798K	Third Party Vehicle. SLH1126E
Survey Location	38 WOODLANDS INDUSTRIAL PARK EAST 1 #07-17 ADMIRALTY INDUSTRIAL PARK	
Contact Person.	MS TEE WEE SIN	
Contact No.	62192098/ 0	Fax No. 62192096
Survey Type	DIRECT SETTLEMENT;	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CYS AUTOMOBILE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/234736)



PRI Documents



Close X

PRI Header Details

Claim No	D18001122MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & CYS AUTC
Workshop Name	CYS AUTOMOBILE SERVICES PTE LTD (Contact Person : MS TEE WEE SIN)	Survey Location & Contact Details	38 WOODLANDS INDUSTRIAL PARK EAST 1 #07-17 ADP Mobile: 0 , Phone: 62192098 , Fax: 62192096 EmailId: CYSAUTO@SINGNET.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA7798K	TP Vehicle No	SLH1126E
PRI Recieved Date	07-02-2018 10:32:22 PM	Surveyor Appointed Date	08-02-2018 12:02:32 PM	Surveyor Accept Date	08-02-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	08-02-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 13 February 2018 11:44 AM
To: Admin-D (LKKAUTO); 'Claim Workflow System'; assignments
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18001122MFSH/1
Attachments: CSFCI18002606T1qd3.pdf

Dear Sir/Madam,

Enclosed herewith preliminary advice of SLH 1126E

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 8 February 2018 2:14 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18001122MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 8 February 2018 12:03 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; EILEENLEE@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18001122MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

SGCARMART.COM[New Cars](#)[Used Cars](#)[Sell My Car](#)[Directory](#)[Products](#)[Articles](#)

FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?

[Home](#) » [Used Cars](#) » [Oscars Auto](#) » [Honda Vezel 1.5A X](#)

Tools & Tips

[Car Buying](#)[Car Selling](#)[Car Aftermarket](#)[Car Ownership](#)[On The Move](#)[Lifestyle](#)

Honda Vezel 1.5A X

[Overview](#)[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)[Add to Shortlist](#)[Add to Compare](#)[Add a Note](#)[Report Error](#)[More Actions](#)

Car Details

Price **\$87,800****Depreciation** **\$9,360 /yr**[View models with similar depreciation](#)**Reg Date** **13-Oct-2016****(8yrs 8mths 3days COE left)****Manufactured** **2016****Mileage** **24,000 km (18.1k /yr)****Transmission** **Auto****Engine Cap** **1,496 cc****Road Tax** **\$682 /yr****Power** **96.0 kW (128 bhp)**[View specs of the Honda Vezel](#)**Curb Weight** **1,190 kg****Features** **Powerful And Responsive 4 Cylinder Inline DOHC I-VTEC, SRS Airbags, ABS, Cruise Control, Traction Control, Keyless Engine Start, Auto Headlights/LED.****Accessories** **Pioneer DVD Player, USB, Bluetooth, Reverse Sensors And Camera, Surveillance Camera., Retractable Side Mirrors, Fog Lamps, Door Visor, Boot Cover.****Description** **Lowest Deprecation \$9.3k, High ARF \$13162, 1 Owner, Honda Vezel 1.5A, Serviced At World Auto Pte Ltd With Full Records, Come With 3 Years/100,000Km Whichever Come First Warranty Until OCT 2019, Accident Free, Flexible Loan With High Trade In, Please Call For More Enquiry Before It's Gone.**[Location Map](#)

Seller Information

Company

Address

[Compare](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5886J
Vehicle Details	
Vehicle No.:	SLH1126E
Vehicle to be Exported:	No
Intended De-registration Date:	09 Feb 2018
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X A
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	L15B4032122
Chassis No.:	RU11112117
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$19,376.00
Original Registration Date:	24 Oct 2016
First Registration Date:	24 Oct 2016
Transfer Count:	0
Actual ARF Paid:	\$9,376.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Oct 2026
PARF Rebate Amount:	\$7,032.00
Intended COE Rebate Details	
COE Expiry Date:	23 Oct 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10

QP Paid:	\$51,506.00
COE Rebate Amount:	\$44,832.00
Total Rebate Amount:	\$51,864.00

The information contained herein is correct as at 09 Feb 2018

OK



進友成汽車服務私人有限公司

CYS Automobile Services Pte Ltd

ROC Reg. No : A05041/2001E

GST Reg. NO: 20-0105041-E

MR TAN PUI SAN
BLK 523B TAMPINES CENTRAL 7
#12-95 (S) 522523

POLICY NO : THIRD PARTY CLAIMS
YOUR REF : SHA 7798 K (FIRST CAPITAL)
OUR REF : TP 5868
VECHICLE NO : SLH 1126 E
MAKE/MODEL : Honda Vezel
DATE OF ACCIDENT : 5.FEB.18

SURVEY BY

DATE : 6.FEB.18

		SS	
1 PC BONNET		895.30	Rx
1 PC FRONT GRILLE (WITH OUTER GARNISH)		770.50	chr
2 PCS FRONT GRILLE CHROME	75.00	150.00	mt
1 PC FRONT GRILLE CHROME EMBLEM		65.80	rel
2 PCS HEADLAMP ASSY	1,738.50	3,477.00	? CRA
2 PCS HEADLAMP LOWER BRACKETS	35.00	70.00	? Vrel
1 PC FRONT BUMPER		801.70	de
2 PCS FRONT BUMPER SIDE RETAINERS	23.00	46.00	? Vrel
1 PC FRONT BUMPER LOWER LIP		351.00	mt
1 PC FRONT BUMPER REINFORCEMENT		321.00	? BT
1 PC FRONT BUMPER LOWER GRILLE		85.10	? XHR
1 PC TAILGATE		1,100.70	bt
2 PCS TAILGATE GLASS MOULDING	158.60	317.20	rel
1 PC TAILGATE OUTER GARNISH		198.10	de
1 PC TAILGATE OUTER GARNISH EMBLEM		24.70	rel
1 PC TAILGATE "VEZEL" EMBLEM		61.40	rel
1 PC TAILGATE OUTER HANDLE		175.50	de
2 PCS TAILGATE LAMP	460.60	921.20	chr
1 PC TAILGATE TOP LOCK		180.00	bt
1 PC TAILGATE LOWER LOCK CATCH		27.40	bt
2 PCS TAILGATE HINGE	50.40	100.80	Rx
2 PCS TAILGATE ABSORBER	180.40	360.80	Rx
1 PC TAILGATE INNER TRIMBOARD		225.10	de
1 PC TAILGATE INNER TRIMBOARD COVER		225.00	? XHR
1 PC TAILGATE INNER HANDLE		24.90	de
1 PC TAILGATE WIPER ARM		80.60	X HR
1 PC TAILGATE WIPER BLADE		48.60	X HR
1 PC TAILGATE WIPER MOTOR		205.60	X HR
1 PC TAILGATE WEATHERSTRIP		95.80	fric
1 PC TAILGATE LOCK SENSOR		195.00	? BT
1 PC REAR NUMBER PLATE LAMP		38.56	dis
2 PCS TAILLAMP ASSY	460.60	921.20	chr
2 PCS TAILLAMP CLIPS	3.90	7.80	rel
2 PCS TAILLAMP PANEL	135.90	271.80	? phafa BT
1 PC REAR END PANEL		416.60	bt
1 PC REAR END PANEL TOP GARNISH		92.30	de
1 PC REAR BUMPER		863.70	de
2 PCS REAR BUMPER SIDE	195.00	390.00	chr de
2 PCS REAR BUMPER REFLECTOR	135.00	270.00	chr
2 PCS REAR BUMPER SIDE RETAINERS	28.00	56.00	rel
		SS	14,929.76
	LESS 20%		2,985.95
		SS	11,943.81



進友成汽車服務私人有限公司

CYS Automobile Services Pte Ltd

ROC Reg. No :A05041/2001E

GST Reg. NO: 20-0105041-E

CON'T FROM PAGE-1

S\$ 11,943.81

2 PCS REAR FENDER	900.10	1,800.20 <i>buc</i>
2 PCS REAR FENDER ARCH GARNISH	150.00	300.00 <i>LH-mis, RH-stp</i>
1 PC REAR FENDER INNER SHIELD L/H		147.50 <i>dec</i>
2 PCS REAR FENDER INNER TRIMBOARD	295.00	590.00 <i>? photo</i>
1 PC REAR COMPARTMENT PANEL		1,130.90 <i>buc</i>
1 PC REAR COMPARTMENT OUTER COVER		190.00 <i>dec</i>
1 PC REAR COMPARTMENT HARDBOARD		230.80 <i>dec</i>
1 PC REAR CHASSIS FRAME L/H		720.10 <i>Buc</i>
1 PC REAR EXHAUST MUFFLER		528.60 <i>dd</i>
1 PC REAR EXHAUST MUFFLER HEAT SHIELD		55.00 <i>? ✓ BT</i>
1 PC REAR EXHAUST CENTER PIPE		956.00 <i>? ✓ Br</i>
1 PC TOOLS TRAY		225.10 <i>one</i>
2 PCS REAR SHOCK ABSORBER	330.60	661.20 <i>? xnn</i>
1 PC REAR AXLE		1,513.60 <i>? xnn</i>
1 PC REAR HANDBRAKE MOTOR R/H		560.00 <i>? xnn</i>
1 PC EDLC MODULE		1,143.30 <i>? ✓ CRA</i>
1 PC REAR DOOR L/H		936.60 <i>✓ BT</i>
1 PC REAR DOOR INNER LOCK L/H		195.80 <i>x xnn</i>
2 PCS REAR DOOR HINGE L/H	40.10	80.20 <i>? xnn</i>
		S\$ 11,964.90
	LESS 20%	2,392.98
		S\$ 9,571.92
1 PCS SEALANT	40.00	S\$ 80.00 <i>all</i>
1 SET NUMBER PLATE		90.00 <i>80 "CRA"</i>
1 SET FRONT BUMPER CLIPS		38.00 <i>" all</i>
1 SET REVERSE SENSOR		350.00 <i>" 200mm</i>
1 SET REAR BUMPER CLIPS		38.00 <i>" all</i>
10 PCS REAR FENDER INNER SHIELD CLIPS	3.90	39.00 <i>all</i>
		635.00
TO DISMANTLE AND REFIX EDLC MODULE		S\$ 380.00 <i>200? photo.</i>
TO REMOVE AND REFIX CUSHION SEAT AND REAR FENDER INNER TRIM BOARD		100.00 <i>80</i>
TO REMOVE AND REFIX TAILGATE GLASS		140.00 <i>120</i>
TO DISMANTLE AND REFIX UNDERCARRIDGE		300.00 <i>200? photo-X</i>
TO DISMANTLE AND REFIX FUEL TANK		120.00 <i>60</i>
TO DISMANTEL AND MANTLE REAR EXHAUST		200.00 <i>120</i>
TO DO FOUR WHEEL COMPUTER ALIGNMENT		150.00 <i>120? xnn X</i>
TO DO CHASSIS ALIGNMENT		250.00 <i>200? photo</i>
TO DO COMPUTER RESET		300.00 <i>150.</i>
		S\$ 24,090.73



進友成汽車服務私人有限公司
CYS Automobile Services Pte Ltd

ROC Reg. No :A05041/2001E

GST Reg. NO: 20-0105041-E

CONT FROM PAGE-2

	SS 24,090.73
TO TRANSFER TALGATE FITTING	100.00 50
TO DISMANTLE AND REFIX REVERSE CAMERA	50.00 30.
TO TRANSFER DOOR FITTING	100.00 x
TO APPLY RUSTING PROOFING ON REPLACED/REPAIRD PANEL	200.00 /00
TO DISMANTLE AND REFIX REVERSE SENSOR	30.00 ✓
TOWING CHARGES	130.00 100 receipt?
TO CHECK WIRING FUNCTION	80.00 50.
LABOUR CHARGES	2800 3,000.00 2400
TO PUTTY AND SPRAY PAINTING CHARGES	2,000.00 /800
TO PERFORM WATER LEAKAGE TEST	40.00 20-

SS 29,820.73

SIN DOLLARS: TWENTY-NINE THOUSAND EIGHT HUNDRED TWENTY AND CENTS SEVENTY-THREE ONLY

YOUR FAITHFULLY,

CYS AUTOMOBILE SERVICES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Taufik 97495749
WP
9/2/18 @ 3pm

Lumpsum
Resurvey After repair
18 days.

sur@lkeauto.com.
* To check repair limit

13/2/18

31228.75



進友成汽車服務私人有限公司

CYS Automobile Services Pte Ltd

ROC Reg. No :A05041/2001E

GST Reg. NO: 20-0105041-E

MR TAN PUI SAN
BLK 523B TAMPINES CENTRAL 7
#12-95 (S) 522523

POLICY NO : THIRD PARTY CLAIMS
YOUR REF : SHA 7798 K (FIRST CAPITAL)
OUR REF : TP 5868
VEHICLE NO : SLH 1126 E
MAKE/MODEL : Honda Vezel
DATE OF ACCIDENT : 5.FEB.18

SURVEY BY

DATE : 6.FEB.18

		S\$	
1 PC BONNET		895.30 <i>Re</i>	
1 PC FRONT GRILLE (WITH OUTER GARNISH)		770.50 <i>ane</i>	
2 PCS FRONT GRILLE CHROME	75.00	150.00 <i>ant</i>	
1 PC FRONT GRILLE CHROME EMBLEM		65.80 <i>rel</i>	
PCS HEADLAMP ASSY	1,738.50	3,477.00 <i>? / cra</i>	
2 PCS HEADLAMP LOWER BRACKETS	35.00	70.00 <i>? / neu</i>	
1 PC FRONT BUMPER		801.70 <i>de</i>	
2 PCS FRONT BUMPER SIDE RETAINERS	23.00	46.00 <i>? / neu</i>	
1 PC FRONT BUMPER LOWER LIP		351.00 <i>ent</i>	
1 PC FRONT BUMPER REINFORCEMENT		321.00 <i>? / bt</i>	
1 PC FRONT BUMPER LOWER GRILLE		85.10 <i>? X m</i>	
1 PC TAILGATE		1,100.70 <i>bt</i>	
2 PCS TAILGATE GLASS MOULDING	158.60	317.20 <i>rel</i>	
1 PC TAILGATE OUTER GARNISH		198.10 <i>de</i>	
1 PC TAILGATE OUTER GARNISH EMBLEM		24.70 <i>rel</i>	
1 PC TAILGATE "VEZEL" EMBLEM		61.40 <i>neu</i>	
1 PC TAILGATE OUTER HANDLE		175.50 <i>der</i>	
2 PCS TAILGATE LAMP	460.60	921.20 <i>cra</i>	
1 PC TAILGATE TOP LOCK		180.00 <i>bt</i>	
1 PC TAILGATE LOWER LOCK CATCH		27.40 <i>bt</i>	
2 PCS TAILGATE HINGE	50.40	100.80 <i>Ro</i>	
2 PCS TAILGATE ABSORBER	180.40	360.80 <i>Rv</i>	
PC TAILGATE INNER TRIMBOARD		225.10 <i>der</i>	
1 PC TAILGATE INNER TRIMBOARD COVER		225.00 <i>? X m</i>	
1 PC TAILGATE INNER HANDLE		24.90 <i>der</i>	
1 PC TAILGATE WIPER ARM		80.60 <i>X m</i>	
1 PC TAILGATE WIPER BLADE		48.60 <i>X m</i>	
1 PC TAILGATE WIPER MOTOR		205.60 <i>X m</i>	
1 PC TAILGATE WEATHERSTRIP		95.80 <i>fuiv</i>	
1 PC TAILGATE LOCK SENSOR		195.00 <i>? / bt</i>	
1 PC REAR NUMBER PLATE LAMP		38.56 <i>de</i>	
2 PCS TAILLAMP ASSY	460.60	921.20 <i>cra</i>	
2 PCS TAILLAMP CLIPS	3.90	7.80 <i>neu</i>	
2 PCS TAILLAMP PANEL	135.90	271.80 <i>? photo / bt</i>	
1 PC REAR END PANEL		416.60 <i>bt</i>	
1 PC REAR END PANEL TOP GARNISH		92.30 <i>de</i>	
1 PC REAR BUMPER		863.70 <i>de</i>	
2 PCS REAR BUMPER SIDE	195.00	390.00 <i>de</i>	
2 PCS REAR BUMPER REFLECTOR	135.00	270.00 <i>neu cra</i>	
2 PCS REAR BUMPER SIDE RETAINERS	28.00	56.00 <i>neu</i>	
		S\$ 14,929.76	
	LESS 20%	2,985.95	
		S\$ 11,943.81	



進友成汽車服務私人有限公司 CYS Automobile Services Pte Ltd

ROC Reg. No :A05041/2001E

GST Reg. NO: 20-0105041-E

CONT FROM PAGE-1

S\$ 11,943.81

2 PCS REAR FENDER	900.10
2 PCS REAR FENDER ARCH GARNISH	150.00
1 PC REAR FENDER INNER SHIELD L/H	
2 PCS REAR FENDER INNER TRIMBOARD	295.00
1 PC REAR COMPARTMENT PANEL	
1 PC REAR COMPARTMENT OUTER COVER	
1 PC REAR COMPARTMENT HARDBOARD	
1 PC REAR CHASSIS FRAME L/H	
1 PC REAR EXHAUST MUFFLER	
1 PC REAR EXHAUST MUFFLER HEAT SHIELD	
1 PC REAR EXHAUST CENTER PIPE	
PC TOOLS TRAY	
2 PCS REAR SHOCK ABSORBER	330.60
1 PC REAR AXLE	
1 PC REAR HANDBRAKE MOTOR R/H	
1 PC EDLC MODULE	
1 PC REAR DOOR L/H	
1 PC REAR DOOR INNER LOCK L/H	
2 PCS REAR DOOR HINGE L/H	40.10

LESS 20%

1 PCS SEALANT	40.00
1 SET NUMBER PLATE	
1 SET FRONT BUMPER CLIPS	
1 SET REVERSE SENSOR	
1 SET REAR BUMPER CLIPS	
10 PCS REAR FENDER INNER SHIELD CLIPS	3.90

TO DISMANTLE AND REFIX EDLC MODULE

TO REMOVE AND REFIX CUSHION SEAT AND REAR FENDER INNER TRIM BOARD

TO REMOVE AND REFIX TAILGATE GLASS

TO DISMANTLE AND REFIX UNDERCARRIDGE

TO DISMANTLE AND REFIX FUEL TANK

TO DISMANTEL AND MANTLE REAR EXHAUST

TO DO FOUR WHEEL COMPUTER ALIGNMENT

TO DO CHASSIS ALIGNMENT

TO DO COMPUTER RESET

1,800.20	buc
300.00	LH-mis, RH-? del
147.50	del
590.00	? photo del
1,130.90	buc
190.00	del
230.80	del
720.10	Buc
528.60	del
55.00	? bt
956.00	? bt
225.10	one
-661.20	? X un
4,513.60	? X un
1,143.30	? X un
936.60	del
195.80	X un
-80.20	? X un

S\$ 11,964.90
2,392.98
S\$ 9,571.92

80.00	S/NETT
90.00	"CR9
38.00	"del
350.00	"200un
38.00	"del
39.00	del
635.00	

S\$ 380.00

100.00

140.00

No photo X 300.00

120.00

200.00

X 150.00

250.00

300.00

S\$ 24,090.73



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18002606/T1qd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 30-05-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 7798K	Veh. Inspected	SLH 1126E	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18001122MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	08/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	RU11112117	Colour	BLACK	
Odometer	19403	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50 R18	BRIDGESTONE	6 mm	
L/H Front Tyre	225/50 R18	BRIDGESTONE	6 mm	
R/H Rear Tyre	225/50 R18	BRIDGESTONE	6 mm	
L/H Rear Tyre	225/50 R18	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/02/2018	Inspection Date	09/02/2018	
Survey held at	CYS AUTOMOBILE SERVICES PTE LTD 38 WOODLANDS INDUSTRIAL PARK EAST 1 #07-17 ADMIRALTY INDUSTRIAL PARK SINGAPORE 757700			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		18 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 1126E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BONNET	TO REPAIR SEE LABOUR	895.30	-
1	FRONT GRILLE (WITH OUTER GARNISH)	CRACKED	770.50	770.50
2	FRONT GRILLE CHROME @\$75.00	CUT	150.00	150.00
1	FRONT GRILLE CHROME EMBLEM	NECESSARY	65.80	65.80
2	HEADLAMP ASSY @\$1738.50	CRACKED	3,477.00	3,477.00
2	HEADLAMP LOWER BRACKETS @\$35.00	NECESSARY	70.00	70.00
1	FRONT BUMPER	DEFORMED	801.70	801.70
2	FRONT BUMPER SIDE RETAINERS @\$23.00	NECESSARY	46.00	46.00
1	FRONT BUMPER LOWER LIP	CUT	351.00	351.00
1	FRONT BUMPER REINFORCEMENT	BENT	321.00	321.00
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	85.10	-
1	TAILGATE	BENT	1,100.70	1,100.70
2	TAILGATE GLASS MOULDING @\$158.60	NECESSARY	317.20	317.20
1	TAILGATE OUTER GARNISH	DEFORMED	198.10	198.10
1	TAILGATE OUTER GARNISH EMBLEM	NECESSARY	24.70	24.70
1	TAILGATE "VEZEL" EMBLEM	NECESSARY	61.40	61.40
1	TAILGATE OUTER HANDLE	DEFORMED	175.50	175.50
2	TAILGATE LAMP @\$460.60	CRACKED	921.20	921.20
1	TAILGATE TOP LOCK	BENT	180.00	180.00
1	TAILGATE LOWER LOCK CATCH	BENT	27.40	27.40
2	TAILGATE HINGE @\$50.40	TO REPAIR SEE LABOUR	100.80	-
2	TAILGATE ABSORBER @\$180.40	TO REPAIR SEE LABOUR	360.80	-
1	TAILGATE INNER TRIMBOARD	DEFORMED	225.10	225.10
1	TAILGATE INNER TRIMBOARD COVER	NOT NECESSARY	225.00	-
1	TAILGATE INNER HANDLE	DEFORMED	24.90	24.90
1	TAILGATE WIPER ARM	NOT NECESSARY	80.60	-
1	TAILGATE WIPER BLADE	NOT NECESSARY	48.60	-
1	TAILGATE WIPER MOTOR	NOT NECESSARY	205.60	-
1	TAILGATE WEATHERSTRIP	TWISTED	95.80	95.80

Report Ref No. CS/FCI18002606/T1qd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAILGATE LOCK SENSOR	DISTORTED	195.00	195.00
1	REAR NUMBER PLATE LAMP	DISTORTED	38.56	38.56
2	TAILLAMP ASSY @\$460.60	CRACKED	921.20	921.20
2	TAILLAMP CLIPS @\$3.90	NECESSARY	7.80	7.80
2	TAILLAMP PANEL @\$135.90	BENT	271.80	271.80
1	REAR END PANEL	BENT	416.60	416.60
1	REAR END PANEL TOP GARNISH	DEFORMED	92.30	92.30
1	REAR BUMPER	DEFORMED	863.70	863.70
2	REAR BUMPER SIDE @\$195.00	DEFORMED	390.00	390.00
2	REAR BUMPER REFLECTOR @\$135.00	CRACKED	270.00	270.00
2	REAR BUMPER SIDE RETAINERS @\$28.00	NECESSARY	56.00	56.00
2	REAR FENDER @\$900.10	BUCKLED	1,800.20	1,800.20
2	REAR FENDER ARCH GARNISH @\$150.00	N/S MISSING / O/S DEFORMED	300.00	300.00
1	REAR FENDER INNER SHIELD L/H	DEFORMED	147.50	147.50
2	REAR FENDER INNER TRIMBOARD @\$295.00	DEFORMED	590.00	590.00
1	REAR COMPARTMENT PANEL	BUCKLED	1,130.90	1,130.90
1	REAR COMPARTMENT OUTER COVER	DEFORMED	190.00	190.00
1	REAR COMPARTMENT HARDBOARD	DEFORMED	230.80	230.80
1	REAR CHASSIS FRAME L/H	BUCKLED	720.10	720.10
1	REAR EXHAUST MUFFLER	DENTED	528.60	528.60
1	REAR EXHAUST MUFFLER HEAT SHIELD	BENT	55.00	55.00
1	REAR EXHAUST CENTER PIPE	BENT	956.00	956.00
1	TOOLS TRAY	CRACKED	225.10	225.10
2	REAR SHOCK ABSORBER @\$330.60	NOT NECESSARY	661.20	-
1	REAR AXLE	NOT NECESSARY	1,513.60	-
1	REAR HANDBRAKE MOTOR R/H	NOT NECESSARY	560.00	-
1	EDLC MODULE	CRACKED	1,143.30	1,143.30
1	REAR DOOR L/H	BENT	936.60	936.60
1	REAR DOOR INNER LOCK L/H	NOT NECESSARY	195.80	-
2	REAR DOOR HINGE L/H @\$40.10	NOT NECESSARY	80.20	-
1	ROOF LINING (ADDITIONAL)	DEFORMED	833.80	833.80
1	WHEEL HOUSING (ADDITIONAL)	BENT	909.80	909.80

Report Ref No. CS/FCI18002606/T1qd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	EXHAUST BOX MOUNTING (ADDITIONAL)	TORN	15.80	15.80
	LESS 20% DISCOUNT		-5,730.81	-4,728.29
			22,923.25	18,913.17
	SPECIAL NETT ITEMS			
2	SEALANT @\$40.00 (SN)	NECESSARY	80.00	60.00
1	SET NUMBER PLATE (SN)	CRACKED	90.00	80.00
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	38.00	38.00
1	SET REVERSE SENSOR (SN)	NOT WORKING	350.00	200.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	38.00	38.00
10	REAR FENDER INNER SHIELD CLIPS @\$3.90 (SN)	NECESSARY	39.00	39.00
			635.00	455.00
	LABOUR			
	TO DISMANTLE AND REFIX EDLC MODULE.		380.00	200.00
	TO REMOVE AND REFIX CUSHION SEAT AND REAR FENDER INNER TRIM BOARD.		100.00	80.00
	TO REMOVE AND REFIX TAILGATE GLASS.		140.00	120.00
	TO DISMANTLE AND REFIX UNDERCARRIAGE.	NOT NECESSARY	300.00	-
	TO DISMANTLE AND REFIX FUEL TANK.		120.00	60.00
	TO DISMANTLE AND MANTLE REAR EXHAUST.		200.00	120.00
	TO DO FOUR WHEEL COMPUTER ALIGNMENT.	NOT NECESSARY	150.00	-
	TO DO CHASSIS ALIGNMENT.		250.00	200.00
	TO DO COMPUTER RESET.		300.00	150.00
	TO TRANSFER TAILGATE FITTING.		100.00	50.00
	TO DISMANTLE AND REFIX REVERSE CAMERA.		50.00	30.00
	TO TRANSFER DOOR FITTING.	NOT NECESSARY	100.00	-
	TO APPLY RUSTING PROOFING ON REPLACED/REPAIRED PANEL.		200.00	100.00
	TO DISMANTLE AND REFIX REVERSE SENSOR.		30.00	30.00
	TOWING CHARGES.		130.00	100.00
	TO CHECK WIRING FUNCTION.		80.00	50.00
	LABOUR CHARGES.INCLUSIVE OF THE REPAIR OF BONNET, TAILGATE HINGE AND TAILGATE ABSORBER.		3,000.00	2,800.00
	TO PUTTY AND SPRAY PAINTING CHARGES.		2,000.00	1,800.00

Report Ref No. CS/FCI18002606/T1qd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PERFORM WATER LEAKAGE TEST.		40.00	20.00
			7,670.00	5,910.00
GRAND TOTAL			31,228.25	25,278.17
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				21,450.00

Report Ref No. CS/FCI18002606/T1qd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.