

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933







NTU	NTUC INCOME INSURANCE CO-OPERATIVE LTD			NS/INC18002617/K1tbn2		
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	02-03-2018 INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SGK 1749B	Veh. Ir	nspected	SHA 7150D	
	Policy No.	5083856656-01	Cover	age (\$)	0.00	
	Claim No.	MT/0981814-002	Exces	s (\$)	0.00	
	Assign From		Assig	n Date	08/02/2018	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI 140	c.c		1685	
	Engine No.	HIDDEN	Year o	of Reg.	2014	
	Chassis No.	KMHLB41UMEU053879	Colou	r	BLUE	
	Odometer	509244	Steeri	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	STANDARD ALLOY RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	205/60 R16	WEST		7 mm	
	L/H Front Tyre	205/60 R16	WEST		7 mm	
	R/H Rear Tyre	205/60 R16	WEST		7 mm	
	L/H Rear Tyre	205/60 R16	WEST		7 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.					
	DAMAGES SEE DETAILS.					
5.						
	Accident Date	07/02/2018		tion Date	08/02/2018	
	Survey held at COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969					
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days					