

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933







NTUC INCOME INSURANCE CO-OPERATIVE LTD			Ref:	NS/INC18002621/K1qbn2	
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	22-02-2018 INC4	
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SFX 4400E	Veh. Ir	nspected	SHC 7022E
	Policy No.	5094799377	Coverage (\$)		0.00
	Claim No.	MT/0981593-002	Exces	s (\$)	0.00
	Assign From		Assig	n Date	08/02/2018
2. Vehicle Particulars & Condition					
	Make & Model	HYUNDAI 140	c.c		1685
	Engine No.	HIDDEN	Year o	f Reg.	2016
	Chassis No.	KMHLB41UMGU083395	Colou	r	YELLOW
	Odometer	353549	Steering		IN ORDER
	Brakes	IN ORDER	Modifi	cation	STANDARD ALLOY RIM
	General	FAIR			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	205/60 R16	WEST	LAKE	7 mm
	L/H Front Tyre	205/60 R16	WEST	LAKE	7 mm
	R/H Rear Tyre	205/60 R16	WEST	LAKE	7 mm
	L/H Rear Tyre	205/60 R16	WEST	LAKE	7 mm
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	07/02/2018	Inspection Date 08/02/2018		
	Survey held at	COMFORTDELGRO ENGINEERING PTE LTD			
	59 LOYANG DRIVE SINGAPORE 508969				
5a.	a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				