

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKQ 1663K

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BOOTLID (NPA) (CONSISTENT)	TO REPAIR SEE LABOUR	-	-
1	REAR BUMPER (CONSISTENT)	DEFORMED	849.70	849.70
10	REAR BUMPER CLIPS (CONSISTENT)	NECESSARY	30.00	30.00
2	REAR BUMPER RETAINER (CONSISTENT)	NOT NECESSARY	121.80	-
2	REAR BUMPER BRACKET (CONSISTENT)	NOT NECESSARY	188.40	-
2	REAR BUMPER REFLECTOR (CONSISTENT)	SERVICEABLE	244.60	-
1	REAR REINFORCEMENT (CONSISTENT)	SERVICEABLE	431.50	-
1	END PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	642.50	-
4	REVERSE SENSOR	SERVICEABLE	844.40	-
	LESS 10% DISCOUNT		-335.29	-87.97
			3,017.61	791.73
	SPECIAL NETT ITEMS			
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
			50.00	20.00
	LABOUR			
	LABOUR FOR REPAIR ON AFFECTED AREA. INCLUSIVE OF THE REPAIR OF BOOTLID AND END PANEL.		1,000.00	250.00
	SPRAY PAINT ON AFFECTED AREA.		900.00	250.00
	CHECK WIRING.		50.00	20.00
	APPLY RUST PROF ON AFFECTED PANEL.	NOT NECESSARY	60.00	-
	REMOVE & REFIT AFFECTED REAR TRIM TO FACILITATE REPAIR.		150.00	40.00
	TO REMOVE AND REFIT REVERSE SENSOR.		80.00	30.00
			-	-
			_	- -
			2,240.00	590.00
	GRAND TOTAL		5,307.61	1,401.73

Report Ref No. CC4/ASM18002632/T1ea3s2



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS 1,401.73

Report Ref No. CC4/ASM18002632/T1ea3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

/mvont

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.