




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18002632/T1ea3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: STACEY NG			Date : 03-06-2020	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 7600S	Veh. Inspected	SKQ 1663K
	Policy No.	VPX/P1680520	Coverage (\$)	0.00
	Claim No.	S8M018CS	Excess (\$)	0.00
	Assign From	STACEY NG	Assign Date	07/02/2018
2. Vehicle Particulars & Condition				
	Make & Model	MAZDA 3	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	JM6BM4278F0144059	Colour	GREY
	Odometer	61318	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/40 R18	FALKEN	6 mm
	L/H Front Tyre	215/40 R18	FALKEN	6 mm
	R/H Rear Tyre	215/40 R18	FALKEN	6 mm
	L/H Rear Tyre	215/40 R18	FALKEN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	08/02/2018	Inspection Date	12/02/2018
	Survey held at	BLK K PANDAN LOOP #01-18		
	Repairer	LI SHENG AUTOMOBILE TRADING		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	