



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2015 TOYOTA COROLLA ALTIS 1.6 (SKT2217T)

Date of Loss

February 3, 2018

Time of Loss

3.15

Loss Description

SKT2217T (INSD) HIT TO THE DIVIDER

Comment

Workshop Details

Total Rebate Amount

60224

Nett Loss Amount

\$17,776.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

05/30/2018



Days of work completion *

111



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#

SKT2217T

Purchase Date

mm/dd/yyyy



Registration State

SINGAPORE

Registration Date *

05/28/2015



Mileage

83162

Age of Vehicle

2

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2015

ASSESSMENT INFO...

2015

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

CHI HAN WEI ZACHARY

POST SURVEY INF...

CATEGORY Make

POLICY INFORMAT... TOYOTA

ASSESSMENT INFO... TOYOTA

CATEGORY Model

POLICY INFORMAT... COROLLA ALTIS 1.6

ASSESSMENT INFO... TOYOTA COROLLA ALTIS 1.6L CVT

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... MR053REH104534023

CATEGORY Date of Birth

FNOL INFORMATI... September 9, 1993

POST SURVEY INF... mm/dd/yyyy



CATEGORY Age

FNOL INFORMATI... 24

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

ASSESSMENT INFO...

CATEGORY Engine No

POLICY INFORMAT... 1ZRX514645

ASSESSMENT INFO...

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO...

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO...

FNOL INFORMATI... 0

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI...

POST SURVEY INF... 

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... 

CATEGORY Address

FNOL INFORMATI... BLK 129 BEDOK NORTH ST 2 13-26,
460129, Singapore

POST SURVEY INF...

CATEGORY

Address type

FNOL INFORMATI...

Personal Correspondence

POST SURVEY INF...

CATEGORY

Gender

FNOL INFORMATI...

Male

POST SURVEY INF...

CATEGORY

Marital status

FNOL INFORMATI...

Unknown

POST SURVEY INF...

CATEGORY

Identification #

FNOL INFORMATI...

S9333289Z

POST SURVEY INF...

[SERVICE REQUESTS](#)[MESSAGES](#)[CLAIMS](#)

Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)[Summary](#)

Detailed Assessment

Inspection Date *

02/09/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

1850

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

205/55R16

Condition of Vehicle at time of survey

General condition

Fair



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Fair



Tyre Condition

Spare wheel

Rear Tyre Size

205/55R16

Front left side

MICHELIN6mm

Front right side

MICHELIN6mm

Rear left side

MICHELIN6mm

Rear right side

MICHELIN6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary **Parts**

Add Approve Deny

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTIC (PART
☐		1	1			FRONT BONNET COVER			Buckled	884.2		15		751.57	Revie
☐		2	1			FRONT BONNET COVER INNER INSULATOR			Deformed	327.5		15		278.38	Revie
☐		3	1			FRONT BONNET COVER INNER FRONT PC RUBBER STRIP			Necessary	40.9		15		34.77	Revie
☐		4	2			FRONT BONNET COVER HINGE			Bent	59.85		15		101.75	Revie
☐		5	1			FRONT BONNER COVER STAND			Serviceable	0	0	0	0	0	Deny
☐		6	1			FRONT BONNET COVER STAND PANEL BUSHING			Necessary	13.5		15		11.48	Revie
☐		7	1			FRONT BONNET LOCK ASSY			Bent	151.4		15		128.69	Revie
☐		8	1			FRONT SUPPORT PANEL			Buckled	488.6		15		415.31	Revie
☐		9	1			FRONT CENTER LOCK PANEL			Bent	154.8		15		131.58	Revie
☐		10	1			FRONT BONNET LOCK CABLE			Serviceable	0	0	0	0	0	Deny
☐		11	1			SET HORN			Damaged	131.8		15		112.03	Revie

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTIC (PART
		12	1			RAD GRILLE COMPLETE W/CHROME MOULDING			Cracked	424.35		15		360.7	Revie
		13	1			GRILLE EMBLEM			Necessary	57.5		15		48.88	Revie
		14	1			GRILLE TOP GARNISH			Cracked	94.3		15		80.16	Revie
		15	2			RH/LH HEADLAMP			Damaged	2406.8		15		4091.56	Revie
		16	2			RH/LH HEADLAMP TOP CHROME MOULDING			Damaged	163.3		15		277.61	Revie
		17	1			FRONT BUMPER			Damaged	472.3		15		401.46	Revie
		18	1			FRONT BUMPER REINFORCEMENT			Bent	325.45		15		276.63	Revie
		19	1			FRONT BUMPER LOWER CENTER GRILLE			Cracked	146.05		15		124.14	Revie
		20	2			FRONT BUMPER RH/LH FOG LAMP			Serviceable	0	0	0	0	0	Deny
		21	2			FRONT BUMPER RH/LH FOG LAMP COVER			Damaged	126.5		15		215.05	Revie
		22	2			FRONT BUMPER RH/LH RETAINER			Necessary	69		15		117.3	Revie
		23	1			SET FRONT BUMPER UNDER DUST COVER			Deformed	172.5		15		146.63	Revie
		24	2			FRONT RH/LH INLET WHEEL HOUSING			Bent	425.5		15		723.35	Revie

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTIC (PART
		25	2			FRONT RH/LH FENDER			Buckled	563.5		15		957.95	Revie
		26	1			SET FRONT FENDER LETTER BADGE			Necessary	46		15		39.1	Revie
		27	2			FRONT RH/LH FENDER INLET SHIELD			Deformed	138		15		234.6	Revie
		28	20			FENDER INLET SHIELD CLIP			Necessary	7.5		15		127.5	Revie
		29	2			FRONT RH/LH FENDER GARNISH			Serviceable	0	0	0	0	0	Deny
		30	1			FRONT LH FUSE BOX			Deformed	345		15		293.25	Revie
		31	1			BATTERY CASING			Deformed	356.5		15		303.03	Revie
		32	1			STEERING AIRBAG			Damaged	2707.1		15		2301.04	Revie
		33	1			STEERING CLOCK SPRING			Damaged	510.65		15		434.05	Revie
		34	1			LH DASHBOARD AIRBAG			Damaged	1095.2		15		930.92	Revie
		35	1			DASHBOARD			Damaged	2321.05		15		1972.89	Revie
		36	2			FRONT RH/LH SEAT SAFETY BELT			Damaged	947.5		15		1610.75	Revie
		37	2			FRONT RH/LH SEAT SAFETY BELT BUCKER			Serviceable	0	0	0	0	0	Deny
		38	1			AIRBAG CONTROL BOX (ECU)			Damaged	762.95		15		648.51	Revie

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTIC (PART
		39	1			FRONT CHASSIS FRAME AIRBAG SENSOR			Serviceable	0	0	0	0	0	Deny
		40	1			FRONT LOWER MEMBER FRAME			Buckled	417.85		15		355.17	Review
		41	1			FRONT CROSS MEMBER			Buckled	2051.5		15		1743.78	Review
		42	1			AIRCON CONDENSER			Bent	671.6		15		570.86	Review
		43	1			SET AIRCON LIQUID DISCHARGE PIPE			Bent	425.5		15		361.68	Review
		44	1			SET AIRCON SUCTION PIPE			Bent	429.2		15		364.82	Review
		45	1			RADIATOR			Bent	933.8		15		793.73	Review
		46	1			RADIATOR TOP HOSE			Buckled	46.75		15		39.74	Review
		47	1			RADIATOR BOTTOM HOSE			Serviceable	0	0	0	0	0	Deny
		48	1			RADIATOR FAN ASSY			Cracked	747.5		15		635.38	Review
		49	1			RADIATOR TOP BY PASS HOSE			Serviceable	0	0	0	0	0	Deny
		50	1			RADIATOR CAP			Serviceable	0	0	0	0	0	Deny
		51	1			WIPER TANK			Deformed	258.75		15		219.94	Review
		52	1			RADIATOR SPARE TANK			Deformed	178.25		15		151.51	Review

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTIC (PART
		53	1			SET ENGINE MOUNTING (4PCS)			Serviceable	0	0	0	0	0	Deny
		54	1			RH ABS PUMP			Serviceable	0	0	0	0	0	Deny
		55	1			ALTERNATOR			Serviceable	0	0	0	0	0	Deny
		56	1			FAN BELT			Serviceable	0	0	0	0	0	Deny
		57	1			CRANK SHAFT PULLEY			Serviceable	0	0	0	0	0	Deny
		58	1			CRANK SHAFT PULLEY OIL SEAL KIT			Serviceable	0	0	0	0	0	Deny
		59	1			ENGINE TIMING COVER			Serviceable	0	0	0	0	0	Deny
		60	1			ENGINE OIL PAN			Serviceable	0	0	0	0	0	Deny
		61	1			ENGINE UNDER DUST COVER			Serviceable	0	0	0	0	0	Deny
		62	1			FRONT RH SHOCK ABSORBER			Serviceable	0	0	0	0	0	Deny
		63	1			FRONT RH SHOCK ABSORBER			Serviceable	0	0	0	0	0	Deny
		64	1			FRONT RH SHOCK ABSORBER TOP MOUNTING			Serviceable	0	0	0	0	0	Deny
		65	1			FRONT RH WHEEL HUB KNUCKLE			Serviceable	0	0	0	0	0	Deny
		66	1			FRONT RH WHEEL HUB			Serviceable	0	0	0	0	0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTIC (PART
☐		67	1			FRONT RH WHEEL BEARING KIT			Serviceable	0	0	0	0	0	Deny
☐		68	1			FRONT RH LOWER ARM			Serviceable	0	0	0	0	0	Deny
☐		69	1			FRONT RH STABILIZER LINK			Serviceable	0	0	0	0	0	Deny
☐		70	2			FRONT RH / LH WHEEL ABS SENSOR			Serviceable	0	0	0	0	0	Deny
☐		71	1			AIR CLEANER (ADDITIONAL)			Cracked	786.24		15		668.3	Revie
☐		72	1			INLET AIR CLEANER (ADDITIONAL)			Cracked	166.68		15		141.68	Revie
☐		73	1			AIR CLEANER HOSE (ADDITIONAL)			Cracked	170.32		15		144.77	Revie
☐		74	1			INLET MANIFOLD (ADDITIONAL)			Cracked	937.82		15		797.15	Revie
☐		75	1			AIRCON COMPRESSOR PUMP (ADDITIONAL)			Bent	4304.23		15		3658.6	Revie
☐		76	1			WATER PUMP (ADDITIONAL)			Bent	281.08		15		238.92	Revie
☐		77	1			ENGINE OIL FILTER HOUSING COVER			Damaged	86.14		15		73.22	Revie
☐		78	1			RH DRIVE SHAFT (ADDITIONAL)			Bent	1702.08		15		1446.77	Revie
☐		79	1			FRONT WINDSCREEN GLASS (ADDITIONAL)			Cracked	668.73		15		568.42	Revie

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PART)
		80	1			FRONT WINDSCREEN MOULDING (ADDITIONAL)			Necessary	84.06		15		71.45	Review
		81	1			FAN BLADE (ADDITIONAL)			Cracked	139.15		15		118.28	Review
		82	1			FAN COWLING (ADDITIONAL)			Cracked	205.85		15		174.97	Review
		83	1			RADIATOR FAN COWLING UPPER GUIDE (ADDITIONAL)			Cracked	99.44		15		84.52	Review
		84	2			FRONT RH / LH SUB CHASSIS MEMBER (ADDITIONAL)			Buckled	965.95		15		1642.12	Review
		85	2			ENGINE TIMING DAMPER			Cracked	114.6		15		194.82	Review

Labour

Add		Approve		Deny						
EDIT		SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	
		1		TOWING CHARGE	0	0	0	Deny		
		2		LIFT-UP WHOLE ENGINE UNIT, DISMANTLE & REMOVE OF FRONTAL UNDER CARRIAGE PARTS & ATTACHMENTS WHERE NECESSARY TO FACILITATE OF REPAIRS	1000	0	0	Reviewing		
		3		REMOVE AIRCON CONDENSER UNIT, AIRCON COMPRESSOR PUMP, AIRCON PIPELINES & ATTACHMENTS WHERE NECESSARY TO FACILITATE OF REPAIRS. ONCOMPLETION, COMPUTERIZED VACUUM & REFILL OF AIRCON GAS, TOP-UP COMPRESSOR OIL	180	0	0	Reviewing		

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	I
 	4		REMOVE & DISMANTLE FRONTAL DAMAGED PARTS & ATTACHMENTS WHERE NECESSARY TO FACILITATE OF REPAIRS. TO JACK-OUT & STRAIGHTEN-UP FRONTAL CHASSIS FRAME, SUPPORT PANEL, BOTH WHEEL HOUSING ADJUST & ALIGN FRONTAL PORTION IN POSITION }	1400	0	0	Reviewing		
 	5		CUT-OUT & REPLACE FRONT SUPPORT PANEL, BOTH WHEEL HOUSING, KNOCK - OUT & PANEL BEATING ON DENTS DUE TO THE ACCIDENT, RENEW AFORESAID BODY PARTS. ONCOMPLETION, ADJUST & ALIGN NECESSARY CONNECTIONS }	0	0	0	Reviewing		
 	6		TO PUTTY & SPRAY PAINTING ON FRONTAL BODY PORTION, BOTH WHEEL HOUSING, CHASSIS FRAME, RENEWED PARTS IN & OUTLET, DAMAGED SECTION WITH WELDED PORTIONS	1400	0	0	Reviewing		
 	7		TO RUST PROOF ALL DAMAGED PARTS & PORTIONS	160	0	0	Reviewing		
 	8		TO REMOVE OF DASHBOARD UNIT, STEERING WHEEL ASSY, PILLAR SAFETY BELTS ASSY, PARTS & ATTACHMENTS WHERE NECESSARY TO FACILITATE OF REPAIRS. REMOVE & REPLACE OF AIRBAG, SAFETY BELTS & BUCKER, AIRBAG ECU, ETC	650	0	0	Reviewing		
 	9		TO CHECK & RECTIFY OF WIRING SYSTEM	100	0	0	Reviewing		
 	10		ONCOMPLETION COMPUTERIZED SCAN / DIAGNOSIST & RESET OF CODES & AIRBAG	100	0	0	Reviewing		
 	11		COMPUTERIZED WHEEL ALIGNMENT & CAMBER CHECKING	60	0	0	Reviewing		

EDIT		SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	
		12		REMOVE & REPLACE OF FRONT WINDSCREEN GLASS, MOULDING & SEALANT (ADDITIONAL)	120	0	0	Reviewing		
		13		REMOVE & REPLACE OF INLET MANIFOLD ASSY (ADDITIONAL)	80	0	0	Reviewing		

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Add

Approve

Deny

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐		1	DAYS OF REPAIR : 14 DAYS	Reviewing			
☐		2	RADIATOR COOLANT (4L)	Reviewing	48	NECESSARY	
☐		3	BRAKE FLUID (2L)	Reviewing	36	NECESSARY	
☐		4	SET FRONT NUMBER PLATE (PRESS TYPE) W/BOX	Reviewing	35	SCRATCHED	
☐		5	FRONT WINDSCREEN SEALANT	Reviewing	100	NECESSARY (SUPPLEMENTARY)	
☐		6	ERP HOLDER	Reviewing	50	NECESSARY (SUPPLEMENTARY)	

Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
----------------------------	--------------------------	-------------------	---------------	----------------	---------------	---------

Claim Amount

\$37,612.22

Claim Amount

\$37,612.22

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$5,250.00	\$5,250.00
Miscellaneous	\$269.00	\$269.00
Excess	-\$1,850.00	-\$1,850.00
Spare Parts	\$33,943.22	\$33,943.22

Submit for Review