

ASS. REC. BY:

REF: CS/FCI18002697/Kfd3 12

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person):

CWS

Lurene jaw

of

FCI

Date/Time: 8/2/18 @ 3:55pm

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHB 7831S

Insured:

SHA0508C

at Workshop m/s

Trans-Cab Auto

Tel:

6287 6666

of

No. 2 AMK Street 63

Policy No:

Claim No:

D18001213MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

07/02/2018

CA / REV / REP. / REV 24 HRS

1 up

H.O.D. Endorsement:

Date/Time:

9:47am @ 9/2/18

Person Contacted:

Candy

Vehicle: IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SHB 7831S - CS/FCI11014473/Kfc

D.O.A: 22/07/2011

SHA 508C - CC3/ALG08031015/Kaj

D.O.A: 13/11/2008

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s Trans Cab

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHB 78315 Yr Regn: 10, 12

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Charolett Epiz c.c. 1891Colour: White / Red A/C: Insured / Std / NI / NASp. Reading: 282715 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KL11A19R5BB 107027Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Mil / S/Rim / STD A/Rim orTyre Size: F: Giti 195/65R15Lig R: Lay

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 9 mmL/Bal. 9 mmD.O.A. 7/2/18

Survey held at

Rear

R/Bal. 7 mmL/Bal. 7 mmD.O.I. 9/2/18

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

12/2 File per 1 to Cathman
 1/2p @ 30501 (Red: 11047.21: -89%)

RECEIVED 13 FEB 2018

Date/Time, File Pass to?

1) 13/2 Typist ☐ : Prel. ReportDate/Time, File Return to? ☒ : Final ReportDays Of Repair: 6Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S - RS \$

Photos

Others

TOTAL

5x15 = 75

170 + 75

50

14

309

Report Format: TPLump Sum / I.B.I: (\$ 32501)

MOTOR SURVEY ASSIGNMENT

Date	08-02-2018	Our Ref No. D18001213MFSH
Accident Date	07-02-2018	Claim Type. Third Party
Insured Vehicle	SHA0508C	Third Party Vehicle. SHB7831S
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	CANDY KONG	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/234840)



PRI Documents



Close



PRI Header Details

Claim No	D18001213MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & TRANS-CAB A
Workshop Name	TRANS-CAB AUTO SERVICES PTE LTD (Contact Person : CANDY KONG)	Survey Location & Contact Details	NO. 2 ANG MO KIO STREET 63 Mobile: 0 , Phone: 62876666 , Fax: 62571330 EmailId: CANDY.KONG@TRANSCAB.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO E		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHA0508C	TP Vehicle No	SHB7831S
PRI Recieved Date	08-02-2018 06:01:12 PM	Surveyor Appointed Date	08-02-2018 03:54:38 PM	Surveyor Accept Date	09-02-2018 10:3

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	09-02-2018	Upload Survey Report *:	Choose File No 1
-----------------------------	--	----------------------	------------	-------------------------	---

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18002697/Ktd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 09-02-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 508C	Veh. Inspected	SHB 7831S	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18001213MFSH	Excess (\$)	0.00	
Assign From	CWS (LURENE JAW)	Assign Date	09/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	07/02/2018	Inspection Date	09/02/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHB7831S
Vehicle to be Exported:	Yes
Intended De-registration Date:	07 Feb 2018
Vehicle Make:	CHEVROLET
Vehicle Model:	EPICA 2.0DSL AT ABS D/AB 2WD 4DR TURBO
Primary Colour:	Red
Manufacturing Year:	2011
Engine No.:	Z20S1458335K
Chassis No.:	KL1LA69RJBB107627
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$14,316.00
Original Registration Date:	31 Oct 2012
First Registration Date:	31 Oct 2012
Transfer Count:	0
Actual ARF Paid:	\$14,316.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Oct 2020
PARF Rebate Amount:	\$10,021.00
Intended COE Rebate Details	

COE Expiry Date:	30 Oct 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$53,263.00
COE Rebate Amount:	\$18,165.00
Total Rebate Amount:	\$28,186.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 07 Feb 2018

OK

TRANS-CAB AUTO SERVICES PTE LTD

AAD1802-081

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB7831S - FCIL

*Not Authored**L/Sy 832506*

Vehicle No.:

SHB7831S - CANDY

Chassis No.:

KL1LA69RJB107627

Date of Accident:

07.02.2018

Vehicle Make:

CHEVROLET

Vehicle Model:

CHEVROLET EPICA 2.0

Third Party Insurer:

FCIL

PART**LIST**

1	1	Rear Door LH	\$	B ₁	1,133.00	✓
2	1	Rear Fender LH	\$	B ₂	1,145.00	✓
3	1	Rear Fender Inner Cowling LH	\$	S ₁	76.60	} X
4	1	Rear Tail Lamp LH	\$	S ₂	479.30	
5	1	Rear Tail Lamp Panel LH	\$	N	359.00	
6	1	Side Rocker Panel Garnish LH	\$	N	236.40	
7	1	Bootlid	\$	N	973.00	
8	1	Bootlid inner trim board	\$	S ₁	400.00	
9	1	Bootlid Weatherstrip	\$	S ₂	344.28	
10	1	Bootlid Lock - Top	\$	N	466.56	
11	1	Bootlid 'CHEVROLET' Badge	\$	N ₁	120.62	
12	1	Bootlid Logo	\$	N ₂	138.84	
13	1	Bootlid 'EPICA LT' Badge	\$	N ₃	119.84	
14	1	Bootlid Reflector Centre	\$	S ₁	217.97	}
15	1	Bootlid Reflector LH	\$	S ₂	128.40	
16	1	Rear Bumper	\$	N	1,202.00	
17	1	Rear Bumper Beam	\$	N	239.94	
18	1	Rear Bumper Centre Absorber	\$	S ₁	260.00	
19	1	Rear Bumper Side Retainer LH	\$	S ₂	68.76	
20	1	Rear Bumper Side Retainer LH	\$	S ₂	68.76	
21	1	Rear Bumper Reflectors LH	\$	S ₁	119.74	

TOTAL	\$	8,298.01
10%	\$	829.80
	\$	7,468.21

Special Nett

1	1 Set	Rear Bumper Fastener Clip	\$	N ₁	30.00	X
2	1 Set	Rear Fender Liner Clip	\$	N ₂	30.00	X
3	1Set	Rear Bumper Parking Sensor	\$	S ₁	300.00	X

TRANS-CAB AUTO SERVICES PTE LTD

AAD1802-081

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB7831S - FCIL

4	2	Rear Windscreen Sealant	\$	80.00	Posa
5	1	Rear Windscreen Inner Sponge Seal	\$	100.00	30sa
6	1	Door Sticker "6555-3333"	\$	80.00	60sa
7	1	Rear Boot Sticker 'Trans-cab'	\$	30.00	X
8	1	Rear Boot Sticker '6555-3333'	\$	30.00	X
9	1	Rear Tyre LH	\$	360.00	X
10	1	Rear Wheel Rim LH	\$	254.00	X
11	1	Hub Cup Rim Rear	\$	35.00	X

TOTAL	\$	1,329.00
TOTAL PARTS	\$	8,797.21

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$ 2,800.00 800

To Rust-Proofing Of The Affected Areas.

\$ 220.00 60

Putty and Spray Painting Of The Affected
Portion.

\$ 2,700.00 800

To Check Electrical Lighting Concerned.

\$ 170.00 20

To Remove And Refit Rear W/Screen Glass To
Facilitate Bodywork Repair.

\$ 170.00 120

To Transfer Of Fender Fittings, Attachments
And Perform Water Seepage Test.

\$ 170.00 100

To transfer of tire, rim and on wheel balancing.

\$ 170.00 X

TOTAL	\$	6,400.00
Over All Total	\$	15,197.21

REPAIR DAYS

LKK Auto Consultants hence notify
the Repairer of the following: **10 DAYS**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18002697/Ktd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 14-02-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 508C	Veh. Inspected	SHB 7831S	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18001213MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	08/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	CHEVROLET EPICA (A)	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	KL1LA69RJBB107627	Colour	WHITE / RED	
Odometer	292715	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	GITI	9 mm	
L/H Front Tyre	195/65 R15	GITI	9 mm	
R/H Rear Tyre	195/65 R15	LING LONG	7 mm	
L/H Rear Tyre	195/65 R15	LING LONG	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/02/2018	Inspection Date	09/02/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 7831S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR DOOR LH	BENT	1,133.00	1,133.00
1	REAR FENDER LH	BENT	1,145.00	1,145.00
1	REAR FENDER INNER COWLING LH	SERVICEABLE	76.60	-
1	REAR TAIL LAMP LH	SERVICEABLE	479.30	-
1	REAR TAIL LAMP PANEL LH	TO REPAIR SEE LABOUR	359.00	-
1	SIDE ROCKER PANEL GARNISH LH	TO REPAIR SEE LABOUR	236.40	-
1	BOOTLID	TO REPAIR SEE LABOUR	973.00	-
1	BOOTLID INNER TRIM BOARD	SERVICEABLE	400.00	-
1	BOOTLID WEATHERSTRIP	SERVICEABLE	344.28	-
1	BOOTLID LOCK-TOP	TO REPAIR SEE LABOUR	466.56	-
1	BOOTLID "CHEVROLET" BADGE	NOT NECESSARY	120.62	-
1	BOOTLID LOGO	NOT NECESSARY	138.84	-
1	BOOTLID "EPICA LT" BADGE	NOT NECESSARY	119.84	-
1	BOOTLID REFLECTOR CENTRE	SERVICEABLE	217.97	-
1	BOOTLID REFLECTOR LH	SERVICEABLE	128.40	-
1	REAR BUMPER	TO REPAIR SEE LABOUR	1,202.00	-
1	REAR BUMPER BEAM	TO REPAIR SEE LABOUR	239.94	-
1	REAR BUMPER CENTRE ABSORBER	SERVICEABLE	260.00	-
1	REAR BUMPER SIDE RETAINER LH	SERVICEABLE	68.76	-
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	68.76	-
1	REAR BUMPER REFLECTORS LH	SERVICEABLE	119.74	-
	LESS 10% DISCOUNT		-829.80	-227.80
			7,468.21	2,050.20
SPECIAL NETT ITEMS				
1	SET REAR BUMPER FASTENER CLIP (SN)	NOT NECESSARY	30.00	-
1	SET REAR FENDER LINER CLIP (SN)	NOT NECESSARY	30.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR BUMPER PARKING SENSOR (SN)	SERVICEABLE	300.00	-
2	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NECESSARY	100.00	30.00
1	DOOR STICKER "6555-3333" (SN)	NECESSARY	80.00	60.00
1	REAR BOOT STICKER "TRANS-CAB" (SN)	NOT NECESSARY	30.00	-
1	REAR BOOT STICKER "6555-3333" (SN)	NOT NECESSARY	30.00	-
1	REAR TYRE LH (SN)	SERVICEABLE	360.00	-
1	REAR WHEEL RIM LH (SN)	SERVICEABLE	254.00	-
1	HUB CUP RIM REAR (SN)	SERVICEABLE	35.00	-
			1,329.00	130.00
	LABOUR			
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF REAR TAIL LAMP PANEL LH,SIDE ROCKER PANEL GARNISH LH,BOOTLID,BOOTLID LOCK-TOP,REAR BUMPER AND REAR BUMPER BEAM.		2,800.00	800.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		220.00	60.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		2,700.00	800.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO REMOVE AND REFIT REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.		170.00	120.00
	TO TRANSFER OF FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	100.00
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
			6,400.00	1,900.00
GRAND TOTAL			15,197.21	4,080.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,250.00

Report Ref No. CS/FCI18002697/Ktd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.