



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2013 ISUZU NPR85UH5AC (YN4296S)

Date of Loss

6 February 2018

Time of Loss

9.45

Loss Description

YN4296S (INSD) C/W UNKNOWN (TP)

Comment

Workshop Details

Total Rebate Amount

39157

Nett Loss Amount

\$28,843.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

17/05/2018



Days of work completion *

97



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#
YN4296S

Registration State

SINGAPORE

Mileage

257161

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2013

ASSESSMENT INFO...

2013

Purchase Date

dd/mm/yyyy



Registration Date *

11/11/2013



Age of Vehicle

4

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

YE MAOMING

POST SURVEY INF...

CATEGORY Make

POLICY INFORMAT... ISUZU

ASSESSMENT INFO... ISUZU

CATEGORY Model

POLICY INFORMAT... NPR85UH5AC

ASSESSMENT INFO... NPR85UH5AC

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... JAANPR85HD7100411

CATEGORY Date of Birth

FNOL INFORMATI... 12 December 1974

POST SURVEY INF... dd/mm/yyyy



CATEGORY Age

FNOL INFORMATI... 43

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

ASSESSMENT INFO...

CATEGORY Engine No

POLICY INFORMAT... 4JJ11A5371

ASSESSMENT INFO...

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO...

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO...

FNOL INFORMATI... 6

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI... 1 January 2012

POST SURVEY INF... 

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... 

CATEGORY Address

FNOL INFORMATI... TBA, Singapore

POST SURVEY INF...

CATEGORY

Address type

FNOL INFORMATI...

Personal Correspondence

POST SURVEY INF...

CATEGORY

Gender

FNOL INFORMATI...

Male

POST SURVEY INF...

CATEGORY

Marital status

FNOL INFORMATI...

Unknown

POST SURVEY INF...

CATEGORY

Identification #

FNOL INFORMATI...

G8588509Q

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

12/02/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

900

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

195/85R16

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Tyre Condition

Spare wheel

Rear Tyre Size

205/85R16

Front left side

YOKOHAMA6mm

Front right side

YOKOHAMA6mm

Rear left side

CHAOYANG6mm

Rear right side

CHAOYANG6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

15

Settlement%

100

Paint Labour/Material Ratio

Paint Labour Ratio

20

Paint Material Ratio

80

Cash Loss

Yes

No

Save

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary **Parts**

Add

Approve

Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		1	1			FRONT WINDSCREEN			Cracked	1260		15		1071	Reviewir
		2	1			FRONT WINDSCREEN ERP BRACKET			Necessary	30		15		25.5	Reviewir
		3	1			FRONT WINDSCREEN MOULDING			Necessary	175		15		148.75	Reviewir
		4	1			FRONT WIPER ARM RH			Cut	58		15		49.3	Reviewir
		5	1			FRONT WIPER ARM LH			Serviceable	0	0	0	0	0	Deny
		6	2			FRONT WIPER ARM COVER			Serviceable	0	0	0	0	0	Deny
		7	1			FRONT PANEL ISUZU LOGO			Necessary	125		15		106.25	Reviewir
		8	1			FRONT PANEL REWARD - NP STICKER			Necessary	65		15		55.25	Reviewir
		9	2			FRONT SIDE PANEL			Deformed	260		15		442	Reviewir
		10	2			FRONT SIDE MIRROR			Cut	42		15		71.4	Reviewir
		11	2			FRONT SIDE MIRROR BRACKET			Bent	280		15		476	Reviewir

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)
		12	1			FRONT L/H ROUND MIRROR			Damaged	50		15		42.5	Reviewir
		13	1			FRONT HEAD LAMP LH			Cut	295		15		250.75	Reviewir
		14	1			FRONT HEAD LAMP RH			Serviceable	0	0	0	0	0	Deny
		15	1			FRONT SIDE LAMP LH			Cracked	85		15		72.25	Reviewir
		16	1			FRONT SIDE LAMP RH			Serviceable	0	0	0	0	0	Deny
		17	1			FRONT GRILLE			Cracked	380		15		323	Reviewir
		18	1			FRONT BUMPER			Bent	440		15		374	Reviewir
		19	2			FRONT BUMPER BRACKET			Bent	120		15		204	Reviewir
		20	1			FRONT BUMPER BRACKET TOP RUBBER			Serviceable	0	0	0	0	0	Deny
		21	1			FRONT BUMPER CENTRE LOWER COVER			Serviceable	0	0	0	0	0	Deny
		22	2			FRONT DOOR			Damaged	950		15		1615	Reviewir
		23	2			FRONT DOOR SIGNAL LAMP			Cut	55		15		93.5	Reviewir
		24	2			FRONT DOOR PROTECTOR			Cut	60		15		102	Reviewir

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		25	2			FRONT DOOR OUTER LOWER COVER			Deformed	165		15		280.5	Reviewir
		26	1			FRONT DOOR GLASS OUTER MOULDING LH			Cut	155		15		131.75	Reviewir
		27	1			FRONT DOOR GLASS OUTER MOULDING RH			Serviceable	0	0	0	0	0	Deny
		28	1			FRONT L/H DOOR OUTER HANDLE			Cut	145		15		123.25	Reviewir
		29	1			FRONT R/H DOOR REAR PILLAR			Damaged	1150		15		977.5	Reviewir
		30	1			FRONT L/H MUD FLAP			Cracked	220		15		187	Reviewir
		31	2			FRONT STEP PANEL			Cut	95		15		161.5	Reviewir
		32	2			FRONT STEP PANEL LAMP			Cut	55		15		93.5	Reviewir
		33	1			FRONT AXLE			Bent	2955		15		2511.75	Reviewir
		34	2			FRONT AXLE BEARING			Necessary	380		15		646	Reviewir
		35	2			FRONT SHOCK ABSORBER			Bent	125		15		212.5	Reviewir
		36	1			FRONT ANTI ROLL BAR			Bent	550		15		467.5	Reviewir
		37	2			FRONT SPRING ASSY			Serviceable	0	0	0	0	0	Deny
		38	2			FRONT SPRING KING PIN SET			Serviceable	0	0	0	0	0	Deny

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)
		39	1			FRONT RADIATOR			Bent	1265		15		1075.25	Reviewir
		40	1			FRONT RADIATOR FAN			Cracked	175		15		148.75	Reviewir
		41	1			FRONT RADIATOR FAN CLUTCH			Serviceable	0	0	0	0	0	Deny
		42	1			FRONT RADIATOR FAN COWLING			Cracked	220		15		187	Reviewir
		43	1			FRONT AIR-CON CONDENSER			Damaged	1150		15		977.5	Reviewir
		44	1			FRONT AIR-CON FAN MOTOR ASSY			Damaged	585		15		497.25	Reviewir
		45	1			FRONT AIR-CON SECTION PIPE			Serviceable	0	0	0	0	0	Deny
		46	1			FRONT AIR-CON DISCHARGE PIPE			Serviceable	0	0	0	0	0	Deny
		47	1			FRONT AIR-CON PIPE (TOP COMPRESSOR)			Serviceable	0	0	0	0	0	Deny
		48	1			FRONT L/H AIR-CON CONDENSER			Damaged	520		15		442	Reviewir
		49	1			FRONT L/H AIR-CON CONDENSER FAN MOTOR ASSY			Damaged	430		15		365.5	Reviewir
		50	1			FRONT L/H AIR-CON CONDENSER SECTION PIPE			Serviceable	0	0	0	0	0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		51	1			FRONT L/H AIR-CON CONDENSER DISCHARGE PIPE			Serviceable	0	0	0	0	0	Deny
		52	1			REAR R/H TAIL LAMP			Cracked	195		15		165.75	Reviewir
		53	1			REAR R/H TAIL LAMP BRACKET			Bent	125		15		106.25	Reviewir
		54	1			REAR L/H AXLE LONG SHAFT			Bent	690		15		586.5	Reviewir
		55	1			REAR R/H AXLE LONG SHAFT			Serviceable	0	0	0	0	0	Deny
		56	1			REAR MUD GUARD			Serviceable	0	0	0	0	0	Deny

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMARK
		1		TO REMOVE & REFIT FRONT WINDSCREEN	120	0	0	Reviewing		
		2		GUM	50	0	0	Reviewing		
		3		TO REMOVE & REFIT L/H & R/H DOOR, GEAR MOTOR, GLASS, LOCK, RUBBER & TRIM BOARD	160	0	0	Reviewing		
		4		TO REMOVE & REFIT FRONT CENTRE AIR-CON CONDENSER, L/H AIR-CON CONDENSER, RADIATOR, FAN, CLUTCH, AIR-CON PIPE & TOP UP GAS	280	0	0	Reviewing		
		5		TO REMOVE & REFIT FRONT SPRING, AXLE, BEARING, KING PIN, SHOCK ABSORBER & ANTI ROLL BAR	450	0	0	Reviewing		

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMO
		6		TO REMOVE & REFIT AXLE, BEARING & LONG SHAFT	350	0	0	Reviewing		
		7		TO REMOVE & REFIT ICE BOX	600	0	0	Reviewing		
		8		TO REMOVE & REFIT ICE BOX CONDENSER & PIPE	450	0	0	Reviewing		
		9		TO CHECK WHEEL ALIGNMENT	80	0	0	Reviewing		
		10		TO CHECK WIRING	60	0	0	Reviewing		
		11		TOWING FEE	200	0	0	Reviewing		
		12		PANEL BEATING	1200	0	0	Reviewing		
		13		SPRAY PAINTING	2200	0	0	Reviewing		

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		1	DAYS OF REPAIR : 21 DAYS	Reviewing			
		2	(REPAIR COST NOT CONCLUDE)	Reviewing			
		3	FRONT BUMPER NUMBER PLATE	Reviewing	25	BENT	
		4	FRONT RIM-2PCS	Reviewing	600	DENTED	
		5	FRONT TYRE-2PCS	Deny	0	NOT NECESSARY	
		6	REAR BUMPER	Reviewing	500	BENT	

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐		7	REAR BUMPER BRACKET - 2PCS	Deny	0	NOT NECESSARY	
☐		8	REAR RIM - 2PCS	Reviewing	300	N/S BENT	
☐		9	REAR TYRE-2PCS	Deny	0	NOT NECESSARY	
☐		10	REAR AXLE	Deny	0	NOT NECESSARY	
☐		11	REAR AXLE BEARING - 2PCS	Deny	0	NOT NECESSARY	
☐		12	REAR ICE BOX ASSY	Reviewing	6500	DAMAGED	
☐		13	REAR ICE BOX CENTRE TOP AIR-CON COVER	Reviewing	680	CRACKED	

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Claim Amount \$29,771.95

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$6,200.00	\$6,200.00
Spare Parts	\$15,866.95	\$15,866.95
Miscellaneous	\$8,605.00	\$8,605.00
Excess	-\$900.00	-\$900.00

Submit for Review

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Add

Approve

Deny

EDIT		SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		1	FINAL LUMP SUM	Reviewing	24500		

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Claim Amount \$23,600.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Miscellaneous	\$24,500.00	\$24,500.00
Excess	-\$900.00	-\$900.00

Submit for Review