

invalid ▾

Menu ←

88m00811  
CK130772

## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### General Details

Involving

1 2009 TOYOTA MARK X 2.5 (SVJ8928L)

Date of Loss

January 30, 2018

Time of Loss

11.00

Loss Description

SVJ8928L (INSD) PARKED AND FOUND DAMAGED

Tanjim 97495749  
14/2/18 @ 1215pm  
Revert Not Authorised  
EX: NIL  
Resurvey before paint  
3 days  
Sur @ (Mhandu.wm)

Comment

### Workshop Details

Total Rebate Amount

0

Nett Loss Amount

\$0.00

Assigned Workshop

MOVA AUTOMOTIVE PTE LTD

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Target Date of Completion \*

02/13/2018



Days of work completion \*

4



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

Parts

Add

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DISC COUNT%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		1	1			HEADLAMP RH			wt ✓	590		590	Reviewing	
		2	1			FRONT BUMPER			de ✓	720		720	Reviewing	
		3	1			FRONT BUMPER SIDE RETAINER RH			wt ✓	35		35	Reviewing	
		4	10			FRONT BUMPER CLIPS			wt ✓	2.5		25	Reviewing	
		5	1			FRONT FENDER RH - REPAIR			Rp	0		0	Reviewing	
		6	1			FRONT FENDER COWLING RH - REPAIR			x	0		0	Reviewing	
		7	1			FRONT SUPPORT HEADLAMP PANEL RH - REPAIR			Rx	0		0	Reviewing	

Labour

Add

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		1		TO INSPECT FRONT LIGHTING MECHANISM	0	40	20	0	Reviewing	
		2		TO REPAIR ON FRONT FENDER RH, HEADLAMP PANEL TO REMOVE & REPLACE DAMAGED ITEMS. REALIGN CONNECTION	0	500	200	0	Reviewing	
		3		TO SPRAY PAINT ON REPAIRED AREAS	0	0	400	500	Reviewing	



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

Claim Amount

\$2,410.00

CATEGORY

Labour

ESTIMATE

\$540.00

REVISED AMOUNT

\$540.00

CATEGORY

Spare Parts

ESTIMATE

\$1,370.00

REVISED AMOUNT

\$1,370.00

CATEGORY

Paint

ESTIMATE

\$500.00

REVISED AMOUNT

\$500.00