

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	DIRECT ASIA INSURANCE (S) PL		Ref:	CS3/DAI18002769/T1ps3q2	
	20 ANSON ROAD #08-01 TWENTY ANSONSINGAPORE 079912		Date:	27/04/2021	
			Code:	DAI	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SLQ 9756L	Veh. Inspected	GBB 1386X	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	75135/CH	Excess (\$)	0.00	
	Assign From		Assign Date	23/02/2018	
2. Vehicle Particulars & Condition					
	Make & Model	MITSUBISHI L200	c.c	2477	
	Engine No.	HIDDEN	Year of Reg.	2008	
	Chassis No.	MMBJNKB407D165576	Colour	BLACK	
	Odometer	275795 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	205 R16	BRIDGESTONE	6 mm	
	L/H Front Tyre	205 R16	BRIDGESTONE	6 mm	
	R/H Rear Tyre	205 R16	BRIDGESTONE	6 mm	
	L/H Rear Tyre	205 R16	BRIDGESTONE	6 mm	
4. Description of Damages					
	THE VEHICLE SUS	STAINED DAMAGES AT THE REAR PORTION.			
5.	General Information				
	Accident Date	07/02/2018	Inspect Date / Time	02/03/2018 (03:15 PM)	
	Survey held at	WOON MENG MOTOR PTE LTI)		
		50 BUKIT BATOK ST 23 #01-06 MIDVIEW BUILDING SINGAPORE 659578			
5a.	a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/DAI18002769/T1ps3q2

Inspected By

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

Automotive Assessor REGD Auto Consultant-SAE, Licensed Appraiser