

CS3/MSG17020587/RLG⁵⁷
 1

range

Nextmen
 From Person: Christina Wong
 MSIG
 12022018

OD (TP) WST TR RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No: XD 1032X

Insured: YL 1437H

at Workshop no: Lys Engineering

T: 9730 8695

at 27A Jurong Port Rd, 619101

Policy No: 28639715 MKC

Claim No: M5314409

Sum Insured:

Make of Veh:
 (Client's Record)

DOA: 20/10/2017

CA / REV / REP / REV 24 HRS

1wp

30/10/2017 @ After 11:30 a.m
 Street 4, sg.kadut

Date/Time: 27/10/17 @ 12:20pm

Vehicle Insured:

Steven

Vehicle IS: OUT

Date/Time	Action/Inspection (X) Estimate	Do Not Tindia
	XD 1032X - X	
	YL 1437H - X	
	Dismantle Part: 31.10.2017	
	After repair: 06.11.2017	

11/17 6:56pm Email to Christina Wong thru mesmen

13/1/18 Submit LS to 6760, 5 days (Red & 5650, 467-)

RECEIVED 13 FEB 2018

Form

REF: MSIG

ASSIGNMENT

Form

Date

30/10/2017

Vehicle

XD 1032X

Page

2006 Sep 25

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No

XD 1032 X

at Workshop m/s

Lys Engineering

at

Street 4, Sungai Kadut

Insured

Policy No

Claims No

Sum Insured

Excess


(Client's Report)

Make of veh

After 11:30 am

(Policy Condition)

Remarks: The veh had commenced its repair at the time of inspection.



Bel or Market Value

IDAC Accident Report Consistent? Yes or No

GIA / PR Seen Consistent? Yes or No

Est. Repairs: days Res: Yes or No

Lum. Surp: % 3 Veh: Yes or No

CA / REV / REP. / 24 HRS 'up'

Date

Person Contacted

Vehicle IN / OUT

Date Time Action Instruction

Type M/Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer /

Make

Nissan CKB45ABTN2 cc 12503

Colour

yellow

A/C Insured / Std / NI / NA

St Reading

95678

T Radio Insured / Std / NI / NA

Eng No

C No

CKB45ABT 00788

Gen Cond: Good / Poor / Burnt

Steering: Jumper / Jammed / Leaked / Burnt or

Brake: Jumper / Jammed / Leaked / Burnt or

Mod: M / S / Rim / STD A / Rim or

Tyre Size

F 295/80R22.5

R

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / QHTSU / SUMI /

TOYO / YOKO or

Front

Rear

R Bal

8

mm

R Bal

8/8

mm

L Bal

8

mm

L Bal

8/8

mm

D/OA

20/10/17

D/OA

30/10/17 @ 4:53pm

Survey held at

LYS ENGINEERING

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

ESTIMATE RANGE OF REPAIR COST — (5K-10K)

Date Time File Pass to

15-11-2017



Prel. Report

Final Report

Date Time File Return to

Days Of Repair:

Resurvey No. of Trip

Survey Fee

Transport

\$

Add Fee:



Est. Inst.

Vehicle

Vehicle

Vehicle

Report Format

PRS

Lump Sum / B



X-01032X

Policy Type: OD / TP / TP RES / TL / EVA /

Typist

(1) Office Assign Form

C	Reference No.	✓		
C	Customer Code	✓		
N	Assign From	✓		
C	Assign Date	✓		
C	Veh No (Inspected)	✓		
C	Veh No (Insured)	✓		
C	D.O.A	✓		
C	Policy No	✓		
C	Claim No	✓		
C	Insurance Authorisation (CA /REV/REP)			
C	Report Type	✓		
C	Weekend Charges			
N	Survey held at/Repairer	✓		
C	Excess			


(1) Assignment Form

(1) Assignment Form					
C	Vehicle No				
C	Regn Month/Year				
N	Vehicle Type				
N	Make & Model				
C	Engine Capacity. (C.C)				
N	Colour				
C	Odometer. (Sp.Reading)				
C	Chassis No				
N	General Condition				
N	Steering				
N	Brake				
N	Modification (Modi)				
C	Tyre Size				
N	Tyre Make				
C	Tyre Balance				
C	Date of Inspection				
N	Survey held				
N	Des.of Damages				

C Damaged Vehicle Photographs Uploaded

N	ALL Parts condition
C	Market Value for OD cases
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)
C	Days of repair
C	Finalised Amount
C	Re-inspection Cases to Finalize within 5 Days

C Resurvey photo Uploaded

	13/7/18
Case Handler	Date

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS3/MSG17020587/R1qb-1

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 12-02-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YL 1437H	Veh. Inspected	XD 1032X
Policy No.		Coverage (\$)	0.00
Claim No.	M534409	Excess (\$)	0.00
Assign From	MERIMEN (CHRISTINA WONG)	Assign Date	12/02/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	20/10/2017	Inspection Date	12/02/2018
Survey held at	LYS ENGINEERING 27A JURONG PORT RD #01-24/26 SINGAPORE 619101		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Oct 2017		27 Oct 2017 11:10 Edit Adj Rpt	\$50.00 Edit Estimates	\$50.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TAR HONG PTE LTD, Co. Reg. No.: 199202627M		
Main Claimant:	SAB LOGISTICS PTE LTD, Co. Reg. No.: 200403878N		
Vehicle Reg. No.:	XD1032X	Date of Loss:	20/10/2017 00:00 - :59
Claim Type:	TP / 534409	Policy/Cover Note No.:	28639715MKC Coverage: 12/12/2016 - 11/12/2017
Vehicle Reg. No. (Insured):	YL1437H	Policy No. (Claimant):	
		Excess:	
Repairer:	Lys Engineering (JURONG) 27A JURONG PORT ROAD, 619101 Jurong East - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 14/02/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

- MSIG_SG (12/02/2018): Report Send Back Alerts - XD1032X (TP)

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Christina Wong <Christina_Wong@sg.msig-asia.com>
Sent: Monday, 12 February 2018 12:02 PM
To: Veron Chen (LKKAuto)
Cc: Catherine Chong (LKK Auto)
Subject: Our ref:M534409 Tp XD1032X DOA 20.10.2018-URGENT

Dear Veron

Please do a paper survey Urgently as we have received ten days notice, last day is today.

Please expedite report, survey report has been sendback through Merimen





Thanks

Best Regards

Christina Wong
Senior Executive, Claims Services (Motor)
Direct line +65 6643 1311 | Direct fax +65 6225 7402 | christina_wong@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | <http://www.msig.com.sg/> | Follow us on    

A member of  INSURANCE GROUP

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

REG/CS/PAY/FA
2.6 OCT 2017

LYS ENGINEERING

WORKSHOP : 27A JURONG PORT RD #01-24/26 S 619101

MAILING ADDRESS : BLK 138 #11-411 BUKIT BATOK WEST AVE 6 S650138

HP : 97308695 FAX : ~~68993276~~ 66748965

Specialise In Repairing All Kinds Of Motor Vehicles, Spray Painting, Welding
And Agent To Claim Damages From Motor Insurance

Your Vehicle : YL 1437H (3rd Party Vehicle)

Our Vehicle : XD 1032X

Date : 23/10/17.

M/s MSIG Insurance (Singapore) Pte Ltd.
4 Shenton Way
#21-01 SGX Centre II
Singapore 068807
Fax : 68277660

* By Fax Only *

Dear Sir,

ACCIDENT INVOLVING XD 1032X & YL 1437H ON 20/10/17 0945am.

We refer to the above matter.

I hereby give you 2 days' notice to conduct a pre-repair inspection of vehicle

XD 1032X at

Pls call Steven Loo @ HP 97308695.

1 Jalan Samulun
S 629119

Yours faithfully,



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/10/2017 16:31
Date Of Accident	20/10/2017 09:45
Exact Location Of Accident	SLE TOWARD TURF CLUB AVENUE
Country/State Of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	XD1032X
Insured/Policyholder	
Name Of Registered Owner	SAB LOGISTICS PTE. LTD.
Co Reg No	200403878N
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62659370
Vehicle Particulars	
Manufacturer	NISSAN
Model	CKB45ABTN2-12.5 D (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	Z/17/VC10/100596
Cover Note Number	
Driver	
Name of Driver	XIANG HONGWEI
Passport No/FIN	G7841237U
Date Of Birth	23/10/1983
Occupation	OUTDOOR
Date Of Driving Pass	23/04/2012
Driving Experience	5 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

AS PER SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YL1437H

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver RAMALINGAN NAGARAJAN

NRIC/Passport Number G7505422Q

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Record's Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time.

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

0A. 20/10/17 @ 9.45 am
Location SLE two turf club Ave
I was driving on the left lane of SLE
when veh B swerved into my lane and hit
the right side of my vehicle, before
swerving back to his lane He later stopped
further in front, on the left lane.
no at fault
witness by / clear
TP driver: Ramalingam Nagarajan
G 25034226

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters
Blk 2 Rivervale Link, #09-02 Singapore 545040
Tel/Fax: 6886 1106 Mobile: 9007 5234
Email: constant_as@yahoo.com.sg
RCB No. 53138015K

Automobile Inspection Report

To: SAB Logistics Pte Ltd
c/o Blk 138 Bukit Batok West Ave 6
#11-411
Singapore 650138

Date : 21/11/2017
Reference No : CAS/17-11/055

General Information

Registration No. : XD 1032X
Accident Date : 20/10/2017

Particulars of Damaged Vehicle

Colour	: Yellow	Make & Model	: Nissan CKB45ABTN2
Engine Capacity	: 12503 cc	Pre-Accident Condition	: Good
Mileage (KM)	: 956178	Engine No.	: PF6170683C
Chassis No.	: CKB45ABT00798	Steering	: In Order
Registration Date	: 25/09/2006	Brake	: In Order

Tyre Condition

	Size	Make	Balance
R/H Front Tyre	295/80R22.5	PIRELLI	90%
L/H Front Tyre	295/80R22.5	PIRELLI	90%
R/H Rear Tyre	295/80R22.5 (D)	LINGLONG	90% / 90%
L/H Rear Tyre	295/80R22.5 (D)	CONTINENTAL	40% / 40%

Inspection

Repairer : LYS Engineering
Blk 138 Bukit Batok West Ave 6, #11-411, Singapore 650138

Adjustment And Recommendation Cost Of Repair

Repairer's Estimate : \$18,319.12
Revised Amount : \$12,400.00
Less Excess : -
Nett Total : \$12,400.00

Remarks

- (A) Survey was done on 30/10/2017
(B) The survey was conducted entirely on WITHOUT PREJUDICE basis.
(C) We have NOT given any instruction to authorize the repair of the vehicle.

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

Constant Appraiser Services

Vehicle No : XD 1032X

Our ref : CAS/17-11/055

Adjustment On Repair Costs And Replacement Of Parts:

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
<u>PARTS REPLACEMENT - LIST ITEMS</u>					
1	1pc	Front corner panel RH	Broken	481.60	481.60 Xsu
2	1pc	Front corner outer garnish RH	Broken	241.20	241.20 Xsu
3	1pc	Front headlamp lower moulding RH	Twisted/Broken	181.60	181.60
4	1pc	Front bumper	Repair	2,431.60	-
5	1pc	Front door RH	Dented/Warped	4,856.50	4,856.50 Rx
6	1pc	Front door checker RH	Bent	68.50	68.50 Xsu
7	2pcs	Front door hinge RH @ \$86.50	Bent	173.00	173.00 Rx
8	1pc	Front step board bottom RH	Twisted/Grazed	426.50	426.50 Rx
9	1pc	Front step board stay RH	Bent	560.50	560.50
10	1pc	Front step board top RH	Twisted/Grazed	426.50	426.50
11	1pc	Front step panel structure RH	Grazed/Cut	380.60	380.60
12	1pc	Front step panel structure lower trim RH	Grazed/Cut	112.00	112.00
13	1pc	Front wheel arch panel RH	Broken	1,085.60	1,085.60 ✓
14	1pc	Front wheel arch panel top rubber step RH	Broken	311.65	311.65
15	1pc	Front wheel arch step garnish RH	Grazed/Broken	342.60	342.60
16	1pc	Front wheel arch splash shield RH	Serviceable	91.60	-
17	1pc	Front wheel guard RH	Broken	241.60	241.60
18	1pc	Radiator spare tank	Dented	167.30	167.30
19	1pc	Brake air tank	Dented	1,520.60	1,520.60 ✓
20	1pc	Brake air tank bracket	Twisted	311.45	311.45 Xsu
				14,412.50	11,889.30
		Less 30%		(4,323.75)	(3,566.79)
		Sub total		10,088.75	8,322.51
<u>PARTS REPLACEMENT - NETT ITEMS</u>					
1	1pc	Front headlamp RH	Serviceable	480.60	-
2	1pc	Front side lamp RH	Cracked/Broken	191.60	191.60
3	1pc	Front door signal lamp RH	Broken	121.60	121.60
4	1pc	Front door emblem 'UD' RH	Necessary	89.65	89.65
5	1pc	Front door glass run channel RH	Necessary	165.50	165.50 Xsu ✓
6	1pc	Rear side tool box	Dented	680.00	680.00
7	1pc	Rear side tool box bracket	Twisted	220.50	220.50 R

Constant Appraiser Services

Vehicle No : XD 1032X

Our ref : CAS/17-11/055

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
<u>PARTS REPLACEMENT – NETT ITEMS (CONT'D)</u>					
8	1pc	Battery cover	Dented/Deformed	324.15	324.15 <i>X su</i>
9	1pc	Fuse box cover	Deformed	61.80	61.80 <i>X su</i>
10	1pc	Rear mudguard RH	Dented/Deformed	850.00	850.00
11	1pc	Rear mudguard bracket RH	Twisted	315.00	315.00 <i>R</i>
12	1pc	Rear mudflap RH	Broken	88.90	88.90
				3,589.30	3,108.70
		Less 10%		(358.93)	(310.87)
		Sub total		3,230.37	2,797.83
<u>PARTS REPLACEMENT – SPECIAL NETT ITEMS</u>					
1	1pc	Side step RH	Dented/Twisted	480.00	480.00
2	1pc	Rear fog lamp RH	Broken	210.00	210.00
3	1pc	Rear fog lamp bracket RH	Twisted	110.00	110.00
4	1pc	Rear platform	Dented/Twisted	980.00	980.00 <i>R</i>
		Sub total		1,780.00	1,780.00
<u>LABOUR & MISC. CHARGES</u>					
1		To remove, refix interior upholstery trim		120.00	80.00
2		To checkup front electrical wiring		80.00	60.00
3		To respray undercoating		120.00	90.00
4		To respray painting & etc		1,300.00	1,100.00 <i>800</i>
5		Panel beating, remove & replacing above parts		1,500.00	1,200.00 <i>1000</i>
6		To remove, refix door mechanism		100.00	70.00 <i>✓</i>
		Grand total		18,319.12	15,500.34
Recommended cost of lump sum repair (To its pre-accident condition)					12,400.00

Constant Appraiser Services

Vehicle No : XD 1032X

Our ref : CAS/17-11/055

Adjustment/Recommendations

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of \$12,400.00 on a contractual basis. Under normal circumstances, the repair period would be about 6 (Six) working days.

Yours faithfully,

Constant Appraiser Services



Lim Long Tian (Sebastian)
Licensed Appraiser
Adv. Dip. In Mechanical Engineering (AUS)
MSAAA

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Oct 2017		27 Oct 2017 11:10 Edit Adj Rpt	S\$6,750.00 Edit Estimates	S\$6,750.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TAR HONG PTE LTD, Co. Reg. No.: 199202627M		
Main Claimant:	SAB LOGISTICS PTE LTD, Co. Reg. No.: 200403878N		
Vehicle Reg. No.:	XD1032X	Date of Loss:	20/10/2017 00:00 - :59
Claim Type:	TP / 534409	Policy/Cover Note No.:	28639715MKC Coverage: 12/12/2016 - 11/12/2017
Vehicle Reg. No. (Insured):	YL1437H	Policy No. (Claimant):	
		Excess:	
Repairer:	Lys Engineering (JURONG) 27A JURONG PORT ROAD, 619101 Jurong East - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 14/02/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

- MSIG_SG (12/02/2018): Report Send Back Alerts - XD1032X (TP)

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)



































Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents
































































































***XD1032X (534409)**
[YL1437H]
TP
SAB LOGISTICS PTE LTD
Oct 20 2017 12:00AM
[TAR HONG PTE LTD]
Lys Engineering

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/11/17 18:57	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
2	14/11/17 18:57	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
3	14/11/17 18:57	General View	 Load JPG	<input checked="" type="checkbox"/>
4	14/11/17 18:57	General View	 Load JPG	<input checked="" type="checkbox"/>
5	14/11/17 18:57	General View	 Load JPG	<input checked="" type="checkbox"/>
6	14/11/17 18:57	General View	 Load JPG	<input checked="" type="checkbox"/>
7	14/11/17 18:57	General View	 Load JPG	<input checked="" type="checkbox"/>
8	14/11/17 18:57	General View	 Load JPG	<input checked="" type="checkbox"/>
9	14/11/17 18:57	General View	 Load JPG	<input checked="" type="checkbox"/>
10	14/11/17 18:57	General View	 Load JPG	<input checked="" type="checkbox"/>
11	14/11/17 18:57	General View	 Load JPG	<input checked="" type="checkbox"/>
12	14/11/17 18:57	General View	 Load JPG	<input checked="" type="checkbox"/>
13	14/11/17 18:57	General View	 Load JPG	<input checked="" type="checkbox"/>
14	14/11/17 18:57	General View	 Load JPG	<input checked="" type="checkbox"/>
15	14/11/17 18:57	General View	 Load JPG	<input checked="" type="checkbox"/>
16	14/11/17 18:57	General View	 Load JPG	<input checked="" type="checkbox"/>
17	14/11/17 18:57	General View	 Load JPG	<input checked="" type="checkbox"/>
18	14/11/17 18:57	General View	 Load JPG	<input checked="" type="checkbox"/>
19	14/11/17 18:57	General View	 Load JPG	<input checked="" type="checkbox"/>
20	14/11/17 18:57	General View	 Load JPG	<input checked="" type="checkbox"/>
21	14/11/17 18:57	General View	 Load JPG	<input checked="" type="checkbox"/>
22	14/11/17 18:57	General View	 Load JPG	<input checked="" type="checkbox"/>
23	14/11/17 18:57	General View	 Load JPG	<input checked="" type="checkbox"/>
24	14/11/17 18:57	General View	 Load JPG	<input checked="" type="checkbox"/>
25	14/11/17 18:57	General View	 Load JPG	<input checked="" type="checkbox"/>
26	14/11/17 18:57	General View	 Load JPG	<input checked="" type="checkbox"/>
27	14/11/17 18:57	General View	 Load JPG	<input checked="" type="checkbox"/>
28	14/11/17 18:57	General View	 Load JPG	<input checked="" type="checkbox"/>
29	14/11/17 18:57	General View	 Load JPG	<input checked="" type="checkbox"/>
30	14/11/17 18:57	General View	 Load JPG	<input checked="" type="checkbox"/>
31	14/11/17 18:57	General View	 Load JPG	<input checked="" type="checkbox"/>
32	14/11/17 18:57	General View	 Load JPG	<input checked="" type="checkbox"/>
33	14/11/17 18:57	General View	 Load JPG	<input checked="" type="checkbox"/>
34	14/11/17 18:57	General View	 Load JPG	<input checked="" type="checkbox"/>

			1		✓
35	14/11/17 18:57	General View	1	Load JPG	✓
36	14/11/17 18:57	General View	1	Load JPG	✓
37	14/11/17 18:57	General View	1	Load JPG	✓
38	14/11/17 18:57	General View	1	Load JPG	✓
39	14/11/17 18:57	General View	1	Load JPG	✓
40	14/11/17 18:57	General View	1	Load JPG	✓
41	14/11/17 18:57	General View	1	Load JPG	✓
42	14/11/17 18:57	General View	1	Load JPG	✓
43	14/11/17 18:57	General View	1	Load JPG	✓
44	14/11/17 18:57	General View	1	Load JPG	✓
45	14/11/17 18:57	General View	1	Load JPG	✓
46	14/11/17 18:57	General View	1	Load JPG	✓
47	14/11/17 18:57	General View	1	Load JPG	✓
48	14/11/17 18:57	General View	1	Load JPG	✓
49	14/11/17 18:57	General View	1	Load JPG	✓
50	14/11/17 18:57	General View	1	Load JPG	✓
51	14/11/17 18:57	General View	1	Load JPG	✓
52	14/11/17 18:57	General View	1	Load JPG	✓
53	14/11/17 18:57	General View	1	Load JPG	✓
54	14/11/17 18:57	General View	1	Load JPG	✓
55	14/11/17 18:57	General View	1	Load JPG	✓
56	14/11/17 18:57	General View	1	Load JPG	✓
57	14/11/17 18:57	General View	1	Load JPG	✓
58	14/11/17 18:57	General View	1	Load JPG	✓
59	14/11/17 18:57	General View	1	Load JPG	✓
60	14/11/17 18:57	General View	1	Load JPG	✓
61	14/11/17 18:57	General View	1	Load JPG	✓
62	14/11/17 18:57	General View	1	Load JPG	✓
63	14/11/17 18:57	General View	1	Load JPG	✓
64	14/11/17 18:57	General View	1	Load JPG	✓
65	14/11/17 18:57	General View	1	Load JPG	✓
66	14/11/17 18:57	General View	1	Load JPG	✓
67	14/11/17 18:57	General View	1	Load JPG	✓
68	14/11/17 18:57	General View	1	Load JPG	✓
69	14/11/17 18:57	General View	1	Load JPG	✓
70	14/11/17 18:57	General View	1	Load JPG	✓
71	14/11/17 18:57	General View	1	Load JPG	✓
72	14/11/17 18:57	General View	1	Load JPG	✓
73	14/11/17 18:57	General View	1	Load JPG	✓
74	14/11/17 18:57	General View	1	Load JPG	✓
75	14/11/17 18:57	General View	1	Load JPG	✓
76	14/11/17 18:57	General View	1	Load JPG	✓
77	14/11/17 18:57	General View	1	Load JPG	✓
78	14/11/17 18:57	General View	1	Load JPG	✓
79	14/11/17 18:57	General View	1	Load JPG	✓
80	14/11/17 18:57	General View	1	Load JPG	✓
81	14/11/17 18:57	Photographs of Damaged Parts	1	Load JPG	✓

82	14/11/17 18:57	Photographs of Damaged Parts		Load JPG	
83	14/11/17 18:57	Photographs of Damaged Parts		Load JPG	
84	14/11/17 18:57	Photographs of Damaged Parts		Load JPG	
85	14/11/17 18:57	Photographs of Damaged Parts		Load JPG	
86	14/11/17 18:57	Photographs of Damaged Parts		Load JPG	
87	14/11/17 18:57	Photographs of Damaged Parts		Load JPG	
88	14/11/17 18:57	Photographs of Damaged Parts		Load JPG	
89	14/11/17 18:57	Photographs of Damaged Parts		Load JPG	
90	14/11/17 18:57	Photographs of Damaged Parts		Load JPG	
91	14/11/17 18:57	Photographs of Damaged Parts		Load JPG	
92	14/11/17 18:57	Photographs of Damaged Parts		Load JPG	
93	14/11/17 18:57	Photographs of Damaged Parts		Load JPG	
94	14/11/17 18:57	Photographs of Damaged Parts		Load JPG	
95	14/11/17 18:57	Photographs of Damaged Parts		Load JPG	
96	14/11/17 18:57	Photographs of Damaged Parts		Load JPG	
97	14/11/17 18:57	Photographs of Damaged Parts		Load JPG	
98	14/11/17 18:57	Photographs of Damaged Parts		Load JPG	
99	14/11/17 18:57	Photographs of Damaged Parts		Load JPG	
100	14/11/17 18:57	Photographs of Damaged Parts		Load JPG	
101	14/11/17 18:57	Photographs of Damaged Parts		Load JPG	
102	14/11/17 18:57	Photographs of Damaged Parts		Load JPG	
103	14/11/17 18:57	Photographs of Damaged Parts		Load JPG	
104	14/11/17 18:57	Photographs of Damaged Parts		Load JPG	
105	14/11/17 18:57	Photographs of Damaged Parts		Load JPG	
106	14/11/17 18:57	Photographs of Damaged Parts		Load JPG	
107	14/11/17 18:57	Photographs of Damaged Parts		Load JPG	
108	14/11/17 18:57	Photographs of Damaged Parts		Load JPG	
109	14/11/17 18:57	Photographs of Damaged Parts		Load JPG	
110	14/11/17 18:57	Photographs of Damaged Parts		Load JPG	
111	14/11/17 18:57	Photographs of Damaged Parts		Load JPG	
112	14/11/17 18:57	Photographs of Damaged Parts		Load JPG	
113	14/11/17 18:57	Photographs of Damaged Parts		Load JPG	
114	14/11/17 18:58	Photo After Spray		Load JPG	
115	14/11/17 18:58	Photo After Spray		Load JPG	
116	14/11/17 18:58	Photo After Spray		Load JPG	
117	14/11/17 18:58	Photo After Spray		Load JPG	
118	14/11/17 18:58	Photo After Spray		Load JPG	
119	14/11/17 18:58	Photo After Spray		Load JPG	
120	14/11/17 18:58	Photo After Spray		Load JPG	
121	14/11/17 18:58	Photo After Spray		Load JPG	
122	14/11/17 18:58	Photo After Spray		Load JPG	
123	14/11/17 18:58	Photo After Spray		Load JPG	
124	14/11/17 18:58	Photo After Spray		Load JPG	
125	14/11/17 18:58	Photo After Spray		Load JPG	
126	14/11/17 18:58	Photo After Spray		Load JPG	
127	14/11/17 18:58	Photo After Spray		Load JPG	
128	14/11/17 18:58	Photo After Spray		Load JPG	
129	14/11/17 18:58	Photo After Spray		Load JPG	

130	14/11/17 18:58	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
131	14/11/17 18:58	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
132	14/11/17 18:58	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
133	14/11/17 18:58	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
Documentation					
				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	27/10/17 11:11	PRI	1	Load PDF	
2	04/12/17 09:22	TPD XD1032X GIA REPORT.	1	Load PDF	
3	04/12/17 09:22	CONSTANT APPRAISER SERVICES INSPECTION REPORT- XD1032X	1	Load PDF	
4	04/12/17 09:22	TP SURVYOR PHOTO - XD1032X.	1	Load PDF	
5	04/12/17 09:22	TP SURVYOR PHOTO 2 - XD1032X	1	Load PDF	
6	04/12/17 09:22	TP SURVYOR PHOTO 3 - XD1032X	1	Load PDF	
7	04/12/17 09:22	TP SURVYOR PHOTO 4 - XD1032X.	1	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	14/02/18 09:10	PRS INVOICE	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG17020587/R1QBS2-1
Date: 14/02/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28639715MKC

Claimant Vehicle No: XD1032X

Insured Vehicle No: YL1437H

Date of Loss: 20/10/2017

Nature of Claim: TP

Claim No: 534409

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: XD1032X

Make & Model: NISSAN CKB45ABTN2, 12.5 D (M)

Engine No: PF6170683C

Reg. Date: 25/09/2006 (Man. Year: 2006)

Chassis No: CKB45ABT00798

Colour: Yellow

Odometer: 956178 km

Engine Capacity: 12503 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes

Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5

Rear Tyre Size: 295/80 R22.5 (D)

Front Left Side: Pirelli 8 mm

Rear Left Side: Pirelli 8/8 mm

Front Right Side: Pirelli 8 mm

Rear Right Side: Pirelli 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,099.12	6,350.95	8,748.17	57.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,220.00	2,100.00	1,120.00	34.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,319.12	8,450.95	9,868.17	53.87
Approved Total (Overridden) (S\$)		6,750.00		
Nett Amount (S\$)	18,319.12	6,750.00	11,569.12	63.15

INSPECTION

Date of Assignment: 27/10/2017

Date Inspected: 30/10/2017

Inspected At:

Lys Engineering (JURONG)
27A JURONG PORT ROAD
Singapore 619101

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 14 Feb 2018)	
Parts:	N/A	NISSAN CKB45ABTN2 12.5 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XD1032X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT CORNER PANEL RH	Serviceable	481.60 FL	*- FL
2	1		*FRONT CORNER OUTER GARNISH RH	Serviceable	241.20 FL	*- FL
3	1		*FRONT HEADLAMP LOWER MOULDING RH	Twisted / Broken	181.60 FL	*181.60 FL
4	1		*FRONT BUMPER	Repair	2,431.60 FL	*- FL
5	1		*FRONT DOOR RH	Repair	4,856.50 FL	*- FL
6	1		*FRONT DOOR CHECKER RH	Serviceable	68.50 FL	*- FL
7	2		*FRONT DOOR HINGE RH	Repair	173.00 FL	*- FL
8	1		*FRONT STEP BOARD BOTTOM RH	Repair	426.50 FL	*- FL
9	1		*FRONT STEP BOARD STAY RH	Bent	560.50 FL	*560.50 FL
10	1		*FRONT STEP BOARD TOP RH	Twisted / Grazed	426.50 FL	*426.50 FL
11	1		*FRONT STEP PANEL STRUCTURE RH	Grazed / Cut	380.60 FL	*380.60 FL
12	1		*FRONT STEP PANEL STRUCTURE LOWER RIM RH	Grazed / Cut	112.00 FL	*112.00 FL
13	1		*FRONT WHEEL ARCH PANEL RH	Broken	1,085.60 FL	*1,085.60 FL
14	1		*FRONT WHEEL ARCH PANEL TOP RUBBER STEP RH	Broken	311.65 FL	*311.65 FL
15	1		*FRONT WHEEL ARCH STEP GARNISH RH	Grazed / Broken	342.60 FL	*342.60 FL
16	1		*FRONT WHEEL ARCH SPLASH SHIELD RH	Serviceable	91.60 FL	*- FL
17	1		*FRONT WHEEL GUARD RH	Broken	241.60 FL	*241.60 FL
18	1		*RADIATOR SPARE TANK	Dented	167.30 FL	*167.30 FL
19	1		*BRAKE AIR TANK	Dented	1,520.60 FL	*1,520.60 FL
20	1		*BRAKE AIR TANK BRACKET	Serviceable	311.45 FL	*- FL
21	1		*FRONT HEADLAMP RH	Serviceable	480.60 FN	*- FN
22	1		*FRONT SIDE LAMP RH	Cracked / Broken	191.60 FN	*191.60 FN
23	1		*FRONT DOOR SIGNAL LAMP RH	Broken	121.60 FN	*121.60 FN
24	1		*FRONT DOOR EMBLEM UD RH	Necessary	89.65 FN	*89.65 FN
25	1		*FRONT DOOR GLASS RUN CHANNEL RH	Serviceable	165.50 FN	*- FN
26	1		*REAR SIDE TOOL BOX	Dented	680.00 FN	*680.00 FN
27	1		*REAR SIDE TOOL BOX BRACKET	Repair	220.50 FN	*- FN
28	1		*BATTERY COVER	Serviceable	324.15 FN	*- FN
29	1		*FUSE BOX COVER	Serviceable	61.80 FN	*- FN
30	1		*REAR MUDGUARD RH	Dented / Deformed	850.00 FN	*850.00 FN
31	1		*REAR MUDGUARD BRACKET RH	Repair	315.00 FN	*- FN
32	1		*REAR MUDFLAP RH	Broken	88.90 FN	*88.90 FN
33	1		*SIDE STEP RH	Dented / Twisted	480.00 FS	*480.00 FS
34	1		*REAR FOG LAMP RH	Broken	210.00 FS	*210.00 FS
35	1		*REAR FOG LAMP BRACKET RH	Twisted	110.00 FS	*110.00 FS
36	1		*REAR PLATFORM	Repair	980.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc, N=NettItemDisc.

Sub Total (\$\$)	19,781.80	8,152.30
- List Item Discount on L Items 30.00/30.00% (\$\$)	4,323.75	1,599.17
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	358.93	202.18

Total Parts (\$\$)	15,099.12	6,350.95
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
-----	-----	----------	-------------	-----------	------------	--------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REFIX INTERIOR UPHOLSTERY TRIM.	New	120.00	80.00
2	TO CHECKUP FRONT ELECTRICAL WIRING.	New	80.00	60.00
3	TO RESPRAY UNDERCOATING.	New	120.00	90.00
4	TO RESPRAY PAINTING & ETC.	New	1,300.00	800.00
5	PANEL BEATING, REMOVE & REPLACING ABOVE PARTS.	New	1,500.00	1,000.00
6	TO REMOVE, REFIX DOOR MECHANISM.	New	100.00	70.00
Gross Labour Cost (S\$)			3,220.00	2,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >