

Auto Insure Pte. Ltd.

AULO III SUBJECT STATES AND AUGUST AND AUGUST AND AUGUST AND AUGUST AUGU

AUTOMOBILE ASSESSMENT REPORT

Page No.1

Our Ref: SLH9690P Your Ref: SDF9243C

ate: 9-Feb-18

BY EMAIL ONLY (claims@autoinsure.com.sg)

ATTENTION: MOTOR CLAIMS DEPT

email: motor.survey@axa.com.sg

8 Shenton way #27-01/02 AXA Tower Singapore 068811

Assessed Vehicle No

: SLH9690P

Car Make and Model

: MITSUBISHI ATTRAGE 1.2 CVT

Date of Accident
Date of Assessment

: 31-Jan-18 : 9-Feb-18

We have carried out a physical assessment of SLH9690P at our workshop Auto Insure Pte Ltd sustained damages to the REAR RH portion of the vehicle.

4. DESCRIPTION OF DAMAGE

At the time of the inspection observed that this vehicle had sustained damages to the REAR RH portion of the vehicle.

Please see attached schedule for details.

Remarks: NIL

Estimated Amount

P/P

Adjusted Amount

: \$ 6,100.00

Est. Repair Days

** Considering that our vehicle is less than 6 months old.

We will not agree to any repair of parts, only replacement will be done. **

Pursuant to your instruction, we have <u>NOT AUTHORIZED</u> repair.

The assessment was conducted on a "<u>WITHOUT PREJUDICE</u>" basis.

If we are not notified of anything within 14 Days from the date hereof, this report shall be treated


as correct.

Disclaime

This report is intended for the exclusive use of the adressee solely in relation to the loss of occurrence in which the assessd vehicle is involved.

No liability or responsibilty whatsoever shall be held by

AUTO INSURE PTE. LTD. For any reliance on this report by any third party.



Our Ref: Your Ref: SLH9690P SDF9243C

s/NO	QTY	DESCRIPTIONS	DESCRIPTIONS ASSESSED CONDITION		EST. BY WORKSHOP	
		PARTS REPLACEMENT - LIST ITEMS				
1	1	REAR BUMPER		\$	1,326.50	
2	2	REAR BUMPER REFLECTOR		\$	380.00	
3	1	REAR BUMPER SIDE RETAINER		\$	118.00	
4	1	REAR END PANEL		\$	658.00	
5	1	REAR FENDER RH		\$	691.80	
1	1	RIM		\$	500.00	
			SUB TOTAL	\$	3,674.30	
			LESS 20%	\$	734.86	
			TOTAL AMOUNT	\$	2,939.44	

S/NO	QTY	SPECIAL NETT ITEMS REAR REVERSE SENSOR	ASSESSED CONDITION	EST. BY WORKSHOP	
	2			\$	280.00
2	1 SET	REAR BUMPER CLIPS		\$	60.00
3	1	REAR LICENCE PLATE WITH HOLDER		\$	75.00
4	1	REAR END PANEL SEALANT		\$	80.00
5	1 SET	REAR FLOOR PANEL SOUND INSULATOR		\$	120.00
6	1	REAR BUMPER TOW CAP		\$	90.00
			SUB TOTAL	\$	705.00
			TOTAL PARTS COST	\$	3,644.44

SLH9690P

SDF9243C

S/NO	DESCRIPTION			WORKSHOP
	LABOUR & PAINTWORK			
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMM RESHAPE THE AFFECTED AREAS AND REPLACED TH COMPONENTS		\$	600.00 300
2	TOWING CHARGE		\$	100.00
3	TO CONDUCT HEADLAMP FO	cus	\$	
4	TO REMOVE/REFIX A/C CONDENSOR & REI	FILL AIRCON GAS	s	
5	TO REMOVE/INSTALL REAR WIND	OSCREEN	\$	
6	TO DIAGNOSE ERASE FAULT MEMORY /	AFTER REPAIR	\$	150.00
7	TO REMOVE / REFIX WIRING SYSTEM AT ACCIDENT AND O	CHECK FOR PROPER FUNCTIONS	\$	100.00
8	TO REMOVE / INSTALL REAR REVERS	SE SENSOR	\$	150.00 460
9	TO REMOVE / REFIX UPHOSTERY, GARNISH AND	ATTACHMENT PARTS	S	
10	TO REMOVE / REFIX REAR LUGGAGE CO	DMPARTMENT	\$	150.00
11	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PL	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED		600.00 449
12	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS		\$	150.00 40
13	TO VACUUM, WAXING & CLEAN		\$	100.00 40
14	TO PERFORM WATER SEEPAGE TEST ON REF	PAIRED PORTIONS	\$	100.00 30
		TOTAL BEFORE GST	\$	5,744.44
		GST 7%	\$	402.11
	7	TOTAL (PARTS & LABOUR):	\$	6,146.55

Adjustments / Recommendations

Our estimator have throughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

Our Workshop has agreed to undertake the job at a sum of \$6,100.00 for direct settlement with the third

Yours Faithfully,

Jason Heng Claims Director LKK Auto Consultants hence notify

- the Repairer of the following:
- To resurvey before/after spray painting To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date:

th the third Resurs

Resurs after report

enail: rasul @ Ikkanto. com