

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 14 Feb 2018

Preliminary Advice

Vehicle No	: SGL3534K	Accident Date	: 01/02/2018
Make	: LEXUS IS	Policy No.	: DMPCSN3050241700
Assignment Date	: 12/02/2018	Excess	: S\$1,500.00
Date of Inspection	: 13/02/2018	Est. Duration of Repair	: 0.00
Inspection At	: S & H MOTOR PTE LTD (SIN MING) 160 SIN MING DRIVE #07-02, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion, front n/s portion and o/s body. The undercarriage and body structure affected due to collision, and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	TOTAL LOSS
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	37,000.00
COE / PARF Rebate	:S\$	20,341.00
Salvage Value	:S\$	
Margin for Repair	:S\$	16,659.00

Brake System	: Leaked
Steering System	: Jammed
Tyre Condition (Front)	: 7/7 MM
Tyre Condition (Rear)	: 6/6 MM

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Pending interview insured.