

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD 5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEX SINGAPORE 069110 INV No. AC2007687

INV Date 16/11/2020

Reference CC6/EQI18002814/Ups3q2

Code EQ

PROFESSIONAL SERVICE FEE

Vehicle No. SKU 3997M Insured Veh. GBB 4558Y

Claim No.

Policy No. DMCPHQ17-001056

Accident Date 08/02/2018

Inspection Date 14/05/2018

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Internationale Des Experts En Automobile					
EQ INSUF	RANCE COM	PANY LTD	Ref : CC6/EQI18002814/Ups3q2			
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date: 16-11-2020				
4		Della Bedla Isra	Code: EQI			
1.	and Mala	-	:- THIRD PARTY CLAIM			
	ured Veh.	GBB 4558Y	Veh. Inspected	SKU 3997M		
	icy No.	DMCPHQ17-001056	Coverage (\$)	0.00		
	im No.		Excess (\$)	0.00		
	ign From		Assign Date	14/05/2018		
2.			culars & Condition			
	ke & Model	TOYOTA HIACE (A)	c.c	2982		
\vdash	jine No.	HIDDEN	Year of Reg.	2015		
	ssis No.	JTFST22P500022329	Colour	WHITE		
	ometer	224715	Steering	IN ORDER		
Bra		IN ORDER	Modification	NIL		
1 - 1 -	neral	GOOD				
3.			ons of Tyres			
		Size	Make	Balance		
	Front Tyre	195 R15	BRIDGESTONE	6 mm		
	Front Tyre	195 R15	BRIDGESTONE	6 mm		
	Rear Tyre	195 R15	BRIDGESTONE	6 mm		
	Rear Tyre	195 R15	BRIDGESTONE	6 mm		
4.			on of Damages			
THE	VEHICLE SUS	STAINED DAMAGES AT THE N/S	REAR PORTION.			
DAM	DAMAGES SEE DETAILS.					
5.		General	Information			
Acc	ident Date	08/02/2018	Inspection Date	14/05/2018		
Sur	vey held at	JIN AUTO SERVICES PTE LTD				
		BLK 14 DEFU LANE 10 #01-412 SINGAPORE 539195				
5a.		Re	emarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair						
EST	IMATED NORI	MAL PERIOD FOR REPAIR:	3 Working Days			



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKU 3997M

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	LABOUR			
	TO REPAIR & RESPRAY REAR LH FENDER PANEL .		600.00	400.00
	COMPANY ARTWORK.		380.00	300.00
			980.00	700.00
	GRAND TOTAL		980.00	700.00

RECOMMENDED COST OF REPAIRS			700.00
-----------------------------	--	--	--------

Report Ref No. CC6/EQI18002814/Ups3q2

CHUA KANG SENG

Licensed Appraiser



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKU 3997M

INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R











