



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS



AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN. : MOTOR CLAIMS FAX :		NAME : Mr Kang William ADDRESS : 171c Edgedale Plains #12-432 Singapore 823171 TEL : 97592564		WIP : 62344 EXCESS : DATE: 10-Feb-18	
VEH NO :	SFC9173M	DATE IN :		CONTACT PERSON :	JESS 6395 7874
CHASSIS NO :	JM6CW1071H0126540	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA5	DATE REG.:	29-Sep-17	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO		QTY		REVISED	PRICES
1	REAR BUMPER	1	MC513-50-221EBB	DD/De ✓	\$ 915.40
2	RETAINER(LHS), REAR BUMPER	1	MC513-50-2J1C	re ✓	\$ 45.30
3	RETAINER(RHS), REAR BUMPER	1	MC513-50-2H1B	re ✓	\$ 45.30
4	BRACKET(LHS), REAR BUMPER	1	MC513-51-077A	re ✓	\$ 5.40
5	BRACKET(RHS), REAR BUMPER	1	MC513-51-067A	re ✓	\$ 5.40
6	GUARD(LHS), REFLECTOR	1	MC513-50-371	11 X	\$ 20.50
7	REFLECTOR LHS	1	MD350-51-5L0E	11 X	\$ 50.40
8	GUARD(RHS), REFLECTOR	1	MC513-50-361	11 X	\$ 20.50
9	REFLECTOR RHS	1	MD350-51-5M0E	11 X	\$ 50.40
10	REAR REINFORCEMENT	1	MC235-56-B9XC	?	\$ 148.00
11	FASTENER, REAR BUMPER	2	MGD7A-50-EA1	re ✓	\$ 6.00
12	RIVET, REAR BUMPER	4	MBN8F-50-355	re ✓	\$ 21.60
13	GROMMET, REAR BUMPER	1	M9991-00-501	re ✓	\$ 2.80
14	GROMMET, REAR BUMPER	4	MBHN1-50-0Z1A	re ✓	\$ 10.00
15	GROMMET, REAR BUMPER	2	MC235-50-ES1	re ✓	\$ 8.80
16	PANEL, REAR END	1	MCG15-70-750B	1 X	\$ 491.10
17	TAILGATE	1	MCGY3-62-02XF	DD/54 ✓	\$ 1,559.00
18	VALVE ONEWAY, TAILGATE	2	MGHP9-58-867	re ✓	\$ 22.80
19	TRIM LOWER, TAILGATE	1	MC513-68-960B	11 X	\$ 411.40
20	WEATHERSTRIP, TAILGATE	1	MC513-62-761C	?	\$ 169.00
21	TAPE PROTECTOR, TAILGATE	2	MBR55-56-994	re ✓	\$ 14.40
22	TAPE PROTECTOR, TAILGATE	2	MTK48-62-864	re ✓	\$ 14.00
23	LOCK, TAILGATE	1	MC513-62-310A	?	\$ 244.00
24	GARNISH, TAILGATE	1	MC513-50-810F50	11 X	\$ 459.40
25	MAZDA, EMBLEM	1	MCGY0-51-711	re ✓	\$ 43.10
26	5, EMBLEM	1	MCGY0-51-721	re ✓	\$ 34.50
27	MASCOT, REAR	1	MTD11-51-731	re ✓	\$ 42.00
28	SKYACTIV, EMBLEM	1	MC597-51-771	re ✓	\$ 76.10
29	MOULD, REAR WINDSCREEN	1	MC513-50-611	re ✓	\$ 57.60
30	FASTENER, REAR WINDSCREEN	2	MD204-50-896A	re ✓	\$ 5.20

31	SPACER, REAR WINDSCREEN	1	MDJ01-50-897	mer ✓	\$ 6.80
32	FASTENER, REAR WINDSCREEN	2	MC273-50-896	mer ✓	\$ 15.60
33	SPACER, REAR WINDSCREEN	4	MGJ6A-50-897	mer ✓	\$ 48.40
34	PROTECTOR, REAR SPOILER	2	MC514-51-979B	mer ✓	\$ 10.40
35	PROTECTOR, REAR SPOILER	2	MC514-51-982B	mer ✓	\$ 22.80
36	PROTECTOR, REAR SPOILER	2	MC514-51-972B	mer ✓	\$ 26.80
37	CLIP, REAR SPOILER	3	MC514-51-958A	mer ✓	\$ 21.90
38	CLIP, REAR SPOILER	1	MC525-51-958A	mer ✓	\$ 8.20
39	GASKET(LHS), TAILGATE LAMP	1	MC513-51-3J8	mer ✓	\$ 90.80
40	GASKET(RHS), TAILGATE LAMP	1	MC513-51-3H8	mer ✓	\$ 90.80
TOTAL PARTS					\$ 5,341.90
LESS 10%					\$ 534.19
TOTAL PARTS COST					\$ 4,807.71
Labour Description					
1	MZ-BR-REAR06	TO REPLACE REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND TAILGATE.REPAIR ALL AREAS AFFECTED BY THE ACCIDENT. 660		1320	\$ 4,620.00
2	MZ-SP-SREAR6	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND TAILGATE. 630		1890	\$ 3,780.00
3	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING		11X	\$ 350.00
4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.		150	\$ 250.00
5	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.		330	\$ 660.00
6	MZ-BR-GLASS1	TO REMOVE & REFIT THE WINDSCREEN GLASS.		NETT ✓	\$ 560.00
7	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS. mer		NETT ✓	\$ 120.00
8	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.		200	\$ 660.00
9	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.		200	\$ 660.00
10	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE. 500		NETT ✓	\$ 70.00
11	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		120	\$ 250.00
12	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		150	\$ 350.00
13	MZ-BR-SUNDRI	SUNDRIES. mer 30		NETT	\$ 100.00
TOTAL LABOUR					\$ - \$ 12,430.00

TOTAL PARTS	\$ -	\$ 4,807.71
TOTAL	\$ -	\$ 17,237.71
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

TRANS EUROKARS PTE LTD

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Authorised Signature

Not Authorized

*LKK
14/2/18*

*Take photo before painting
tel. 62533561*

6 day confirmed.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: